

(08/11/13) wef

ASS. REC. BY: *Marius*

REF:

CS/TP19010637/UGD3 n2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

Cor 30-6-2024

Vehicle: IN / OUT

Veh No:

Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / *PIR* / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: *Frnt* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) *24/6/19*

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

170+15

50

50+50

83

80

498

RECEIVED 24 JUN 2019

Ref. No : <u>CS/TP19010637/Uqd3</u>	Res. Date: <u>17/6/18</u>	Date Received:
Veh. No : <u>SJ55122E</u>	SP: _____	WKSP: <u>Bury</u>
C/No : _____		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME

NEW CARS | PRE-LOVED CARS | INSURANCE |

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Feb 2014 Audi A6 2.0 TFSI MU.



100% Accident Free. Serviced
 By Audi Workshop. No Repairs
 Needed. High COE.
 Direct Owner. StarAd.

click here to view
 our **PRISTINE**
 at

Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted

71 vehicles

stream

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	stream	Any	Any	2009	Any	Any	
	Honda Stream 1.8A RSZ (COE till 05/2024)	\$36,800	\$7,530 /yr	07-May-2009	1,799 cc	-	
3.18% Per Annum. \$788 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gear Metallic Paint. New Pure Leather. New Rims, 16" Tyres. New Pi...							
3.18%P.A \$0 Admin Fees@Gv Finance. 2 Years Warranty.\$2500 Down Monthly From \$638							
GV Credit Pte Ltd							
Posted: 18-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda							
	Honda Stream 1.8A (COE till 05/2024)	\$35,800	\$7,290 /yr	15-May-2009	1,799 cc	-	
3.18% Per Annum. \$638 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gear Metallic Paint. New Pure Leather. New Rims, 16" Tyres. New Pi...							
3.18%P.A \$0 Admin Fees@Gv Finance. 2 Years Warranty.\$2500 Down Monthly From \$638							
GV Credit Pte Ltd							
Posted: 18-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda							
	Honda Stream 1.8A X (COE till 04/2024)	\$35,800	\$7,350 /yr	04-May-2009	1,799 cc	-	
Full Loan Available At \$800 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Sch Fast, Easy And Flexible Loan Approval! We Are sgCarMart...							
88 Motor Trading							
Posted: 17-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda							
	Honda Stream 1.8A (COE till 05/2024)	\$35,800	\$7,220 /yr	05-Jun-2009	1,799 cc	-	
3.18% Interest Rate Per Annum. \$638 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims, 16"...							
GV Credit Pte Ltd							
Posted: 17-Jun-2019 Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda							

Is your COE expiring? Let us help you renew it!

ur COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town 2 days without effort! Enquire today.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2297G

Vehicle Details

Vehicle No.: SJS5122E

Vehicle to be Exported: No

Intended Deregistration Date: 18 Jun 2019

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8L A

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R18A13801020

Chassis No.: JHMRN68609S201001

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$25,100.00

Original Registration Date: 20 Aug 2009

First Registration Date: 20 Aug 2009

Transfer Count: 2

Actual ARF Paid: \$25,100.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Aug 2019

PARF Rebate Amount: \$12,550.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2024

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$21,504.00

COE Rebate Amount: \$319.00

Total Rebate Amount: \$12,869.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jun 2019

OK

11/06 2019 TUE 9:54 FAX

marcus

0001/009

MSME16075420 / SME Motor Pro Ltd - KKKU Bunk
 ENTRY DATE & TIME: 10/06/2019 15:41
 SUBMITTED BY: CHIA Pui Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/06/2019 15:41
 Date Of Accident 08/06/2019 14:30
 Exact Location Of Accident JUNCTION OF WOODLANDS AVE 12 & AVE 1
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJS5122E
 Insured/Policyholder
 Name Of Registered Owner CS LEASING & LIMOUSINE PTE LTD
 Co Reg No 201912297G
 Email Address NOEMAIL

Mobile Phone No
 Alternative Phone No OFFICE-82802277

Vehicle Particulars

Manufacturer HONDA
 Model STREAM

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5109035088-000004

Cover Note Number

Driver

Name of Driver LUQMAN HAKIM BIN KAMSAN

NRIC No S8607369B

Date Of Birth 15/03/1986

Occupation INDOOR

Date Of Driving Pass 07/05/2008

Driving Experience 11 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-92769923

Fax Number

Contact Number

Email Address NOEMAIL

11/06 2019 TUE 9:55 FAX

002/009

Address BLK 473 SEMBAWANG DRIVE #03-361
 Postcode 750473
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Passenger 1

NAME: : JURIAH BTE SELAMAT
 GENDER: : FEMALE

Passenger 2

NAME: : KAMSAN BIN RASMAN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

SEMBAWANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 4 SEMBAWANG CRESCENT, POSTCODE: 757633, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-5549999 - FAX NO: 68522499

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20190606/2138.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ7058T
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver

11/06 2019 TUE 9:55 FAX

003/009

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLR3981L

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

11/06/2019 TUE 9:55 FAX

0004/009

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BUNEL

Source: SketchPlanForm_V01

11/06 2019 TUE 9:56 PRX


005/009

Sketch Plan #2 Pg. 1

A - 5J5572E
 B - 5LJ70587
 C - 5LR3981L

SKETCH PLAN

Woodlands Ave 12



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Report

DECLARATION

I hereby declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

GMRMC SketchPlanForm_V3


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

11/06 2019 TUE 9:56 FAX

006/009

Sketch Plan #3 Pg. 1


**SINGAPORE
POLICE FORCE**


T/20190608/2138

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549399

1 of 4

Report No. T/20190608/2138

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/06/2019 22:57		Vide Report No.:		Station Diary No.: 178
Name of Informant: LUQMAN HAKIM BIN KAMSAN		Address: APT BLK 473 SEMBAWANG DRIVE #03-361 SINGAPORE 750473		
ID Type / ID No.: NRIC NO / S8607399B		Contact No.: Home/Office: Mobile: 92769623		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 33	Date of Birth: 15/03/1986	Type of Informant: Driver	
Race: Malay		Language:	Institution / School Name:	
Occupation: Air traffic controller		Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/06/2019 14:30	Type of Location:
Location: Junction of Road 1 and Road 2 WOODLANDS AVENUE 12 WOODLANDS AVENUE 1 Woodlands Ave 12 junction of Woodlands Ave 1 towards BKE				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Vehicle No.	Vehicle Type	Damage	Count
SJS5122E	Car	Slightly Damaged	2
SLJ7058T	Car	Slightly Damaged	0
SLR3981L	Car	Slightly Damaged	0

11/06 2019 TUE 9:57 FAX

007/009

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190608/2138

2 of 4

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20190608/2138

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	LUQMAN HAKIM BIN KAMSAN	ID No.	S8607369B
Related Vehicle	SJS5122E (Car)	Contact No.	92769923
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	08/06/2019	Date Discharge	08/06/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Name	IVAN TAN WEN QUAN	ID No.	S8423092F
Related Vehicle	SLJ7058T (Car)	Contact No.	88153439
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	LEE KONG LEON, JEFFERSON	ID No.	S7820778J
Related Vehicle	SLR3981L (Car)	Contact No.	96385285
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 08/06/2019 at about 1430hrs, I was driving a rented vehicle, SJS5122E along Woodlands Ave 12 junction of Woodlands Ave 1 towards BKE. The traffic light just turns green as such the vehicle in front of me moved off. I was about to drive off when my vehicle got hit from the vehicle at the back, SLJ7058T.

Subsequently, I went out from my vehicle to make a check. It was a collision between two other cars, SLJ7058T and SLR3981J. According to the last vehicle's driver, he was not paying attention to the front when he accidentally presses onto his accelerator causing him to hit the vehicle in front of him. Due to the impact, the vehicle had also slightly hit onto my vehicle.

11/06 2019 TUE 9:57 FAX

0008/009

Sketch Plan #5 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20190608/2138

3 of 4

Report No. T/20190608/2138

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT

The damage of my vehicle is heavily dented at the back of my vehicle.

The damages of the vehicle behind me, SLJ7058T were dents on the front and back of the vehicle and the bumper nearer to the right came off.

The damage of the last vehicle, SLR3981L was the right and left fog lamp were broken.

During the accident, no one was injured. As such, we exchanged particulars.

While I was driving off, I felt pain at my neck and lower back as such I went to get it check at National University Hospital. I was then given a 4 days MC. My mother who was the back passenger received 4 days MC as well at NUH.

11/06 2019 TUE 9:57 FAX

009/009

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549990



T/20190608/2138

4 of 4

Report No. T/20190608/2138

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L /

Sgt 2 WAN FARAH DINA BINTE SAIFULLIZAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sgt 3 KOH CHEE SENG, KEVIN
Contact No.: 65472073

Authentication Stamp
NP 158

Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:
08/08/2019 22:57

Classification Of Case:



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-33/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwei2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Not Authorized
 1/58 5500
 6dy.

SJS5122E

	Rear windscreen moulding	rec	86.50	✓
	Tailgate	body	903.20	✓
	Tailgate 'H' logo	rec	45.00	✓
	Tailgate 'stream' emblem	rec	32.20	✓
	Tailgate outer garnish	cne	266.30	✓
	Tailgate weatherstrip	twl	116.90	✓
	Tailgate inner lock	m	109.30	✓
	Tailgate inner trim board	re/cne	288.60	✓
	Tailgate inner trim board clips	rec	30.00	✓
	Rear bumper	DD	665.40	✓
2 pcs	Rear bumper side retainers @ 25.20	Bent	50.40	✓
1 set	Rear bumper clips	rec	30.00	✓
2 pcs	Rear bumper lower brackets @ 25.00	Bent	50.00	✓
2 pcs	Tail lamps @ 338.60	cne	677.20	✓
	Rear end panel	body	306.10	✓
	Rear end panel top garnish	twl	182.40	✓
2 pcs	Rear fenders @ 977.10	R	1954.20	X
2 pcs	Rear fender inner trim boards @ 316.50	re/cne	633.00	✓
	Rear spare tyre bracket	src	242.30	X
	Rear floor panel	R	911.40	X
		20%	758.40	4472.50
	S. Net			
	Rear windscreen sealant	rec	50.00	40
1 set	Rear bumper reverse sensor	shorts	300.00	200
1 set	Rear reverse camera	shorts	450.00	380
	Rear end panel sealant	rec	50.00	✓



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-28-53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

5JS5122G

To check wiring	\$0.00 - 30
To Dismantle & replacing reverse sensor	\$0.00 - 50
To Dismantle & refix rear windscreen	150.00 - 120
To transfer Tailgate mechanism	100.00 - 80
To Dismantle & refix seat cushion upholstery	120.00 - 100
To Dismantle & refix rear exhaust	100.00 80
To spray rust proofing	100.00 80
labour for sand beating & replacing parts	1080.00 900
To putty & spray painting	1500.00 - 1200
TOTAL \$11820.40	

By Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP19010637/Uqd3n2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 26-06-2019		
ON BEHALF OF CS LEASING & LIMOUSINE PTE LTD		Code : TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SJS 5122E	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		14/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMRN68609S201001	Colour	GREY	
Odometer	135683	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	PIRELLI	6 mm	
L/H Front Tyre	205/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2019	Inspection Date	14/06/2019	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 5122E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	86.50	86.50
1	TAILGATE	BADLY DENTED	903.20	903.20
1	TAILGATE 'H' LOGO	NECESSARY	45.00	45.00
1	TAILGATE 'STREAM' EMBLEM	NECESSARY	32.20	32.20
1	TAILGATE OUTER GARNISH	CRACKED	266.30	266.30
1	TAILGATE WEATHERSTRIP	TWISTED	116.90	116.90
1	TAILGATE INNER LOCK	DENTED	109.30	109.30
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	288.60	288.60
1	TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER	DENTED	665.40	665.40
2	REAR BUMPER SIDE RETAINER @\$25.20	BENT	50.40	50.40
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER LOWER BRACKETS @\$25.00	BENT	50.00	50.00
2	TAILLAMPS @\$338.60	CRACKED	677.20	677.20
1	REAR END PANEL	BADLY DENTED	306.10	306.10
1	REAR END PANEL TOP GARNISH	TWISTED	182.40	182.40
2	REAR FENDERS @\$977.10	TO REPAIR SEE LABOUR	1,954.20	-
2	REAR FENDER INNER TRIM BOARDS @\$316.50	DEFORMED / CRACKED	633.00	633.00
1	REAR SPARE TYRE BRACKET	SERVICEABLE	242.30	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	911.40	-
	LESS 20% DISCOUNT		-	-894.50
			7,580.40	3,578.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	450.00	380.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			850.00	670.00
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	30.00

Report Ref No. CS/TP19010637/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	80.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	100.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	80.00
	TO SPRAY RUST PROOFING.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDERS AND REAR FLOOR PANEL.		1,080.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,580.00	1,200.00
			3,390.00	2,640.00
GRAND TOTAL			11,820.40	6,888.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CS/TP19010637/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.