



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19009610/Ksd3e2-1

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 96Z	Veh. Inspected	SJR 2525B
Policy No.		Coverage (\$)	0.00
Claim No.	D19003503/CCPL/CJ – TPD1	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	30/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS G (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305117172	Colour	METALLIC BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FALKEN	4 mm
L/H Front Tyre	185/60 R15	FALKEN	4 mm
R/H Rear Tyre	185/60 R15	FALKEN	5 mm
L/H Rear Tyre	185/60 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/05/2019	Inspection Date	31/05/2019
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **18 Working Days**