Burreups .		REF. CS AIGIG	010646/1	Hoser	Special Instruction:	
From (Person); Estimated Cost:	Norsiah	10/10/06/10	NILOTENET COL	Y2 A	Party Purt. Third Parties: Claimant:	\$ 5847.86
To Inspect Vehicle at Workshop m/s	e Noc	SGV 5991H	Insured: Tel:	Ew 368J	Surveyor: Pre A Workshop: Ery	tup Auto
Policy No:			Claim No:	750315910	559 (005)	
Sum Insured:			Excess:			
Make of Veh: (Client's Record)			D.O.A.	8/1/2010	1	
Canada Maria						
Date/Time:		Person Contacted;	17.		O.D. Endorsoment/Date	
Date/Time: Date/Time:	Confi	rmed withF it Final Fig 2700 - US	inal Fig	days (Red (Red s 344-76)	1\$/_%; 0	riginal_5 _{days)}
Date/Time Ac	tion/Instructio	US		- Constituted		137
	SQV 59M	The state of the s				
	EW 368T				gamanare acm	attended to the same
						写例开设-
					N C BIC	
					E-harman and article	
		RECEIVED 2 6	JUN 2019			
		KECEIVED				
Powe(I) - P	4 5					
Para(I) : Par	ts found no	t replaced (To b	ighlight R	or UB, LE	Etc)	
Para(2): Con	nments on	consistency of 1	(n			
	antento on	consistency of dan	tages (Parts	Not Consiste	nt:NC)	
Para(3) : Net	t Value					
	No. of the last				Fee Charged	Date
M	arket Value	1	Inspected/		Basic & Add	200
Salvage Value		Evaluated by:	y.	Transport	200	
					Photos Others	
	ett Value	:			Total	200
1) Date/Time_2\(DIPLO E	ile Pass to [Up18]	2) Date/Time		File Return to	7.00
3) Date/Time	F	ile Pass to_	4) Date/Time		File Return to	
5) Date/Time	F	ile Pass to	6) Date/Time		Eila Datum to	

<u>A</u> :	SSIGNMENT
From: Date: 06/6/19	Veh No: SGV SEPI H YOROGH: 21" JWN 205
Estimated Cost:	Type: M.Car J.M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS VTP RES/ OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SGV 5991+	Make: Toyota vios J Auto ac 1,497
at Workshop m/s Eng Hup Pruto Parts	Colour SILVER NC: (Insured Std / NI / NA
at Workshop m/s Eng Hup Muto Parts of BILL 1 No. 387 Wood lands Estate	Sp.Reading 189 342 T/Radio(Insured / Std / NI / NA
Insured: 5677954	Eng/No:
Policy No.	C/No: MED 53H Y 930 500 2672
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering Inorder F Jammed / Loaked / Burnt or
(Client's Record)	Brake: (Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD-A/Rim or
loan owner wasting	1. Tyro Sizo: F: 185 /60 R15
(Policy Condition)	R: 11
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF DUNLOPCE) FIRESTONE (R)
Bal, or Market Value:	Front Roar
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. 8/1/19 D.O.I. 6/6 '19
Lum Sum: % 3 Val.: Yes or No	Survey held at ENT HUP ANTO .
	Des. of Damages : Frt / Rear O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / O	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	ALG I
	10 Ala
	Mare-10
	25/6/2019
	7 1 .1
Cale/Time, File Paus to? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, Fire Return to?	Transportation:
a) Add Fe	eo: : Site Insp (\$)s+#3si
- C	
	: Interview (\$) Photos
Report Format :	: Interview (\$) Photos : Tech. Invs (\$) Others

Nivitha (LKK Auto)

MINIT	ia (LKK Auto)		
From: Sent: To: Cc: Subject	t:	Florence KOH <florencekohef@yahoo.com.sg> Monday, 3 June 2019 9:55 AM assignments; Admin-D (LKKAuto) 'Md Noor, Norsiah' Re-Inspection Our Ref: 75031591055G(005) Your Ref: CKK//ACC claim SGV 5991H</florencekohef@yahoo.com.sg>	/10430/19 property
Dear G	i. Nivitha		
We ref	er to your email date	d 31st May 2019.	
We cor	nfirm the reinspectio	n date and time as follows:-	
Date:	6th June 2019 Thu	rsday	
Time: Place:	10.00am Eng Hup Auto Part	s Accessories Co	
	Blk 1, No. 387 Wo	odlands Estate, S677954	
Tel: 623			
On Frida	ay, 31 May 2019, 5:47:	10 pm GMT+8, Admin-D (LKKAuto) <admin-d@lkkauto.com> wrote:</admin-d@lkkauto.com>	
Dear Flo	rence,		
May we	arrange at 10am?		

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

GOH JEN SIANG C/O Block 1, 387 Woodlands Road Yew Tee Industrial Estate Singapore 677954 INSURANCE DETAILS

Insured

Policy No. / Claim No. : -

Sum Insured

Excess Clause

Windscreen Coverage :

Type of Claims

: Third Party Claims

Third Party Insurer Third Party Policy No. : -

REFERENCE

Assigned By

As above

Accident Date

08 January 2019

Assignment Date

08 January 2019

Inspection Date

09 January 2019

Our Reference No.

PAS/EH/190112/TP

Inspection Report Date: 14 January 2019

Workshop Name:

Eng Hup Auto Parts Accessories Co

Inspection Address:

Mileage

Block 1, 387 Woodlands Road Yew Tee

. 189342

Km/h

Industrial Estate Singapore 677954

PARTICULARS OF VEHICLE

Registration No.

SGV 5991 H

Make/Model

TOYOTA VIOS J AUTO

Yr of Manuf/Regn

2007

Carrying Capacity

4 Seater

Chassis No.

MR053HY9305002672

Engine No.

1NZX545696

Colour

Metallic Silver

Class

Passenger (Private)

Radio/Casette : Fitted CD Disc Player : Fitted

Air Conditioner : Fitted

Clock : Fitted

Seat Belt : Fitted

Wing Mirror Other : Fitted

Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work

: Good

Paint Work

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Any Apparent

· None

Wreck Value (Parf) : -

Market Value

VEHICLE VALUE

Eng Modifications

TYRE SIZE & CONDITION

Type of Wheel Rims: Alloy

Front N/s Size

185/60R15

80 %

DUNLOP

FIRESTONE

80 %

Size Make

Front O/s Size Make 185/60R15

80 %

Rear N/s size Make

185/60R15

80 %

Rear O/s

DUNLOP 185/60R15

FIRESTONE

80 %

Spare Size Make

Make

185/60R15 FIRESTONE

Spare Size

Make

Jack & Tools

: Intact/ Missing

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO.: SGV 5991 H


APPENDIX A



POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear Portion. (see Diagram D)



FORT STATE OF THE STATE OF THE

NEAR SIDE

THO NT

GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The bootlid, rear bumper and panel, both rear fenders and chassis were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on <u>09/01/2018</u> & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Eng Hup Auto Parts Accessories Co. as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part-By-Part Repair Basis of \$ 5,847.86 after deducting the Policy Excess Clause of \$ NA.

As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's				Our		
	Es	timate	Amount	Re	evised	Amount	
Spares Parts	_	4827	15	_	3097	86	
Towing Charges					•		
PB Labour Charges		1600	00		1200	00	
Others Misc Charges	Ξ	500	00	Ξ	350	00	
Paintwork		1400	00		1200	00	
Total	5	8327	15	\$	5847	86	

Under normal circumstances, the duration of repairs should not exceed <u>Five (05)</u> days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame.

Attached photographs taken during inspection Forty - Eight (48) Photographs.

SPECIAL REMARKS

- The inspection was conducted on a 'without prejudice' basis
- 2. On 10/01/2019, we examined the extent of damages
- On 12/01/2019, we examined the new replacement parts
- On 14/01/2019, we examined the repaired vehicle.

Inspection Report Date: 14 January 2019

Yours Faithfully,





T F NG PHILIP FOO A C I C A E, A M I M I A I A M E, A M S A E-A Licensed Appraiser/Adjuster VEHICLE REGN NO :

SGV 5991 H

OUR REFERENCE :

PAS/EH/190112/TP


INSPECTION REPORT DATE :

14-Jan-19

APPRAISEMENT SCHEDULE

1 1p	No Qty		Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
1			PARTS SUPPLY - LIST ITEMS		\$ cts	\$ cts
1	1 1	pc	Control of the Contro	Badly dented	568.60	568 60
1pt Bootlid centre logo	2 1	pr	Bootlid hinge@\$84.50	Section of the section of the section of	103 (22) (42) (3	300.00
1pc Bootlid 'J' emblem Necessary 48.50 48.50 1pc Bootlid 'Vios' emblem Necessary 57.60 57.60 1pc Bootlid upper lock Bent 136.75 136.5					5770-37633-37	68 50
1pc Bootlid 'Vios' emblem Necessary 57.60 57.60 1pc Bootl rubber Torn 179.60 179.6	4 1	pc				
1pc Boot rubber Torn 179.60 179.67 1pc Bootlid upper lock Bent 136.75 136.3 19c Bootlid lower lock Bent 112.20 112.3 1	5 1	pr	Bootlid 'Vios' emblem	State of the state	2352000	57.60
1pc	6 1	pc	Boot rubber			- Part 4.540
1	7 1	pc	Bootlid upper lock			191400000
2 2 2 2 3 8 8 8 8 6 1 1 1 1 1 1 1 1 1	8 1	pc		TO 101	11122	
10	9 2	pes	Bootlid rear no. plate lamp@\$75			112.20
1	10 1	pc				
12	11 1	pc	Bootlid centre mldg			
14 2pts Taillamp@\$289.50 Cracked 579.00 579.00 15 1pc Rear panel Badly dented 578.40 578.40 16 1pc Rear panel garnish Warped 196.30 196.3 17 1set Rear panel garnish clips Necessary 30.00 30.0 18 1pc Rear bumper Badly dented 486.50 486.5 19 2pts Rear bumper bracket@\$121.10 Bent 242.20 242.2 20 2pts Rear bumper side retainer@\$112 Bent 224.00 224.0 21 2pts Rear bumper reflector@\$94.50 Cracked 189.00 189.0 22 1set Rear bumper clips Necessary 40.00 40.0 22 1set Rear bumper clips Necessary 4477.15 3757.1 Less: 25% discount 4477.15 350.00 280.0 Total spare parts 4827.15 3097.8 LABOUR & MISC. CHARGES ARemove the necessary affected parts <td></td> <td>pc</td> <td>-</td> <td></td> <td>4 AND AND AND AND AND AND AND AND AND AND</td> <td></td>		pc	-		4 AND	
14 2pts Taillamp@\$289.50 Cracked 579.00 579.00 15 1pc Rear panel Badly dented 578.40 578.40 16 1pc Rear panel garnish Warped 196.30 196.3 17 1set Rear panel garnish clips Necessary 30.00 30.0 18 1pc Rear bumper Badly dented 486.50 486.5 19 2pcs Rear bumper bracket@\$121.10 Bent 242.20 242.2 20 2pcs Rear bumper side retainer@\$112 Bent 224.00 224.0 21 2pcs Rear bumper reflector@\$94.50 Cracked 189.00 189.0 22 1set Rear bumper clips Necessary 40.00 40.0 22 1set Rear bumper sensor Dented 350.00 280.0 3 2pctAll NETT ITEMS 4827.15 3097.8 1 1set Rear bumper sensor Dented 350.00 480.0 1 Abou	13 2	pes				20.00
15	14 2			Friday and Control of the Control of		
16 1pc Rear panel garnish Warped 196.30 196.30 17 1set Rear panel garnish clips Necessary 30.00 30.00 18 1pc Rear bumper Badly dented 486.50 486.50 19 2pts Rear bumper bracket@\$121.10 Bent 242.20 242.2 20 2pts Rear bumper side retainer@\$112 Bent 224.00 224.0 21 2pts Rear bumper reflector@\$94.50 Cracked 189.00 189.0 21 2pts Rear bumper clips Necessary 40.00 40.0 40.00 40.00 40.00 40.0 40.0 4477.15 3757.1 939.2 2817.8 1 1set Rear bumper sensor Dented 350.00 280.0 1 1set Rear bumper sensor Dented 350.00 280.0 1 1set Rear bumper sensor 1set 4827.15 3097.8 1 LABOUR & MISC. CHARGES 1set 1set 1set 1set 1set 1set 1set <td< td=""><td></td><td>pc</td><td>17 E-170</td><td></td><td>500A 300 S</td><td></td></td<>		pc	17 E-170		500A 300 S	
15et Rear panel garnish clips Necessary 30.00 30.00 30.00 18 1pc Rear bumper Badly dented 486.50 486.50 486.50 2pts Rear bumper bracket@\$121.10 Bent 242.20 242.20 242.20 224.00	16 1	pc	The state of the s	10.500		
18 1pc Rear bumper Badly dented 486.50 486.50 19 2pcs Rear bumper bracket@\$121.10 Bent 242.20 242.20 20 2pcs Rear bumper side retainer@\$112 Bent 224.00 224.00 21 2pcs Rear bumper reflector@\$94.50 Cracked 189.00 189.00 22 1set Rear bumper clips Necessary 40.00 40.00 4477.15 3757.1 939.2 2817.8 1 Iset Rear bumper sensor Dented 350.00 280.0 Total spare parts 4827.15 3097.8 LABOUR & MISC. CHARGES 4827.15 3097.8 Remove the necessary affected parts 1600.00 309.0 Putty and Spraypaint 1400.00 300.0 1200.0 Check electrical 100.00 300.0 1200.0 Tuff Kote 150.00 120.0 120.0	17 1	set	Rear panel garnish clips	223		
19 2pcs Rear bumper bracket@\$121.10 Bent 242.20 242.20 20 2pcs Rear bumper side retainer@\$112 Bent 224.00 224.0 21 2pcs Rear bumper reflector@\$94.50 Cracked 189.00 189.0 22 1set Rear bumper clips Necessary 40.00 40.0 4477.15 3757.1 3757.1 3757.1 2817.8 1 1set Rear bumper sensor Dented 350.00 280.0 Total spare parts 4827.15 3097.8 LABOUR & MISC. CHARGES Remove the necessary affected parts 4827.15 3097.8 1 Remove the necessary affected parts 1600.00 309.0 1200.0 2 Putty and Spraypaint 1400.00 300.0 1200.0 3 Check electrical 100.00 80.0 4 Tuff Kote 150.00 120.0	18 1	pc			- SERVICES	
20 2pts Rear bumper side retainer@\$112 Bent 224.00 224.00 21 2pts Rear bumper reflector@\$94.50 Cracked 189.00 189.00 22 1set Rear bumper clips Necessary 40.00 40.00 4477.15 3757.1 3757.1 2817.8 1 1set Rear bumper sensor Dented 350.00 280.0 Total spare parts 4827.15 3097.8 LABOUR & MISC. CHARGES 4827.15 3097.8 Remove the necessary affected parts 1600.00 3097.8 Putty and Spraypaint 1400.00 3097.8 Check electrical 100.00 3097.8 Tuff Kote 150.00 1200.0		DES	Rear bumper bracket@\$121.10		0.500,000	letatilitie.
21 2pcs Rear bumper reflector@\$94.50 Cracked 189.00 189.00 40.00 40.00 40.00 40.00 40.00 40.00 4477.15 3757.1 2817.8 4477.15 2817.8 2817.8 4477.15 2817.8 4277.15 427	20 2	055				
Less: 25% discount 1		ocs				
Less: 25% discount Less: 25% discount SPECIAL NETT ITEMS 1	22 1	set	100		PC.000000000000000000000000000000000000	
Less: 25% discount SPECIAL NETT ITEMS 1						
SPECIAL NETT ITEMS 1			Less: 25% discount		1177.43	110000000
1 1set Rear bumper sensor Dented 350.00 280.00 Total spare parts LABOUR & MISC. CHARGES Remove the necessary affected parts cut/weld rear panel, both rear fenders and chassis and replace parts Putty and Spraypaint 1400.00 300 1200.00 Check electrical 100.00 80.00 Tuff Kote 150.00 120.00			SPECIAL NETT ITEMS		4477.15	2817.86
Total spare parts LABOUR & MISC. CHARGES Remove the necessary affected parts cut/weld rear panel, both rear fenders and chassis and replace parts Putty and Spraypaint Check electrical Tuff Kote Page 150.00 13097.8 1400.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00	1 1	set		Dented	350.00	290.00
LABOUR & MISC. CHARGES Remove the necessary affected parts cut/weld rear panel, both rear fenders and chassis and replace parts Putty and Spraypaint Check electrical Tuff Kote Pamous and refit sees by LABOUR & MISC. CHARGES 1600.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00 1200.00			A second		0.0000000000000000000000000000000000000	
Remove the necessary affected parts cut/weld rear panel, both rear fenders and chassis and replace parts Putty and Spraypaint Check electrical Tuff Kote Pamove and refit seed by Pamove and refit seed by Pamove and refit seed by Parts Pamove and refit seed by Pamove and					4027.13	3097.88
cut/weld rear panel, both rear fenders 1600.00 200 1200.00	1			ts		(
2 Putty and Spraypaint 1600.00 3 1200.00 3 1200.00 3 1200.00 1						
2 Putty and Spraypaint 1400.00 3 1200.00 3 Check electrical 100.00 80.0 4 Tuff Kote 150.00 120.00			and chassis and replace parts	7.17	1600.00	700 120 0 0 0
3 Check electrical 100.00 80.0 4 Tuff Kote 150.00 120.0	2					
4 Tuff Kote 150.00 120:0	3					
S Pamous and reference by	4		Tuff Kote			
	5		Remove and refit rear bumper sense	ors	100.00	60.00
A Rewise reas postion	6					30.00
Remove and rofit hostilid annual sources	7		The state of the s	its		50.00

PRECISION APPRAISAL SERVICES



MLKH19003509 / Lee Kuan Hwa Motor Service - Sungei Kadut ENTRY DATE & TIME 08/01/2019 17:05 SUBMITTED BY: Chua Siew Chen

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	08/01/2019 17:05
Date Of Accident	08/01/2019 14:30
Exact Location Of Accident	ALONG PIE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGV5991H
Insured/Policyholder	
Name Of Registered Owner	GOH JEN SIANG
NRIC No	S7125178J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98634947
Alternative Phone No	Office-98634947
Vehicle Particulars	
Manufacturer	тоуота
Model	VIOS J(AUTO)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMPG18001921
Cover Note Number	
Driver	
Name of Driver	GOH JEN SIANG
NRIC No	S7125178J
Date Of Birth	16/07/1971
Occupation	INDOOR
Date Of Driving Pass	16/07/2007

11 YEARS AND 5 MONTHS

Gender Mobile Number

nder

MALE (LOCAL) +65-98634947

Fax Number

Contact Number

EMail Address

NOEMAIL

Civitali Addicess

APT BLK 289G BUKIT BATOK STREET 25 #14-102 S(656289)

Address Postcode

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

NO

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident?

this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NO 1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

21 BUKIT BATOK EAST AVE 4 S(659840)

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

EW368J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver KOK MENG HUAT

NRIC/Passport Number S1685768H

Contact Number Address Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation-
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the ledgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal information"] and disclose and transfer such Personal Information to all insurer(s) who have insured whicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers lawyers/law fams, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any empiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agent/circluding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud direction, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclessed
 - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN NO

SKEICH POAN					volucie	A - SGV 541
-				-	vehicle	B- EN 368
-			В	A	D	
	Along	PIE				
DESCRIBE CIRCUMSTAN						
blease leter	to police	report				
OECLARATION (We declare the foregoing a	sart culars are true in e	nery respect.				
Policyholder's Signature Date & Time:	Driver's Sig (If driver is Date & Tim	mature not the policyhold		Reporting Name: NRIC/Fib	g Centre Persannel	's Signature

Driving License









Police Report





Report No. 3291001002005

POLICE REPORT (NP200)

Folice Staten Of Origin bush Detail N.P.C 21 Part Battle Det Avenue 4 SIBICAPORTE 598840 Tel No. 1600-665999

Date/Time Report Made 26/21/2019 16:34	Mae Fia	Station Diary No 96			
Name Of Informati COLLICH S AND	ADDRESS AND BLEVE BATCH STREET 25 814 103 SHOAPORE SEAZES				
D Type / ID No N/BC NO / S7125*TEL	Contact		Motore 98534947		
Selection CHIVES	Ervai Address			1424	
Occupation PHOPERTY AGENT	Man	Age 47	Date of Sylls 10/07/1971	Flace: Cvireee	
metation/Subsor Namo	Englange Englant				
CateChine Of Incident (INC172016 14 09: 08/01/2016 14 30	- Along Pite SINGAPORE				

Brief details.

Dr 36/01/2019 at about 1413hrs while I was triving my our regionalise rus. SCV5001H without any passenger with the stung IT is towards frien when feet an impact from the seer. I managed to broke and also my car. I alighted and discovered that a satisfiguration no. CASSS, had solided into the monet my car and there were 7 or 3 with disc revolves with chain collision behind the eard ear. I did not take note of other values and only have with the overmore behind me.

Sugnishina Litt Officer Hincording The Report.

JYS SIMT BUILDHANIZA SINTE SI AL

Significan Of Interpreter Not applicable

Officer in Charge Of Crass J.F.R.M. Retire N.F.C./ AEP BE1850N CHONG HE DA Cortact No.: 67910010

Signature Of Informacit.

Duter Time: 0001/0012 18:34

Disselfcation Of Case.

Authenticator Stamp

SN 114

Simple of the Force

Police Report





2 (42

POLICE REPORT (NP299)

CONTINUATION OF HEIPORT

Report No. (1991)101(082)005

the deservoirs had the provided for details as Kah Many Huat of NAIC Ket 9/00/5760H (Fift. \$7909871). He accepted that he level hit the back of my par on 98801/2019 and sign on paper to commit to the accident.

My car suffered damages on the rear portion. At some of carties involved do not required any inmediate medical attention however I are pursently triving instell white reporting the matter at Police station and I will out a stocks if need by. I are intiging this report for vector and to outmit to my fraurance company.

55114

Signature Of Officer Recording The Regard

JISISHT SHI BAAN ZABAT - B TANK

Signature Cr Interpreture. Not applicable

Officer In Change Off Case: .7 Even Brook N.P.C.7 ASP BENEION CHONG --- DA Control No.: 879 10000

Authoritemen Davisp

0 Bollie Force Singram

Signature Of Informent W

Oscertime: 08/01/2019 15:34

Classification (If Case)

Third party driver letter

97989871

I toh Aleng Hant 5165578844 of EW 368 J have hit the

back of 564599141.

cele 1 119

Insurance cert

ERGO

Certificate of Insurance

MOTIVE COLOR TO DE REPORTE TIMES, AND CONTRACTOR TO A COLOR ASSETTED THE ANGLE OF THE PROPERTY AND THE PROPERTY AND THE PROPERTY ASSETTED THE THE COLOR FROM THE COLOR AND THE COLOR AND

CALIFORNIA SHIPE many the col Select formation humber () 2020-200 Country
Penglips
Accordingtowness
Communication Date of Newson 2 19 19 19 19

Exercise Date of Newson 2 2 19 19 19

Exercise Date of Newson 2 2 19 19 19 6333 2222 Expery Date of Standards THE TOTAL THE TOTAL SHEET AND THE SHEET AND Famili Finance Congany Machine base Donne (475-0477 AAP 6067; 11)

The Processor THE TOTAL BY MADE AND A SECOND CONTRACT OF THE PROCESSOR OF

reads. They prove provide a common a support of the content of the

Companyone as to the

The state of discussions prompt and a second

THE PARTY COM-

The factor was passed to the properties of the factor could be the properties of the factor of the f

in this sales against appropriate motion to stand or they take an illustrated. Our proper laters asserted by their most of the property of the property of the sales and the sales and the sales are the sales and the sales are the sales and the sales are t

20. If a condition that before before the control make a condition of the control of the condition of the conditi

for any entates of the bill have treat Paulan, many reference

and the state of t

335/40715/11 61807

TOTAL PROCESSOR FOLLOW FROM THE CONTROL OF THE SECTION OF THE SECT











MCC419003664 / Cycle & Carriage Industries Pte Ltd - Pandan Loop ENTRY DATE & TIME: 09/01/2019 09:44 SUBMITTED BY: Lim Xin Yi

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	09/01/2019 09:44
Date Of Accident	08/01/2019 14:15
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	EW368J
insured/Policyholder	
Name Of Registered Owner	LIM KIAT SENG
NRIC No	S1808680H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98328322
Alternative Phone No	Office-98328322
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	\$320
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO.
Policy Number	1800028466
Cover Note Number	
Driver	
Name of Driver	KOK MENG HUAT
NRIC No	S1685768H
Date Of Birth	15/04/1965
Occupation	INDOOR
Date Of Driving Pass	24/02/1992

26 YEARS AND 10 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-97879871

Fax Number

Contact Number

EMail Address

NOEMAIL

Address -

33A HARVEY AVE

Postcode

489512

Was driver an employee of the Insured's Company

If No. Relationship of the Driver with the Insured

PAID DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

CAR C (SGV5991H) JAMMED BRAKES AND I MANAGED TO STOP MY CAR IN TIME BEHIND CAR C. SECONDS LATER, CAR B (GBG6058J) CAME FROM THE BACK AND KNOCKED INTO THE BACK OF MY CAR, THE IMPACT CAUSED MY CAR TO ROLL FORWARD KNOCKING INTO THE BACK OF CAR C SLIGHTLY.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

REFER CSE YIK

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBG6058J

Vehicle Make/Model/Colour

NISSAN VAN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGV5991H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TOYOTA VIOS

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

MPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful and accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to <u>regulated policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the cambe and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (POPA)

understand, acknowledge, agree and consent that

- (a) My injury, my workshop and the General injurance Association of Singapore ("GIA") may/are permitted to collect, use, discisse and/or process my personal data/personal information set out in this [form) and any other personal information provided by me or possessed by misurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all injurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"). The insurers little from the function Authority of Singapore and any relevant government.
 - processing, handling and/or dealing with my stams including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - [iii] carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of cartain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail.
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (h) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers have firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Inquirers aristor GIA to their third party service providers or agents/including their (awyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of flaud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / discosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraux, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for comprying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time

Driver's Signature


(If driver is not the policyholder)

Date & Time

VIA CREATION OF THE LAND OF TH

discon

NRIC/FIN No.:



Cer c journed brakes and I managed to Stop vuy car in time behind car c. Seconds laker, car B (van) came from the back and knocked into the back of my car, the impact caused my car to coll Jourard knocking into the back of car c slightly.

DECLARATION

(We deciare the foregoing perfouses are true in every respect

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your incurance company for any further details)

Policyholder's Signature Date & Timer

Orivers and the policyholder)

Date & Time

Negating Centre Personnel's

Flame

NRIC/FIN No.

CERTIFICATE OF INSURANCE

MERCEDES-BENZ MOTOR INSURANCE PRIVATE VEHICLE

Name of Pulicyhuldes : LIM HIAT SENG Period of Insurance : 23 Mar 2018 To 22 Mar 2018 Engine No. : 27582430787806

Chassis No.

W002221622A387920

Vehicle No.

: EW366J

Policy No.

1800026466

Endorsement No.

Issued Date

: 04 Apr 2018

AMOUT THE COVER

Make/Model

MERCEDES Roor 53305, Sedan

Engine Capacity/Tornage 2,596.00 CC Driver Restrictor

NA

Suminazed Menet Value

Off Prick Car No

First Year of Registration 2018 Insuring with COEPARF YES

Person or Classes of Persons Entitled to Drive?

The Proof of the part actions or specific the Prince point to appropriate (Prince Paper or Period Strong Report for Strong Report for the specific or specific or companies to contract the specific or companies the spec

Age Caratrion

All Age Condton

Lenstation as to use?

Discrete to world principle and planter purposes and to the Policy office a purpose.

The many step one of steep can be the discrete at any force, ordered to any force and any force as any force as a second or a second or any force and any force any force any force and any force and any force and any force and any force any force and any force any force and any force any force any force and any force any force and any force and any force any force and any force any force and any force and any force any force and any force and any force any force and any force any force any force and any force and any force any force any force any force any force any force and any force any force any force an

Look of Disk 2005a-

Commission and income to broken 4 of the manu operand prices and Emperophisms for King with one forces the error floor business Act, 1867 (Mallocus) 4.9 and to be included under the error floor business and the error fl

EXCESS

Seattle 1 Fire: \$1 the Durage: \$800 Years 50 House Cover - \$1

Section 3: Property Damage - St.

Windsoner Ltd.

Named Driver and Excess serve assessor

I REMOTE SERVICE BRIDGE DAMAGES

APPROVED REPORTING CENTRESIAUTHORISED REPAIRERS (FOR CLAIMS RELATED HERAIRS)

1 Screek Armine Committee monotonic representatives and State Stat

Construct Assessing Construction Superior States (Superior Superior Superio

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan IDBS BANK LTD

(Not bordly posity the Borosity to elect the Contract of transless in accept in accepting our organization of the Main investigation have been and Compression to Contract the National Society (Notice of Compression to Con

(1) 对 (100 may 1) (100 may 1)

stonestychi.

CYCLE & CARRISOF - DOWN 239 ALEXINGS HOUSE

SINGSYCKIC NAMED

Underwritten by AIG Asia Pacific Insurance File. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISCO REPRESENTATIVE

Accident Sketch Plan



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Class 4

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms Heavy Motor Cars and Motor Tractors the weight of which unlader exceeds 2500 kilograms


24 Feb 1992

01 Dec 1998

FOR CACUSE ONLY

NF 428A











































LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to	Federation Internationale Des Ex	perts En Automobile
---------------	----------------------------------	---------------------

AIG ASIA PACIFIC INSURANCE PTE LTD Ref : CS/AIG19010646/Ntd3e2

78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120

Date: 26-06-2019

SINGAPORE 079120					
			Code: AIG		
1.	Po	licy Particulars :- THIRD F	PARTY CLAIM (RESURVE	EY INSPECTION)	
	Insured Veh.	EW 368J	Veh. Inspected	SGV 5991H	
	Policy No.	1800028466	Coverage (\$)	0.00	
	Claim No.	7503159105SG(005)	Excess (\$)	0.00	
	Assign From	NORSIAH	Assign Date	03/06/2019	
2.		Vehicle P	articulars & Condition		
	Make & Model	TOYOTA VIOS J AUTO	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	MR053HY9305002672	Colour	SILVER	
	Odometer	189342	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	DUNLOP	6 mm	
	L/H Front Tyre	185/60 R15	DUNLOP	6 mm	
	R/H Rear Tyre	185/60 R15	FIRESTONE	6 mm	
	L/H Rear Tyre	185/60 R15	FIRESTONE	6 mm	
4.	1278 F 1611	Descr	iption of Damages	TENERAL STATE	
	THE VEHICLE HA	D COMPLETED ITS REPAIR	WORKS.		
	REPAIR CONDITI	ON SEE DETAILS.			
5.		Gen	eral Information		
	Accident Date	08/01/2019	Inspection Date	06/06/2019	
	Survey held at	ENG HUP AUTOPARTS AC	CESSORIES CO.		
	~	387J BLK 1 WOODLANDS I SINGAPORE 677899	ROAD		
5a.	Remarks				
		ON WAS CONDUCTED ON A'			
5b.		Estim	ate Days of Repair	STATE SAID	
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 5991H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	REPLACED	568.60	568.60
2	BOOTLID HINGE @\$84.50	SERVICEABLE	169.00	
1	BOOTLID CENTRE LOGO	REPLACED	68.50	68.50
1	BOOTLID 'J' EMBLEM	REPLACED	48.50	48.5
1	BOOTLID 'VIOS' EMBLEM	REPLACED	57.60	57.60
1	BOOT RUBBER	SERVICEABLE	179.60	5
1	BOOTLID UPPER LOCK	SERVICEABLE	136.75	3
1	BOOTLID LOWER LOCK	SERVICEABLE	112.20	6
2	BOOTLID REAR NO. PLATE LAMP @\$75.00	SERVICEABLE	150.00	3
1	BOOTLID KEY LOCK	SERVICEABLE	128.00	9
1	BOOTLID CENTRE MLDG	SERVICEABLE	188.00	1
1	BOOTLID CENTRE MLDG OUTER HANDLE	SERVICEABLE	85.00	
2	TAILLAMP PAD @\$10.00	REPLACED	20.00	20.0
2	TAILLAMP @\$289.50	SERVICEABLE	579.00	1
1	REAR PANEL	REPLACED	578.40	578.4
1	REAR PANEL GARNISH	REPLACED	196.30	196.3
1	SET REAR PANEL GARNISH CLIPS	REPLACED	30.00	30.0
1	REAR BUMPER	REPLACED	486.50	486.50
2	REAR BUMPER BRACKET @\$121.10	SERVICEABLE	242.20	
2	REAR BUMPER SIDE RETAINER @\$112.00	SERVICEABLE	224.00	
2	REAR BUMPER REFLECTOR @\$94.50	REPLACED	189.00	189.0
1	SET REAR BUMPER CLIPS	REPLACED	40.00	40.0
	LESS 25% DISCOUNT			-570.8
			4,477.15	1,712.55
	SPECIAL NETT ITEMS			
	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	350.00	3
			350.00	
	LABOUR			
	REMOVE THE NECESSARY AFFECTED PARTS CUT / WELD REAR PANEL, BOTH REAR FENDERS AND CHASSIS AND REPLACE PARTS.		1,600.00	700.00

Report Ref No. CS/AIG19010646/Ntd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

2,700.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PUTTY AND SPRAYPAINT.		1,400.00	800.00
	CHECK ELECTRICAL		100.00	30.00
	TUFF KOTE.		150.00	40.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	30.00
	REWIRE REAR PORTION.		50.00	30.00
	REMOVE AND REFIT BOOTLID COMPONENTS.		100.00	30.00
			3,500.00	1,660.00
	GRAND TOTAL		8,327.15	3,372.55

Report Ref No. CS/AIG19010646/Ntd3e2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

MUHAMMAD NAZRIL BIN ABDULLAH

MUHAMMAD NAZRIL BIN AB

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.