

INS. CASE OWNER:

CC 4, ALG 190 10667, Uda3

LKK:

IDAC:

Surveyor:

MARRUS

ASSIGNMENT

DOI:

12/6/19

Date / Time:

14/6/19

Registered in Merimen:

12/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 3744 E

Claim No.:

Name of Insured:

GSF Innovation (2006) PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

13/06/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT YES / NO, TP GIA REPORT YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability:

%

Final ? Yes / No

SJQ 75174



INSRS:

WSP:

Tel:

Liability:

RMKS:

bwin



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 23/8/19

Confirm with Abby

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/bn)

SS \$4815.00

Loss of Rental (LOR):

SS \$700.00

(

7

days)

x

\$100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

Total: SS 5517.00 Global Sum SS: 5500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 5500.00

Name 1:

Abwin Service Pte Ltd

Payee 2, (Strike J.N.A.)

SS

Name 2:

Payee 3, (Strike J.N.A.)

SS

Name 3:

ASSIGNMENT

From: 17/6/19 Date: 17/6/19

Estimated Cost: TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJQ7517Y

at Workshop m/s: Abwin Service

of 8 kaki Bukit Ave 4 #07-48

Insured: premier

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 28

IDAC Accident Rpt: _____ Consistent? : Yes or No

PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 6 days. Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS dup LTA12095

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJQ 7517Y In Regn: 5, 09

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota Corolla Altis c.c 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 96304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053EE106145849

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 205/65-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hgs, lead

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 13/6/19 D.O.I: 17/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>coe 29-2-2024 net 15925</u>
	<u>L/S - \$4500 (Red \$4617.98 / 517)</u>

Date/Time, File Pass to? ☐ : Prelim. Report

if ☐ : Final Report

Date/Time, File Return to?

3

Report Form: _____

Long Sum J.E.D. 17

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : (Assess) and (\$

Survey Fee: _____

Transportation: _____

S + RS: \$

Flake: _____

Flake: _____

Flake: _____

Flake: _____

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000026**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 17-JUN-2019
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6 AUTO
 CHASSIS NO : MR053ZEE106145849
 ENGINE NO : 3ZZ4891032
 SERVICE ADVISOR : ABBY LIM
 PAGE : 1 OF 2

SJQ7517Y**KOH SENG SEON**

BLK 549B SEGAR ROAD

#11-640

SINGAPORE 672549

CONTACT NO : 97575333

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

- 1 BOOT LIT
- 1 BOOT LIT LAMP R/H
- 1 BOOT LIT LOCK
- 1 BOOT LIT OUTER CHROME MOULDING
- 1 BOOT LIT (TOYOTA) LOGO
- 1 BOOT LIT EMBLEM (COROLLA ALTIS)
- 1 BOOT LIT INNER TRIM
- 2 BOOT LIT INTER STOPPER
- 1 REAR BOOT WEATHERSTRIP
- 1 REAR END PANEL
- 1 REAR END PANEL TOP GARNISH
- 1 FENDER INNER TRIM R/H
- 1 SPARE TYRE TOP BOARD
- 1 TAIL LAMP R/H
- 1 TAIL LAMP L/H
- 1 TAIL LAMP PANEL R/H
- 1 TAIL LAMP LOWER BRACKET R/H
- 1 REAR BUMPER
- 1 REAR BUMPER SPONGE
- 1 REAR BUMPER BRACKET R/H
- 1 REAR BUMPER SIDE RETAINER (LONG)
- 1 REAR BUMPER SIDE RETAINER (SHORT)
- 1 REAR BUMPER SIDE REFLECTOR
- 1 BOOT LIT EMBLEM (1.6)

00/Buc 909.70 ✓
 11 211.90 X
 11 126.80 ✓
 11 223.21 X
 11 45.67 ✓
 11 45.67 ✓
 De/Torn 251.60 ✓
 11 29.00 X
 11 194.70 ✓
 11 590.60 ✓
 11 202.70 ✓
 De/Torn 378.40 ✓
 Torn 389.40 ✓
 11 414.10 ✓
 11 414.10 X
 11 129.24 X
 11 45.70 X
 Dis 523.90 ✓
 11 175.70 X
 11 97.70 ✓
 11 57.80 ✓
 11 46.95 ✓
 11 47.77 X
 11 45.67 ✓

Sub Total**5,597.98****0.00****SPECIAL NETT**

- 10 BOOT LIT INNER TRIM CLIPS

11 50.00 ✓

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000026**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJQ7517Y
KOH SENG SEON
 BLK 549B SEGAR ROAD
 #11-640
 SINGAPORE 672549
 CONTACT NO : 97575333

DATE : 17-JUN-2019
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6 AUTO
 CHASSIS NO : MR053ZEE106145849
 ENGINE NO : 3ZZ4891032
 SERVICE ADVISOR : ABBY LIM
 PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
10	END PANEL TOP GARNISH CLIPS	11 50.00 X	
10	REAR BUMPER CLIPS	22 30.00 ✓	
10	FENDER INNER TRIM CLIPS	22 30.00 ✓	
1 set	REVERSE SENSOR	slub 250.00 200	
1	REVERSE CAMERA	11 380.00 X	
1	REAR END PANEL SEALANT	22 50.00 ✓	
1	BOOT LIT SEALANT	11 50.00 X	
10	TAIL LAMP SIDE CLIPS	11 50.00 X	
Sub Total		940.00	0.00

LABOUR

1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	1,000.00 800	
1	CHECK WIRING	50.00 30	
1	REMOVE AND REFIX BOOT LIT COMPONENT	100.00 60	
1	REMOVE AND REFIX EXHAUST PIPE	150.00 60	
1	REMOVE & REFIX SENSOR & TEST	80.00 50	
1	REMOVE AND REFIX CAMERA & TEST	100.00 2	
1	TO APPLY UNDERCOATING FOR RUST ROOFING	100.00 60	
1	SPRAY PAINTING ON ACCIDENT AREA	1,000.00 980	
Sub Total		2,580.00	0.00

SUB-TOTAL	9,117.98	0.00
GST - 7 %	638.26	0.00
TOTAL	9,756.24	0.00

ABWIN SERVICE PTE LTD

Prepared By

LKK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

1-4321-36

25%

2-3241.02

S.N-360.00

1.6L-2040.00

16.01.07

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8259D

Vehicle Details

Vehicle No.:	SJQ7517Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4891032
Chassis No.:	MR053ZEE106145849
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,500.00
Original Registration Date:	26 May 2009
First Registration Date:	26 May 2009
Transfer Count:	2
Actual ARF Paid:	\$17,500.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	29 Feb 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,864.00
COE Rebate Amount:	\$12,095.00
Total Rebate Amount:	\$12,095.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jun 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CHEAPEST CAR

INSURANCE RENEWAL



Free roadside assistance

Free claims support

GET A CHEAPER QUOTE NOW!

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



3.18%P.A \$0 Admin Fees@Gv Finance.2 Years Warranty.\$3000 Down Monthly From \$788 Gv Credit Pte Ltd -StarAd

KA-HUP

VALUE FOR MONEY

VALUE FOR TIME

A PEACE OF MIND

HOTLINE: 6741 9997

VIEW OUR SERVICES

Browse by Category

< Back (1 2 3 4 5 6 7 8) Next >

Sort by Date Posted

20 results/page

142 vehicles

altis

Advanced Search

Submit

	Make	Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	altis		Any	Any	2009	Any	Any	Any	Available
<div><div></div><div><div>Toyota Corolla Altis 1.6A (COE till 05/2024)</div><div>3.18% P.A. \$488 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims 16" Tyres. New Pioneer D...</div><div>3.18%P.A \$0 Admin Fees@Gv Finance.2 Years Warranty.\$1800 Down Monthly From \$488 Gv Credit Pte Ltd</div><div>Posted: 17-Jun-2019</div><div>Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div></div>		Toyota Corolla Altis 1.6A (COE till 05/2024)	\$30,800	\$6,250 /yr	22-May-2009	1,598 cc	-	Sedan	Available
<div><div></div><div><div>Toyota Corolla Altis 1.6A (New 5-yr COE)</div><div>3.18% Per Annum. \$488 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims / 16" Tyres. New P...</div><div>3.18%P.A \$0 Admin Fees@Gv Finance.2 Years Warranty.\$1800 Down Monthly From \$488 Gv Credit Pte Ltd</div><div>Posted: 17-Jun-2019</div><div>Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div></div>		Toyota Corolla Altis 1.6A (New 5-yr COE)	\$30,800	\$6,150 /yr	24-Jun-2009	1,598 cc	-	Sedan	Available
<div><div></div><div><div>Toyota Corolla Altis 1.6A (COE till 06/2024)</div><div>3.18% Per Annum. \$488 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims/16" Tyres. New Pio...</div><div>3.18%P.A \$0 Admin Fees@Gv Finance.2 Years Warranty.\$1800 Down Monthly From \$488 Gv Credit Pte Ltd</div><div>Posted: 17-Jun-2019</div><div>Tags: 2008 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div></div>		Toyota Corolla Altis 1.6A (COE till 06/2024)	\$30,800	\$6,180 /yr	09-Jun-2009	1,598 cc	-	Sedan	Available
<div><div></div><div><div>Toyota Corolla Altis 1.6A (COE till 05/2024)</div><div>1 Owner. Well Taken Care By The Previous Owner. Loan Available With High Trade In. Price Negotiable. Call Now Or Visit Our Showroom Today!</div><div>Posted: 17-Jun-2019</div><div>Tags: 2008 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div></div>		Toyota Corolla Altis 1.6A (COE till 05/2024)	\$33,800	\$6,870 /yr	18-May-2009	1,598 cc	113,000 km	Sedan	Available
<div><div></div><div><div>Toyota Corolla Altis 1.6A</div><div>Option Sell With 5 Or 10 Years COE Renewal, 1 Owner, Full Servicing History Since Day 1 With Low Mileage Done At 10K KM Yearly, Tip Top Condition, Low Depreciation And Best Price In Town, 100% Accident...</div><div>Sng Auto Trading</div><div>Posted: 17-Jun-2019</div><div>Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota</div></div></div>		Toyota Corolla Altis 1.6A	\$15,800	N.A	01-Sep-2009	1,598 cc	109,611 km	Sedan	Available

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

Compare

https://www.sgcarmart.com/used_cars/listing.php?RGD=2009&MOD=altis&RPG=20&VEH=0&AVL=2

17-Jun-19

CW4/Alh

PRE-REPAIR INSPECTION REQUEST – SJQ7517Y vs SLR3744E (OI) on D.O.A.: 13/06/2019

From: Hor, Yinnul
To: 'assignments@ikkauto.com'; Admin A (admin-a@ikkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
Sent: 6/14/2019 4:07:30 PM

Hi,

Please refer to the enclosed request from **Abwin Service Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

5:12pm @ 14/6/19
person @ finda
vehicle in
agreed survey
on 17/6/19

From: Abby Lim [mailto:abbylim@abwinm9.com]
Sent: Friday, June 14, 2019 4:04 PM
To: Hor, Yinnul
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR3744E AND SJQ7517Y ON 13/06/2019

This message is from an external sender; be cautious with links and attachments.

Hi Yinnul,

Please arrange LEX to survey the vehicle.

Warmest regards,

Abby Lim

Claims Department
DHD +65 6713 9400

Abwin Service Pte Ltd
T +65 6713 9420 | F +65 6713 9415
No. 8 Kaki Bukit Avenue 4
#07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875

From: Hor, Yinnul [mailto:Yinnul.Hor@aig.com]
Sent: Friday, 14 June, 2019 3:55 PM
To: abbylim@abwinm9.com
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahxin.Tong@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR3744E AND SJQ7517Y ON 13/06/2019

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-la, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-06-21 03:54 EDT to read your message.
After that, open the attachment.

[More info](#)

From: Yinnul.Hor@aig.com
To: abbylim@abwinm9.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, BaijiLKaur@aig.com, NoorMariasa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashri.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencryp PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR3744E AND SJQ7517Y ON 13/06/2019
Date: Fri, 14 Jun 2019 07:54:39 +0000
Without Prejudice

Your Reference : SJQ7517Y
Our Reference : SLR3744E

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hon Yinnul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Abby Lim (mailto:abbylim@abwinm9.com)
Sent: Friday, June 14, 2019 3:35 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] ACCIDENT INVOLVING SJQ 7517Y AND SLR 3744E ALONG UBI ROAD 2 SLIP ROAD TO KPE ON 13/06/2019

This message is from an external sender; be cautious with links and attachments.

Hi Mdm/Sir,

We refer to the above accident.

We have been appointed by the owner, **KOH SENG SEON** the registered owner of vehicle no. **SJQ 7517Y**.

Kindly arrange your surveyor to attend the Pre-repair inspection **within 2 working days**.

The said vehicle can be inspected at: **No. 8 Kaki Bukit Avenue 4, #07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you.

Warmest regards,

Abby Lim

Claims Department
DID +65 6713 9400

Abwin Service Pte Ltd
T +65 6713 9420 | F +65 6713 9415
No. 8 Kaki Bukit Avenue 4



ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G



19-AUG-2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #09-16 SINGAPORE 079120
SINGAPORE 079120

Dear Sirs,

ACCIDENT ON 13-Jun-2019 INVOLVING SJQ7517Y & SLR3744E AT UBI ROAD 2 (SLIP ROAD) TO KPE

We are authorised repair workshop for the owner of vehicle, SJQ7517Y, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SLR3744E, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repair	\$4,815.00
2. 7 days Car Rental x \$110.00	\$770.00
3. Loss Of Use	-
4. Survey Fees	-
5. LTA Fees	-
6. TP/GIA Fees	\$2.00
7. Medical Fees	-
8. Others	-
(E&OE)	\$5,587.00

We enclosed the following documents to support the claims:-

<input checked="" type="checkbox"/> Repair/Excess Bill	<input checked="" type="checkbox"/> GIA/Police Report(s)	<input type="checkbox"/> Power of Attorney	<input type="checkbox"/> Medical Bill
<input type="checkbox"/> Surveyor Report	<input checked="" type="checkbox"/> GIA/TP Search	<input checked="" type="checkbox"/> Car Rental Bill	<input type="checkbox"/> Witness Statement
<input type="checkbox"/> Coloured Photographs	<input type="checkbox"/> Insurance Certificate	<input type="checkbox"/> Others : _____	

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully,

ABWIN SERVICE PTE LTD

ABBY LIM

Claim Department

Email :



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19010667/Udb3

26 JUNE 2019

GSF INNOVATION (2006) PTE LTD

51 UBI AVE 3
#05-35 FRONTIER
SINGAPORE 408867

Dear Sir/Madam,

**ACCIDENT INVOLVING SLR 3744E & SJQ 7517Y ALONG/AT UBI RD 2 HEADING
TOWARDS AIRPORT ON 13/06/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJQ 7517Y against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: JiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Date: 14/06/2019

From: Koh Seng Sean (Name of Policyholder)

My Vehicle No.: SJQ 7517Y

Other Vehicles: SLR 3744E

Accident Date: 13/06/2019

Location: Ubi Road 2 (Slip Road) to KPE

LETTER OF AUTHORISATION

To: AIG Asia Pacific Insurance Pte Ltd (Third Party and/or Third Party Insurer)

I have authorised ABWIN SERVICE PTE LTD to proceed with the repairs to my accident damaged vehicle and to proceed with 3rd Party Insurance Claims against Third Party and / or its Insurer on my behalf for property damages, costs, and expenses, including loss of use, loss of rental, medical fees and legal costs.

To have absolute discretion to agree to any settlement of compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).

As ABWIN SERVICE PTE LTD will be handling the entire 3rd Party Claims, which includes signing / submission of all relevant documents and negotiation of my claims on my behalf, kindly forward and make payable all proceeds of my claims to ABWIN SERVICE PTE LTD.

I confirm that the payment of any negotiated settlement with and accepted by ABWIN SERVICE PTE LTD will serve as an effectual discharge of my claims against the Third Party and / or its Insurer for the damage caused.

I further confirmed and accept that:

- i) I will indemnify & keep Abwin Service Pte Ltd indemnified in connection with or arising from the claim and under no circumstances that will hold Abwin Service Pte Ltd liable for any losses or damages of whatever nature arising from or in connection with the claim;
- ii) Abwin Service Pte Ltd does not guarantee and never represented that the Insurer & or Third Party will fully indemnify me for the damage and/or the repair costs and that I shall continue to be liable to Abwin Service for the whole repair costs.

Policyholder's Signature / Company's Stamp (if applicable)

Name: Koh Seng Sean

NRIC No./ROC No.: S8858259D

Designation:

Witness's Signature

Name:

NRIC No.:

"The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, ABWIN SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,500.00 (Global Sum) for vehicle no. SJO 7517Y that was damaged pursuant to the accident which occurred on 13/06/2019 (date) along UBI RD 2 (SLIP RD) TO KPE involving vehicle no/s SLR 3744E.

This is pursuant to the inspection conducted on 17/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KOH SENG SEON ("the third party claimant") of vehicle no. SJO 7517Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJO 7517Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23rd (day) of August (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**TAX INVOICE : SC1907-28028 (1)****AIG ASIA PACIFIC INSURANCE PTE LTD**

78 Shenton Way
#09-16
Singapore

DATE : 23-Aug-2019
JOB SHEET NO :
SERVICE ADVISOR : ABBY LIM
PAGE : 1 OF 1

VEHICLE NO SJQ 7517Y
MAKE TOYOTA
MODEL COROLLA ALTIS 1.6 AUTO
MILEAGE : 0 KM

NO	DESCRIPTION	QTY	UNIT PRICE	SUM (SGD)
1	COSTS OF REPAIR FOR VEHICLE SJQ 7517Y DOA 13/06/2019	1.00	4,500.00	4,500.00

REMARKS : JOB TYPE : THIRD PARTY CLAIMS AGAINST SLR3744E

SGD : ONE THOUSAND SIXTY EIGHT AND CENTS NINTY	SUB-TOTAL :	4,500.00
THREE ONLY	GST - 7 % :	315.00
	TOTAL :	4,815.00

* This is a computer-generated document. No signature required.

BALANCE : 4,815.00



Invoice

Invoice No : WPLIN0003321
 Invoice Date : 21/6/2019
 Due Date : 21/6/2019
 VHA No : 3790
 Referral ID : A002

Description :	Amount
---------------	--------

Rental for	7	Day/s @	\$110	per Day \$	770.00
------------	---	---------	-------	------------	--------

Vehicle No : SJN5379H

Vehicle Description : Toyota Altis 1.6A

Rental Period : 14/06/2019 to 21/06/2019

Total Amount Payable : \$ 770.00

Invoice No:	
Alt No:	
Good Received	
Invoice Verified	
Approved	

WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

VHA No: 3790

Invoice No: WPLIN 3321

Hirer's Vehicle No:

UEN: 201505115E

VEHICLE RENTAL AGREEMENT**HIRER'S PARTICULARS**

Name: (as in I/C) KOH SENG SEON

NRIC / FIN No: S8858259D

Address (Res): BLK 549B SEGAR RD #11-640
S(672549)

Name & Address of Employer:

Occupation: Driving Exp:

Singapore Driving Licence No:

Issue Date: Date of Birth: 7/3/88

Tel: (O) (R) HP:

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C)

NRIC / FIN No:

Address (Res):

Occupation: Driving Exp:


Singapore Driving Licence No:

Issue Date: Date of Birth:

Tel: (O) (R) H/P:

VEHICLE CHECK LISTINDICATE:
A - ACCIDENTS
D - DENTS
S - SCRATCHES


RIGHT



FRONT



TOP



LEFT

MISSING / FAULTY ACCESSORIES / PARTS

REMARKS:

Vehicle No: SIN 5329H

Replace Veh No: SJQ 7517Y

Mileage Out: 188077

Mileage Out:

Make & Model:

Auto / Manual

TOYOTA ALTIS

Out : Date

14/06/2019

Time:

1015

HIRE / PERIOD EXPIRY

Time:

NON-WAIVER EXCESS=\$ 20007

CHARGES

Daily 7 @ \$ 110 per day

\$ 770 -

Weekly @ \$ per week

Monthly @ \$ per month

Hours @ \$ per hour

Extension @ \$

Delivery/Collection Service

SUB-TOTAL \$**PETROL LEVEL**

Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F

Fuel

Traffic / Parking Fines

TOTAL CHARGES \$

Hirer's Signature

Additional Driver's Signature

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

***IMPORTANT**

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.

2. ONLY PERSON ABOVE 21 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.

3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.

4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.

5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
01/06/19	2pm				

Third Party Insurer Enquiry

Our Ref No: GR-19-095025

Date of Request: 14/06/2019

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 14/06/2019
Enquiry By: Lim Hui Li, Abby
Vehicle No.: SLR3744E
Accident Date: 13/06/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLR3744E	AIG Asia Pacific Insurance Pte. Ltd.	14/08/2018-13/08/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

1 is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-095025

Date of Request: 14/06/2019

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date 14/06/2019
Enquiry By Lim Hui Li, Abby
Vehicle No. SLR3744E
Accident Date 13/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jun 2019 Edit Reg		17 Jun 2019 00:00 Edit Adj Rpt	\$4,500.00 Edit Estimates	\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GSF INNOVATION (2006) PTE LTD , Co. Reg. No.: 200814661E								
Main Claimant:	KOH SENG SEON , ID: S8858259D								
Vehicle Reg. No.:	SJQ7517Y	Date of Loss:	13/06/2019 00:00 - :59 [120 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3388717992SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLR3744E	Policy No. (Claimant):	PNPV2019-00002388						
		Excess:							
Repairer:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (18/06/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ7517Y (3388717992SG)
[SLR3744E]
TP
KOH SENG SEON
Jun 13 2019 12:00AM
[GSF INNOVATION (2006) PTE LTD]
Abwin Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences

















































1 per page
1


No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	

Photos/Images

3 per page
3

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 16:58	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
22	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
23	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
24	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
25	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
26	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
27	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
28	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
29	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
30	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
31	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
32	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
33	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>
34	17/06/19 16:59	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
67	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
68	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
69	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
70	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
71	17/06/19 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
72	17/06/19 16:59	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 14:53	ACKNOWLEDGEMENT EMAIL TO AIG DD 14.06.2019	 Load PDF	
2	17/06/19 14:53	EMAIL FROM AIG DD 14.06.2019	 Load PDF	
3	18/06/19 16:50	TP GIA REPORT	 Load PDF	
4	30/08/19 09:24	WORKSHOP INVOICE	 Load PDF	
5	30/08/19 09:24	AUTHORISATION TO ACT FORM	 Load PDF	
6	30/08/19 09:24	Release Voucher	 Load PDF	
7	30/08/19 09:24	RENTAL RECEIPT	 Load PDF	
8	30/08/19 09:24	GIA SEARCH	 Load PDF	
9	30/08/19 09:24	LOD	 Load PDF	
10	30/08/19 09:24	LETTER TO OI	 Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	18/06/19 09:19	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR3744E (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SJQ7517Y (TP veh)		1.6 (A)
Date of Accident:	13/06/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		9,756.24
Final Repair Cost	:	\$		5,500.00
Loss of Use	:	\$		_____ days at \$0.00 per day
Rental (if any)	:	\$		7 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		5,500.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Abwin Service Pte Ltd	: \$	5,500.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

30 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010667/UDA3Q2

Date: 30/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJQ7517Y

Insured Vehicle No : SLR3744E

Date of Loss: 13/06/2019

Nature of Claim: TP

Claim No: 3388717992SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ7517Y**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4891032

Reg. Date: 26/05/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106145849

Colour: Grey

Odometer: 96304 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Habilead 6 mm

Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,537.98	3,601.02	2,936.96	44.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	2,040.00	540.00	20.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,117.98	5,641.02	3,476.96	38.13
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	9,117.98	4,500.00	4,617.98	50.65
+ GST 7.00/7.00% (S\$)	638.26	315.00	323.26	50.65
Nett Amount (S\$)	9,756.24	4,815.00	4,941.24	50.65
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,517.00		
Global Sum Settlement (S\$)		5,500.00		

INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 17/06/2019 Inspected At:

Abwin Service Pte Ltd (HQ)
No. 8 Kaki Bukit Avenue 4, #07-48
Premier@Kaki Bukit Gate 2
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Buckled	909.70 F	*909.70 FL
2	1		*BOOT LID LAMP R/H	Not Necessary	211.90 F	*- FL
3	1		*BOOT LID LOCK	Twisted	126.80 F	*126.80 FL
4	1		*BOOT LID OUTER CHROME MOULDING	Not Necessary	223.21 F	*- FL
5	1		*BOOT LID (TOYOTA) LOGO	Necessary	45.67 F	*45.67 FL
6	1		*BOOT LID EMBLEM (COROLLA ALTIS)	Necessary	45.67 F	*45.67 FL
7	1		*BOOT LID INNER TRIM	Deformed / Torn	251.60 F	*251.60 FL
8	2		*BOOT LID INNER STOPPER	Not Necessary	29.00 F	*- FL
9	1		*REAR BOOT WEATHERSTRIP	Twisted	194.70 F	*194.70 FL
10	1		*REAR END PANEL	Badly Dented	590.60 F	*590.60 FL
11	1		*REAR END PANEL TOP GARNISH	Twisted	202.70 F	*202.70 FL
12	1		*FENDER INNER TRIM R/H	Deformed / Torn	378.40 F	*378.40 FL
13	1		*SPARE TYRE TOP BOARD	Torn	389.40 F	*389.40 FL
14	1		*TAIL LAMP R/H	Cracked	414.10 F	*414.10 FL
15	1		*TAIL LAMP L/H	Not Necessary	414.10 F	*- FL
16	1		*TAIL LAMP PANEL R/H	Repair	129.24 F	*- FL
17	1		*TAIL LAMP LOWER BRACKET R/H	Not Necessary	45.70 F	*- FL
18	1		*REAR BUMPER	Distorted	523.90 F	*523.90 FL
19	1		*REAR BUMPER SPONGE	Not fitted	175.70 F	*- FL
20	1		*REAR BUMPER BRACKET R/H	Bent	97.70 F	*97.70 FL
21	1		*REAR BUMPER SIDE RETAINER (LONG) O/S	Bent	57.80 F	*57.80 FL
22	1		*REAR BUMPER SIDE RETAINER (SHORT) O/S	Bent	46.95 F	*46.95 FL
23	1		*REAR BUMPER SIDE REFLECTOR	Not Necessary	47.77 F	*- FL
24	1		*BOOT LIT EMBLEM (1.6)	Necessary	45.67 F	*45.67 FL
25	10		*BOOT LID INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
26	10		*END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
27	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	10		*FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
30	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*BOOT LIT SEALANT	Not Necessary	50.00 FS	*- FS
33	10		*TAIL LAMP SIDE CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 6,537.98 4,681.36
 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00 1,080.34

Total Parts (S\$) 6,537.98 3,601.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRNGTHEN PARTS ON ACCIDENT AREA	New	1,000.00	800.00
2	CHECK WIRING	New	50.00	30.00
3	REMOVE AND REFIX BOOT LID COMPONENT	New	100.00	60.00
4	REMOVE AND REFIX EXHAUST PIPE	New	150.00	60.00
5	REMOVE & REFIX SENSOR & TEST)	New	80.00	50.00
6	REMOVE AND REFIX CAMERA & TEST)	New	100.00	0.00
7	TO APPLY UNDERCOATING FOR RUST ROOFING	New	100.00	60.00
8	SPRAY PAINTING ON ACCIDENT AREA	New	1,000.00	980.00
Gross Labour Cost (S\$)			2,580.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >