

ASSIGNMENT

From:

Date:

17/6/19

Veh No:

XE 320R

yr Regn:

2008 / Jan

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

XE 320R

Make:

NISSAN CW B45CLPHNB C.C. 13074

at Workshop m/s

Colour:

yellow

A/C:

Insured / Std / NI / NA

of

14 Tampines Ind. Drive

Sp. Reading:

510 233

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

CW B4CLP00098

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

(Client's Record)

Make of Veh:


1:30pm - 2pm

(Policy Condition)

8332118

Remark: The veh had commenced its

repair at the time of inspection.



Bat. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

1-2-1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Tyre Size:

F:

295/50R22-5

R:

2/p

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CHENGSHAN

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

15/06/19

D.O.I.

17/06/19

Survey held at

14, Tampines Ind. Dr

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P = \$43,000 / - (Red = \$21,821 / 34%)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + PS. 31

Photo:

Video:

Total:

Report Format:

Lump Sum / LD etc

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Welding (\$



Cecilia

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER

Contact : 64819588 83518839

Estimate : ES006704

Date : 17/06/2019
Vehicle Num : XE320R
Make/Model : NISSAN CWB45CLPHNB-2008
Chassis/Eng# : CWB4CLP00098/GE13334373B
Accident Date : 17/06/2019
Claim No :
Reference :
Policy No :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO SUPPLY AND INSTALL VERDEGRO US-100K (TMA'S) TRUCK
MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3) C/W
HYDRAULIC LIFT UP
TO DISMANTLE CARRIAGE KNOCK AND STRAIGHTEN REAR CHASSIS
FRAME, RE-ALIGN BODY AND RUST PROOFING

Labour Total S\$:

7420?
612000
59,800.00
1000 2,800.00
62,600.00

Rasul
Hp 90010068

43000

5 days

P/P

17/06/19 @ 1430

Reay new parts

LKK Auto Consultants hence notify
the Repairer of the following:
• To reserve before after spray painting
• To display damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• (If illegal modifications) is allowed
• Supplementary item(s) must be re-surveyed and
is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

SingDollars : Sixty-Two Thousand Six Hundred Only

Total S\$: 62,600.00

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which
may be required after the work has begun

\$64,881.00



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 83518839

Supplementary Estimate : ES006708

Date : 17/06/2019
Vehicle Num. : XE320R
Make/Model : NISSAN CWB45CLPHNB-2008
Chassis/Eng# : CWB4CLP00098/GE13334373B
Accident Date : 15/06/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR BUMPER <i>repair</i>		1,520.00
3.	1	REAR FENDER (REAR) L/H <i>repair</i>		325.00
3.	1	REAR FENDER MUDFLAP L/H <i>repair X SCL</i>		186.00

Special Nett Total S\$: 2,031.00

LABOUR :
TO CHANGE REAR BUMPER, REAR FENDER L/H AND MUDFLAPS *(labour included in revised estimate)* 250.00 X 1.00
Labour Total S\$: 250.00

SingDollars : Two Thousand Two Hundred Eighty-One Only

Total S\$: 2,281.00

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 83518839

Supplementary Estimate : ES006708

Date : 17/06/2019
Vehicle Num. : XE320R
Make/Model : NISSAN CWB45CLPHNB-2008
Chassis/Eng# : CWB4CLP00098/GE13334373B
Accident Date : 15/06/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR BUMPER <i>repair</i>		1,520.00
3.	1	REAR FENDER (REAR) L/H <i>repair</i>		325.00
3.	1	REAR FENDER MUDFLAP L/H <i>TOOK</i>		186.00
Special Nett Total S\$:				2,031.00
LABOUR :				
TO CHANGE REAR BUMPER, REAR FENDER L/H AND MUDFLAPS <i>(labour included in revised estimate)</i>				250.00 X
Labour Total S\$:				250.00

SingDollars : Two Thousand Two Hundred Eighty-One Only

Total S\$: 2,281.00

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 83518839

Estimate : ES006704

Date : 17/06/2019
Vehicle Num. : XE320R
Make/Model : NISSAN CWB45CLPHNB-2008
Chassis/Eng# : CWB4CLP00098/GE13334373B
Accident Date : 17/06/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO SUPPLY AND INSTALL VERDEGRO US-100K (TMA'S) TRUCK
MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3) C/W
HYDRAULIC LIFT UP
TO DISMANTLE CARRIAGE KNOCK AND STRAIGHTEN REAR CHASSIS
FRAME, RE-ALIGN BODY AND RUST PROOFING

Labour Total S\$:

price?
59,800.00
~~2,800.00~~
62,600.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

SingDollars : Sixty-Two Thousand Six Hundred Only

Total S\$: 62,600.00
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which
may be required after the work has begun

Rasul
Hp 90010068
5 days
P/P
17/06/19 @ 1430
Ready new parts



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

NOTICE OF ACCIDENT

Your Ref : SH8011Z

Our Ref : XE320R

15th June 2019

By email : motorclaim@iii.com.sg

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

#04/05 IOB Building

Singapore 049711

Attention: Motor Claim Department

Dear Sir,

ACCIDENT INVOLVING XE320R AND SH8011Z ON 15/6/2019 ALONG SLE TOWARDS BKE BEFORE MANDAI EXIT AT ABOUT 04:00 HRS.

We act for **CHYE THIAM MAINTENANCE PTE LTD** owner of vehicle no. **XE320R** with instruction to repair the vehicle.

Please provide us a list of at least 10 motor surveyors.

Contact person	Ms Lily / Li Hui (Tel: 6455 0012)
Email	lihui@completevms.com.sg

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you. Please note that there will also be a storage charge of \$60 per day on the 2 day notice period commencing from the date of this letter.

Your Faithfully

Please acknowledge :-

li hui
Complete VMS Pte Ltd

Appointed Surveyor:

Rasul (Lkk)

Date & Time:

17/06/19 @ 1430

c.c.f.m

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 17 June 2019 12:08 PM
To: Gan Li Hui; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Zuhaidah Samsuri
Subject: RE: NOTICE OF ACCIDENT: XE320R Your ref: SH8011Z

12.24pm 17/6/19
VNI
person@lily

Dear Sir / Mdm,

Please conduct a survey on TP vehicle XE320R and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Gan Li Hui [mailto:lihui@completevms.com.sg]
Sent: 17 June, 2019 10:17 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: NOTICE OF ACCIDENT: XE320R Your ref: SH8011Z

Without Prejudice

Dear OIC,

Please arrange LKK Auto Consultants Pte Ltd to conduct survey.

Thank you & Best Regards,
Gan Li Hui (Ms)
Complete VMS PTE LTD
Block 176 Sin Ming Drive, #03-14
Sin Ming Autocare Complex, Singapore 575721
Tel: 6455 0012 Fax: 6554 0012

On Mon, 17 Jun 2019 at 09:37, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100. Ext – 248

From: Gan Li Hui [mailto:lihui@completevms.com.sg]

Sent: 15 June, 2019 10:32 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: NOTICE OF ACCIDENT: XE320R Your ref: SH8011Z

Without Prejudice

Dear Sir,

ACCIDENT INVOLVING XE320R AND SH8011Z ON 15/6/2019 ALONG SLE
TOWARDS BKE BEFORE MANDAI EXIT AT ABOUT 04:00 HRS.

We act for CHYE THIAM MAINTENANCE PTE LTD owner of vehicle no. XE320R with
instruction to repair the vehicle.

Please provide us a list of at least 10 motor surveyors.

Contact person Ms Lily / Li Hui (Tel: 6455 0012)

Email lihui@completevms.com.sg

If you fail to conduct the pre-repair inspection within the next 2 working days excluding
any intervening Saturday, Sunday or Public Holiday, the said workshop will commence
repairs thereafter without further reference to you. Please note that there will also be a
storage charge of \$60 per day on the 2 day notice period commencing from the date of this
letter.

Thank you & Best Regards,
Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using,
disclosing and processing your personal data, sharing your personal data with our service providers
(located both inside and outside Singapore) and/or with other insurers in the general insurance industry,
including the General Insurance Association of Singapore. This enables us to ensure proper processing,

handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***XE320R (MCT19060369)**

[SH8011Z]

TP

CHYE THIAM MAINTENANCE PTE LTD

Jun 15 2019 4:00PM

[~]

COMPLETE VMS PTE LTD

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/08/2019 17:00 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$47517.45) - XE320R - Claim Handler: Zuhaidah Bte Samsuri

Approved:47517.45:Please negotiate LOU @ \$250 to \$300 per day.



Your Ref: SH8011Z
Our Ref : TPDS19096 - XE320R

19th July 2019

By Postage

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04 #05
IOB Building
Singapore 049711

Attention: Motor Claims Department

Dear OIC,

**ACCIDENT INVOLVING VEHICLE: XE320R AND SH8011Z ALONG SLE TOWARDS BKE
BEFORE MANDAI EXIT ON 15.06.2019.**

We are the authorized repair workshop for the owner of motor vehicle no. **XE320R** which is involved in the captioned accident with your insured vehicle **SH8011Z**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1	Cost of Repair as agreed with surveyor	S\$ 46,010.00 (inclusive GST)
2	5days of Loss of USE@ \$450.00	S\$ 2,250.00
3	LTA Search fee	S\$ 7.45
	Total	<u>S\$ 48,267.45</u>

We enclosed herewith the following documents to support the claims:-

- Proforma Invoice
- Rental agreement
- Lta search fee

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours Faithfully

Chiu Siong Lim
For Complete VMS Pte Ltd

To: Complete VMS Pte Ltd
176, Sin Ming Drive,
#03-14, Sin Ming Autocare Complex
Singapore 575721

LETTER OF AUTHORIZATION

RE: ACCIDENT BETWEEN XE 320 R / SH 80112 / SLK 2878X (Vehicle Numbers)
ON 15/6/2019 (Date of Accident) AT SLE towards BKE before Mandai exit

1. I/We, the owner of vehicle no. XE 320 R hereby appoint you to act for me to repair and recover damages sustained to my vehicle in the above accident from the third party driver and / or his / her insurers.
2. In this respect, I/We have authorized you to repair, correspond, negotiate and settle on my behalf, all claims against the parties involved in the subject accident. All final financial awards in my favor pertaining to the subject accident claim are to be paid to Complete VMS Pte Ltd.
3. By way of this Letter of Authorization, I/We also further authorized you to sign all Discharge Vouchers and any other related documents in settlement of the subject accident claims. I/We hereby undertake to ratify and reaffirm such signing of Discharge Vouchers and/or documents from any third party insurers by us.
4. During the settlement process with the third party insurers / drivers, you may act fully on my behalf and all negotiations and correspondences given by you to the third party insurers / driver are as if given directly from me. With regards to the settlement of the above subject accident claim, I/We agree and undertake to ratify all correspondences and negotiations given by you to the third party insurers / driver and further agree and undertake to be bound by all acts performed or carded out by you.
5. I/We understand that should the subject accident claims fail or not able to reach an amicably settlement with the third party insurers or driver, I/We will have to appointed a solicitors by way of signing a warrant to act in present of the appointed solicitor to further pursue the matter and to commence legal proceedings in Court in my/our name against the third party driver and/or his employers (if applicable). I/We further agrees that should I/We fails or disagrees to appoint a solicitors at that stage, I/We shall be fully liable for all costs incurred to you until that point of time.
6. I/We further confirm my/our understanding that I/We shall render my/our full co-operation pertaining to the settlement of the subject accident and method of repair adopted shall be in accordance to the standard practices of the industry and will be at the full discretion of you.
7. I/We hereby agree that upon settlement of the above subject accident claim, I/We are required to sign Discharge Voucher/s issued by the third party insurers. After which all settlement monies shall be used to settle all costs and fee incurred to carry out the above subject accident repairs and claims. This settlement monies shall constitute a full discharge of your payment obligation to us.
8. Any indemnity / discharge voucher signed by the workshop is without prejudice to my rights to claim for compensation for my personal injury (if any). Complete VMS Pte Ltd is only authorized to negotiate and finalized with Third Party for my property damages

Signature



Witness's Name & Signature

Name

Hebe

Date

15/06/19

Company Stamp (if applicable)

Email

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT19000369
Claimant Ref: XE 320R

We/I, COMPLETE VMS PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 48,010.00 (repair cost), S\$ 1,400.00 (loss of use/~~rental~~), S\$ 7.45 (search fee), vehicle no. XE 320R that was damaged pursuant to the accident which occurred on 15/06/2019 (date) at SLE (BKE) BEF MANDALAY (location) involving vehicle no. SH 80112 (insured vehicle). This is pursuant to the inspection conducted on 17/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHYE THAM MAINTENANCE PTE LTD ("the third party claimant") of vehicle no. XE 320R to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to XE 320R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 47,417.45 to COMPLETE VMS PTE LTD

Dated this 20 day of September 2019

CLAIMANT:

Signature:

Signed by "the workshop" (workshop)

Name:

NRIC:

Address:

Nationality:

Occupation:

Leow Lily
S1413397F
178, Sin Ming Drive, #03-14
Singapore 575721
Singaporean

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

This indemnity is signed without prejudice
to my rights to claim for compensation
for my personal injury.

COMPLETE VMS PTE LTD

176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare Complex, S575721

Tel: 6455 0012 Fax: 6554 0012 Email: main@completevms.com.sg

Business Reg. No. 200416180E GST Reg. No.: 200416180E



INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04/05 IOB BUILDING
SINGAPORE 049711

Contact : 63476100 Fax No. : 62244174

Tax Invoice : VM014726

Invoice Date : 20/09/2019

Vehicle Num. : XE320R

Make/Model : NISSAN CVB45CLPHNB

Mileage(Km) :

PO/WO/RO# :

Ref./Remark : MCT19060369

S/N	Quantity	Particular	Unit Price	Amount S\$
		COST OF REPAIR AS AGREED AT		43,000.00

SingDollars : Forty-Six Thousand Ten Only

A handwritten signature in black ink, appearing to be 'A' or 'H' with a loop, positioned above the company name.

COMPLETE VMS PTE LTD

Total S\$	43,000.00
GST S\$	3,010.00
Amount Due S\$	46,010.00

Terms : Cash



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Jun 2019 / 10:22:15

Receipt Date/Time : 15 Jun 2019 / 10:22:15

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190615-000403

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SH8011Z				
As at 15 Jun 2019/00:00:01				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SH8011Z Enquiry Fee 20190615102123310808	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx2417	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Vehicle Not In Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019 Edit Reg		17 Jun 2019 00:00 Edit Adj Rpt	S\$43,000.00 Edit Estimates	S\$43,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303921R								
Main Claimant:	CHYE THIAM MAINTENANCE PTE LTD , Co. Reg. No.: 198801700E								
Vehicle Reg. No.:	XE320R	Date of Loss:	15/06/2019 16:00 - :59 [136 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060369	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH8011Z	Policy No. (Claimant):	5108281586						
		Excess:							
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (30/08/2019): Alert - Adj Mandate Approved (S\$47517.45) - XE320R - Claim Handler: Zuhaidah Bte... III_SG (23/07/2019): Alert - Adj Mandate Approved (S\$0.00) - XE320R - Claim Handler: Zuhaidah Bte Sam... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE320R (MCT19060369)
[SH8011Z]
TP
CHYE THIAM MAINTENANCE PTE LTD
Jun 15 2019 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
COMPLETE VMS PTE LTD

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/06/19 20:35	ACKNOWLEDGEMENT EMAIL TO III DD 17.06.2019	Load PDF	
2	21/06/19 11:54	TP ESTIMATE - MARKED	Load PDF	
3	21/06/19 11:54	TP GIA REPORT	Load PDF	
4	22/08/19 11:49	LTA SEARCH	Load PDF	
5	08/10/19 09:25	WORKSHOP INVOICE	Load PDF	
6	08/10/19 09:25	AUTHORISATION TO ACT FORM	Load PDF	
7	08/10/19 09:25	DISCHARGE VOUCHER	Load PDF	
8	08/10/19 09:25	LOD	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	18/06/19 08:33	Singapore Accident Statement	Load PDF	
2	15/08/19 18:06	Letter of Demand from Third Party TPD LOD FROM COMPLETE VMS (XE320R)	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010696/R1GA3Q2

Date: 08/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: XE320R Insured Vehicle No: SH8011Z
 Date of Loss: 15/06/2019 Nature of Claim: TP Claim No: MCT19060369

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE320R
 Make & Model: NISSAN CWB45CLPHNB, 13.1 D (M) Engine No: GE13334373B
 Reg. Date: 25/01/2008 (Man. Year: 2007) Chassis No: CWB4CLP00098
 Colour: Yellow Odometer: 510233 km
 Engine Capacity: 13074 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
 Front Left Side: Cheng Shan 8 mm Rear Left Side: Cheng Shan 8/8 mm
 Front Right Side: Cheng Shan 8 mm Rear Right Side: Cheng Shan 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	62,600.00	43,000.00	19,600.00	31.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	62,600.00	43,000.00	19,600.00	31.31
+ GST 7.00/7.00% (S\$)	4,382.00	3,010.00	1,372.00	31.31
Nett Amount (S\$)	66,982.00	46,010.00	20,972.00	31.31
+ Loss of Use (5.0 x S\$280.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		47,417.45		

INSPECTION

Date of Assignment: 17/06/2019
 Date Inspected: 17/06/2019 Inspected At: 14 TAMPINES IND DRIVE
 Repairer: COMPLETE VMS PTE LTD (HQ)
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Aug 2019)

Parts: N/A NISSAN CWB45CLPHNB 13.1 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE320R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY AND INSTALL VERDEGRO US-100K (TMAS) TRUCK MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3) C/W HYDRAULIC LIFT UP	New	59,800.00	42,000.00
2	TO DISMANTLE CARRIAGE KNOCK AND STRAIGHTEN REAR CHASSIS FRAME ,RE-ALIGN BODY AND RUST PROOFING	New	2,800.00	1,000.00
Gross Labour Cost (\$\$)			62,600.00	43,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >