

22/03/2011

ASS. REC. BY:

REF: CS/MSIG 19010697/ UV d3 12

Special Instruction:

Surveyor: MARCUSASSIGNMENT (Office)From (Person): Chhia Nyuk Pui

of

MSIGDate/Time: 17.6.19 16.14p.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGJ 192

Insured:

4P 27252at Workshop m/s Hui wong

Tel:

62864541of BK 5 Refu Lane 10, #01-576Policy No: 2896297 MKC

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13.6.201919.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 17.6.19 4.22p.m

Person Contacted:

Winson TanVehicle IN/OUT

| Date/Time | Action/Instruction                                 |
|-----------|----------------------------------------------------|
|           | Estimate <input checked="" type="checkbox"/>       |
|           | call back again on 18/6/19                         |
|           | SGJ 192 - CCB / AIG 13022746 / UVJ 392             |
|           | 4P 27252 - X                                       |
|           |                                                    |
| 19/6/19   | Informed Nyuk Pui pending workshop est via merimen |

P.O.D - 02/12/2013

(08/11/13) wef

ASS. REC. BY: *Merimen*

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: *56719C*  
 at Workshop m/s *Merimen*  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: *5* days Res.: Yes or No  
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT  
 Person Contacted: \_\_\_\_\_

Veh No: *56719L* Yr Regn: *1 16*  
 Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CA*  
 Make: *Toyota Camry* c.c. *2494*  
 Colour: *Grey* A/C: Insured / Std / NI / NA  
 Sp. Reading: *105295* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *MR053AK500 4010494*  
 Gen. Cond: *Good* / Fair / Poor / Burnt  
 Steering: *Inorder* / Jammed / Leaked / Burnt or  
 Brake: *Inorder* / Jammed / Leaked / Burnt or  
 Modi: *Nil* / S/Rim / STD A/Rim or  
 Tyre Size: F: *215/55-21*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front *6* mm Rear *6* mm  
 R/Bal. *6* mm L/Bal. *6* mm  
 D.O.A. *13/6/19* D.O.I. *19/6/19*  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*Rear*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*anoly Estate.*  
*18/7/19* Rear end panel dented need time to repair  
*confirm N/S & 2300 with repairer (Red 3457.58, 60%)*  
*18/7/19* Send preli revised via merimen

RECEIVED 19 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?

2) *19/7 - typist*Days Of Repair: *5*Resurvey No. of Trip: *2*

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : *Merimen*Lump Sum / I.B.I.: (\$ *2300*)*150**11**161*

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|       |                                                                                                  |       |                                                                                                     |
|-------|--------------------------------------------------------------------------------------------------|-------|-----------------------------------------------------------------------------------------------------|
| To:   | MSIG Insurance (Singapore) Pte. Ltd.<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807 | From: | LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| Attn: | Chhia Nyuk Pui                                                                                   | Date: | 18 Jul 2019                                                                                         |

**Preliminary Advice**

|                    |                                                                                       |                         |              |
|--------------------|---------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : YP2725Z                                                                             | Accident Date           | : 13/06/2019 |
| TP Vehicle No      | : SGJ19L                                                                              | Assignment Date         | : 17/06/2019 |
| Make               | : TOYOTA CAMRY                                                                        | Est. Duration of Repair | : 5.00       |
| Date of Inspection | : 19/06/2019                                                                          |                         |              |
| Inspection At      | : HUI WANG ENTERPRISE PTE LTD (HQ)<br>BLK 5 DEFU LANE 10, #01-576<br>SINGAPORE 539187 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                                 |      |                     |
|---------------------------------|------|---------------------|
| Repairer's Estimate (Gross)     | :S\$ | 5,757.58            |
| Revised Amount                  | :S\$ | 2,300.00 (LUMP SUM) |
| Check Items (Estimated)         | :S\$ | 0.00                |
| Total                           | :S\$ | 2,300.00            |
| Lump Sum Repair                 | :S\$ |                     |
| <b>Total Loss Consideration</b> |      |                     |
| New for Old Value               | :S\$ |                     |
| Pre-Accident Value              | :S\$ |                     |
| COE / PARF Rebate               | :S\$ |                     |
| Salvage Value                   | :S\$ |                     |
| Margin for Repair               | :S\$ |                     |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 14 Jun 2019 |               | 17 Jun 2019<br>16:14<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Reference                                                                                                  | Claim Details                                              | Documents                                                                       | Show All |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|---------------------------------------------------------------------------------|----------|----------|-------------|--------------|------------|---------|---------|-------------|--------------|------------|-------|-------------|--|--|--|--|--|--|--|--|--|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                            | <b>[Created by insurer]</b>                                |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Insured:                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Simple Craft Interior Trading, Co. Reg. No.: 45034400B                                                     |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Main Claimant:                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | JOE SIO TIN @ RUSTINA JUSUF, ID: S2206670F                                                                 |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Vehicle Reg. No.:                                                                                                                                                                                                                                                                                                                                                                                                                                                                | SGJ19L                                                                                                     | Date of Loss:                                              | 13/06/2019 17:00 - :59<br>[40 Months and 10 Days From<br>LTA Reg Date (Man Yr)] |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Claim Type:                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | TP                                                                                                         | Policy/Cover Note No.:                                     | 28962697MKC (Comprehensive)<br>Coverage: 26/05/2017 -<br>25/05/2020             |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                                                                                                                                                                                                                                                                                      | YP2725Z                                                                                                    | Policy No. (Claimant):                                     |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                            | Excess:                                                    |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Repairer:                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Hui Wang Enterprise Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-576, 539187 Defu Lane - Tel: 6283 0717            |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Handling Insurer:                                                                                                                                                                                                                                                                                                                                                                                                                                                                | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521] |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Adjuster:                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/06/2019]                         |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Driver/Custodian (Insured):                                                                                                                                                                                                                                                                                                                                                                                                                                                      | HOSSAIN SADDAM (26 / Male), NRIC: G3101538W Email:                                                         |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| Adj Asg. Remarks:                                                                                                                                                                                                                                                                                                                                                                                                                                                                | on WP, Liab: 100%. TP agree on SJE - assign LKK Auto Consultants. Contact: Winson Tan @DID: 62864541       |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| <b>ASSOCIATED MAIL RECEIVED</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                            | <a href="#">View All</a> <a href="#">Compose Case Mail</a> |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| There are no mail for this case.                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                                                                                                            |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| <div> <b>ALL ASSOCIATED TASKS</b> </div> <div> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> |                                                                                                            |                                                            |                                                                                 |          | Due Date | Priority    | Type         | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? | No results. |  |  |  |  |  |  |  |  |  |
| Due Date                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Priority                                                                                                   | Type                                                       | Task Group                                                                      | Subject  | Handler  | Assigned By | Completed On | Created On | Done?   |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |
| No results.                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                            |                                                            |                                                                                 |          |          |             |              |            |         |         |             |              |            |       |             |  |  |  |  |  |  |  |  |  |

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |                |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID:      | 670F           |

**Vehicle Details**

|                               |                    |
|-------------------------------|--------------------|
| Vehicle No.:                  | SGJ19L             |
| Vehicle to be Exported:       | No                 |
| Intended Deregistration Date: | 18 Jul 2019        |
| Vehicle Make:                 | TOYOTA             |
| Vehicle Model:                | CAMRY 2.5 AUTO     |
| Primary Colour:               | Grey               |
| Manufacturing Year:           | 2015               |
| Engine No.:                   | 2ARU292482         |
| Chassis No.:                  | MR053AK5004010494  |
| Maximum Power Output:         | 133.0 kW (178 bhp) |
| Open Market Value:            | \$28,170.00        |
| Original Registration Date:   | 03 Feb 2016        |
| First Registration Date:      | 03 Feb 2016        |
| Transfer Count:               | 0                  |
| Actual ARF Paid:              | \$31,438.00        |

**Intended PARF Rebate Details**

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 02 Feb 2026 |
| PARF Rebate Amount:           | \$23,578.00 |

**Intended COE Rebate Details**

|                             |                                       |
|-----------------------------|---------------------------------------|
| COE Expiry Date:            | 02 Feb 2026                           |
| COE Category:               | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):          | 10                                    |
| QP Paid:                    | \$60,001.00                           |
| COE Rebate Amount:          | \$39,246.00                           |
| <b>Total Rebate Amount:</b> | <b>\$62,824.00</b>                    |

The information contained herein is correct as at 18 Jul 2019

OK

Telephone: 62864541 Fax: 62810647

Model: Toyota Camry

Acc.Date: 13/06/2019

Vehicle No: SGJ19L

$$\begin{array}{r} 1901.46 \\ 252 \\ \hline 1426.09 \\ 2896.09 \end{array}$$

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010697/UVD3N2

Date: 24/07/2019

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 28962697MKC |
| Claimant Vehicle No : | SGJ19L                               | Insured Vehicle No : | YP2725Z     |
| Date of Loss:         | 13/06/2019                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | N/A         |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SGJ19L                       | Engine No:  | 2ARU292482        |
| Make & Model:               | TOYOTA CAMRY, 2.0 (A)        | Chassis No: | MR053AK5004010494 |
| Reg. Date:                  | 03/02/2016 (Man. Year: 2015) | Odometer:   | 105295 km         |
| Colour:                     | Grey                         |             |                   |
| Engine Capacity:            | 2494 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55R17     | Rear Tyre Size:  | 215/55R17     |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                          | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 3,507.57        | 1,626.09        | 1,881.48        | 53.64        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 2,250.00        | 1,270.00        | 980.00          | 43.56        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,757.57</b> | <b>2,896.09</b> | <b>2,861.48</b> | <b>49.70</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,300.00</b> |                 |              |
| <b>(S\$)</b>                             | <b>5,757.57</b> | <b>2,300.00</b> | <b>3,457.57</b> | <b>60.05</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>403.03</b>   | <b>161.00</b>   | <b>242.03</b>   | <b>60.05</b> |
| <b>Nett Amount (S\$)</b>                 | <b>6,160.60</b> | <b>2,461.00</b> | <b>3,699.60</b> | <b>60.05</b> |

## INSPECTION

|                             |            |                                  |
|-----------------------------|------------|----------------------------------|
| Date of Assignment:         | 17/06/2019 |                                  |
| Date Inspected:             | 19/06/2019 | Inspected At:                    |
|                             |            | Hui Wang Enterprise Pte Ltd (HQ) |
|                             |            | Blk 5 Defu Lane 10, #01-576      |
|                             |            | Singapore 539187                 |
| Estimated Period of Repair: | 5.0 days   |                                  |

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 24 Jul 2019)          |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGJ19L)                                                                                                                                      |                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition       | Repairer's  | Amount     |
|-----|-----|----------|-----------------------------|-----------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                | Dented/Deformed | 1,219.70 FL | *691.76 FL |
| 2   | 1   |          | *REAR BUMPER LOWER TRAY     | Torn            | 510.40 FL   | *366.10 FL |
| 3   | 1   |          | *REAR LEFT BUMPER REFLECTOR | Cracked         | 210.30 FL   | *69.20 FL  |
| 4   | 1   |          | *REAR LEFT BUMPER RETAINER  | Bent            | 150.50 FL   | *98.10 FL  |
| 5   | 1   |          | *REAR END PANEL             | Repair          | 1,110.80 FL | *- FL      |
| 6   | 1   |          | *REAR REINFORCEMENT         | Dented          | 854.20 FL   | *322.10 FL |
| 7   | 1   |          | *BOOTLID REFLECTOR N/S      | Cracked         | 354.20 FL   | *354.20 FL |
| 8   | 1   |          | *SET REVERSE SENSOR         | Shorted         | 200.00 FS   | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,610.10</b> | <b>2,101.46</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>1,102.53</b> | <b>475.37</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>3,507.57</b> | <b>1,626.09</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                            |          |                 |                 |
| 1                               | LABOUR FOR PANEL BEATING & REPLACING PARTS | New      | 1,200.00        | 520.00          |
| 2                               | SPRAY PAINT                                | New      | 1,000.00        | 700.00          |
| 3                               | WIRING CHECK & REPLACING REVERSE SENSOR    | New      | 50.00           | 50.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                            |          | <b>2,250.00</b> | <b>1,270.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >