rom (Perso	n): Jas tan	of	ASM (AXA)	Date/Time:	17/6/19
stimated Co			Bill to:		
DIFFIN	STTP RES / OD RES			•	
	ehicle No:		4	nsured:	
	m/s	K.kim		Tel: 6452	7018
olicy No:	P2199587	Ming Dr		Saucah	
um Insured			Claim No:		S9M01PK5
ake of Veh			Excess:	TBA	1.1.
MIND OF A CH	E.			D.O.A.	3/6/19
Hent's Recor	rd)			D.O.F.	1 - 11
A REV	/ REP. / REV 24 FIR	s			
A REV	/ REP. / REV 24 FIR	S Person Contro	stade Senders	H.O.D. Endon	ement:
ate/Time:	1 REP. / REV 24 HR. 4:50pm 0 17/6/10	Person Contac		H.O.D. Endon	ement:
A REV	Action/Instruction	Person Contac	Obtain writt	H.O.D. Endon	ement:
A REV	1 REP. / REV 24 HR. 4:50pm 0 17/6/10	Person Contac	Obtain writt	H.O.D. Endon	ement:
A REY	Action/Instruction no voidance ED 26268	Person Contact  School (  of waru	Objection writing -	H.O.D. Endon Vehicle IN O	on from BMS
A REV  ate/Time:  [6]190	Action/Instruction no voidance ED 2626B-	Person Contact  Introductive  of warm  to Jan	Obtain writt	H.O.D. Endon Vehicle IN (0) en ronfimati	ement:

ASS. REC. BY:  REF: A LA / CS	1 ASM 190107071 Kad3
10-11-1	
10-110-1	Veh No: ED 2626 B Yr Regn: // Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or AC: Insured / Std / NI / NA  Sp.Reading Sull Tradio: Insured / Std / NI / NA  Eng/No:  C/No: TTD ZSZEMONU 034466  Gen. Cond: Good / Fair / Poor / Burnt  Steering: Inorder / Jammed / Leaked / Burnt or  Brake: Inorder / Jammed / Leaked / Burnt or  Modi: Nil / S/Rim / STD A/Rim or  Tyre Size: F: 205/608/16
Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  DAC Accident Rport:  Consistent?: Yes or No  Consistent?: Yes or No  Est. Repairs:  O3 days Res.: Yes or No  Lum Sum:  Lum Sum:  Lum Sum:  Lum Sum:  Person Contracted:  Vehicle: IN / OUT	R:  BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /  TOYO / YOKO or  Fron!  R/Bai.  R/Bai.  R/Bai.  Pmm  L/Bai.  D.O.A.  Pmm  L/Bai.  D.O.I.  Rear  Pmm  D.O.I.  Rear  Pmm  D.O.I.  D.O.I.  Pmm  D.O.
Date / Time   Action / Instruction   Fix pars 70	The state of the s
128/07 Typist : Final Report Re:  Outo/Time, File Return to?  Add Fee:  Report Format : SMART CLAIMS	ys Of Repair: 3 survey No. of Trip: 1 Survey Fee: Transportation:  Site Insp (\$ ) _ \$ • RS _ \$I  Interview (\$ ) Fixeds  Tech Invs (\$ ) Others
Lump 8um / I.B.I: (\$ 1279.12	Tech Invs (\$ ). Others  Weekend (\$ )

TOTAL



# Service Request Details

Claim

S9M01PK5

Reference

None Ø

Loss Date

June 1, 2019

Report Date

Jun 3, 2019 12:00:00 AM

Request Date

June 17, 2019

Due Date

June 24, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

#### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

#### Vehicle Information

Incident Vehicle Registration #

ED2626B

PRIUS+

Service Address

, , ,

Primary Contact/Insured

**QUCK SWEE SIANG** BLK 6 ANGKLONG LANE, #15-02, 579980, Singapore 97569956 SWEESIANGQ@HOTMAIL.COM

Claim Handler

TAN Jas 6568804844 jas.tan@axa.com.sg

Additional Instructions

OD K KIM HIN OD XS TBA to obtain written confirmation from BMS no voidance of warranty

Metrics Notes Assessment History Documents Messages Invoices

#### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 24 June 2019 9:50 AM

To:

service@kkimhin.com.sg; survey@kkimhin.com.sg

Cc:

sandrakhong@gmail.com; simon@kkimhin.com.sg; survey2@kkimhin.com.sg

Subject:

RE: ED 2626 B - sms from Toyota sales lady to client

Dear Sir/Madam,

Please be informed that the excess of above vehicle is NIL.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Monday, 24 June 2019 9:19 AM

To: service@kkimhin.com.sg; survey@kkimhin.com.sg

Cc: sandrakhong@gmail.com; simon@kkimhin.com.sg; survey2@kkimhin.com.sg

Subject: RE: ED 2626 B - sms from Toyota sales lady to client

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle ED 2626B (excess TBA).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: service@kkimhin.com.sg <service@kkimhin.com.sg>

Sent: Friday, 21 June 2019 3:02 PM

To: Shiau Chan (LKKAuto) < siewsc@lkkauto.com>

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg;

survey2@kkimhin.com.sg

Subject: ED 2626 B - sms from Toyota sales lady to client

Dear Shiau Chan

As spoken, enclosed.

LKK AUTO CONSULTANTS PTE LTD (OD) .

Menu



# Re:RE: Re:OI ED 2626B - obtain written confirmation from BMS no voidance of warranty

Type

**Q** Question

Message excess nil

Reply

#### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 24 June 2019 9:19 AM

To:

service@kkimhin.com.sg; survey@kkimhin.com.sg

Cc.

sandrakhong@gmail.com; simon@kkimhin.com.sg; survey2@kkimhin.com.sg

Subject:

RE: ED 2626 B - sms from Toyota sales lady to client

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle ED 2626B (excess TBA).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: service@kkimhin.com.sg <service@kkimhin.com.sg>

Sent: Friday, 21 June 2019 3:02 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg;

survey2@kkimhin.com.sg

Subject: ED 2626 B - sms from Toyota sales lady to client

Dear Shiau Chan

As spoken, enclosed.

Understand AXA requested for confirmation in writing that Borneo Motors will not void client warranty if she choose to repair at other AXA Authorised workshop other than Borneo Motors.

This is the sms that her Toyota sales person sent to client.

Client feels helpless like caught between AXA and Borneo Motors.

Thanks & Regards Sandra 6452 7018 K. Kim Hin Auto Pte Ltd LKK AUTO CONSULTANTS PTE LTD (OD) \*

Menu

Model

PRIUS+

Service Address

1 + 1

## Primary Contact/Insured

QUCK SWEE SIANG BLK 6 ANGKLONG LANE, #15-02, 579980, Singapore 97569956 SWEESIANGQ@HOTMAIL.COM

#### Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

OD K KIM HIN OD XS TBA to obtain written confirmation from BMS no voidance of warranty

Messages	Invoices	History	Documents	Assessment	Metrics	Notes	
New Messag	e						
TYPE				0			
SENT		6/2	1/19 4:02 PM				
FROM		1AT	N Jas				
SUBJECT			OI ED 2626B - ol	otain written conf /	irmation from	BMS no	
BODY		ple	ase proceed to au	thorize.			
		+					
TYPE				0			

LKK AUTO CONSULTANTS PTE LTD (OD) -

LKK AUTO CONSULIANTS PTE LTD (OD) FKUM OI ED 2626B - obtain written confirmation from BMS no voidance SUBJECT of warranty Dear Jas, according to the repairer, the insured u... BODY 0 TYPE 6/19/19 3:39 PM SENT LKK AUTO CONSULTANTS PTE LTD (OD) FROM OI IA OF VEHICLE ED 2626B UPLOADED SUBJECT Dear Jas, please be informed that the OI IA of veh... BODY 0 TYPE 6/17/19 5:02 PM SENT LKK AUTO CONSULTANTS PTE LTD (OD) **FROM** VNI SUBJECT BODY Please be informed that vehicle is not in the work...

Menu



# OI ED 2626B - obtain written confirmation from BMS no voidance of warranty

Type

Question

#### Message

Dear Jas, according to the repairer, the insured unable to get the confirmation of no voidance of warranty from Borneo Motor, the workshop's replied email on the matter and insured's whastapp has been uploaded. Kindly advise. - Shiau Chan

Reply

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

# **Immediate Advice**

To: AXA Insurance Pte Ltd

17/6/2019

# **Survey Details:**

Date of loss	3-Jun-19	
Date of appointment	17-Jun-19	
Date of survey	19-Jun-19	
Location of survey	K KIM HIN	

## Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	ED 2626B	
Make and Model	TOYOTA PRIUS PLUS (AUTO)	
Date of registration	29/10/2018	
Excess	TBA	
Market Value	\$	94,000.00
Parf Rebate	\$	48,088.00
Nett Loss	\$ 45,912	

# Repair details:

Initial Estimate	\$ 2,124.64

# Proposed/Revised repair cost:

Parts	\$ 1,127.50
Check items (estimate)	\$ 41.80
Labour	\$ 410.84
Total	\$ 1,580.14
Lump Sum(if applicable)	\$ ¥*

Number of days for repair	<u>3</u>

51 UBLAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.

Pending for insured to obtain a written confirmation on no voidance of warranty from repairer. WE HAVE NOT AUTHORISE REPAIR.

### Mandate:

	%	
Liability(TP)	ć	
Proposed repair cost	>	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Singapore NRIC

42211

#### > Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner f	Particulars
-----------------	-------------

Owner ID Type:

Owner ID: Vehicle Details

Vehicle No.: ED2626B

Vehicle to be Exported: No

Intended Deregistration Date: 03 Jun 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS PLUS (AUTO)

Primary Colour: Silver
Manufacturing Year: 2018

Engine No.: 2ZR0C59996

 Chassis No.:
 JTDZS3EU00J034464

 Maximum Power Output:
 100.0 kW (134 bhp)

 Open Market Value:
 \$30,006.00

 Original Registration Date:
 29 Oct 2018

 First Registration Date:
 29 Oct 2018

Transfer Count: 0

Actual ARF Paid: \$24,009.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Oct 2028 PARF Rebate Amount: \$18,006.00

Intended COE Rebate Details

COE Expiry Date: 28 Oct 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

 COE Period(Years):
 10

 QP Paid:
 \$32,001.00

 COE Rebate Amount:
 \$30,082.00

 Total Rebate Amount:
 \$48,088.00

The information contained herein is correct as at 03 Jun 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

•	$\sim$	DEM	T STA	44.0	ENT	
	uu					

Date Of Report

03/06/2019 16:32

Date Of Accident

01/06/2019 16:00

Exact Location Of Accident

ANG MO KIO BLK 453 CARPARK (A37) EXIT

Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number

ED2626B

#### Insured/Policyholder

Name Of Registered Owner

QUCK SWEE SIANG

NRIC No

S1764221I

Email Address

SWEESIANGQ@HOTMAIL.COM

Mobile Phone No

(LOCAL) +65-97569956

Alternative Phone No

OFFICE-97569956

#### **Vehicle Particulars**

Manufacturer

TOYOTA

Model

PRIUS-1.5 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy YES

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

#### Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

P2199587

Cover Note Number

#### Driver

Name of Driver

QUCK SWEE SIANG

NRIC No Date Of Birth S1764221I 13/12/1966

Occupation

INDOOR

Date Of Driving Pass

25/10/1989

Driving Experience

29 YEARS AND 7 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-97569956

Fax Number

Contact Number

OFFICE-97569956

EMail Address

SWEESIANGQ@HOTMAIL.COM

Address

BLK 6 ANGKLONG LANE #15-02

Postcode

579980

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: NIGEL CHOW

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FW8243X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 11

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 1/1/10

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signati

Name:

NRIC/FIN No.

#### Sketch Plan Pg. 2

SKETCH PLAN	
R=ED26 B=FW	
I was in the carpork at ting the kin Bik 453 m	ancet
and food centre. I stopped at the carpore exit	as
there was a long turning in from the right suddenly a motorcyclist (vehicle number FW824)	
suddenly a motorcyclist (vernice number + W824.	3 X )
came from behind me long and but the right	pour
of my con bumper.	19-11-22-0-2
He said he was alright and dight need to s	ee me
doctor when I asked if he was ok. He no	
off without giving his details.	
11 0	
	ar and a second
CLARATION  We declare the foregoing particulars are true in every respect.	1005e
	HIN ACA
ch 3/6/19	( )3
icyholder's Signature Driver's Signature Reporting Centre Personnel's 34	Mary T

(If driver is not the policyholder) Date & Time: Name: NRIC/FIN No.:

Date & Time:

Company Chop (if applicable)

## K.Kim Hin Auto Pte Ltd 160 Sin Ming Drive, #02-20, Sin Ming AutoCity 575722

Claim Reference:

Assessment number: 190302

Version: 1810

Date calculated: 11/06/2019 2:14 PM

**Full Report** Registration: ED2626B Printed: 11/06/2019 2:14 PM

#### Summary Information

Claim

Location: Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Singapore (SG) SANDRA KHONG Work Provider: Currency:

Date of Incident: Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD 03/06/19

#### Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer:

**Model Specs** 

FROM 10.2018

TWO COAT PEARL/MICA

TOYOTA

PRIUS V BASE MODEL

70 A4 01 ED2626B

LED HEADLAMP

FOG LAMPS

PREPARE OFF VEHICLE

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

# K.Kim Hin Auto Pte Ltd 160 Sin Ming Drive, #02-20, Sin Ming AutoCity 575722

Claim Reference:

Full Report Registration: FD2626B

Assessment number: 190302

Registration: ED2626B

Version: 1810

Printed: 11/06/2019 2:14 PM

Date calculated: 11/06/2019 2:14 PM


#### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All Underbody



#### Labour

_	Time Base 10 WU/h	Price = 45.	00 SGD/h
Code	Description	WU	Price SGD
190011)	DETACH + REFIT BATTERY CABLE INCLUDES: R + R BOOT STORAGE BOX AND NECESSARY ATTACHED PARTS	2.0	9.00
NO NUMBER	R + R FRONT LOWER ENGINE COVER	1.0	4.50
B010)	R + R FRONT BUMPER	7.0	31.50
во20)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R RADIATOR GRILLE, FRONT FOG LAMPS AND NECESSARY ATTACHED PARTS	13.0	58.50
750011)	R + R FRONT MANUFACTURER BADGE	3.0	13.50
NO NUMBER	R + R L/F BUMPER MOUNTING	1.0	4.50
NO NUMBER	R + R R/F BUMPER MOUNTING	1.0	4.50

Mon Norhand Buhony Bapaing Excess TBA

# K.Kim Hin Auto Pte Ltd 160 Sin Ming Drive, #02-20, Sin Ming AutoCity 575722

Pax 62564315

Claim Reference:

Assessment number: 190302

Version: 1810

Date calculated: 11/06/2019 2:14 PM

**Full Report** 

Registration: ED2626B

Printed: 11/06/2019 2:14 PM

**Labour Cost** Hrs Panel / Mechanical Labour

2.80

WU 28.0

126.00

Total of Labour

126.00

Paint		
Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	R/F BUMPER COVER NEW PART PAINT K1R	3.0
	FRONT BUMPER NEW PART PAINT K1R	12.0
	L/F WING SURFACE PAINT	6.0

#### **Paint Material Per Part**

Code	Description	Price SGD
0278	R/F BUMPER COVER NEW PART PAINT K1R	0.98
0283	FRONT BUMPER NEW PART PAINT K1R	55.10
0741	L/F WING SURFACE PAINT	10.21

Labour Cost - Paint		Hrs	wu	Price SGD
Factor	45.00 SGD/h			
Time Paint			21.0	
Preparation Main Work Metal		0.50	5.0	22.50
Preparation Comp. Work Plastic		1.50	15.0	67.50
Total	10 WU/h	4.10	41.0	184.50

#### Material Cost - Paint New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Material-constant Plastic Total

th	
- 1	
0.1	
	arts prices are appear to configuration hild party survey is on a "Without Prejudice" basis
P 2	

Price SGD
56.08
10.21
9.00

25.05

100.34

**Spare Parts** 

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0253	FRONT LWR AIR GRILLE	53102 47180		Pd/44 240.00
0278	R/F BUMPER COVER	52127 47060		Sh 42.00 x
0283	FRONT BUMPER	52119 47969		550 cm 690.00

# K.Kim Hin Auto Pte Ltd 160 Sin Ming Drive, #02-20, Sin Ming AutoCity 575722

Claim Reference:

**Full Report** 

Assessment number: 190302

Registration: ED2626B

Version: 1810

Printed: 11/06/2019 2:14 PM

Date calculated: 11/06/2019 2:14 PM

Code	Description	Part Number	Supplier		Price SGD
0317	L/F BUMPER BRACKET	52116 47030			~ 38.00 X
0318	R/F BUMPER BRACKET	52115 47030			VC 38.00 7
0330	LOWER FRONT SPOILER	76851 47070		S <sub>L</sub>	120.00 X
0351	CLIP FASTENING	90189 06193		NN M	15.00
0413	LWR RADIATOR GRILLE	53113 47060		₹.	90.00 X
0431	FRONT MANUFACT BADGE	75310 33050			د 80.00 د
0638	R/F FOG LAMP CPL	81210 47010		Sh	130.00 X
8784	FRONT LWR ENGINE CV	R52618 47060			√ 75.00 X
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,558.00
u: Used parts	Addition(+10.00%)				155.80
	Total				1,713.80
Final Calculat	tion				
				SGD	SGD
Parts				1,558.00	
Addition(+10.0	00%)			155.80	
Total Parts	V-200-2005 P.C.				1,713.80

	SGD	SGD
Parts	1,558.00	
Addition(+10.00%)	155.80	
Total Parts		1,713.80
Labour Time Base 10 WU/h		
Total 28.0 WU X 45.00 SGD/h	126.00	
Total of Labour		126.00
Paint Work Time Base 10 WU/h		
Labour Cost 41.0 WU X 45.00 SGD/h	184.50	
Material Cost	100.34	
Total Paint Including Material		284.84
Repair Cost Excludes GST		2,124.64
GST (+7.0%)		148.72
Repair Cost Included GST		2,273.36

# K.Kim Hin Auto Pte Ltd 160 Sin Ming Drive, #02-20, Sin Ming AutoCity 575722

Claim Reference:

Assessment number: 190302

Version: 1810

Date calculated: 11/06/2019 2:14 PM

**Full Report** 

Registration: ED2626B

Printed: 11/06/2019 2:14 PM

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS