



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2018 TOYOTA PRIUS+ (ED2626B)
Date of Loss	1 June 2019
Time of Loss	16.00
Loss Description	ED2626B (INSD) C/W FW8243X (MOTORCYCLE)
Comment	<div></div>

Workshop Details

Total Rebate Amount	<div>48088</div>
Nett Loss Amount	\$45,912.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion	<div>20</div>

*

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition



Taxes & Ratio

Parts & Labour

Miscellaneous


Summary

Vehicle & Driver Details

Vehicle Registration#	ED2626B	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>29/10/2018</div> <div></div>
Mileage	<div>8411</div>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2018	<div>2018</div>
Make	TOYOTA	<div>TOYOTA</div>
Model	PRIUS+	<div>PRIUS PLUS (AUTO)</div>
Type		<div></div> <div>▼</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	QUICK SWEE SIANG	<div></div>
Date of Birth	13 December 1966	<div>dd/mm/yyyy</div> <div></div>
Age	53	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type of Paint		
Chassis No	JTDZS3EU00J034464	JTDZS3EU00J034464
Engine No	2ZR0C59996	2ZR0C59996
Engine Capacity		1798
Sum Insured	0	0
Market Value	0	94000

CATEGORY	EMPLOYEE INFORMATION	
Occupation		
Education Qualification	Other	
Driving Experience	4	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy
License Expiration Date		dd/mm/yyyy
Address	BLK 6 ANGKLONG LANE, #15-02, 579980, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	<div>▼</div>
Marital status	Married	<div>▼</div>
Identification #	S1764221I	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

19/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Un
named Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/60 R16

Front left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Rear Tyre Size

205/60 R16

Rear left side

YOKOHAMA9mm

Rear right side

YOKOHAMA9mm

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts











Add

Approve

Deny







Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT LWR AIR GRILLE (WCP) (10%)	Cracked	0	264	No					264	Reviewing	
<input type="checkbox"/>		0	1		R/F BUMPER COVER	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRONT BUMPER (WCP) (10%)	Cracked	0	605	No					605	Reviewing	
<input type="checkbox"/>		0	1		L/F BUMPER BRACKET	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/F BUMPER BRACKET	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		LOWER FRONT SPOILER	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		CLIP FASTENING	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		LWR RADIATOR GRILLE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRONT MANUFACT BADGE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/F FOG LAMP CPL	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRONT LWR ENGINE CVR	Serviceable	0	0	No					0	Deny	

Labour

AddApproveDenySubmit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		28.0 WU X 45.00 SGD/H	0	103.5	0	0	Reviewing		
<input type="checkbox"/>		0		LABOUR COST 41.0 WU X 45.00 SGD/H	0	202.5	0	0	Reviewing		
<input type="checkbox"/>		0		MATERIAL COST	0	104.12	0	0	Reviewing		

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous


Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$1,279.12

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$869.00
Labour	\$0.00	\$410.12

Submit for Review