



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving1 2010 FORD GALAXY 2.3 GHIA (SLD7744C)

Date of Loss3 June 2019

Time of Loss0.00

Loss DescriptionSLD7744C (INSD) C/W SMH5628K (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount\$19,000.00

Assigned WorkshopLKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLD7744C

Registration State SINGAPORE

Mileage 100909

Purchase Date dd/mm/yyyy

Registration Date * 31/08/2010



Age of Vehicle 8

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2010	2010
Make	FORD	FORD

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	FIFE KATHERYN CAMPBELL	
Date of Birth		dd/mm/yyyy

Model CATEGORY	GALAXY 2.3 GHIA POLICY INFORMATION	GALAXY 2.5 INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	WF0MXXGBWMAS56485	<input type="text" value="WF0MXXG"/>
Engine No	AS6485	<input type="text" value="AS56485"/>
Engine Capacity		<input type="text" value="2261"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="19000"/>

CATEGORY Age	FNOL INFORMATION 0	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	274 CANADA ROAD, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/>
Gender	Unknown	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	G1751779T	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

19/06/2019

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good

▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		R/R DOOR (WCP) (10%)	Bent	0	1265	No					1265	Reviewing
		0	1		R/R DOOR SEAL	Serviceable	0	0	No					0	Deny
		0	1		R/R WINDOW REGULATOR	Serviceable	0	0	No					0	Deny
		0	1		R/R DOOR TRIM FRONT	Serviceable	0	0	No					0	Deny
		0	1		R/R DOOR TRIM REAR	Serviceable	0	0	No					0	Deny
		0	1		R/R DOOR BADGE	Serviceable	0	0	No					0	Deny
		0	1		R/R DOOR MOULDING (WCP) (10%)	Dented	0	176	No					176	Reviewing
		0	1		R/SILL PANEL	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		REAR BUMPER (WCP) (10%)	Buckled	0	429	No					429	Reviewing
		0	1		R/R BUMPER CORNER (WCP) (10%)	Damaged	0	104.5	No					104.5	Reviewing
		0	1		R/BRACKET MOUNTING	Serviceable	0	0	No					0	Deny
		0	1		R/R BUMPER BRACKET	Serviceable	0	0	No					0	Deny
		0	1		R/PROTECTION FOIL	Serviceable	0	0	No					0	Deny
		0	1		R/R WHEEL HUB/BRG	Serviceable	0	0	No					0	Deny
		0	1		R/R DR OUT HANDLE (WCP) (10%)	Damaged	0	368.5	No					368.5	Reviewing
		0	1		R/R SPORT RIM (WCP) (10%)	Dented	0	825	No					825	Reviewing

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		WHEEL ALIGNMENT	0	60	0	0	Reviewing	
		0		180.0 WU X 45.00 SGD/H	0	324	0	0	Reviewing	
		0		LABOUR COST 95.0 WU X 45.00 SGD/H	0	690.16	0	0	Reviewing	

