

ASS. REC. BY:

REF:

CS/ASMT 1010755/R/d3eb

Special Instruction:

Sungar - Rasul

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MSIG

Date/Time: 18/6/19 @ 9:40am

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKT1233C

Insured:

at Workshop in/s

volkswagen

Tel:

9386 7833

of

17 furs Ave 9

Policy No:

Claim No:

Sum Insured:

Excess:

IBA \$500/-

Make of Veh:

(Client's Record)

D.O.A.

16/06/2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:20am 18/5/19

Person Contacted:

Gemmaire

Vehicle: B1 OUT

Date/Time	Action/Instruction
	SKT1233C-X
19/06/19	@ 11:00 am revised ZA to Pauline Poh Li Ping via memo
19/06/19	@ 11:02 am mandate requested authorize repair to Pauline via memo
19/06/19	@ 18:35 pm mandate approved by Jocelyn Ng Shan Ben via memo

Surveyor: Rasul

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKT 1233Cat Workshop m/s: VOLKSWAGENof 17, TUNAS AVE 9

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: IBA \$500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 55K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT 1233C Yr Regn: 2015 / MAYType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen JETTA 1.4 C.C. 1390Colour: BROWN A/C: Insured / Std / NI / NASp. Reading: 45469 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW222162FM001688Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 205/55 R16R: 21BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/06/19 D.O.I. 18/06/19Survey held at 17, TUNAS AVE 9

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/06/19 @ 10:19 am inform c/a to ~~the~~ Humare (owner) via email.

Repair limit \$7K

02/07/19 Confirmed P/P \$ 6,106.70 @ 7 days with Rasul
(\$ 6,205.39 Red - 50%)

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

02/07/19

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Survey Fee: 200

Transportation:

S + RS \$

Photos


Others

TOTAL

Report Format:

Lump Sum (I.B.) (\$ 6,106.70 P/P)

200
11
211



2/7/2019

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 18 June 2019 9:40 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: 0414_001.pdf

Importance: High

SKT1233C - MSIG (inhouse) OD - DOA: 16/06/2019 Car in tuas 18/06/19.

Manual Assigned

Dear LKK

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Tang Shu Shi (VGS - SG/Singapore) [<mailto:shushi.tang@vw.com.sg>]
Sent: Monday, 17 June 2019 6:37 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>
Cc: Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>; Oh Aik Seong (VGS - SG/Singapore) <Aikseong.Oh@vw.com.sg>; Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>
Subject: SKT1233C - MSIG (inhouse) OD - DOA: 16/06/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Claims,

Please arrange vehicle to be survey at 17 Tuas Ave 9, Singapore 639197.

Vehicle in workshop.

Best Regards,

Tang Shu Shi
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore (Macpherson)
1 Kampong Ampat
Singapore 368314

DID: +65 6922-3502
Mobile: +65 9386-7833
Main Line : +65 6305-7299
Main Fax: +65 6285-8620
shushi.tang@vw.com.sg
<https://www.volkswagen.com.sg/>



From: Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>
Sent: Monday, 17 June 2019 6:36 PM
To: Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>
Subject: Scan Image

Internal

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5663Z
Vehicle Details	
Vehicle No.:	SKT1233C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL 1634G5
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	CAXF13416
Chassis No.:	WVWZZZ16ZFM001688
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,625.00
Original Registration Date:	19 May 2015
First Registration Date:	19 May 2015
Transfer Count:	0
Actual ARF Paid:	\$9,625.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2025
PARF Rebate Amount:	\$7,218.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,589.00
COE Rebate Amount:	\$40,551.00
Total Rebate Amount:	\$47,769.00

The Information contained herein is correct as at 19 Jun 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 8 July 2019 11:04 AM
To: 'Cheong Pearlyn (VGS - SG/Singapore)'; 'Oh Aik Seong (VGS - SG/Singapore)'; Rasul (LKKAuto)
Cc: 'Ong Germaine (VGS - SG/Singapore)'; 'Foo John (VGS - SG/Singapore)'; 'Tang Shu Shi (VGS - SG/Singapore)'; 'Chee Steven (VGS - SG/Singapore)'
Subject: RE: SKT1233C - FINALISE

Dear Pearlyn,

Confirmed final fig \$ 6,106.70 @ 7 days of repairs before excess \$ 500/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Oh Aik Seong (VGS - SG/Singapore) [mailto:Aikseong.Oh@vw.com.sg]
Sent: Friday, 28 June 2019 11:15 AM
To: Rasul@lkkauto.com
Cc: Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>; Foo John (VGS - SG/Singapore) <John.Foo@vw.com.sg>; Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>; Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>; Cheong Pearlyn (VGS - SG/Singapore) <Pearlyn.cheong@vw.com.sg>
Subject: SKT1233C - FINALISE

Dear Rasul,

Please confirmed

COR \$5606.70 after less excess before GST

Best regards,

Pearlyn Cheong

Body and Paint
17 Tuas Avenue 9
Singapore 639197

Mobile: +65 8518 7912
Aikseong.Oh@vw.com.sg
<http://www.vw.com.sg>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 20 June 2019 10:19 AM
To: 'Ong Germaine (VGS - SG/Singapore)'; 'Tang Shu Shi (VGS - SG/Singapore)'
Cc: 'Chee Steven (VGS - SG/Singapore)'; SUR; pauline_soh@sg.msig-asia.com
Subject: RE: SKT 1233C OD (MSIG) DOA - 16/06/2019

Dear Germaine,

As instructed by our client, please proceed at repair cost not exceeding \$7,000.00 (inclusive supplementary) to repair the insured vehicle **SKT 1233C (Excess \$ 500/-)** on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Germaine (VGS - SG/Singapore) [mailto:Germaine.ong@vw.com.sg]
Sent: Thursday, 20 June 2019 10:12 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>
Cc: Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>; SUR <sur@lkkauto.com>; Pauline Soh <pauline_soh@sg.msig-asia.com>
Subject: RE: SKT 1233C OD (MSIG) DOA - 16/06/2019

Dear Shirley

MSIG mentioned that they have given the authorisation yesterday

We have yet to receive from your end

Best Regards,

Germaine Ong
Body and Paint Department
Volkswagen Group Singapore Pte Ltd
17 Tuas ave 9
Singapore 639197

Shirley Hiew (LKK Auto)

From: Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>
Sent: Wednesday, 19 June 2019 10:37 AM
To: Shirley Hiew (LKK Auto); Tang Shu Shi (VGS - SG/Singapore)
Cc: Chee Steven (VGS - SG/Singapore); SUR
Subject: RE: SKT 1233C OD (MSIG) DOA - 16/06/2019

Ok. We will accept the repair limit

Best Regards,

Germaine Ong
Body and Paint Department
Volkswagen Group Singapore Pte Ltd
17 Tuas ave 9
Singapore 639197

Hp: +6592361588
germane.ong@vw.com.sg
<http://www.vw.com.sg>



Internal

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 19 June 2019 10:32 AM
To: Tang Shu Shi (VGS - SG/Singapore) <shushi.tang@vw.com.sg>
Cc: Chee Steven (VGS - SG/Singapore) <steven.chee@vw.com.sg>; Ong Germaine (VGS - SG/Singapore) <Germaine.ong@vw.com.sg>; SUR <sur@lkkauto.com>
Subject: SKT 1233C OD (MSIG) DOA - 16/06/2019

Hi Shu Shi,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 7,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKT1233C (596864)**

OD

Jun 16 2019 10:00AM

[LIM THIAM CHYE]

Volkswagen Group Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 08/07/2019 10:45 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6106.70) - SKT1233C - Claim Handler: Pauline Soh Li Ping

Approved:6106.70.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKT1233C (596864)**

OD

Jun 16 2019 10:00AM

[LIM THIAM CHYE]

Volkswagen Group Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/06/2019 18:35 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6016.55) - SKT1233C - Claim Handler: Pauline Soh Li Ping

Approved:6016.55:Repair at not exceeding \$7,000.00 including check and supp parts and subject to excess \$500.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 03 Jul 2019

Preliminary Advice

Vehicle No	: SKT1233C	Accident Date	: 16/06/2019
Make	: VOLKSWAGEN JETTA GP	Policy No.	: A80431314AVW
Assignment Date	: 18/06/2019	Excess	: S\$500.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 7 days
Inspection At	: Volkswagen Group Singapore (HQ) 17 Tuas Ave 9 Singapore 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,312.09
Revised Amount	:S\$	6,106.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,106.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	47,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,231.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 19 Jun 2019

Preliminary Advice

Vehicle No	: SKT1233C	Accident Date	: 16/06/2019
Make	: VOLKSWAGEN JETTA GP	Policy No.	: A80431314AVW
Assignment Date	: 18/06/2019	Excess	: S\$500.00
Date of Inspection	: 18/06/2019	Est. Duration of Repair	: 7 days
Inspection At	: Volkswagen Group Singapore (HQ) 17 Tuas Ave 9 Singapore 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,312.09
Revised Amount	:S\$	6,016.55
Check Items (Estimated)	:S\$	440.86
Total	:S\$	6,457.41
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	47,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,231.00

Remarks

- (X) The vehicle is economical for repair. Repairer able to undertake the repair limit not exceeding \$ 7,000.00 on part by part basis.
- () The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/06/2019 14:37
Date Of Accident	16/06/2019 10:35
Exact Location Of Accident	BLK 153A SERANGOON NORTH CARPART
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT1233C
Insured/Policyholder	
Name Of Registered Owner	LIM THIAM CHYE
NRIC No	S1205663Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90174641
Alternative Phone No	OFFICE-90174641

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA TSI HIGH 90 D7F

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80431314 AVW
Cover Note Number	

Driver

Name of Driver	LIM THIAM CHYE
NRIC No	S1205663Z
Date Of Birth	15/01/1957
Occupation	INDOOR
Date Of Driving Pass	05/06/1978
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90174641
Fax Number	
Contact Number	OFFICE-90174641
Email Address	NOEMAIL

Address	38 FERNSVALE LINK #13-23
Postcode	797534
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

- (ii) for complying with requirements under any regulations, laws or court orders;


 A/6/9
 Reporting Officer's Signature
 Name:
 NRIC/FIN No.

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

one way RMD

Square Iron

Car side path

Date: 16 June 2019

Time: 10.35 AM

Location: Block 153A, Serangan North Carpark.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

PL
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Name:
NRIC/FIN No.:

Y A/6/19.



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGA Centre 2 Singapore 068807
Tel: (65) 6627 7888 Fax: (65) 6627 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form R.T.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 80411314 AVW

Excess: SGD500

Windscreen Excess: SGD100

1. Index Mark and Registration Number of Vehicle

SKT1233C

2. Name of Policyholder

Lim Thian Chye

3. Effective Date of the Commencement of Insurance for the purposes of the Act

19/05/2019

4. Date of Expiry of Insurance

18/05/2020

5. Persons or Classes of Persons entitled to drive*

Lim Thian Chye

Chen Way Leong

Lim Kee Teng

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory

Winnor Consultancy Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Lai
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

2WCPUKH52078041211352337

Accident Sketch Plan



VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Tax invoice
Preview

Page

1/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
LIM
THIAM CHYE
38 FERNVALE LINK
#13-23
Singapore 797534

Document no.
Document date 17-06-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001006/ 1
Job order date 17-06-2019
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKT1233C	1634G5	19-05-2015	VWVZZZ16ZFM001688	JETTA TSI High 90 D7F	36,031

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
5C6807183A	Guide Piece	1	pcs.	31.65	28.00% #1	22.79	24.39
	BUMPER SIDE BRACKET LH	1	pcs.	31.65	28.00% #1	22.79	24.39
5C6807184A	Guide Piece	1	pcs.	31.65	28.00% #1	22.79	24.39
	BUMPER SIDE BRACKET RH	1	pcs.	561.97	28.00% #1	404.62	432.94
5C6821106A	Fender RH	1	pcs.	561.97	28.00% #1	404.62	432.94
N 10621301	Expanding Nut	6	pcs.	1.36	28.00% #1	5.88	6.29
5C6805912N	Wheelhouse Liner	1	pcs.	165.80	28.00% #1	119.38	127.74
	FENDER LINER RH	1	pcs.	27.18	28.00% #1	19.57	20.94
5C6821112A	End Plate	1	pcs.	27.18	28.00% #1	19.57	20.94
	CLOSING ELEMENT	1	pcs.	1,960.95	28.00% #1	1,411.88	1,510.71
5C6831056K	Door	1	pcs.	1,960.95	28.00% #1	1,411.88	1,510.71
	RHS FRT DOOR	1	pcs.	58.66	28.00% #1	42.24	45.20
5C6837652	Door Seal	1	pcs.	58.66	28.00% #1	42.24	45.20
D 378500A2	Sound Absorber Laminated	1	pcs.	38.79	28.00% #1	27.93	29.89
	DOOR INSULATOR	1	pcs.	1,348.72	28.00% #1	971.08	1,039.08
5C6809836	Sectional Part-Pillar A W RH	1	pcs.	1,348.72	28.00% #1	971.08	1,039.08
5C6810530	Filler Plate For Side Mem	1	pcs.	35.19	28.00% #1	25.34	27.11
D 506KD1A3	2k-Insert Foam	1	pcs.	130.29	28.00% #1	93.81	100.38
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	62.20	28.00% #1	44.78	47.91
D 007600A1	Inox-Spray	1	pcs.	62.88	28.00% #1	45.27	48.44
D 180003M2	2k-Body Adhesive	1	pcs.	398.47	28.00% #1	286.90	306.98
5C6071303B	Scuff Plate - Sill Panel	1	pcs.	521.82	28.00% #1	375.71	402.01
D 314D36M2	Long-Life Underseal	1	pcs.	79.34	28.00% #1	57.12	61.12
	LABOUR	8	pcs.	475.00	#1 1425	3,800.00	4,066.00
	Spray Painting	7	pcs.	500.00	#1 1725	3,500.00	3,745.00
	TRANSFER DOOR MECHANISM	1	pcs.	475.00	#1 2375	428.00	508.25
	MSIG (INHOUSE) OD CLAIM						
	DOA: 16/06/2019						
	EXCESS: \$500						
	SURVEY BY:						

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	560.00	11,752.09	1,546.63	7%	861.85	1,546.63	12,312.09	13,173.94
Total	560.00	11,752.09	1,546.63		861.85	1,546.63	12,312.09	13,173.94

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page 2/2

Document no.	
Document date	17-06-2019
Customer no.	5211001211
Customer GST-ID	200412212G
Dealer	39999
Job order number	2019001006/ 1
Job order date	17-06-2019
Service Advisor	SHU SHI TANG

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
LIM
THIAM CHYE
38 FERNVALE LINK
#13-23
Singapore 797534

License plate	Model code	First registration	VIN	Model	Mileage
SKT1233C	1834G5	19-05-2015	WVWZZZ16ZFM001688	JETTA TSI High 90 D7F	36,031

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX). Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

Handwritten notes:
2/16/19
Rahul
Hp 90010068
7 days
18/06/19 @ 1600
EXCESS: TBA
REVERT
Paying before part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice

Preview

Page 1/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
LIM
THIAM CHYE
38 FERNVALE LINK
#13-23
Singapore 797534

Document no.
Document date 28-06-2019
Customer no. 5211001211
Customer GST-ID 200412212G
Dealer 39999
Job order number 2019001006/ 1
Job order date 17-06-2019
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKT1233C	1634G5	19-05-2015	WWZZZ16ZFM001688	JETTA TSI High 90 D7F	36,031

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
5C6807183A	Guide Piece	1	pcs.	31.65	28.00% #1	22.79	24.39
	BUMPER SIDE BRACKET LH*XR-200619						
5C6807184A	Guide Piece	1	pcs.	31.65	28.00% #1	22.79	24.39
	BUMPER SIDE BRACKET RH*XR-200619						
5C6821106A	Fender	1	pcs.	561.97	28.00% #1	404.62	432.94
	RH*XR-200619						
N 10621301	Expanding Nut	6	pcs.	1.36	28.00% #1	5.88	6.29
	AO-210619						
5C6805912N	Wheelhouse Liner	1	pcs.	165.80	28.00% #1	119.38	127.74
	FENDER LINER RH*AO-210619						
5C6821112A	End Plate	1	pcs.	27.18	28.00% #1	19.57	20.94
	CLOSING ELEMENT*AO-210619						
5C6831056K	Door	1	pcs.	1,960.95	28.00% #1	1,411.88	1,510.71
	RHS FRT DOOR*CD-210619						
D 378500A2	Sound Absorber Laminated	1	pcs.	38.79	28.00% #1	27.93	29.89
	DOOR INSULATOR*XR-200619						
D 314D36M2	Long-Life Underseal	1	pcs.	79.34	28.00% #1	57.12	61.12
	XR-200619						
	LABOUR	3	pcs.	475.00	#1	1,425.00	1,524.75
	Spray Painting	3.5	pcs.	500.00	#1	1,750.00	1,872.50
	TRANSFER DOOR MECHANISM	0.5	pcs.	475.00	#1	237.50	254.13
	DOOR SEAL	1	pcs.	58.66	28.00% #1	42.24	45.20
	Insurance Excess	-1	pcs.	500.00	#1	-500.00	-535.00
	MSIG (INHOUSE) OD CLAIM						
	DOA: 16/06/2019						
	EXCESS: \$500						
	SURVEY BY:						

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	560.00	5,046.70	829.95	7%	392.47	829.95	5,606.70	5,999.17
Total	560.00	5,046.70	829.95		392.47	829.95	5,606.70	5,999.17

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice

Preview

Page 2/2

Company
MSIG INSURANCE PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 048581

Customer Details:
Mr
LIM
THIAM CHYE
38 FERNVALE LINK
#13-23
Singapore 797534

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

28-06-2019
5211001211
200412212G
39999
2019001006/ 1
17-06-2019
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKT1233C	1634G5	19-05-2015	WVWZZZ16ZFM001688	JETTA TSI High 90 D7F	36,031

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSG33. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS. Irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2019		18 Jun 2019 18:20 Edit Adj Rpt	\$56,106.70 Edit Estimates	\$56,106.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LIM THIAM CHYE, ID: S1205663Z, Tel: +6590174641, Email: NOEMAIL								
Vehicle Reg. No.:	SKT1233C	Date of Loss:	16/06/2019 10:00 - :59 [48 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 596864	Policy/Cover Note No.:	A80431314AVW (Comprehensive) Coverage: 19/05/2019 - 18/05/2020						
		Excess:	S\$500.00						
Repairer:	Volkswagen Group Singapore (HQ) 17 Tuas Ave 9, 639197 Tuas - Tel: 81214693								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Soh Li Ping]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/07/2019]								
Driver/Custodian:	LIM THIAM CHYE (62 / Male) , NRIC: S1205663Z, Tel: +6590174641 Email: NOEMAIL								
Adj Asg. Remarks:	Survey & revert. Please contact us ASAP if you cannot attend this assignment. Pls revert. Outstanding premium Manually assigned to LKK via email on 18/06/2019								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (08/07/2019): Alert - Adj Mandate Approved (\$56106.70) - SKT1233C - Claim Handler: Pauline Soh... - MSIG_SG (19/06/2019): Alert - Adj Mandate Approved (\$56016.55) - SKT1233C - Claim Handler: Pauline Soh...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT1233C (596864)
 OD
 Jun 16 2019 10:00AM
 [LIM THIAM CHYE]
 Volkswagen Group Singapore

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/06/19 11:00	Adjuster Immediate Advice					1	Load HTM		
2	03/07/19 10:14	Adjuster Immediate Advice					1	Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	02/07/19 14:19	General View					1	Load JPG	☒	
2	02/07/19 14:19	General View					1	Load JPG	☒	
3	02/07/19 14:19	General View					1	Load JPG	☒	
4	02/07/19 14:19	General View					1	Load JPG	☒	
5	02/07/19 14:19	General View					1	Load JPG	☒	
6	02/07/19 14:19	General View					1	Load JPG	☒	
7	02/07/19 14:19	General View					1	Load JPG	☒	
8	02/07/19 14:19	General View					1	Load JPG	☒	
9	02/07/19 14:19	General View					1	Load JPG	☒	
10	02/07/19 14:19	General View					1	Load JPG	☒	
11	02/07/19 14:19	General View					1	Load JPG	☒	
12	02/07/19 14:19	General View					1	Load JPG	☒	
13	02/07/19 14:19	General View					1	Load JPG	☒	
14	02/07/19 14:19	General View					1	Load JPG	☒	
15	02/07/19 14:19	General View					1	Load JPG	☒	
16	02/07/19 14:19	General View					1	Load JPG	☒	
17	02/07/19 14:19	General View					1	Load JPG	☒	
18	02/07/19 14:19	General View					1	Load JPG	☒	
19	02/07/19 14:19	General View					1	Load JPG	☒	
20	02/07/19 14:19	General View					1	Load JPG	☒	
21	02/07/19 14:19	General View					1	Load JPG	☒	
22	02/07/19 14:19	General View					1	Load JPG	☒	
23	02/07/19 14:19	General View					1	Load JPG	☒	
24	02/07/19 14:19	General View					1	Load JPG	☒	
25	02/07/19 14:19	General View					1	Load JPG	☒	
26	02/07/19 14:19	General View					1	Load JPG	☒	
27	02/07/19 14:19	General View					1	Load JPG	☒	
28	02/07/19 14:19	General View					1	Load JPG	☒	
29	02/07/19 14:19	General View					1	Load JPG	☒	
30	02/07/19 14:19	General View					1	Load JPG	☒	
31	02/07/19 14:19	General View					1	Load JPG	☒	
32	02/07/19 14:19	General View					1	Load JPG	☒	
33	02/07/19 14:19	General View					1	Load JPG	☒	
34	02/07/19 14:22	Reinspection Photo					1	Load JPG	☒	

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
35	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
36	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
37	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
38	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
39	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
40	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
41	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
42	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
43	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
44	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
45	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
46	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
47	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
48	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
49	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
50	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
51	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
52	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
53	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
54	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
55	02/07/19 14:22	Reinspection Photo	Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	18/06/19 14:28	Valid Driving Licence	Load PDF		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	18/06/19 18:18	Survey Request - Manual Assigned	Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/06/19 10:58	ESTIMATE.pdf	Load PDF		
2	19/06/19 10:58	SKT 1233C GIA.pdf	Load PDF		
3	03/07/19 10:11	ESTIMATE MARKED.pdf	Load PDF		
4	12/07/19 10:46	Workshop Invoice	Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print	
1	17/06/19 15:14	Accident Statement	Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print	
1	17/06/19 15:12	Accident Photo	Load JPG	☒	
2	17/06/19 15:12	Accident Photo	Load JPG	☒	
3	17/06/19 15:12	Accident Photo	Load JPG	☒	
4	17/06/19 15:12	Accident Photo	Load JPG	☒	
5	17/06/19 15:12	Accident Photo	Load JPG	☒	
6	17/06/19 15:12	Accident Photo	Load JPG	☒	
7	17/06/19 15:12	Accident Photo	Load JPG	☒	
8	17/06/19 15:12	Accident Photo	Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print	

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	17/06/19 14:47	Sketch Plan	 Load TIF	☐
2	17/06/19 14:47	Sketch Plan #2	 Load TIF	☐
3	17/06/19 14:47	Accident Sketch Plan	 Load JPG	☒
4	17/06/19 14:47	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19010755/R1SD3E2

Date: 12/07/2019

REFERENCE

Insured/Claimant:	LIM THIAM CHYE	Policy No:	A80431314AVW	Claim No:	596864
Date of Loss:	16/06/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT1233C		Engine No:	CAXF13416
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A)		Chassis No:	WVWZZZ16ZFM001688
Reg. Date:	19/05/2015 (Man. Year: 2014)		Odometer:	45469 km
Colour:	Brown			
Engine Capacity:	1390 cc			
Market Value/New Car Price:	S\$55,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,977.09	2,134.20	1,842.89	46.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,335.00	3,972.50	4,362.50	52.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,312.09	6,106.70	6,205.39	50.40
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	11,812.09	5,606.70	6,205.39	52.53
+ GST 7.00/7.00% (S\$)	826.85	392.47	434.38	52.53
Nett Amount (S\$)	12,638.94	5,999.17	6,639.77	52.53

INSPECTION

Date of Assignment:	18/06/2019		
Date Inspected:	18/06/2019	Inspected At:	Volkswagen Group Singapore (HQ) 17 Tuas Ave 9 Singapore 639197
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)	
Parts: 143	VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKT1233C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Necessary	22.79 FS	*22.79 FS
2	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Necessary	22.79 FS	*22.79 FS
3	1		*FENDER RH	Bent	404.62 FS	*404.62 FS
4	6		*EXPANDING NUT	Necessary	5.88 FS	*5.88 FS
5	1		*WHEELHOUSE LINER FENDER LINER RH	Deformed	119.38 FS	*119.38 FS
6	1		*END PLATE CLOSING ELEMENT	Necessary	19.57 FS	*19.57 FS
7	1		*DOOR RHS FRT DOOR	Bent	1,411.88 FS	*1,411.88 FS
8	1		*DOOR SEAL	Necessary	42.24 FS	*42.24 FS
9	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	27.93 FS	*27.93 FS
10	1		*SECTIONAL PART-PILLAR A W RH	Repair	971.08 FS	*- FS
11	1		*FILLER PLATE FOR SIDE MEM	Repair	25.34 FS	*- FS
12	1		*2K-INSERT FOAM	Not Necessary	93.81 FS	*- FS
13	1		*SEALANT CAN BE SPRAYED	Not Necessary	44.78 FS	*- FS
14	1		*INOX-SPRAY	Not Necessary	45.27 FS	*- FS
15	1		*2K-BODY ADHESIVE	Not Necessary	286.90 FS	*- FS
16	1		*SCUFF PLATE - SILL PANEL	Serviceable	375.71 FS	*- FS
17	1		*LONG-LIFE UNDERSEAL	Necessary	57.12 FS	*57.12 FS
Total Parts (S\$)					3,977.09	2,134.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	DIAGNOSTIC AND PROGRAMMING	New	360.00	360.00
3	LABOUR	New	3,800.00	1,425.00
4	SPRAY PAINTING	New	3,500.00	1,750.00
5	TRANSFER DOOR MECHANISM	New	475.00	237.50
Gross Labour Cost (S\$)			8,335.00	3,972.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >