

ASS. REC. BY:

REF

CS3/AG/1908781/Ucd302

Special Instruction:

Surveyor: Marcus

Maimen

ASSIGNMENT (Office)

From (Person): Azlan Syazirinda of AIG

Date/Time: 16/6/19 @ 12:15pm

Estimated Cost: Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB214Y

Insured: 8KJ 9440X

at Workshop m/s: Gino Success

Tel: 67426231

of: 1 Kaki Bukit Ave 6 # 02-03 Autobay

Policy No: 2100340653

Claim No: 5861261978SG

Sum Insured: Excess:

Make of Veh: D.O.A. 16/06/2019

(Client's Record) CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 12:45pm @ 16/6/19 Person Contacted: Ahnaf

Vehicle: IN / OUT

Date/Time	Action/Instruction
	1st initial /
	SLB214Y-X
	8KJ 9440X-X

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: SLB214Y
 at Workshop m/s Success
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB214Y Yr Regn: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota C.C. 2493
 Colour: black A/C: Insured / Std / NI / NA
 Sp. Reading: 207407 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: AGH30 0024958
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/50R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 7 mm Rear 7 mm
 R/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 16/6/19 D.O.I. 18/6/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/5 Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/6/19 Repairer informed vehicle withdrawn claims already due to vehicle sold already.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)) \$ + RS. \$ _____
☐ : Interview (\$ _____)) Photos
☐ : Tech. Invs (\$ _____)) Others
☐ : Weekend (\$ _____))

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

180
11
191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2019 Edit Reg		18 Jun 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Siow Lye Kwee, ID: S1016384F		
Main Claimant:	NA, Co. Reg. No.: NA		
Vehicle Reg. No.:	SLB214Y	Date of Loss:	16/06/2019 00:00 - :59
Claim Type:	TP / 5861261978SG	Policy/Cover Note No.:	2100340653
Vehicle Reg. No. (Insured):	SKJ9440X	Policy No. (Claimant):	
		Excess:	
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (19/06/2019): Request To Upload TP GIA Report
- AIG_SG (19/06/2019): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- Pre repair inspection request - SLB214Y VS SKJ9440X (OI) DOA: 16/06/2019

From: Azlan, Syazairdina
To: admin-a@lkkauto.com; assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Hor, Yinnul, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wanh
Sent: 6/18/2019 12:15:46 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Tuesday, June 18, 2019 11:39 AM
To: Azlan, Syazairdina
Subject: [EXTERNAL] RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLB214Y [OUR REF, TCL.GCN.RO.50385.19.ESS YOUR REF, SKJ 9440X]
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We refer to your email of even date.

Our client is agreeable to appoint **Marcus Chua, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SLB 214Y**.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **EURO SUCCESS SERVICES PTE LTD**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Without Prejudice

Your Reference : TCL.GCN.RO.50385.19.ESS
Our Reference : SKJ9440X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd

Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC '001	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Ruby Ong

Sent: Monday, 17 June 2019 4:57 PM

To: Hor, Yinrul <Yinrul.Hor@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Mithoosingh, Aashweenjeetkaur

<Aashweenjeetkaur.Mithoosingh@aig.com>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLB214Y [OUR REF. TCL.GCN.RO.50385.19.ESS]

Importance: High

Your ref: SKJ 9440X

WITHOUT PREJUDICE

Our ref: TCL.GCN.ro.50385.19.ess

17 June 2019

AIG Asia Pacific Insurance Pte Ltd

By Email Only

Motor Claims Department

78 Shenton Way

#08-16 AIG Building

Singapore 079120

VERY URGENT

Dear Sirs,

CLAIMANT: AMV PTE LTD

ACCIDENT INVOLVING SLB 214Y & SKJ 9440X AT BLOCK 631 BEDOK RESERVOIR ROAD CARPARK ON 16 JUNE 2019 @ 1930HRS

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 16 June 2019 at about 1930hrs at Block 631 Bedok Reservoir Road carpark involving our client's vehicle registration number SLB 214Y and vehicle registration number SKJ 9440X driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/06/2019 16:59
Date Of Accident	16/06/2019 19:30
Exact Location Of Accident	BEDOK RESERVOIR ROAD BLK 631 (CARPARK)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLB214Y
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VELLFIRE 2.5Z G EDITION CVT 2WD MR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105672825 CLASSIC
Cover Note Number	
Driver	
Name of Driver	DAI LI
Passport No/FIN	G6506679W
Date Of Birth	03/12/1990
Occupation	OUTDOOR
Date Of Driving Pass	29/10/2009
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97799766
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 34 BEDOK SOUTH AVENUE 2 #16-387
Postcode	460034
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ9440X
Vehicle Make/Model/Colour	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR HID
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

17 JUN 2019

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Reporting Centre: IDAC@sinnet.com.sg
Email: vackb@sinnet.com.sg
Name:
NRIC/FIN No:

Bedok Reservoir Road Blk 681 Car park



A: SLB 214Y

B: SKJ 9A40X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, my vehicle is parked at the above location. When I come back to the car park, I saw the right side of the car being damaged then I took video and saw the vehicle B.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

SARUC Declaration Form - V3

17 JUN 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: rock@idac.com.sg

Name:

NRIC/FIN No.:

last deer's Repair

2/4/7.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019 Edit Reg		18 Jun 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Siow Lye Kwee , ID: S1016384F									
Main Claimant: NA , Co. Reg. No.: NA									
Vehicle Reg. No.: SLB214Y		Date of Loss: 16/06/2019 00:00 - :59							
Claim Type: TP / 5861261978SG		Policy/Cover Note No.: 2100340653							
Vehicle Reg. No. (Insured): SKJ9440X		Policy No. (Claimant):							
		Excess:							
Repairer: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (19/06/2019): Request To Upload TP GIA Report AIG_SG (19/06/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB214Y (5861261978SG)
[SKJ9440X]**

TP

NA

Jun 16 2019 12:00AM

[Siow Lye Kwee]

Euro Success Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Photos/Images														3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	18/06/19 17:01	Chassis Number												Load JPG			
2	18/06/19 17:01	Odometer Reading												Load JPG			
3	18/06/19 17:02	General View												Load JPG			
4	18/06/19 17:02	General View												Load JPG			
5	18/06/19 17:02	General View												Load JPG			
6	18/06/19 17:02	General View												Load JPG			
7	18/06/19 17:02	General View												Load JPG			
8	18/06/19 17:02	General View												Load JPG			
9	18/06/19 17:02	General View												Load JPG			
10	18/06/19 17:02	General View												Load JPG			
11	18/06/19 17:02	General View												Load JPG			
12	18/06/19 17:02	General View												Load JPG			
13	18/06/19 17:02	General View												Load JPG			
14	18/06/19 17:02	General View												Load JPG			
15	18/06/19 17:02	General View												Load JPG			
16	18/06/19 17:02	General View												Load JPG			
17	18/06/19 17:02	General View												Load JPG			
18	18/06/19 17:02	General View												Load JPG			
19	18/06/19 17:02	General View												Load JPG			
20	18/06/19 17:02	General View												Load JPG			
21	18/06/19 17:02	General View												Load JPG			
22	18/06/19 17:02	General View												Load JPG			
23	18/06/19 17:02	General View												Load JPG			
24	18/06/19 17:02	General View												Load JPG			
25	18/06/19 17:02	General View												Load JPG			
26	18/06/19 17:02	General View												Load JPG			
27	18/06/19 17:02	General View												Load JPG			

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010781/UCD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100340653
Claimant Vehicle No : SLB214Y **Insured Vehicle No :** SKJ9440X
 Date of Loss: 16/06/2019 Nature of Claim: TP Claim No: 5861261978SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB214Y**
 Make & Model: TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: AGH300024958
 Colour: Black Odometer: 209407 km
 Engine Capacity: 2493 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm
 Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/06/2019
 Date Inspected: 18/06/2019 Inspected At: Euro Success Services Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6 #02-03
 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	0.00 F	*- F
					Total Parts (S\$)	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >