

ASS. REC. BY:

REF: CS/MSG19010788/Klad322

Special Instruction:

Surveyor: Kalvin**ASSIGNMENT (Office)**From (Person): Jowyn Tay Mui Lingof MSGDate/Time: 18.6.19 15.04 p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1436DInsured: 4p 86014at Workshop m/s PremierTel: 65446689of 23 Changi South Ave 2 #01-02Policy No: 1000955880

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 14.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 18.6.19 3.09 p.mPerson Contacted: VincentVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SHD 1436D - CCH / AIG 13012111 / M1 23+2w+	DOA - 04/07/2013
	4P 86014 - X	
18/6/19 @ 1.34pm	revised to Jowyn Tay via Messenger.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019 11:05		18 Jun 2019 15:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TOYOCEM MARKETING PTE LTD, Co. Reg. No.: 199100160W								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHD1436D	Date of Loss:	14/06/2019 00:00 - :59 [22 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	1000955880 (Comprehensive) Coverage: 19/04/2019 - 18/04/2020						
Vehicle Reg. No. (Insured):	YP8601H	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/06/2019]								
Adj Asg. Remarks:	on WP. VEHICLE AVAILABLE FOR SURVEY. LIAB"; dispute (OI NR) TP Agree on SJE - Assign LKK. Contact: Vincent Chua @ 65446689								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 19 Jun 2019

Preliminary Advice

Insured Vehicle No	: YP8601H	Accident Date	: 14/06/2019
TP Vehicle No	: SHD1436D	Assignment Date	: 18/06/2019
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 3.00
Date of Inspection	: 18/06/2019		
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 23 CHANGI SOUTH AVE 2, #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,173.58
Revised Amount	:S\$	1,173.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,173.58

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1436D
Previous Vehicle No.: -
Effective Date of Ownership: 19 Jul 2017
Original Regn Date: 19 Jul 2017
Registration Date: 19 Jul 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ128612
Engine No.: D4FBGZ125028
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,618.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Jul 2025
Minimum PARF Benefit: \$8,019.00
No. of Transfers: 0
IU Label No.: 1050706383
COE No.: 2017071901003932M
COE Expiry Date: 18 Jul 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium: - / \$48,200.00
PQP Paid: \$38,560.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/06/2019 12:33
Date Of Accident	14/06/2019 12:05
Exact Location Of Accident	AIRPORT BLVD INTO T3 LINK SOUTH - T1 TAXI STAND
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD1436D
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	130-1.6 (FD) DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	
Driver	
Name of Driver	YIAP CHEOK MING
NRIC No	S7435509I
Date Of Birth	23/10/1974
Occupation	OUTDOOR
Date Of Driving Pass	11/04/1996
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90798436
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 615 #10-1246 BEDOK RESERVOIR ROAD
Postcode	470615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - NO PAX VEH. B - 2 PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8601H
Vehicle Make/Model/Colour	LORRY
Details Of Properties	VEH. B
Vehicle Category	GOODS VEHICLE
Name of Driver	OUN HOO SUN
NRIC/Passport Number	S0677188B
Contact Number	92428205
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

14 JUN 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/MS Sketch Plan Pg. 1

57435509I
5HD1436D

Describe Circumstance of the Accident.

ON 14/06/2019 @ 1205HRS, I WAS DRIVING MY TAXI (SHD 1436 D) – TRAVELLING ALONG AIRPORT BOULEVARD INTO T3 LINK SOUTH, TOWARDS THE TAXI QUEUE OF CHANGI AIRPORT T1, IN THE RIGHT LANE.

WHILE I WAS MOVING AHEAD (BEFORE THE YELLOW BOX JUNCTION), SUDDENLY VEHICLE B (YP 8601 H – LORRY) WHICH WAS INITIALLY IN THE LEFT LANE, FAILED TO KEEP FOR PROPER LOOK OUT & CLEARANCE – HAD ENCROACHED ONTO MY PATH ON LEFT ABRUPTLY.


AS SUCH, THE RIGHT PORTION OF VEHICLE B COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT FRONT & THE LEFT WING MIRROR WAS TOTAL DAMAGED. I AM NOT AWARE OF DAMAGES TO VEHICLE B.

NO INJURY INVOLVED.

NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD 2 PASSENGERS ONBOARD.

*VIDEO FOOTAGE CAPTURED



 57435509I

Driver's Signature & NRIC Number
Friday, June 14, 2019 @ 12:43:18 PM

(attended by)

Premier Automotive Services Pte Ltd

**#01-02, 23 Changi Sth Ave 2
486443**

Claim Reference:

Assessment number: SHD1436D

Version: 1810

Date calculated: 18/06/2019 3:40 PM

Full Report

Registration: SHD1436D

Printed: 18/06/2019 3:41 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	14/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	I30 (GD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 80 01
Registration:	SHD1436D
VIN number:	
Odometer:	
Model Specs	
5-DOOR (HATCHBACK)	

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHD1436D

Version: 1810

Date calculated: 18/06/2019 3:40 PM

Full Report

Registration: SHD1436D

Printed: 18/06/2019 3:41 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
87602R00	R + R LEFT MIRROR		2.0	10.00
0283	FRONT BUMPER REPAIR		10.0*	50.00
0741	L/F WING REPAIR		10.0*	50.00
2247	L/A-PILLAR REINF REPAIR		10.0*	50.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.20	32.0	160.00
Total of Labour				160.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h
Code	Description		WU Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC		14.0

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHD1436D

Version: 1810

Date calculated: 18/06/2019 3:40 PM

Full Report

Registration: SHD1436D

Printed: 18/06/2019 3:41 PM

Paint Work

SYSTEM AZT

Time Basis 10WU/h

Code	Description	WU	Price SGD
	L/F WING REPAIR PAINTING <50%	9.0	
	LEFT FRONT DOOR SURFACE PAINT	7.0	
	L/A-PILLAR REINF SURFACE PAINT	4.0	
	L/B-PILLAR REINF SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER REPAIR PAINT PLASTIC	30.90
0741	L/F WING REPAIR PAINTING <50%	7.50
1481	LEFT FRONT DOOR SURFACE PAINT	15.31
2247	L/A-PILLAR REINF SURFACE PAINT	3.52
2287	L/B-PILLAR REINF SURFACE PAINT	3.52


Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			38.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	6.10	61.0	305.00

Material Cost - Paint

	Price SGD
Repair Painting	7.50
Repair Painting Plastic	30.90
Surface-/Blend Paint	22.35
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	91.55

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
1737	L/DOOR MIRROR	87610A6110			749.28
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				749.28
u: Used parts	Subtotal Discount(+35.00%)				-262.25

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHD1436D

Version: 1810

Date calculated: 18/06/2019 3:40 PM

Full Report

Registration: SHD1436D

Printed: 18/06/2019 3:41 PM

Total	487.03
--------------	---------------

Extras

Code	Description	Price SGD
1000	FENDER STICKER	30.00*
1001	DOOR STICKERS	100.00*
Total Extras		130.00

Final Calculation

	SGD	SGD
Parts	749.28	
Total Discount(+35.00%)	-262.25	
Total Parts		487.03
Labour Time Base 10 WU/h		
Total 32.0 WU X 50.00 SGD/h		
Total of Labour		160.00
Total Of Extras		130.00
Paint Work Time Base 10 WU/h		
Labour Cost 61.0 WU X 50.00 SGD/h		
Material Cost		
Total Paint Including Material		396.55
Repair Cost Excludes GST		1,173.58
GST (+7.0%)		82.15
Repair Cost Included GST		1,255.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Kaharic 11/11/19
18/6/19 1700
3 P, PIP
Before Part p 11
































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019 11:05		18 Jun 2019 15:04 Edit Adj Rpt	S\$1,173.58 Edit Estimates	S\$1,173.58 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TOYOCEM MARKETING PTE LTD , Co. Reg. No.: 199100160W									
Main Claimant: PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H									
Vehicle Reg. No.: SHD1436D		Date of Loss:	14/06/2019 00:00 - :59 [22 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP		Policy/Cover Note No.:	1000955880 (Comprehensive) Coverage: 19/04/2019 - 18/04/2020						
Vehicle Reg. No. (Insured): YP8601H		Policy No. (Claimant):							
		Excess:							
Repairer: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 18/07/2019]									
Adj Asg. Remarks: on WP. VEHICLE AVAILABLE FOR SURVEY. LIAB": dispute (OI NR) TP Agree on SJE - Assign LKK. Contact: Vincent Chua @ 65446689									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD1436D
[YP8601H]
TP
PREMIER TAXIS PTE LTD
Jun 14 2019 12:00AM
[TOYOCEM MARKETING PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/06/19 13:37	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/06/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/06/19 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	21/06/19 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	21/06/19 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	21/06/19 09:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/06/19 11:08	PRI	 Load PDF	<input type="checkbox"/>
2	17/06/19 11:08	TP GIA	 Load PDF	<input type="checkbox"/>
3	18/06/19 12:15	TP agree on SJE.	 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010788/K1QD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000955880

Claimant Vehicle No : SHD1436D

Insured Vehicle No : YP8601H

Date of Loss: 14/06/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD1436D

Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)

Engine No: D4FBGZ125028

Reg. Date: 19/07/2017 (Man. Year: 2016)

Chassis No: TMAD281UVHJ128612

Colour: Silver

Odometer: 244841 km

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Maxxis 7 mm

Rear Left Side: Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	617.03	617.03	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	556.55	556.55	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,173.58	1,173.58	0.00	0.00
+ GST 7.00/7.00% (S\$)	82.15	82.15	0.00	0.00
Nett Amount (S\$)	1,255.73	1,255.73	0.00	0.00

INSPECTION

Date of Assignment: 18/06/2019

Date Inspected: 18/06/2019 Inspected At:

Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 26 Jun 2019)
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1436D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/DOOR MIRROR	Broken	749.28 FL	*749.28 FL
2	1		*FENDER STICKER	Necessary	30.00 FS	*30.00 FS
3	1		*DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	879.28
					- List Item Discount on L Items 35.00/35.00% (\$\$)	262.25
					Total Parts (\$\$)	617.03

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	32.0 WU X 50.00 SGD/H	New	160.00	160.00
2	LABOUR COST 61.0 WU X 50.00 SGD/H	New	305.00	305.00
3	MATERIAL COST	New	91.55	91.55
Gross Labour Cost (S\$)			556.55	556.55

Report was unsubmitted during this print-out.

< END OF ESTIMATES >