

ASS. REC. BY:

Surveyor: Adrian

REP:

CS/ASM19010810/Asd300

Initial Instruction:

ASSIGNMENT (Office)

From (Person):

Richard Ang

&

ASM(CAXX)

Date/Time:

18/6/19

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 9283P

Insured:

at Workshop no:

Progressive

Tel:

67415336

of

BLK 3022A ubi Rd / #81-45/46

Policy No:

Claim No:

S9M01AKS

Sum Insured:

Excess:

\$800.00

Make of Veh:

(Car's Record)

D.O.A.

13/6/19

☒ CA / REV / REP. / REV 24 HRS

20/6/2019

Date/Time:

402pm 018/6/19

Person Contacted:

pei wen

I.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

18/06/19

SKW 9283P-X

21/6/19

@ 09:17 am revised IA to Richard Ang via Smart Claim.

21/6/19

@ 13:57 pm mandan requested authorize repair to Richard Ang via Smart Claim.

05/07/19

@ 11:42 am authorization renewed to Richard Ang

ASM(AXA)

ASSIGNMENT

From:

Date:

20/6/2019

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

SKW9283P

at Workshop m/s:

Progressive

at Blk 3022A Ubi Rd 1# 01-45/46

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

\$800.00

(Client's Record)

Make of Veh.:

200-2.30pm

see 2 go

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

78K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

63 1/2

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.:

SKW9283P

Yr Regn:

2015 / Nov

Type: ☒ M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester

C.C.

1995

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

30041

T/Radio:

Insured / Std / NI / NA

Eng/No.:

C/No.:

JFISJSK65FG059117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/55R17

R: 235/55R17

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

20/06/19

Survey held at

Progressive (Ubi)

Des. of Damages:

☒ Fr

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AXA.

05/07/19

@ 14:04 pm re inform CLA to PCU Wai (yes) via email.

16/10/19

Confirmed r/p \$ 1,444.52 @ 3 days with Adrian (\$ 4,626.40 Red - 76%)

RECEIVED 17 OCT 2019

Date/Time, File Pass 1/2



Prel. Report

Type 4



Final Report

Date/Time, File Pass 1/2

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

F + RS: 34

Tolls:

Other:

Total:

200

Report Form:

Lump Sum:

1,444.52

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Witness (\$

Service Request Details

Claim

S9M01QKS

Reference

None 

Loss Date

June 13, 2019

Report Date

Jun 13, 2019 3:31:30 PM

Request Date

June 18, 2019

Due Date

June 25, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SKW9283P



FORESTER 2.0

Service Address

3022A, UBI ROAD 1, , 408716

Primary Contact/Insured

LABCON CONTRACTOR PTE LTD

52 UBI AVENUE 3, #03-28 FRONTIER, 408867, Singapore

94248109

LORENZ@LABCON.COM.SG

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

1) Progressive Auto 2) Excess - \$800

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 7873K

Vehicle Details

Vehicle No.: SKW9283P
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 Jun 2019
Vehicle Make: SUBARU
Vehicle Model: FORESTER 2.0I-L CVT AWD SR
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: FB20Y070479
Chassis No.: JF1SJ5KC5FG059117
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$14,528.00
Original Registration Date: 23 Nov 2015
First Registration Date: 23 Nov 2015
Transfer Count: 0
Actual ARF Paid: \$14,528.00
Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Nov 2025
PARF Rebate Amount: \$10,896.00
Intended COE Rebate Details
COE Expiry Date: 22 Nov 2025
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$59,889.00
COE Rebate Amount: \$38,495.00
Total Rebate Amount: \$49,391.00

The information contained herein is correct as at 18 Jun 2019

OK

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

Cheapest, Only 30,800 No Gimmick, Call Us Now!



Cheapest, Only 30,800 No
Gimmick, With High Buy Back
Value! Call Us Now.
No Link Insurance StarAd



Lake View
Credit Pte Ltd

VIEW OUR CARS

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

 Save Search

 Print

8 vehicles

Search

Sort by Date Posted

20 results/page

Advanced Search

Search

View All

Search Selection

Forester

Any

Any

2015

Any

Any

Any

Available



Subaru Forester 2.0XT Sunroof \$72,800

\$11,190 /yr

04-Mar-2015

1,998 cc

78,500 km

SUV

Available

1 Owner, 5 Years Warranty, Fully Maintained By Motor Image, Auto Glym XGloss Protection Sealant Just Done. Spacious Inner Cabin Legroom, Call For Viewing.

Posted: 14-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

CONTACT OWNER



Subaru Forester 2.0XT Sunroof \$74,888

\$11,140 /yr

29-May-2015

1,998 cc

69,582 km

SUV

Available

The Best SUV, 1 Owner, Full Agent Service Record, 5 Years Warranty, Call Us Now!

Posted: 12-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0i-L Sunroof \$68,500

\$9,990 /yr

17-Aug-2015

1,995 cc

42,447 km

SUV

Available

Bank Loan At 2.48% 5 Years Warranty, One Owner Sunroof Model, Mileage Clocked 42447 Km Selling Cheapest And Lowest Depre With 100% Guaranteed Forester 2.0 Premium Sunroof In The Market With Fully Main...

Posted: 17-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$74,898

\$10,700 /yr

29-Aug-2015

1,998 cc

59,888 km

SUV

Available

Full Agent Maintained, Comes With Free Comprehensive 120 Points Check And 6 Months Warranty From M8M Wheelpower. Well Maintained By Previous Owner, Owner Upgrade To Cont'l Model. Accident-Free, Bank/In...

Posted: 15-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

 Car Buying

 Car Selling

 Car Ownership

 Car Aftermarket

 On The Move

 Lifestyle



Subaru Forester 2.0XT Sunroof \$76,800

\$10,940 /yr

10-Sep-2015

1,998 cc

74,100 km

SUV

Available

1 Owner And Agent Unit! Best Selling SUV! Last Batch Of Turbocharged 2.0L Engine With 240Bhp At Your Disposal, SI-Drive System, Offers 3 Modes: Intelligent, Sport And Sport Sharp For Driver To Triumph ...

Car Buyers Automotive Pte Ltd

Posted: 14-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$81,800

\$11,580 /yr

30-Sep-2015

1,998 cc

83,000 km

SUV

Available

1 Owner, Agent Unit, Well Maintained, Recently Serviced & New Radiator Replaced. Premium V-Cool Solar Film, Whole Car Sound Proofed Except Roof, Broad Front & Rear Cam, 19 Inch Pro Drive Rims With Mic...

Prem Roy Motoring

Posted: 17-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

PREMIUM AD



Subaru Forester 2.0XT Sunroof \$77,800

\$10,790 /yr

27-Oct-2015

1,998 cc

70,340 km

SUV

Available

1 Owner Only, Fully Agent Maintained With Record, Still Under 5 Year Agent Warranty, Very Low Mileage Down, Electric Knockdown Rear Seats, Loan Available. Price Negotiable. Call Us Now Hurry.

Posted: 15-Jun-2015

Tags: 2015 Subaru Forester, 2015 Subaru Forester, Subaru Forester, Subaru Forester, Subaru Forester, Subaru, Forester, Forester, Used Subaru

PREMIUM AD

MINIATURES BESTVIEW

Compare

Subaru Forester 2.0i-L

\$68,888

\$9,450 /yr

29-Dec-2015

1,995 cc

90,500 km

SUV

Available

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 July 2019 2:04 PM
To: 'Peiwen'
Cc: SUR; 'Lily'; 'Wendy'; 'Wayne'
Subject: RE: SKW 9283P OD (AXA) DOA - 13/06/2019

Dear Pei Wen,

As instructed by our client, please proceed to repair the insured vehicle **SKW 9283P (Excess \$ 800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Peiwen [mailto:peiwen@procarcare.com.sg]
Sent: Monday, 24 June 2019 8:23 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Lily <bhlim@procarcare.com.sg>; Wendy <wendy@procarcare.com.sg>; Wayne <wayne@procarcare.com.sg>
Subject: RE: SKW 9283P OD (AXA) DOA - 13/06/2019

Hi Shirley,

We unable to source used parts for above mentioned vehicle.

Kindly inform AXA and revert.

Thank You.

Regards,

Pei Wen NG
Claims Advisory
Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg



**With effect from 1 Sep 2018, Progressive Automotive Pte Ltd has been rebranded as Progressive Car Care Pte Ltd. You may now reach us at our new email addresses (@procarcare.com.sg). We look forward to your continued support.*

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Friday, June 21, 2019 3:30 PM

To: peiwen@progauto.com.sg

Cc: SUR

Subject: SKW 9283P OD (AXA) DOA - 13/06/2019

Hi Pei Wen,

As spoken, please check used parts availability from stockist.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:SKW 9283P - AUTHORIZATION

Type

🔗 Question

Message

Hi, pls proceed to authorise repair. TY.

Reply



SKW 9283P - AUTHORIZATION

Type

🔔 Question

Message

Hi Richard/Kitty, kindly let us have your authorize approval. Thanks. From : Shirley Hiew

Reply



RE: Re:IA RE-UPLOADED (SKW 9283P)

Type

🔔 Question

Message

Hi Kitty, Repairer have checked with at least 3 stockist for the availability of used parts required for the repairs of this vehicle and the stockist all came back with negative replies. On our part, we have separately checked with our own sources and they, similiarly, did not have the required parts. Thanks. From : Shirley Hiew.

Reply

Repairs have checked with at least 3 stockists for the availability of ~~parts~~ used parts required for the repairs of this vehicle and the stockist all came back with negative replies.

On our part, we have ^{separately} ~~separately~~ checked with ~~some~~ ^{our} own sources and they, similarly, did not have the required parts.



Re:IA RE-UPLOADED (SKW 9283P)

Type

🔗 Question

Message

Hi Shirley, Please get your surveyor to check used parts availability from stockist.

Reply



IA RE-UPLOADED (SKW 9283P)

Type

🔗 Question

Message

Damages consistent, repair cost economical. we have not authorize repair. Repairer requested the vehicle on part by part basis due to no second hand parts. Kindly let us have your authorize approval. Thanks. From : Shirley Hiew.

Reply



IA - SKW 9283P

Type

🔗 Question

Message

IA uploaded. Damages consistent, repair cost economical. We have authorize repair. Thanks. From : Shirley Hiew

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

61 UBI AVE 1, #02-28 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563541 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01/07/2019

Survey Details:

Date of loss	13-Jun-19
Date of appointment	18-Jun-19
Date of survey	20-Jun-19
Location of survey	BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKW 9283P
Make and Model	SUBARU FORESTER 2.0I-L CVT AWD SR
Date of registration	23-Nov-15
Excess	\$800
Market Value	\$78,000
Part Rebate	\$49,391
Nett Loss	\$28,609

Repair details:

Initial Estimate	6,070.92
------------------	----------

Proposed/Revised repair cost:

Parts	\$443.10
Check items (estimate)	\$491.00
Labour	\$856.62
Total	\$1,790.72
Lump Sum(if applicable)	\$

Number of days for repair	<u>4 DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199507198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORIZE REPAIR. REPAIRER REQUESTED REPAIR THE VEHICLE ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

81 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408003 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/06/2019

Survey Details:

Date of loss	5-Apr-18
Date of appointment	30-Apr-18
Date of survey	2-May-18
Location of survey	10 Ang Mo Kio Ind. Park 2A, #01-09 S568047

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKW 9283P
Make and Model	SUBARU FORESTER 2.0I-L CVT AWD SR
Date of registration	23-Nov-15
Excess	\$800
Market Value	\$78,000
Parf Rebate	\$49,391
Nett Loss	\$28,609

Repair details:

Initial Estimate	6,070.92
------------------	----------

Proposed/Revised repair cost:

Parts	\$443.10
Check items (estimate)	\$491.00
Labour	\$856.62
Total	\$1,790.72
Lump Sum(if applicable)	\$

Number of days for repair	4 DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No: 198627198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563541 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE
HAVE AUTHORIZED REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2019 14:18
Date Of Accident	13/06/2019 08:50
Exact Location Of Accident	YIO CHU KANG ROAD TO BOUNDARY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW9283P
Insured/Policyholder	
Name Of Registered Owner	LABCON CONTRACTOR PTE LTD
Co Reg No	200007873K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67494477
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER-2.0 I-L CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA409521
Cover Note Number	

Driver

Name of Driver	LORENZ LIM WEE KHNG
NRIC No	S7337721H
Date Of Birth	13/10/1973
Occupation	INDOOR
Date Of Driving Pass	23/02/1998
Driving Experience	21 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97857667
Fax Number	
Contact Number	
Email Address	LIMLORENZ@GMAIL.COM

Address 58 LI HWAN DRIVE
 Postcode 557092
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMF3360E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver RAVEENDRA KUMAR KANESHALINGAM
 NRIC/Passport Number S2193347C
 Contact Number
 Address BLK 548 SERANGOON NORTH AVENUE 3 #11-01
 Postcode 550548
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under the law, court orders.

Policyholder's Signature

Date & Time:

13/6/19

13 30 h5

Driver's Signature

(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN

	Vehicle A - SKW 9287 P B - SMF 3360 E
	Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13 June 2019 at about 0530 hrs, I was turning from Yio Chu Kang Rd to Boundary Road.

My front car proceeded & I followed. Suddenly the car applied emergency brake and I was unable to stop in time.

I collided into the rear of my front car SMF 3360 E.

That is all.

DECLARATION I/We declare that the particulars are true in every respect. Please note that your policy may have a fourteen (14) days cooling-off period. If you wish to cancel your policy, you must be made within the stipulated time frame. Policyholder's Signature: Date & Time: 13/6/19 1330 hrs	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/PIN No.:
--	--	---

Common Statement

ACCIDENT STATEMENT (Part I)

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims.

1 Date of accident: 3/6/19 Time: 0950 2 Exact location of accident: Bandang Rd. Yid Chu Kang Rd. to

3 Injured? Even if slight: No ☒ Yes ☐

4 Material damage: To vehicles other than vehicle A and B: No ☒ Yes ☐ To objects other than vehicles: No ☒ Yes ☐

5 Witness' name, address and tel no. (to be undivided / written as passenger in vehicle A or vehicle B):

Vehicle Video Camera Available: No ☒ Yes ☐

Registration No. (VEHICLE A) SKW9285A

6 Insured / policyholder (see insurance cert.):

Name: Labin Contractor

Address: 52 Ubi Ave 3 #03-25

Unit: 52 (488867)

NRIC / Passport no: 202007873K

Tel no. (From Home or Work): 93454977

or 93557617

7 Vehicle:

Make, type: Subaru Forester 2.0

8 Insurance company: ANT ☒ TPT ☐ TPO

Does the policy cover damage to vehicle A? No ☐ Yes ☒

Policy No: GR449521

9 Driver: ☐ Driver or Owner

Name: LORREN LIN

NRIC / Passport no: S7337421H

Class of licence: 3

or 43857617

Gender: Male ☒ Female ☐

12 CIRCUMSTANCES

Put a cross (X) in each of the relevant boxes applicable to your vehicle.

12.1 Chain Collision ☐

12.2 Collision with obstacle ☐

12.3 Collision with motorcyclist ☐

12.4 Collision into parked vehicle ☐

12.5 Collision with pedestrian ☐

12.6 Collision with property ☐

12.7 Collision - changed lane ☐

12.8 Collision - cross traffic ☐

12.9 Collision - head-on ☐

12.10 Collision - rear-end ☐

12.11 Collision - Mass Follow ☐

12.12 Collision - crossing over of centre ☐

12.13 Collision - side-swipe ☐

12.14 Collision - T-bone ☐

12.15 One driving / using cell phone ☐

12.16 Excessive speed / speeding ☐

12.17 Other ☐

12.18 Other ☐

12.19 Other ☐

12.20 Other ☐

12.21 Other ☐

12.22 Other ☐

12.23 Other ☐

12.24 Other ☐

12.25 Other ☐

12.26 Other ☐

12.27 Other ☐

12.28 Other ☐

12.29 Other ☐

12.30 Other ☐

12.31 Other ☐

12.32 Other ☐

12.33 Other ☐

12.34 Other ☐

12.35 Other ☐

12.36 Other ☐

12.37 Other ☐

12.38 Other ☐

12.39 Other ☐

12.40 Other ☐

12.41 Other ☐

12.42 Other ☐

12.43 Other ☐

12.44 Other ☐

12.45 Other ☐

12.46 Other ☐

12.47 Other ☐

12.48 Other ☐

12.49 Other ☐

12.50 Other ☐

12.51 Other ☐

12.52 Other ☐

12.53 Other ☐

12.54 Other ☐

12.55 Other ☐

12.56 Other ☐

12.57 Other ☐

12.58 Other ☐

12.59 Other ☐

12.60 Other ☐

12.61 Other ☐

12.62 Other ☐

12.63 Other ☐

12.64 Other ☐

12.65 Other ☐

12.66 Other ☐

12.67 Other ☐

12.68 Other ☐

12.69 Other ☐

12.70 Other ☐

12.71 Other ☐

12.72 Other ☐

12.73 Other ☐

12.74 Other ☐

12.75 Other ☐

12.76 Other ☐

12.77 Other ☐

12.78 Other ☐

12.79 Other ☐

12.80 Other ☐

12.81 Other ☐

12.82 Other ☐

12.83 Other ☐

12.84 Other ☐

12.85 Other ☐

12.86 Other ☐

12.87 Other ☐

12.88 Other ☐

12.89 Other ☐

12.90 Other ☐

12.91 Other ☐

12.92 Other ☐

12.93 Other ☐

12.94 Other ☐

12.95 Other ☐

12.96 Other ☐

12.97 Other ☐

12.98 Other ☐

12.99 Other ☐

12.100 Other ☐

Registration No. (VEHICLE B) SMF 3360 E

6 Insured / policyholder (see insurance cert.):

Name:

Address:

NRIC / Passport no:

Tel no. (From Home or Work):

or

7 Vehicle:

Make, type:

8 Insurance company: ☐ C ☐ TPT ☐ TPO

Does the policy cover damage to vehicle B? No ☐ Yes ☐

Policy No. (if available):

9 Driver (See driving licence):

Name: Roxleya Kurni

NRIC / Passport no:

Class of licence: 3

or

Gender: Male ☒ Female ☐

10 Indicate the point of initial impact with an arrow (→)

10.1 

11 Sketch of accident when impact occurred:

Please indicate: 1. layout of the road; 2. the direction of vehicles A and B with arrows; 3. their positions at the time of impact; 4. the road signs; 5. names of the roads or roads.

REFER TO ATTACHED

10 Indicate the point of initial impact with an arrow (→)

10.2 

13 Vehicle damage to vehicle A:

Front Bumper

14 My remarks:

15 Signatures of drivers:

A 

B 

13 Vehicle damage to vehicle B:

14 My remarks:

* In the event of injury or in the event of dispute as to liability, each driver should seek legal advice.

Do not alter anything in this statement after signing. Subsequently, each driver should sign and date.

For insured's Individual Statement (over 12) see appendix 4

Individual Statement

INDIVIDUAL STATEMENT (Part II)		Own Workshop (only if applicable)													
To be completed and submitted within 24 hours to your insurer or Idac or appointed workshop (Use a separate sheet of paper where necessary)															
Insured	1. Occupation (if more than one, state all)		Email:												
	2. Vehicle registration no. <u>C.C.</u>		If commercial vehicle, state permissible carrying capacity												
	3. Is driver the owner? ☒ Yes ☐ No ☐ If no, state relationship to driver with owner		State the vehicle number and name of owner of driver's own vehicle (where applicable)												
	4. Exact purpose for which vehicle was being used at time of accident: ☐ Private use ☐ Commercial use ☐ Hire & reward ☐ Public hire ☐ Others - please specify														
Of which vehicle are you the owner?	5. Is the vehicle still in use? ☒ Yes ☐ No ☐ If no, state where it is at present														
	6. Are you claiming under your own insurance policy for repair to your vehicle? ☒ Yes ☐ No														
	If no, state action to be taken: ☐ Third Party ☐ Reporting Only ☐ Third Party (Own Workshop)														
	7. Date of birth: <u>13/10/73</u> Occupation: <u>Indoor</u> Date of license pass: <u>23/3/99</u> Was vehicle driven with the insured's permission? ☒ Yes ☐ No Was driver an employee of the insured's company? ☒ Yes ☐ No														
Driver or person in charge of vehicle at the time of accident (including insured)	8. Give details of any pre-existing impairment of sight or hearing and of any other disability														
	9. Full details of all driving convictions including pending prosecutions in the last 18 months														
	<table border="1"> <thead> <tr> <th>Date</th> <th>Offence</th> <th>Penalty</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </tbody> </table>			Date	Offence	Penalty									
	Date	Offence	Penalty												
10. Name(s), address(es) and approximate age(s)															
Injured person	Injuries sustained		Was injured conveyed to hospital by ambulance?												
	If vehicle occupants, state in which vehicle		Was injured conveyed to hospital by ambulance?												
	Were seat belts being worn?		Was injured conveyed to hospital by ambulance?												
	Yes No		Yes No												
Damage to property & vehicles (other than vehicles A and B)	11. Name(s) and address(es) of owner(s)		Insurer's name and address (if known)												
	Vehicle registration no. or details of property														
	Nature of damage														
Police action	12. Was the accident reported to the Police? ☒ Yes ☐ No														
	If yes, please state which Police station														
	13. Was notice of intended prosecution given? ☒ Yes ☐ No														
	If yes, against whom?														
Accident details	14. Weather conditions: ☒ Clear ☐ Rain ☐ Others														
	15. Road surface: ☒ Wet ☐ Dry ☐ Others														
	16. Speed of vehicles: A. ☐ km/h B. ☐ km/h														
	17. What warnings were given by driver or other party?														
	18. Were speed signs illuminated? ☐ Yes ☐ No														
	19. What lights were displayed on your vehicle/the other vehicle(s)?														
	20. If your vehicle is commercial, state weight of load carried at time of accident														
	21. State how accident happened, width of roads, speed limits, etc. (if known)														
	22. State number of Passengers (including Driver)														
	Declaration: I/We declare the foregoing particulars are true in every respect														
Policyholder's signature: _____ Date: _____															
Driver's signature (if driver is not the policyholder): _____ Date: _____															

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027
Assessment number: 008134
Version: 1810
Date calculated: 17/06/2019 3:15 PM

Full Report
Registration: SKW9283P
Printed: 17/06/2019 3:16 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ray Lin	Currency:	SGD
Claim Reference:	OD 0619 - 7027	Date of Incident:	13/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	SUBARU		
Model:	FORESTER (SJ)		
Sub Model:	BASE MODEL		
Model Sheet Number:	62 71 01		
Registration:	SKW9283P		
VIN number:			
Odometer:			
Model Specs			
AUTO AIR CON	FOG LAMPS	HEADLAMP WASHERS	2.0 LTR 110 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027
 Assessment number: 008134
 Version: 1810
 Date calculated: 17/06/2019 3:15 PM

Full Report
Registration: SKW9283P
Printed: 17/06/2019 3:16 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R FRONT BUMPER		5 2.0	9.00
EI0004R ZAX	RENEW FRONT BUMPER		9 7.0	31.50
	INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY			
LI0011R	ADD: ADJUST FRONT FOG LAMPS		X 2.0	9.00
EI0001R)	R + R RADIATOR GRILLE		X 2.0	9.00
WW0009R	R + R FRONT WASHER NOZZLE/S		X 2.0	9.00
NO NUMBER	R + R UPPER RADIATOR GRILLE MOULDING		✓ 2.0	9.00
NO NUMBER	R + R FRONT BUMPER SUPPORT		X 3.0	13.50
LI0002R	R + R LEFT HEADLAMP		X 3.0	13.50
LI0002R	R + R RIGHT HEADLAMP		X 3.0	13.50
NO NUMBER	ADJUST HEADLAMPS		X 2.0	9.00
NO NUMBER	R + R FRONT UPPER CROSSMEMBER		X 5.0	22.50
NO NUMBER	R + R CROSSMEMBER SUPPORT		10 3.0	13.50
COM001R	R + R RIGHT HORN		✓ 4.0	18.00
CO0004R	R + R RADIATOR		X 12.0	54.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027

Assessment number: 008134

Version: 1810

Date calculated: 17/06/2019 3:15 PM

Full Report

Registration: SKW9283P

Printed: 17/06/2019 3:16 PM

Code	Description	WU	Price SGD
AC0001R	DRAIN AIR CONDITIONING	X 4.0	18.00
CO0001R)	DRAIN + REFILL COOLANT	X 2.0	9.00
IN0004R	R + R INTAKE PIPE	X 1.0	4.50
AC0002R	REFILL AIR CONDITIONING	X 4.0	18.00
1019	L/F PANEL SUPPORT REPAIR	? 15.0*	67.50
No NUMBER	R+R FRONT BUMPER IMPACT DAMPER	2	9
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	7.80	78.0
	Total of Labour		211.50
			351.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	5.0 X
	CROSSMEMBER SUPPORT SURFACE PAINT	4.0 ✓
	FRT UPP CROSSMEMBER SURFACE PAINT	4.0 ✓
	FRONT BUMPER NEW PART PAINT K1R	13.0 ✓
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0 ✓
	RADIATOR GRILLE TRIM NEW PART PAINT K1R	3.0 9
	GRILLE NEW PART PAINT K1R	4.0 10
	L/H-LAMP WASHER LID NEW PART PAINT K1R	3.0 ✓
	R/H-LAMP WASHER LID NEW PART PAINT K1R	3.0 ✓
	BONNET SURFACE PAINT	11.0 ✓
	L/F WING SURFACE PAINT	5.0 ✓
	R/F WING SURFACE PAINT	5.0 ✓
	L/F PANEL SUPPORT SURFACE PAINT	4.0 ✓

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	X 6.23
0988	CROSSMEMBER SUPPORT SURFACE PAINT	✓ 3.49
1017	FRT UPP CROSSMEMBER SURFACE PAINT	✓ 2.24
0281	FRONT BUMPER NEW PART PAINT K1R	✓ 61.99
0301	FRT BUMPER TRIM CAP NEW PART PAINT K1R	✓ 0.49
0407	RADIATOR GRILLE TRIM NEW PART PAINT K1R	2.03 2.46
0410	GRILLE NEW PART PAINT K1R	6.08 7.38
0625	L/H-LAMP WASHER LID NEW PART PAINT K1R	0.37 0.49
0626	R/H-LAMP WASHER LID NEW PART PAINT K1R	0.37 0.49
0471	BONNET SURFACE PAINT	✓ 38.84

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027
 Assessment number: 008134
 Version: 1810
 Date calculated: 17/06/2019 3:15 PM

Full Report
 Registration: SKW9283P
 Printed: 17/06/2019 3:16 PM

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING SURFACE PAINT	✓ 9.46
0742	R/F WING SURFACE PAINT	✓ 9.46
1019	L/F PANEL SUPPORT SURFACE PAINT	✓ 1.00

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	45.00 SGD/h			
	Time Paint	74	67.0	
	Preparation Main Work Metal	0.50	5.0	22.50
	Preparation Comp. Work Plastic	2.50	15.0	112.50
Total	10 WU/h	8.70	87.0	391.50
		10.4		468.40

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	62.43
Surface-/Blend Paint	64.49
Material-constant Metal	✓ 9.00
Material-constant Plastic	✓ 28.60
Total	173.42
Repair - Painting Plastic	8.11
Surface Painting Plastic	0.74

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0281	FRONT BUMPER	57709SG001	Deland	✓	320.00
0297	L/FOG LAMP COVER	57731SG030	3 not	+	20.00
0298	R/FOG LAMP COVER	57731SG020	3 not	+	20.00
0301	FRT BUMPER TRIM CAP	57731SG000	Deland	✓	9.00
0319	L/F INN BUMPER BRKT	57707SG030	3 not	✓	11.00
0320	R/F INN BUMPER BRKT	57707SG020	3 not	✓	11.00
0333	FRT BUMPER ABSORBER	57722SG020	Best	2	135.00
0340	FRT BUMPER SUPPORT	57711SG0009P	2 not	+	180.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	2 not	✓	20.00
0407	RADIATOR GRILLE TRIM	91121SG020	2 not	+	70.00
0410	GRILLE	91121SG040	2 not	+	160.00
0426	GRILLE MOUNTING KIT	USE SINGLE PARTS	2 not	+	27.00
0427	RAD GRILLE BRACKET	91165SG030	2 not	+	18.00
0428	UPP RAD GRILLE MLDG	91121SG001	2 not	+	70.00
0565	LEFT HEADLAMP ASSY	84913SG010	3 not	+	900.00
0566	RIGHT HEADLAMP ASSY	84913SG000	3 not	+	900.00
0567	L/HEADLAMP BRACKET	57707SG010	2 not	+	26.00

506

110%: 556.60

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027
 Assessment number: 008134
 Version: 1810
 Date calculated: 17/06/2019 3:15 PM

Full Report
 Registration: SKW9283P
 Printed: 17/06/2019 3:16 PM

Code	Description	Part Number	Supplier	Price SGD
0568	R/HEADLAMP BRACKET	57707SG000	new	+ 26.00
0617	L/H-LAMP WASHER JET	86636SG020		+ 125.00
0625	L/H-LAMP WASHER LID	86636SG040B7		+ 60.00
0626	R/H-LAMP WASHER LID	86636SG030B7	new	+ 60.00
0637	L/F FOG LAMP CPL	84501AJ060		+ 185.00
0638	R/F FOG LAMP CPL	84501AJ060		+ 185.00
0988	CROSSMEMBER SUPPORT	53029SG0219P	Pyis	+ 70.00
1017	FRT UPP CROSSMEMBER	53029SG0109P	new	+ 40.00
4465	CONDENSER	73210SG002	new	+ 400.00
7761	RADIATOR	45111SG000	new	+ 430.00
1000	FRT BUMP NOZZLE HOSEVALUE		new	+ 60.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,538.00
u: Used parts	Addition(+10.00%)			453.80
	Total			4,991.80

Extras

Code	Description	Price SGD
1001	FRT NO PLATE Bent	+ 35.00*
1002	AIR CON COOLANT new	+ 100.00*
1003	ANTI FREEZE	+ 20.00*
	Total Extras	155.00

35

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0619 - 7027
Assessment number: 008134
Version: 1810
Date calculated: 17/06/2019 3:15 PM

Full Report
Registration: SKW9283P
Printed: 17/06/2019 3:16 PM

Final Calculation

	SGD	SGD
Parts	4,538.00	
Addition(+10.00%)	453.80	
Total Parts		4,991.80
Labour Time Base 10 WU/h		
Total 78.0 WU X 45.00 SGD/h	351.00	
Total of Labour		351.00
Total Of Extras		155.00
Paint Work Time Base 10 WU/h		
Labour Cost 87.0 WU X 45.00 SGD/h	391.50	
Material Cost	181.62	
Total Paint Including Material		573.12
Repair Cost Excludes GST		6,070.92
GST (+7.0%)		424.96
Repair Cost Included GST		6,495.88

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to LKK confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

614742
Adrian Lim
P/P 20/06/19 0322p
-0402p
Authorised Repair.
Excess \$800.



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADE GLASS
Dept Direct: 6417 8781 / 8743 9528



Dept Direct: 6303 8610

Dept Direct: 6306 9411

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8789

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201907-06185

DATE : 11/07/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKW9283P

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

807027

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
17 S57709-SG000/001 SJ5 14	FR BUMPER	U1 HL2-F14	1	320.00	320.00
22 S57707-SG020 SJG	FRT BUMPER RETAINER RH	U1 HL2-J3-C	1	11.00	11.00
37 S57707-SG030 SJG	FRT BUMPER RETAINER LH	U1 HL2-J3-C	1	11.00	11.00
43 S90914-0007 LEG 99 BL5 SJG	CLIP	U1 HL2-N7-B	10	2.00	20.00
55 S57731-SG000 SJ5	TOW COVER FR	U1 L2-M47-A	1	9.00	9.00

SUB-TOTAL : 371.00
ADD GST 7.00 % 25.97

E. & O.E

TOTAL AMOUNT SGD : 396.97

[P] 11/07/2019 12:01:35PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 11/07/2019 11:59:02AM

JAB Auto Pte. Ltd.

Sales Executive: EDMUND



AR201907-06185

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/08 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 8417 8781 / 8745 9920



Wiper blades: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201908-04433

DATE : 13/08/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKW9283P

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
557722-SG020	ENERGY ABSORBER,FR BUMPER	U1	1	135.00	135.00
SJG		HL1-H3			

SUB-TOTAL : 135.00

ADD GST 7.00 % 9.45

E. & O.E TOTAL AMOUNT SGD : 144.45

[P] 13/08/2019 10:35:41AM

[E] 13/08/2019 10:34:47AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: OD 0619 - 7027
Repairer Reference: 008134
Date calculated: 16/10/2019 1:59 PM

Full Report
Registration: SKW9283P
Printed: 16/10/2019 1:59 PM

Summary Information

Claim

Location: Singapore (SG)
Printed by: KK LAU
Claim Reference: OD 0619 - 7027
Estimated Repair Time:
Actual Repair Days:

Work Provider:
Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

AXA Insurance Pte Ltd
SGD
13/06/19

Vehicle Details

Vehicle

Manufacturer: SUBARU
Model: FORESTER (SJ)
Sub Model: BASE MODEL
Model Sheet Number: 62 71 01
Registration: SKW9283P
VIN number:
Odometer:

Model Specs

AUTO AIR CON
TWO COAT METALLIC

FOG LAMPS
PREPARE OFF VEHICLE

HEADLAMP WASHERS

2.0 LTR 110 KW


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
EI0004R	R + R FRONT BUMPER		5.0	22.50
EI0004R ZAX	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		9.0	40.50
WW0009R	R + R FRONT WASHER NOZZLE/S		2.0	9.00
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER		2.0	9.00
COM001R	R + R RIGHT HORN		4.0	18.00
0988	CROSSMEMBER SUPPORT REPAIR		10.0*	45.00
1019	L/F PANEL SUPPORT REPAIR		15.0*	67.50
Labour Cost			Hrs	WU
Panel / Mechanical Labour			4.70	47.0
Total of Labour				211.50

Paint

Code	Description - TWO COAT METALLIC	SYSTEM AZT	Time Basis 10 WU/h	
			WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R		13.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R		3.0	
	RADIATOR GRILLE TRIM REPAIR PAINT PLASTIC		9.0	
	GRILLE REPAIR PAINT PLASTIC		10.0	
	BONNET SURFACE PAINT		11.0	
	L/H-LAMP WASHER LID SURFACE PAINT PLAST.		3.0	
	R/H-LAMP WASHER LID SURFACE PAINT PLAST.		3.0	
	L/F WING SURFACE PAINT		5.0	
	R/F WING SURFACE PAINT		5.0	
	CROSSMEMBER SUPPORT SURFACE PAINT		4.0	
	FRT UPP CROSSMEMBER SURFACE PAINT		4.0	
	L/F PANEL SUPPORT SURFACE PAINT		4.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINT K1R	61.99
0301	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.49
0407	RADIATOR GRILLE TRIM REPAIR PAINT PLASTIC	2.03
0410	GRILLE REPAIR PAINT PLASTIC	6.08
0471	BONNET SURFACE PAINT	38.84
0625	L/H-LAMP WASHER LID SURFACE PAINT PLAST.	0.37
0626	R/H-LAMP WASHER LID SURFACE PAINT PLAST.	0.37
0741	L/F WING SURFACE PAINT	9.46
0742	R/F WING SURFACE PAINT	9.46
0988	CROSSMEMBER SUPPORT SURFACE PAINT	3.49
1017	FRT UPP CROSSMEMBER SURFACE PAINT	2.24
1019	L/F PANEL SUPPORT SURFACE PAINT	1.00

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			74.0	
Preparation Main Work Metal		0.50	5.0	22.50
Preparation Comp. Work Plastic		2.50	25.0	112.50
Total	10 WU/h	10.40	104.0	468.00

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		62.48
Repair Painting Plastic		8.11
Surface-/Blend Paint		64.49
Surface Painting Plastic		0.74
Material-constant Metal		9.00
Material-constant Plastic		28.60
Total		173.42

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER	57709SG001		320.00
0301	FRT BUMPER TRIM CAP	57731SG000		9.00
0319	L/F INN BUMPER BRKT	57707SG030		11.00
0320	R/F INN BUMPER BRKT	57707SG020		11.00
0333	FRT BUMPER ABSORBER	57722SG020		135.00
0350	FRT BUMPER CLAMP KIT USE SINGLE PARTS			20.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			506.00
u: Used parts	Addition(+10.00%)			50.60
	Total			556.60

Extras

Code	Description	Price SGD
1000	FRONT NO PLATE	35.00*
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	506.00	
Addition(+10.00%)	50.60	
Total Parts		556.60
Labour Time Base 10 WU/h		
Total 47.0 WU X 45.00 SGD/h	211.50	
Total of Labour		211.50
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 104.0 WU X 45.00 SGD/h	468.00	
Material Cost	173.42	
Total Paint Including Material		641.42
Repair Cost Excludes GST		1,444.52
GST (+7.0%)		101.12
Repair Cost Included GST		1,545.64
Deductions (Excludes GST)		
Deduction For Excess	-800.00	
Total Of Deductions (Excludes GST)		-800.00
Grand Total Excludes GST		644.52
GST (+7.0%)		45.12
Grand Total Included GST		689.64

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.