



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving1 2015 SUBARU FORESTER 2.0 (SKW9283P)

Date of Loss13 June 2019

Time of Loss8.30

Loss DescriptionSKW9283P (INSD) C/W SMF3360E (TP)

Comment

## Workshop Details

Total Rebate Amount

49391

Nett Loss Amount\$28,609.00

Assigned WorkshopLKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SKW9283P	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="23/11/2015"/>
Mileage	<input type="text" value="30041"/>	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2015	<input type="text" value="2015"/>
Make	SUBARU	<input type="text" value="SUBARU"/>
		<input type="text"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	<input type="text"/>	
Date of Birth	<input type="text" value="dd/mm/yyyy"/>	

Model CATEGORY	FORESTER 2.0 POLICY INFORMATION	FORESTER 2.0I- INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	JF1SJ5KC5FG059117	<input type="text" value="JF1SJ5KC5FG05"/>
Engine No	FB20Y070479	<input type="text" value="FB20Y070479"/>
Engine Capacity		<input type="text" value="1995"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="78000"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation		<input type="text"/>
Education Qualification		<input type="text"/>
Driving Experience		
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY  
Address

FNOL  
INFORMATION

POST SURVEY

Address type

Gender

Marital status

Identification #



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

20/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

800

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

## Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts























Add























Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT BUMPER (WCP) (10%)	Deformed	0	352	No					352	Reviewing
		0	1		L/FOG LAMP COVER	Serviceable	0	0	No					0	Deny
		0	1		R/FOG LAMP COVER	Serviceable	0	0	No					0	Deny
		0	1		FRT BUMPER TRIM CAP (WCP) (10%)	Deformed	0	9.9	No					9.9	Reviewing
		0	1		L/F INN BUMPER BRKT (WCP) (10%)	Necessary	0	12.1	No					12.1	Reviewing
		0	1		R/F INN BUMPER BRKT (WCP) (10%)	Necessary	0	12.1	No					12.1	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRT BUMPER ABSORBER (WCP) (10%)	Bent	0	148.5	No					148.5	Reviewing
		0	1		FRT BUMPER SUPPORT	Serviceable	0	0	No					0	Deny
		0	1		FRT BUMPER CLAMP KIT (WCP) (10%)	Necessary	0	22	No					22	Reviewing
		0	1		RADIATOR GRILLE TRIM	Serviceable	0	0	No					0	Deny
		0	1		GRILLE	Serviceable	0	0	No					0	Deny
		0	1		GRILLE MOUNTING KIT	Serviceable	0	0	No					0	Deny
		0	1		RAD GRILLE BRACKET	Serviceable	0	0	No					0	Deny
		0	1		UPP RAD GRILLE MLDG	Serviceable	0	0	No					0	Deny
		0	1		LEFT HEADLAMP ASSY	Serviceable	0	0	No					0	Deny
		0	1		RIGHT HEADLAMP ASSY	Serviceable	0	0	No					0	Deny
		0	1		L/HEADLAMP BRACKET	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		R/HEADLAMP BRACKET	Serviceable	0	0	No					0	Deny
		0	1		L/H-LAMP WASHER JET	Serviceable	0	0	No					0	Deny
		0	1		L/H-LAMP WASHER LID	Serviceable	0	0	No					0	Deny
		0	1		R/H-LAMP WASHER LID	Serviceable	0	0	No					0	Deny
		0	1		L/F FOG LAMP CPL	Serviceable	0	0	No					0	Deny
		0	1		R/F FOG LAMP CPL	Serviceable	0	0	No					0	Deny
		0	1		CROSSMEMBER SUPPORT	Repair	0	0	No					0	Deny
		0	1		FRT UPP CROSSMEMBER	Serviceable	0	0	No					0	Deny
		0	1		CONDENSER	Serviceable	0	0	No					0	Deny
		0	1		RADIATOR	Serviceable	0	0	No					0	Deny
		0	1		FRT BUMP NOZZLE HOSEVALUE	Serviceable	0	0	No					0	Deny

Labour






Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
------	----------	----------------------------	-----------	---------------------------	---------------------------	--------------------------	--------------------------	--------------------	---------

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		78.0 WU X 45.00 SGD/H	0	211.5	0	0	Reviewing	
		0		LABOUR COST 87.0 WU X 45.00 SGD/H	0	468	0	0	Reviewing	
		0		MATERIAL COST	0	173.42	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		
<input type="checkbox"/>		0	FRT NO PLATE	Reviewing		35	BENT	
<input type="checkbox"/>		0	AIR CON COOLANT	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	ANTI FREEZE	Deny		0	NOT NECESSARY	





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$644.52

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$556.60
Labour	\$0.00	\$852.92
Miscellaneous	\$0.00	\$35.00
Excess		-\$800.00

Submit for Review