	ASS. REC. BY:	REF:	CSK5M01901	The state of the s	3 n2 Spe	cial Instructio	n:	-	
rivan	From (Person): Hwan		ASSIGNME of SMO	ENT (Office)		D-4-60'	196.19	11.249.	m
	Estimated Cost:			Bill to:	1	Jate/ Lime:			
	To Inspect Vehicle No at Workshop m/s Single Buta	n 94 sin	7	S	Insured:	SLA 91992	7460 L		
	Policy No: DAM1P			Man O	Nane				
	Sum Insured:		Claim No: C	In I Diel	02-10-8				
	Make of Veh: (Client's Record)			LAVOID.	D	.o.A. 16	6.2019		
	CA / REV / REP. / Date/Time: 14.6.19	KEY 24 HKS	rson Contacted:	wei Leang	Vel	H.O.D. Rad	orsement:		
15	Date/Time Action/	Instruction (V) Estimate				-		
	SJ S	45217 - (S) 7460 L- X	17P14001137	101602	be	A - DO	08/201	7,	
	196@14:44	vensed via	menimen	· pveli	aduse				

08/11/13) , Wel REF:	SMO/
ASS. REC. BY: Marcus	SIGNMENT //
	Veh No: SJS 452/7 Yr Regn: 18/8/09
From: Date:	Type M. Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover/
Estimated Cost:	Truck/Trailer or (A/
OD ITP I WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SYS 4(-)/T	Make: Hyunder 130 c.c /5-9/ A/C: Insured/Std/NI/NA
at Workshop m/s S11 44 574	Colour T/Radio: Insured / Std / NI / NA
of	Sp. Readility
Insured:	Eng/No:
Policy No.	CINO: KMYDCSIDMA4054701
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inordee Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil LS/Refm / STD A/Rim or
	Tyre Size: F: 206/50216
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: #8 9200	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen:	L/Bal. 6 mm
Est. Repairs: 4 days Res.: Yes or No	D.O.A. 16/6/18 D.O.I. 19/0/18
3 Val.: Yes or No	Survey held at
L147534	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / C	OUT MS 3 5 5.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction LSO 2 2 Le 1666	urli mer ling ORed: 1380',47%)
add the see all	inte my han (Ned: 1370,47%)
10/6/18 1/5 4 /500 CONTINO	Open 13007 1
f 1	0.7 1115 2019
RECEIVED	2 7 JUN 2019
Data Time Elle Date 102	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation: 250
A 4 4	Fee: : Site Insp (\$)s+Rss [[
2) Add	: Interview (\$) Photos
Report Format : (γ	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 1500)	:Weekend (\$)
Lump objets its it is	TOTAL 261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

Sompo Insurance Singapore Pte. Ltd. To:

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Hwang Shiang Yi Attn:

Date: 19 Jun 2019

Preliminary Advice

Insured Vehicle No : SLA7460L

TP Vehicle No

: SJS4521T

Accident Date

: 16/06/2019

Make

: HYUNDAI I30 (FD)

Assignment Date

: 19/06/2019

: 4.00

Date of Inspection : 19/06/2019

Est. Duration of Repair

Inspection At

: SIN YU SIN WORKSHOP (HQ)

1 KAKI BUKIT AVE 6 #01-52 (AUTO BAY @ KAKI BUKIT)

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/sbody portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,922.00
Revised Amount	:S\$	4,054.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,054.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Status	
Main	17 Jun 2019	***************************************	19 Jun 2019 11:24 Assign				New Assignm Cancel Case	nent
	Main	Ref	erence	Claim	Details	Docume	nts	Show All
CLAIM S	UBFOLDER DE	TAILS				[Cre	ated by insure	r]
Insured:		PRISCI	LLA HO SEOK LA	Y, ID: S7816	913C			
Main Clair	mant:	кон w	EI HONG, ID: S	58728538C				
Vehicle Re	eg. No.:	SJS45	21T	Date	of Loss:	16/0	6/2019 16:00 - :	59
Claim Type:		TP / C	MTD1902908	Police	Policy/Cover Note No.:		D19MTPV01004254 (Comprehensive)	
Vehicle R	eg. No. (Insured)	SLA74	SLA7460L		Policy No. (Claimant):			
	3830. N. 100 (100) 23 50 C-031	0.0000000000000000000000000000000000000		Excess:				
Repairer:		919931	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit), 417883 Kaki Bukit 91993103/97825292					
Handling	Insurer:	Sompo 5205]	Insurance Sing	apore Pte. Ltd	. (HQ) - Tel: 6461 6	5555 [Handled	by Hwang Shia	ng Yi - 632
Adjuster:		LKK AL	to Consultants I	te Ltd (HQ) -	Tel: 6256-3561 [Final Rpt due	28/06/2019]	
Driver/Cu	stodian (Insured): LIM CH	E MIN () , NRIC	: S7429521E,	Tel: +6597640805	Email:		
Adj Asg.	Remarks:	WS: WE	I LEANG 9199310	3				
ASSOCI	ATED MAIL REG	CEIVED				View Al	Compose	Case Mail
There are	no mail for this	case.						
8								
ALL ASS	OCIATED TAS	KS			View All Search	Tasks Cre	ate New Task	Complete
Due Da	te Priority	Type Task G	roup Subject	Handler	Assigned By	Completed On	Created O	n Done
No result	es management	Automotiva constituto						

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!



Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

QUOTZ

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

New 5 Years Renewal Coe Toyota Altis 1.6A



3.18%P.A \$0 Admin Fees@Gv Finance, 2 Years Warranty, \$1800. Down Monthly From \$488 GV Credit Pte Ltd StarAd

« Back (1 2 3) Next »





Post an Ad

Browse by Category

60 vehicles

Hyundai i30

Advertiser Login

~

Make

Model

Ways of Selling

Hyundai i30

Price Anv Depreciation Any

Reg Date 2009 Eng Cap

Mileage Any Veh Type Any

Submit (

Status Available

✓ 20 results/page ✓

\$42,800

\$4,280 /yr

13-Nov-2009

1.591 cc

Any

123,525 km

Sort by Date Posted

Advanced Search 🐹

Hatchback Available

PREMIUM AD

5 Years COE At \$27800. The Highest Spec Of i30 Comes With Sunroof. Superbly Well Maintained By Previous Owner. Gearbox And Engine Still In Excellent State. Warranty Provided. Flexible Loan Scheme And ...

SmartCars Boutique Pte Ltd

(New 10-yr COE)

Posted: 19-3un-2019 Tags: 2009 Hyundai i30, 2009 hyundai i30, Hyundai i30, hyundai i30, Hyundai i30, Used Hyundai



Hyundai i30 Wagon 1.6A Sunroof (COE till 05/2024)

Hyundai i30 1.6A Sunroof

\$29,800

\$6,020 /yr

20-Jun-2009

1.591 cc

Stationwagon

Available

PARMINIA KO

Full Loan Available At \$600 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart...

88 Motor Trading

Posted: 19-Jun-2019 Tags: 2009 Hyundai i30, 2009 hyundai i30, Hyundai i30, hyundai i30, Hyundai i30, Used Hyundai



Hyundai i30 Wagon 1.6A Sunroof (New 5-yr COE)

\$28,800

\$5,750 /yr

23-Oct-2009

1.591 cc

73,000 km Stationwagon Available

Various Loan Options To Cater Your Comfortable Financial Plan, Very Well Maintained And Purchase With No Regrets, Hassle Free With Workshop Service, Extended Warranty Available, One Of Our Company Car..

88 Motor Trading

Posted: 18-Jun-2019 Tags: 2009 Hyundai i30, 2009 hyundai i30, Hyundai i30, hyundai i30, Hyundai i30, Hyundai i30, Used Hyundai



Hyundai i30 Wagon 1.6A Sunroof (New 5-yr COE)

\$28,800

\$5,750 /vr

15-Aug-2009

1.591 cc

Stationwagon

Available

CONTRACTOR OF THE PARTY OF THE

Well Maintained Unit, Spacious And Reliable! Sunroof Model. Good Condition And Ideal For Short Term Usage! Fuel Efficient. Call For A Viewing Appointment Today!

Mayfair Motoring

Posted: 18-Jun-2019 Tags: 2009 Hyundai i30, 2009 hyundai i30, Hyundai i30, hyundai i30, Hyundai i30, Used Hyundai



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Hyundai i30 1.6A Sunroof (COE till 03/2024)

\$25,999

\$28,800

\$5,440 /vr

30-Mar-2009

1.591 cc

Hatchback

Available

PREMIUM AD

Exclusive Sapphire Blue Unit! We Did A Better Replacement On Newer Engine Control Unit (ECU) & Newer Gearbox For A Better Usage On New 5 Years COE. Receipt Prove Is Provided. Purchase Comes With FREE ...

Available

Compare

Hyundai i30 Wagon 1.6A Sunroof (New 5-yr COE)

\$5,750 /vr

15-Jul-2009

1.591 cc

70,000 km

Stationwagon

STREET, MARKET

https://www.sgcarmart.com/used_cars/listing.php?BRSR=0&MOD=Hyundai+i30&RPG=20&AVL=2&...

Posted: 18-Jun-2019 Tags: 2009 Hyundai i30, 2009 hyundai i30, Hyundai i30, hyundai i30, Hyundai i30, Used Hyundai

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	64VV COLOGO COLOGO COLOVA CANADA CANADA
Owner ID Type:	Singapore NRIC
Owner ID:	8538C
Vehicle Details	
Vehicle No.:	SJS4521T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	FD I30 CW 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U701347
Chassis No.:	KMHDC81DMAU054701
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$14,576.00
Original Registration Date:	18 Aug 2009
First Registration Date:	18 Aug 2009
Transfer Count:	4
Actual ARF Paid: Intended PARF Rebate Details	\$14,576.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Aug 2019
PARF Rebate Amount:	\$7,288.00
Intended COE Rebate Details	
COE Expiry Date:	17 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COED LA A	\$246.00
COE Rebate Amount:	\$240.00

The information contained herein is correct as at 19 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	17/06/2019 17:13
Date Of Accident	16/06/2019 16:40
Exact Location Of Accident	ALONG MARGARET DRIVE.
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJS4521T
Insured/Policyholder	
Name Of Registered Owner	KOH WEI HONG
NRIC No	S8728538C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91855927
Alternative Phone No	OFFICE-91855927
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	130
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109315081

_				
D	ri		a	-
u		v	u	

Cover Note Number

KOH WEI HONG Name of Driver S8728538C NRIC No 20/08/1987 Date Of Birth INDOOR Occupation 28/05/2008 Date Of Driving Pass Driving Experience 11 YEARS AND 0 MONTHS

MALE Gender

(LOCAL) +65-91855927 Mobile Number

Fax Number

OFFICE-91855927 Contact Number

NOEMAIL **EMail Address**

Address

BLK 17 HOUGANG AVE 3 #08-133

Postcode

530017

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG MARGARET DRIVE, SUDDENLY VEHICLE B DROVE OUT FROM THE SMALL ROAD AND HIT ONTO MY LEFT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLA7460L

Vehicle Make/Model/Colour

VEH B

Details Of Properties Vehicle Category

PRIVATE CAR

Name of Driver

LIM CHEE MIN

NRIC/Passport Number

S7429521E

Contact Number

97816380

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary
 - (II) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their iswyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection,
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

Accident Sketch Plan Pg. 1



NRIC/FIN No.:

Page 5 of 16

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email: Sinyusin@hotmail.com

19 June 2019

QUOTATION FOR ACCIDENT REPAIR OF SJS4521T HYUNDAI 130
THIRD PARTY INSURER: SOMPO INSURANCE

				4/1
S/No.	Parts List	Qty		Amount (\$) he / he
12			R	
1.	Front door LH	1	100	\$ 1197.00 -
	Front door window glass outer moulding LH Front door mechanism lock LH	1	10	\$ 180.00 📈
3.		1	10	\$ 280.00
4. 5.	Front door black tape LH	1	SIL	\$ 21.00
6.	Front door outer protector LH Rear door RH	1 70	Ind	\$ 140.00
7.	Rear door black tape RH		211	\$ 1228.00 \$ 42.00
8.		2 21.00	11	\$ 180.00 ×
9.	Rear door window glass outer moulding LH Rear door mechanism lock LH	1	17	\$ 280.00 ×
)		3~1	
	Rear door outer protector LH	1	1	\$ 140.00
	Rear bumper	1	10	\$ 447.00 \$ 230.00
12.	Rear wheel bearing hub LH	1		\$ 230.00
		Subtotal before discount	t	\$ 3365.00
		Discount 20%		\$ 673.00
				(110
		Subtotal 1		\$ 2692.00
S/No.	Parts S/Nett	Qty		Amount(\$)
1.	Rear sport rim RH	1	1	\$350 🗴
		Special Nett Sub-Total		\$ 350
Labour				
To remov	ve & transfer front and rear left door componen	ts		\$ 150 . 60
To transf	er front and rear door glass, regulator gear, mo	tor, railing, channel, trim board.		>
	sm lock and handle	G ,,		\$ 80
To rustpr	oof affected areas			\$100 60
To condu	ict wheel alignment			\$ 150 60
To straigl	hten, repair, realign on front & rear affected are	a and replace damaged parts		\$ 1200 500
ALCOHOLDS.				Qua 3
To spray	painting on affected area	hence notify		\$ 1200
	tha Re we will the but			\$ 2880
	1.10-0 00-00-00-00-0			
	AT 1 CONTRACTOR	s) during resurvey	/	
Tot	tal Cost Of Repairs(Total cost of parts +	Total labour cost) \$ 5922.	00	6722
		- Mound	action!	
	1.50	and the result/leyed and		
	mach ette a conse	Hum Insurance Company		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO19010842/UTD3N2

Date:

28/06/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Policy No:

D19MTPV01004254

Claimant

Insured Vehicle

Vehicle No:

SJS4521T

No:

SLA7460L

Date of Loss:

16/06/2019

Nature of Claim:

TP

Claim No:

CMTD1902908

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model:

SJS4521T

HYUNDAI 130 (FD), 1.6 DOHC (A)

Engine No:

G4FC9U701347

Reg. Date: Colour:

18/08/2009 (Man. Year: 2009) Grey 1591 cc

N/A

Chassis No: Odometer:

KMHDC81DMAU054701 153986 km

Engine Capacity: Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Handbrake (Serviceable):

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

205/50R16

Rear Tyre Size:

205/50R16

Front Left Side: Front Right Side:

Yokohama 6 mm Yokohama 6 mm Rear Left Side:

Yokohama 6 mm

Rear Right Side:

No

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 3.842.00	Adjuster's 1,240.00	Difference 2,602.00	Diff %
Miscellaneous Items	0.00	0.00	0.00	67.73
Labour	2,880.00	1,480.00	1,400.00	48.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,722.00	2,720.00	4,002.00	59.54
Approved Total (Overridden) (S\$)	N. A. Commission	1,500.00		
Nett Amount (S\$)	6,722.00	1,500.00	5,222.00	77.69

INSPECTION

Date of Assignment:

19/06/2019

Date Inspected:

19/06/2019 Inspected At:

Sin Yu Sin Workshop (HQ)

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @

Kaki Bukit)

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts:	144	HYUNDAI I30 (FD) 1.6 DOHC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	no print-code for SJS4521T)
Validity:	These estima numbers with	tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT DOOR LH	Repair	1,197.00 FL	*-FL
1		*FRONT DOOR WINDOW GLASS OUTER MOULDING LH	Not Necessary	180.00 FL	*-FL
1		*FRONT DOOR MECHANISM LOCK LH	Not Necessary	280.00 FL	*-FL
1		*FRONT DOOR BLACK TAPE LH	Not Necessary	21.00 FL	*-FL
1		*FRONT DOOR OUTER PROTECTOR LH	Scratched	140.00 FL	*140.00 FL
1		*REAR DOOR RH	Dented/Bent	1,228.00 FL	*1,228.00 FL
2		*REAR DOOR BLACK TAPE RH	Necessary	42.00 FL	*42.00 FL
1		*REAR DOOR WINDOW GLASS OUTER MOULDING	Not Necessary	180.00 FL	*-FL
1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	280.00 FL	*-FL
1		*REAR DOOR OUTER PROTECTOR LH	Bent	140.00 FL	*140.00 FL
1		*REAR BUMPER	Repair	447.00 FL	*-FL
1		*REAR WHEEL BEARING HUB LH	Not Necessary	230.00 FL	*-FL
1		*REAR SPORT RIM RH	Repair	350.00 FS	*-FS
nchise	part. S=S	pcNett. L=ListItemDisc.			
			Sub Total (S\$)	4,715.00	1,550.00
		- List Item Discount on L Items 20.	.00/20.00% (S\$)	873.00	310.00
		7	Total Parts (S\$)	3,842.00	1,240.00
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*FRONT DOOR LH *FRONT DOOR WINDOW GLASS OUTER MOULDING LH *FRONT DOOR MECHANISM LOCK LH *FRONT DOOR BLACK TAPE LH *FRONT DOOR OUTER PROTECTOR LH *REAR DOOR RH *REAR DOOR BLACK TAPE RH *REAR DOOR WINDOW GLASS OUTER MOULDING LH *REAR DOOR MECHANISM LOCK LH *REAR DOOR OUTER PROTECTOR LH *REAR BUMPER *REAR BUMPER *REAR WHEEL BEARING HUB LH *REAR SPORT RIM RH *Chise part. S=SpcNett. L=ListItemDisc.	1 *FRONT DOOR LH 1 *FRONT DOOR WINDOW GLASS OUTER MOULDING Not Necessary 1 *FRONT DOOR MECHANISM LOCK LH 1 *FRONT DOOR MECHANISM LOCK LH 2 *FRONT DOOR OUTER PROTECTOR LH 3 *REAR DOOR RH 4 *REAR DOOR BLACK TAPE RH 5 *REAR DOOR BLACK TAPE RH 6 *REAR DOOR WINDOW GLASS OUTER MOULDING Not Necessary 1 *REAR DOOR WINDOW GLASS OUTER MOULDING Not Necessary 1 *REAR DOOR MECHANISM LOCK LH 1 *REAR DOOR OUTER PROTECTOR LH 2 *REAR DOOR OUTER PROTECTOR LH 3 *REAR BUMPER 4 *REAR BUMPER 5 *REAR BUMPER 6 *REAR WHEEL BEARING HUB LH 7 *REAR SPORT RIM RH 7 *REAR SPORT RIM RH 8 *REAR SPORT R	*FRONT DOOR LH

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
ur Items			
TO REMOVE & TRANSFER FRONT AND REAR LEFT DOOR COMPONENTS }	New	150.00	60.00
TO TRANSFER FRONT AND REAR DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHNAISM LOCK AND HANDLE }	New	80.00	0.00
TO RUSTPROOF AFFECTED AREAS	New	100.00	60.00
TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
TO STRAIGHTEN,REPAIR,REALIGN ON FRONT & REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	500.00
TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	800.00
Gross Labou	Gross Labour Cost (S\$)		1,480.00
	TO REMOVE & TRANSFER FRONT AND REAR LEFT DOOR COMPONENTS } TO TRANSFER FRONT AND REAR DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHNAISM LOCK AND HANDLE } TO RUSTPROOF AFFECTED AREAS TO CONDUCT WHEEL ALIGNMENT TO STRAIGHTEN,REPAIR,REALIGN ON FRONT & REAR AFFECTED AREA AND REPLACE DAMAGED PARTS TO SPRAY PAINTING ON AFFECTED AREA	TO REMOVE & TRANSFER FRONT AND REAR LEFT New DOOR COMPONENTS } TO TRANSFER FRONT AND REAR DOOR New GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHNAISM LOCK AND HANDLE } TO RUSTPROOF AFFECTED AREAS New TO CONDUCT WHEEL ALIGNMENT New AFFECTED AREA AND REPLACE DAMAGED PARTS TO SPRAY PAINTING ON AFFECTED AREA New	TO REMOVE & TRANSFER FRONT AND REAR LEFT New 150.00 DOOR COMPONENTS } TO TRANSFER FRONT AND REAR DOOR New 80.00 GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHNAISM LOCK AND HANDLE } TO RUSTPROOF AFFECTED AREAS New 100.00 TO CONDUCT WHEEL ALIGNMENT New 150.00 TO STRAIGHTEN,REPAIR,REALIGN ON FRONT & REAR New 1,200.00 AFFECTED AREA AND REPLACE DAMAGED PARTS TO SPRAY PAINTING ON AFFECTED AREA New 1,200.00

< END OF ESTIMATES >