



Your Ref: D18/6099/SG

Date: 03rd September 2019

Our Ref: CS1/FCI19010848/Esd3s2

M/s MS First Capital Insurance Ltd

36 Robinson Road
#16-01 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT: BICYCLE
INSURED VEHICLE: SHA 473T
ACCIDENT DATE: 12/08/2018**

We thank you for your instruction on 19/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of BICYCLE from M/s RADstation Pte Ltd.
- b) Singapore Accident Statement of Vehicles SHA 473T.
- c) Colour damaged vehicle photographs of BICYCLE.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : BICYCLE
2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.