

ASS. REC. BY:

REF: CS/MSG 19010850 / Avd307⁹ Special Instruction:Surveyor: Adrian ASSIGNMENT (Office)From (Person): Irene Tan Get Ing of MSG Date/Time: 19.6.19 14:44pm

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKC 2969X Insured: GBC 6292Uat Workshop m/s Modern Automotive Tel: 67484422of Blk 3023A ubi road 1 #01-61Policy No: 29123900 MKC Claim No: 596908

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18.6.2019
(Client's Record) rupu 24.6.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 19.6.19 2.49pm Person Contacted: Grace Chin Vehicle- IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 2969X - X
	GBC 6292U - (CY/ AIG 1700 8350 / K1U 9392) DOA- 25/04/2017
17/19	Informed Irene pending workshop est by merimen
5/7/19	Adrian confirmed LS \$ 2900 (Prod 2132.90, 42%)
8/7/19	Send preli revised via merimen

ASS-REG. BY.

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKC2969X Yr Regn: 2011 August

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Peugeot 308 c.c. 1598

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 233820 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF34C5FVAAS257843

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 215/50R17
R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/06/19

Survey held at Moderi

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPMS16</u>
	<u>MV: 27.51K</u>
	<u>PV: 23.71K</u>
	<u>Nett: 3.81K</u>

RECEIVED 08 JUL 2019

Manita
8/7/2019

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>8/7-typist</u>	2) _____
3) _____	4) _____
5) _____	6) _____
Prel. Report: _____	
Final Report: _____	

Part Prices Check:	
IN	OUT

Survey Fee:	Date:
Basic & Add.	<u>150</u>
__ S + RS, __ SI	
Photos	
Others	<u>11</u>
TOTAL	<u>161</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jun 2019		19 Jun 2019 14:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	ABSOLUTE INSTRUMENT SYSTEMS (PTE) LTD , Co. Reg. No.: 200707241H								
Main Claimant:	WANG CHEOW HONG , ID: S7511719A								
Vehicle Reg. No.:	SKC2969X	Date of Loss:	18/06/2019 00:00 - :59 [94 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 596908	Policy/Cover Note No.:	29123900MKC (Comprehensive) Coverage: 13/05/2019 - 12/05/2020						
Vehicle Reg. No. (Insured):	GBC6292U	Policy No. (Claimant):							
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/06/2019]								
Adj Asg. Remarks:	on WP. Liab: 100%. TP agree on SJE - assign LKK Auto. Contact: Grace Chin @ 6748 4422								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Irene Tan Gek Ing **Date:** 08 Jul 2019

Preliminary Advice

Insured Vehicle No : GBC6292U	Accident Date : 18/06/2019
TP Vehicle No : SKC2969X	Assignment Date : 19/06/2019
Make : PEUGEOT 308CC	Est. Duration of Repair : 4
Date of Inspection : 26/6/2019	
Inspection At : MODERN AUTOMOTIVE PTE LTD	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,032.90
Revised Amount	:S\$	2,900.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,900.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SKC2969X (596908)**
[GBC6292U]

TP
WANG CHEOW HONG
Jun 18 2019 12:00AM
[ABSOLUTE INSTRUMENT SYSTEMS (PTE) LTD]
Modern Automotive Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/07/2019 14:42 PM.
To MSI_ITAN
Subject TP SURVEY SKC 2969X

Dear Irene,

Please be informed that we have inspected the vehicle SKC 2969X on 26/6/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1719A
Vehicle Details	
Vehicle No.:	SKC2969X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Jun 2019
Vehicle Make:	PEUGEOT
Vehicle Model:	308 1.6 TURBO SR
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	10FJBJ0971186
Chassis No.:	VF34C5FVAAS257843
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$19,878.00
Original Registration Date:	08 Aug 2011
First Registration Date:	08 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$19,878.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2021
PARF Rebate Amount:	\$11,926.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,002.00
COE Rebate Amount:	\$11,772.00
Total Rebate Amount:	\$23,698.00

The information contained herein is correct as at 30 Jun 2019

OK

308 Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Peugeot 308 1.6A Glass Roof	\$23,888	\$8,090 /yr	29-Apr-2011	1,598 cc	105,000 km	Weili Auto LLP	Available

Very Nice Condition. Smells Good And New Paintwork. See To Believe.

Office No. - 62922933

Leng - 96947131 | Ed - 90706167

Peugeot 308CC 1.6A Turbo Sport	\$31,800	\$8,210 /yr	15-Jun-2011	1,598 cc	99,000 km	D&L Auto Trading	Available
--------------------------------	----------	-------------	-------------	----------	-----------	------------------	-----------

Guaranteed Accident Free, High OMV \$32K, Beautiful Leather Interior, Extremely Well Maintained, Wear And Tear Replaced, 80% Loan At 2.28%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunc...

Office No. - 62960188

Darren Low - 96236322

Peugeot 308 1.6A Turbo Glass Roof	\$27,900	\$8,140 /yr	15-Sep-2011	1,598 cc	50,000 km	Otua Auto Pte Ltd	Available
-----------------------------------	----------	-------------	-------------	----------	-----------	-------------------	-----------

Consignment Code: A160. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please D...

Office No. - -

Francis Chen - 87539539 | Paul - 87671091

Peugeot 308CC 1.6A Turbo Sport	\$35,800	\$8,450 /yr	25-Oct-2011	1,598 cc	116,837 km	Mayfair Motoring	Available
--------------------------------	----------	-------------	-------------	----------	------------	------------------	-----------

Owner Consignment Unit. Well Maintained And Best Of All Asking Just Above Paper And Body Price. Affordable Convertible To Own. Nice Red Paintwork. Loan And Trade In Available! Call For A Viewing Appoi...

Office No. - 64792220

Nelson Ng - 92369669 | Paul Foo - 97505007 | Richard Goh - 97648399

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2019 16:29
Date Of Accident	18/06/2019 12:20
Exact Location Of Accident	406 ANG MO KIO AVENUE 10 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC2969X
Insured/Policyholder	
Name Of Registered Owner	WANG CHEOW HONG
NRIC No	S7511719A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96984899
Alternative Phone No	OFFICE-96984899

Vehicle Particulars

Manufacturer	PEUGEOT
Model	308 1.6 TURBO SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP301224
Cover Note Number	

Driver

Name of Driver	WANG LAI HUANG @WAN LAI HUANG
NRIC No	S0087517A
Date Of Birth	06/10/1948
Occupation	INDOOR
Date Of Driving Pass	23/10/1967
Driving Experience	51 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96984989
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLOCK 327 SERANGOON AVENUE 3 #08-322
Postcode	550327
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 18.06.2019 at about 1220hrs, I parked my vehicle (A: SKC2969X) along Block 406 Ang Mo Kio Avenue 10 Open Carpark of Lot 170. When I return back to my vehicle, there is a driver of vehicle (B: GBC6292U) standing in front of my vehicle and informed that he have hit onto front portion of my vehicle. However I have no idea how the accident happened. Vehicle A (SKC2969X): No passenger on board. Vehicle B (GBC6292U): 1 male passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC6292U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SONG ZHI FEI
NRIC/Passport Number	G2024946W
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: PASSENGER

GENDER: MALE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

wellk

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]
628096800

RE : ESTIMATE FOR ACCIDENT REPAIR SKC2969X (PEUGEOT 308)

- 2 To putty and spray up paint works
- 3 To check wiring system

	\$	400.00 250
	\$	50.00 30
Total labour	\$	850.00
GRAND TOTAL	\$	5,032.90

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total : 3659.10
L/S : 2.9K.
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jun 2019		19 Jun 2019 14:44 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ABSOLUTE INSTRUMENT SYSTEMS (PTE) LTD , Co. Reg. No.: 200707241H								
Main Claimant:	WANG CHEOW HONG , ID: S7511719A								
Vehicle Reg. No.:	SKC2969X	Date of Loss:	18/06/2019 00:00 - :59 [94 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 596908	Policy/Cover Note No.:	29123900MKC (Comprehensive) Coverage: 13/05/2019 - 12/05/2020						
Vehicle Reg. No. (Insured):	GBC6292U	Policy No. (Claimant):							
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/07/2019]								
Adj Asg. Remarks:	on WP. Liab: 100%. TP agree on SJE - assign LKK Auto. Contact: Grace Chin @ 6748 4422								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC2969X (596908)**
[GBC6292U]
TP
WANG CHEOW HONG
Jun 18 2019 12:00AM
[ABSOLUTE INSTRUMENT SYSTEMS (PTE) LTD]
Modern Automotive Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 08:44	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/07/19 08:38	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	08/07/19 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	08/07/19 08:38	Reinspection Photo	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
				<input checked="" type="checkbox"/>
35	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	08/07/19 08:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
73	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
74	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
75	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
76	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
77	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
78	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
79	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
80	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
81	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
82	08/07/19 08:38	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)				
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/06/19 13:39	PRI	Load PDF	
2	19/06/19 13:39	TP GIA	Load PDF	
3	19/06/19 14:23	TP agree on SJE.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010850/AGVD3E2

Date: 10/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29123900MKC
Claimant Vehicle No : SKC2969X	Insured Vehicle No :	GBC6292U
Date of Loss: 18/06/2019	Nature of Claim:	TP Claim No: 596908

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC2969X	Engine No:	10FJB0971186
Make & Model:	PEUGEOT 308CC, 1.6 Turbo Sport (A)	Chassis No:	VF34C5FVAAS257843
Reg. Date:	08/08/2011 (Man. Year: 2010)	Odometer:	233820 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,182.90	3,029.10	1,153.80	27.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	630.00	220.00	25.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,032.90	3,659.10	1,373.80	27.30
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	5,032.90	2,900.00	2,132.90	42.38
+ GST 7.00/7.00% (S\$)	352.30	203.00	149.30	42.38
Nett Amount (S\$)	5,385.20	3,103.00	2,282.20	42.38

INSPECTION

Date of Assignment:	19/06/2019	
Date Inspected:	26/06/2019	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jul 2019)	
Parts:	N/A	PEUGEOT 308CC 1.6 Turbo Sport (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC2969X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	950.00 FL	*950.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*FRONT BUMPER SIDE HOLDER - LH & RH	Necessary	90.00 FL	*90.00 FL
4	1		*FRONT BUMPER PROTECTOR	Deformed	149.00 FL	*149.00 FL
5	1		*FRONT BUMPER PROTECTOR TOW COVER	Missing	25.00 FL	*25.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	395.00 FL	*395.00 FL
7	1		*FRONT BUMPER LOWER GRILLE SIDE COVER - LH & RH	O/S Deformed	70.00 FL	*35.00 FL
8	1		*FRONT BUMPER LOGO	Necessary	120.00 FL	*120.00 FL
9	1		*FRONT BUMPER INNER FRAME	Cracked	385.00 FL	*385.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	442.00 FL	*- FL
11	1		*FRONT BUMPER LOWER BEAM	Not Necessary	295.00 FL	*- FL
12	2		*FRONT BUMPER FOG LAMP - LH & RH	Not Necessary	510.00 FL	*- FL
13	2		*HEADLAMP - LH & RH	Cracked	1,120.00 FL	*1,120.00 FL
14	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
15	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,641.00	3,359.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	458.10	329.90
Total Parts (\$\$)	4,182.90	3,029.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	400.00	350.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	400.00	250.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
			Gross Labour Cost (S\$)	850.00
				630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >