

ASS. REC. BY:

REF:

CS3/CTI/9010858/71cd30

Special Instruction:

1/7/19

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

19/6/19 @ 2.53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLK 606 C

Insured:

GV 5256 Y

at Workshop m/s

28 Auto Werkz

Tel:

9362 8159.

of

Blk 1002 Bukit Merah Lane 3 # 01-83

Policy No:

DMCVSN19009619000.

Claim No:

SNM19D 202797 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14/6/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:11pm @ 19/6/19

Person Contacted:

Rayer

Vehicle IN/OUT

Date/Time

Action/Instruction

1 done! X

SLK 606 C - X

GV 5256 Y - NA/INCI 6018 373/h4

DUT: 29/09/2016

Dismantle: 20/6/2019

After repair: 25/6/2019

DATE

Tanp

REF

CTI

ASSIGNMENT

From
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No
at Workshop n/s
of
Insured
Policy No
Claims No
Sum Insured
Excess
(Client's Record)
Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Vehicle: IN / OUT

Veh No: SLR 606C Yt Regn: 2012 / Feb.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta. C.C. 1390

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 175817 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW ZZZ 16 Z CM 082998

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Cor front

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 19/6/19 @ 4187

Survey held at Auto Werks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 1 days

- Estimated repair range \$4,000 - \$5,000

9/7/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format: PRE

Lump Sum / L.B.L (\$)

Survey Fee:

Transportation:

3-4 RS. SI

Photos

Other:

TOTAL

150

150

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 19 June 2019 2:53 PM
To: assignments; Wendy Jiang
Cc: Ong Chin Kiat
Subject: CTP REF NO. SNM19D202797 RS REF NO. SLK606C - AACCIDENT INVOLVING GV5256Y AND SLK606C ON 14 JUNE 2019[1906-7315]

WITHOUT PREJUDICE

Dear Sir/Mdm (LKK),

Please assist to get your surveyor to survey the abovementioned vehicle (SLK606C).

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]
Sent: Wednesday, 19 June, 2019 2:46 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: lua_siewhui@rssolomon.com
Subject: Re: CTP REF NO. SNM19D202797 RS REF NO. SLK606C - AACCIDENT INVOLVING GV5256Y AND SLK606C ON 14 JUNE 2019[1906-7315]

Dear Irene,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please arrange your Surveyors to contact Mr. Roger of 28 Auto Werkz Pte Ltd at tel no. 9362 8159 for a pre-repair survey of our client's vehicle located at Blk 1002 Bukit Merah Lane 3 #01-83 Singapore 159719.

Thank you and Best Regards.

Yours sincerely
Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.

On Wed, Jun 19, 2019 at 2:42 PM Irene Tay <irene.tay@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

| |
|----------------|
| ADRIAN LING |
| Kelvin Ang |
| SEE CHEW SENG |
| LOW SAR HUEI |
| HONG FOOK CHOY |
| XING QUO QIANG |
| KENNETH KONG |
| SIMON HO |
| CHUA WEIJIE |
| MARCUS CHUA |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7653A |
| Vehicle Details | |
| Vehicle No.: | SLK606C |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 01 Jul 2019 |
| Vehicle Make: | VOLKSWAGEN |
| Vehicle Model: | JETTA 1.4 TSI AT 1623Q5 |
| Primary Colour: | Blue |
| Manufacturing Year: | 2011 |
| Engine No.: | CAV358578 |
| Chassis No.: | WVWZZZ16ZCM082998 |
| Maximum Power Output: | 118.0 kW (158 bhp) |
| Open Market Value: | \$24,662.00 |
| Original Registration Date: | 13 Feb 2012 |
| First Registration Date: | 13 Feb 2012 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$24,662.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 12 Feb 2022 |
| PARF Rebate Amount: | \$14,797.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 12 Feb 2022 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$50,001.00 |
| COE Rebate Amount: | \$13,080.00 |
| Total Rebate Amount: | \$27,877.00 |

The information contained herein is correct as at 01 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|---|
| Date Of Report | 15/06/2019 10:08 |
| Date Of Accident | 14/06/2019 17:00 |
| Exact Location Of Accident | JUNCTION OF YISHUN AVE 1 & YISHUN ST.43 |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SLK606C |
| Insured/Policyholder | |
| Name Of Registered Owner | CHAN GUAN RONG KAVAN |
| NRIC No | S8827653A |
| Email Address | JAEGERG550@GMAIL.COM |
| Mobile Phone No | (LOCAL) +65-91384022 |
| Alternative Phone No | OTHERS-91384022 |
| Vehicle Particulars | |
| Manufacturer | VOLKSWAGEN |
| Model | JETTA 1.4 TSI AT 1623Q5 |
| Exact Purpose for which vehicle was being used at time of accident | PTE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5100015231 |
| Cover Note Number | 20/04/18 - 12/08/19 |
| Driver | |
| Name of Driver | CHAN GUAN RONG KAVAN |
| NRIC No | S8827653A |
| Date Of Birth | 01/08/1988 |
| Occupation | INDOOR |
| Date Of Driving Pass | 08/01/2013 |
| Driving Experience | 6 YEARS AND 5 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91384022 |
| Fax Number | |
| Contact Number | OTHERS-91384022 |
| Email Address | JAEGERG550@GMAIL.COM |

| | |
|---|-------------------------------|
| Address | BLK 404 YISHUN AVE 6 #10-1242 |
| Postcode | 760404 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACH. *THIRD PARTY CLAIM BY 28 AUTO WERKS PTE LTD*

Attachment(s)

| | |
|---|----------------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | DRIVER WILL EMAIL DIRECT TO NTUC |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | GV5256Y |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|---|----------------------|
| Name | CHAN GUAN RONG KAVAN |
| Approximate Age | |
| Injuries Sustain | SLIGHT BACKACHE |
| Injured person in which vehicle? | SLK606C |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SLK 606 C

INSURER : NTUC


DATE & TIME: 14/6/19 @ 17:00


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on Yishun Ave 1 when a lorry (GV5256Y) abruptly changed lane from lane 4 to lane 2. I was unable to brake in time and collided to the rear of the lorry. The accident happened on 14 June 2019 at 17:00H at the T junction of Yishun Ave 1 and Yishun Street 43.

The lorry was travelling on lane 4 ⁱⁿ front of a van when the van changed lane to lane 2, the lorry abruptly changed to lane 2 as well. The first time I saw the lorry was when the van slammed brake and the lorry abruptly change into lane 3. I started braking however the lorry continued changing lane to the 1st lane with the intention to turn right at the junction. Due to the abrupt lane change, the lorry was diagonally in between lane 2 & 1.

I had a slight backache and went to a GP. Was given 2 days mc.

Note Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (457)
NRIC/FIN No.:

☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☒ Claim ODP/TP at other workshop (28 Auto Work Pte Ltd)






































...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 01 Jul 2019 | | 01 Jul 2019 11:07 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | ABS LEASING SERVICES PTE LTD , Co. Reg. No.: 201819528D | | | | | | | | |
| Main Claimant: | CHAN GUAN RONG KAVAN , ID: S8827653A | | | | | | | | |
| Vehicle Reg. No.: | SLK606C | Date of Loss: | 14/06/2019 17:00 - :59 [88 Months and 1 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM19D202797C02 | Policy/Cover Note No.: | DMCVSN19009619000 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | GV5256Y | Policy No. (Claimant): | 5100015231 | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | 28 Auto Werkz Pte Ltd (HQ) Blk 1002 Bukit Merah Lane 3, #01-83, 159719 Bukit Merah - Tel: | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat] | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/07/2019] | | | | | | | | |
| Driver/Custodian (Insured): | MUHAMMAD'ADLI BIN ABDUL WAHID (38 / Male) , NRIC: S8016487D Email: | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |


Claim Documents







*SLK606C (SNM19D202797C02)
[GV5256Y]
TP
CHAN GUAN RONG KAVAN
Jun 14 2019 5:00PM
[ABS LEASING SERVICES PTE LTD]
28 Auto Werkz Pte Ltd



| | | | | | | | | | | |
|------------------|-----------------|-----------------------------------|---|-----------|-------------------------------------|--|------|------------|-----------------|-------------------------------------|
| Upload Documents | | | Upload Photos | | Compose New Letter | | View | | View in Browser | |
| Photos/Images | | | | | | | | 3 per page | | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print | | | | | |
| 1 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 2 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 3 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 4 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 5 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 6 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 7 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 8 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 9 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 10 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 11 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 12 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 13 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 14 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 15 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 16 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 17 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 18 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 19 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 20 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 21 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 22 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 23 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 24 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 25 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 26 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 27 | 09/07/19 15:49 | General View |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 28 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 29 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 30 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 31 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 32 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 33 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 34 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 35 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 36 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |
| 37 | 09/07/19 15:50 | Photographs of Damaged Parts |  | Load JPG | <input checked="" type="checkbox"/> | | | | | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 09/07/19 15:50 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 11/07/19 19:42 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 11/07/19 19:42 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 11/07/19 19:42 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 11/07/19 19:42 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 11/07/19 19:42 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

Linked Accident Report Documents

| Assessment Reports | | | View | View in Browser |
|--------------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 15/06/19 14:10 | Accident Statement |  Load HTM | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 15/06/19 13:54 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|----------------------------------|--|-------------------------------------|
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 15/06/19 14:09 | Sketch Plan |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 15/06/19 14:09 | Sketch Plan #2 |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| | | | |
|--|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19010858/T1CD3E2

Date: 15/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19009619000

Claimant Vehicle
No : SLK606CInsured Vehicle
No : GV5256Y

Date of Loss: 14/06/2019

Nature of Claim: TP

Claim
No: SNM19D202797C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK606C**

Make & Model: VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)

Engine No: CAV358578

Reg. Date: 13/02/2012 (Man. Year: 2011)

Chassis No: WWWZZZ16ZCM082998

Colour: Blue

Odometer: 175817 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 01/07/2019

Date Inspected: 19/06/2019 Inspected At:

28 Auto Werkz Pte Ltd (HQ)
Blk 1002 Bukit Merah Lane 3, #01-83
Singapore 159719

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 15 Jul 2019) |
| Parts: | 143 | VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLK606C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >