

1.000000
 ANS. REC. BY: GO REF: CS3/MSG19003183/6545-1 Special Instruction:
 SMV (v/v) menmen GO ASSIGNMENT (Office)
 From (Person): Chhin Nyule Pui of MSG Date/Time: 19.6.2019
 Estimated Cost: _____ Bill to: _____
 OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SBA 113D Insured: SME 9645A
 at Workshop n/s: Xin Yun Auto Tel: 98391666
 of Blic 8 Kaki Bkt Ave 4 # 05-23
 Policy No: 29112616MCY Claim No: 585367
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 16/02/2019
 (Client's Record)
 CA / REV / REP. / REV 24 HRS ^{up?} R.O.D. Endorsement: _____
 Date/Time: 1:54pm @ 20/2/19 Person Contacted: Yi shih Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SBA 113D - NBA/AIG/ISD/4551/X
	SME 9645A - X
	\$H650, 6 Days.
	11800

(\$ 25,000.00 Red - 68%)

RECEIVED 09 JUL 2019

Do Not Finalise

 8/7/2019

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$120k

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SB A1130 Yr Regn: 23 Dec 2011
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW X6 M c.c. 4395
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading 98960 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cl/No: WBSG 802040LJ8996
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 315/25 R23
 R: 11
 BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

<u>Front</u>	<u>Rear</u>
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. _____	D.O.I. <u>20-02-19</u>
Survey held at <u>W/S</u>	<u>5pm</u>

 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000
	COE: 86995

Date/Time, File Pass to?	<input type="checkbox"/> : Prel. Report	Days Of Repair:	<u>4</u>
1) _____	<input type="checkbox"/> : Final Report	Resurvey No. of Trip:	<u>-</u>
Date/Time, File Return to?		Survey Fee:	<u>120</u>
2) _____		Transportation:	
Report Format : <u>PRS</u>	Add Fee:	<input type="checkbox"/> Site Insp (\$ _____)	} <u> </u> S + RS <u> </u> SI
Lump Sum / I.B.I: (\$ _____)	<input type="checkbox"/> Interview (\$ _____)	} Photos	
	<input type="checkbox"/> Tech. Invs (\$ _____)	} Others	<u>10</u>
	<input type="checkbox"/> Weekend (\$ _____)	} _____	
		TOTAL	<u>120</u>

Nivitha (LKK Auto)

From: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Sent: Wednesday, 19 June 2019 9:13 AM
To: SUR; Admin-D (LKKAuto)
Subject: FW: Your ref: BK.19056.19.st. Our ref: 585367(OIV: SME9645A)

Hi LKK Team

Our ref: 585367

Please do paper survey for us.

TP documents granted in Merimen.

Thanks.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

From: Chhia Nyuk Pui
Sent: Tuesday, 14 May, 2019 7:17 PM
To: 'bonnie kwok' <litigation@bonniekwok.com>
Subject: RE: Your ref: BK.19056.19.st. Our ref: 585367(OIV: SME9645A)

Dear Sir/Madam

Without Prejudice
Save as to Costs

We refer to your letter dated 30/04/2019.

We are looking into the claim and shall come back to you soon.

Thank you.

Please note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data for the purpose of assessing your claim. This may include disclosing and sharing your personal data with our service providers and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore, for the proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws (collectively, "the Purpose"). We may also need to disclose or share your personal data with service providers who are sited outside Singapore for the Purpose.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Wednesday, 19 June 2019 1:51 PM
To: Admin-D (LKKAuto)
Cc: assignments; Accounts (LKKAuto)
Subject: Report Send Back Alerts - SBA113D (TP)

Dear Nivitha / Summer,

FYNA Please...

Pending for Survey Report- CS3/MSG19003183/GCD3E2

19 Jun 2019 09:13	Ins Send Back Adj Rpt	Hi LKK Team Our ref: 585367 Please do a paper survey for us. TP documents granted in Merimen. Thanks. Chhia Nyuk Pui Senior Executive, Claims Service Direct line +65 6594 2521 Direct fax +65 6643 1349 nyukpui_chhia@sg.msg-asia.com	[I] Chhia Nyuk Pui
19 Jun 2019 09:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/21	[I] Merimen Administrator
19 Jun 2019 09:13	Adj Mandate Set	Maintained.	[I] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Wednesday, 19 June 2019 9:20 AM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SBA113D (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team




This email has been checked for viruses by AVG antivirus software.
www.avg.com

BONNIE KWOK LLC
Advocates & Solicitors

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
(Not for service of court documents)
GST Reg No. 2012035472

Your Ref: 585367
Our Ref: BK.19056.19.st
(Please quote our reference when replying)



30 April 2019

M/s MSIG Insurance (Singapore) Pte. Ltd.
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

By Hand

Dear Sirs

ACCIDENT INVOLVING SBA 113 D & SME 9645 A ON 16 FEBRUARY 2019

We act for Mr. Lim Loon Huat, the owner of vehicle no. SBA 113 D in the above matter.

We are instructed that on the 16 February 2019, your insured driving vehicle no. SME 9645 A had negligently collided into our client's said vehicle.

We are instructed that as a result of the said collision, our client has suffered loss and damage as follows: -

i.	Cost of Repairs	-\$ 36,800.00
ii.	Vehicle Rental	-\$ 4,250.00
iii.	Towing fees	-\$ 120.00
iv.	Survey Report fees	-\$ 1,736.00
v.	LTA search fees	-\$ 8.00
vi.	GIA search fees	-\$ 29.00
vii.	Transport, Postage, Xerox and other incidental	-\$ 53.50
viii.	Costs	-\$ 1,605.00
	Total	<u>\$ 44,601.50</u>

We enclose herewith a copy of the LTA search result, GIA report of our client and your insured, survey report and invoice, repair bill, towing receipt, rental invoice and agreement, the certificate of insurance and 76 original photographs for your attention.

Kindly note that under the NIMA protocol, all requests for resurvey are required to be made during the protocol period in eight (8) weeks from receipt of this letter.

Kindly revert whether liability is admitted.

Yours faithfully

BONNIE KWOK

Enc. (by hand)

c.c. Client; and
Koh Hwee Lin



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

INVOICE

Name: Lim Boon Huat	Date of Invoice: 2/4/2019
Xin Yun Auto Pte Ltd Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875	

Claim Type: Third Party	Date of Accident: 16/2/2019
Vehicle Reg No: SBA113D	Claimant: Lim Boon Huat
Vehicle Make/Model: BMW X6 M	
Description	Amount (S\$)
Lump Sum Repair as per recommendation	36,800.00
Total	36,800.00
Singapore Dollar: Thirty six thousand and eight hundred dollars only.	



KAOLIN MOTOR TRADING CO

Thomson Road Post Office, P.O. Box 95, Singapore 915704
Tel: 6452 0716; 6458 4013
Registration No. T16472001

24 HOURS TOWING SERVICES

Meters

Singapore Auto AC Ltd

CASH SALE
JOB ORDER

No. 7012468

Vehicle No.

SBA 1130

Date 14/3/19

Destination

Joo chiat P to W3

Model BMW X6M

Time In

Time Out

Remarks

Amount \$ 100

- ☐ Change Spare Tyre / Jumpstart
- ☐ Basement / Multi Carpark
- ☐ Accident
- ☐ Using King Dolly (Extra Trailer)
- ☐ Lowered Bodykit / Suspension

- ☐ Loaded With Goods
- ☐ Dismantle Shaft / Brake / Equipment
- ☐ Open Door
- ☐ Crane up / Winch out

No 459113

Driver

Received By

biSAFE



Invoice

SBA113D
LIM LOON HUAT
31 CHAPEL ROAD
S(429537)

Invoice No : GPLIN0001204
Invoice Date : 5/3/2019
Due Date : 5/3/2019
VHA No : 1380
Referral ID : X003

Description :	Amount
Rental for 17 Day/s @ \$250 per Day \$	4,250.00

Vehicle No : SLR8224G

Vehicle Description : Toyota Estima 2.4 A

Rental Period : 16/02/2019 to 05/03/2019

Total Amount Payable : \$ 4,250.00

GOOD WAY RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807



VHA No: 1380

Invoice No: GPLIN1204

Hirer's Vehicle No: SBA113D

UEN: 201505120D

VEHICLE RENTAL AGREEMENT



HIRER'S PARTICULARS Name: (as in I/C) <u>Lim Loon Huet</u> NRIC / FIN No: <u>S1583287H</u> Address (Res): <u>300 Chiat Place</u> <u>Grife wan tan mee</u> Name & Address of Employer: <u>31 CHAPEL RD S(429537)</u> Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: <u>23/10/63</u> Tel: (O) _____ (R) _____ HP: _____		Vehicle No: <u>SLR82246</u> Replace Veh No: _____ Mileage Out: <u>21850</u> Mileage Out: _____ Make & Model: <u>TOYOTA ESTIMA</u> Auto / Manual Out: Date <u>16/02/2019</u> Time: <u>16:15</u> HIRE / PERIOD EXPIRY _____ Time: _____ NON-WAIVER EXCESS=\$ <u>30000</u>																																																													
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC / FIN No: _____ Address (Res): _____ Occupation: _____ Driving Exp: _____ Singapore Driving Licence No: _____ Issue Date: _____ Date of Birth: _____ Tel: (O) _____ (R) _____ H/P: _____		<table border="1"> <tr> <th colspan="4">CHARGES</th> </tr> <tr> <td>Daily</td> <td>17</td> <td>@ \$ 250</td> <td>per day</td> </tr> <tr> <td>Weekly</td> <td></td> <td>@ \$</td> <td>per week</td> </tr> <tr> <td>Monthly</td> <td></td> <td>@ \$</td> <td>per month</td> </tr> <tr> <td>Hours</td> <td></td> <td>@ \$</td> <td>per hour</td> </tr> <tr> <td>Extension</td> <td></td> <td>@ \$</td> <td></td> </tr> <tr> <td colspan="4">Delivery/Collection Service</td> </tr> <tr> <td colspan="4">SUB-TOTAL \$</td> </tr> </table>		CHARGES				Daily	17	@ \$ 250	per day	Weekly		@ \$	per week	Monthly		@ \$	per month	Hours		@ \$	per hour	Extension		@ \$		Delivery/Collection Service				SUB-TOTAL \$																															
CHARGES																																																															
Daily	17	@ \$ 250	per day																																																												
Weekly		@ \$	per week																																																												
Monthly		@ \$	per month																																																												
Hours		@ \$	per hour																																																												
Extension		@ \$																																																													
Delivery/Collection Service																																																															
SUB-TOTAL \$																																																															
VEHICLE CHECK LIST INDICATE: D - DENTS S - SCRATCHES A - ACCIDENTS 		<table border="1"> <tr> <th colspan="10">PETROL LEVEL</th> </tr> <tr> <td>Out</td> <td>E</td> <td>1/8</td> <td>1/4</td> <td>3/8</td> <td>1/2</td> <td>5/8</td> <td>3/4</td> <td>7/8</td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/8</td> <td>1/4</td> <td>3/8</td> <td>1/2</td> <td>5/8</td> <td>3/4</td> <td>7/8</td> <td>F</td> </tr> <tr> <td colspan="10">Fuel</td> </tr> <tr> <td colspan="10">Traffic / Parking Fines</td> </tr> <tr> <td colspan="10">TOTAL CHARGES \$</td> </tr> </table>		PETROL LEVEL										Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F	Fuel										Traffic / Parking Fines										TOTAL CHARGES \$									
PETROL LEVEL																																																															
Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																						
In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F																																																						
Fuel																																																															
Traffic / Parking Fines																																																															
TOTAL CHARGES \$																																																															
MISSING / FAULTY ACCESSORIES / PARTS REMARKS: _____		Hirer's Signature  Additional Driver's Signature _____																																																													

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given GOOD WAY RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

- VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF COW AND/OR PAJ WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY GOOD WAY RENT-A-CAR PTE LTD.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO GOOD WAY RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
5/3/19	1515	23005			

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:

LIM LOON HUAT

Date of Issue:

06 Dec 2018

Registration No.:

SBA113D

Effective Date of Commencement:

23 Dec 2018 00:00

Chassis No.:

WBSGZ02040LJ89096

Certificate No.:

SD18V14087/ VPE / R00

Date of Expiry:

22 Dec 2019 23:59

Type of Certificate:

MX1

Persons or Classes of Persons entitled to drive*:

A) The Policyholder.

B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

A) Use for hire or reward.

B) Use for racing, pace-making, reliability trials or speed-testing.

C) Use for the carriage of goods (other than samples) in connection with any trade or business.

D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:
Coverage(s):

Comprehensive, Unlimited Windscreen, NCD Protection

Sum Insured:

MARKET VALUE AT THE TIME OF LOSS

Excess:

Section I (Singapore) S\$2500, Section I (Outside Singapore) S\$3000, Windscreen Excess S\$500

Name of Finance Company:
Name of Producer:

ONG CHAI LAY (A1247)

PLFNU/SD18V14087/06-Dec-2018/MotorC/v1.0

Enquire Vehicle & Owner Information (Vehicle No. SME9645A As At 16 Feb 2019 / 00:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: XINYUN - SBA113D

Current Owner Details

Owner ID Type: Company

Owner ID: 201617259H

Owner Name: BLUECAR EAST ASIA PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 16

Registered Street Name: SCIENCE PARK DRIVE

Registered Unit No.: # 04 - 01

Registered Building Name: DNV GL TECHNOLOGY CENTRE

Registered Postal Code: 118227

Current Vehicle Details

Vehicle No.: SME9645A

Make Description/Model: BLUECAR / BLUECAR

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

TAX INVOICE

Our Ref No: GR-19-045323

Date of Request: 22/03/2019

Your Ref No: XINYUN (SBA113D)

BONNIE KWOK LLC
101A UPPER CROSS STREET #08-12, PEOPLE'S PARK CENTRE
SINGAPORE 058358

Dear Sir/Madam,

Your Vehicle No: SBA113D
Date of Accident: 18/02/2019
Place of Accident: JOO CHIAT PL
Involving Vehicle No: SME9645A

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☐ Cash ☒ Cheque MB 008322

TAX INVOICE

Our Ref No: GR-19-045324
Date of Request: 22/03/2019

Your Ref No: XINYUN (SBA113D)

BONNIE KWOK LLC
101A UPPER CROSS STREET #08-12, PEOPLE'S PARK CENTRE
SINGAPORE 058358

Dear Sir/Madam,

Date of Accident: 16/02/2019
Vehicle No: SBA113D
Place of Accident: JOO CHIAT PLACE
Involving Vehicle No: SME9645A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SME9645A	JOO CHIAT PLACE	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.


Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☐ Cash ☒ Cheque MB 008321



SINCERE
APPRAISAL SERVICES PTE LTD

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : office@sincereappraisal.com.sg

INVOICE

Lim Boon Huat
C/O Xin Yun Auto Pte Ltd
Blk 8 Kaki Bukit Avenue 4
#05-23 Premier
Singapore 415875

Invoice No: 020419-123
Our ref: 123/TP/2019
Date: 2/4/2019

Claim Type: Third Party
Vehicle Reg No: SBA113D
Vehicle Make/Model: BMW X6 M

Date of Loss: 16/2/2019
Claimant: Lim Boon Huat

Description	Amount (S\$)
1. Professional Fee (including Transport, 76 Photographs and Miscellaneous charges)	1736
Total	1736
Singapore Dollar: One thousand seven hundred and thirty six dollars only.	

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



SINCERE
APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 123/TP/2019

Date: 2/4/2019

REFERENCE

Date of loss: 16/2/2019
Claimant: Lim Boon Huat

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBA113D	Make &	BMW
Reg date:	23/12/2011	Model	X6 M
Colour:	White	Engine No:	20150001S63B44A
Type:	Motor Car	Chassis No:	WBSGZ02040LJ89096
Type of Claims:	Third Party	Odometer No:	98960km
		Engine Cap:	4395cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size:	Sportmaxx 315/25ZR23 70%	Front Right Size:	Sportmaxx 315/25ZR23 70%
Rear Left Size:	Sportmaxx 315/25ZR23 70%	Rear Right Size:	Sportmaxx 315/25ZR23 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

	Repairer S\$	Adjuster S\$
Parts	S 42,953.10	S 42,533.10
Labour	S 4,040.00	S 3,430.00
Calculated Cost (S\$) :	S 46,993.10	S 45,963.10

Recommended Lump Sum Repair Cost (S\$) : \$ 36,800.00

Date of Assignment: 18/2/2019
Date Inspected: 18/2/2019
Est. repair Period: 14 days

Inspected At: Xin Yun Auto Pte Ltd
Blk 8 Kaki Bukit Avenue 4
#05-23 Premier
Singapore 415875

POINT OF IMPACT

Damaged at the right hand front portion	
---	--

BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the carpark of Joo Chiat Place.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the right hand front portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$46,993.10. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$36,800.00.

We have not authorised the repair. Under normal circumstances, estimated 14 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front sports bumper with PDC 2400	grazed/cut/warped	\$ 4,800.00	\$ 4,800.00 /
2	1	Front bumper right retainer	bent/necessary	\$ 241.00	\$ 241.00 X
3	1	Front bumper right bracket 1 NN	bent/necessary	\$ 158.00	\$ 158.00 X
4	2	Front bumper tow cover	necessary	\$ 132.00	\$ 132.00 X
5	1	Front bumper lower cover 640	cracked	\$ 1,285.00	\$ 1,285.00 /
6	2	Front bumper lower side inner garnish 41X NN	cracked 140	\$ 287.00	\$ 287.00 /
7	2	Front bumper lower side garnish RH/CA	cracked 190	\$ 382.00	\$ 382.00 /
8	2	Front grille assy NN	warped	\$ 856.00	\$ 856.00 X
9	1	Front right fender 1400	dented/warped	\$ 2,850.00	\$ 2,850.00 /
10	1	Front right fender upper cowling NN	cracked/torn	\$ 395.00	\$ 395.00 X
11	1	Front right fender lower cowling NN	cracked/torn	\$ 395.00	\$ 395.00 X
12	1 set	Front right fender inner shield 190	cracked	\$ 382.00	\$ 382.00 /
13	1	Front right electric suspension assy 1800	malfunction	\$ 3,660.00	\$ 3,660.00 /
14	1	Front right lower arm 480	bent	\$ 950.00	\$ 950.00 /
15	1	Front right brake disc NN	bent	\$ 387.00	\$ 387.00 X
16	1	Front right brake air duct NN	warped	\$ 250.00	\$ 250.00 X
17	1	Front right upper arm 525	bent	\$ 1,050.00	\$ 1,050.00 /
18	1	Front right wheel hub bearing 250	bent	\$ 515.00	\$ 515.00 /
19	1	Front right camber arm X	bent	\$ 760.00	\$ 760.00 X
20	1	Front right trailing arm X NN	bent	\$ 720.00	\$ 720.00 X
21	1	Front right trailing link X	bent	\$ 320.00	\$ 320.00 X
22	1	Front right stabilizer link	bent	\$ 315.00	\$ 315.00 /
23	1	Front right drive shaft NN	bent	\$ 3,813.00	\$ 3,813.00 X
24	1	Front power steering rack and pinion assy 3200	malfunction/broken	\$ 6,400.00	\$ 6,400.00 /
25	1	Front sports bumper wire mesh NN	bent	\$ 450.00	\$ 450.00 X
26	1	Front right brake disc plate	bent	\$ 185.00	\$ 185.00 X
				\$ 31,938.00	\$ 31,938.00
Less 5%				\$ 1,596.90	\$ 1,596.90
				\$ 30,341.10	\$ 30,341.10

11530

5% 10953.5

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
<u>Special Nett Items</u>					
1	16	Front sports bumper clips	necessary	\$ 80.00	\$ 80.00 5*
2	8	Front right fender inner shield clips	necessary	\$ 30.00	\$ 30.00 /
3	8	Front right fender upper cowlings clips	necessary	\$ 30.00	\$ 30.00 20
4	8	Front right fender lower cowlings clips	necessary	\$ 30.00	\$ 30.00 20
5	1	Front right sports rim 1800	grazed/dented/warped	\$ 4,882.00	\$ 4,882.00 /
6	1	Front right tyre 300 ÷ 200 Δ	warped/cut	\$ 1,400.00	\$ 980.00 /
7	6	Front grille clips {nnv	necessary	\$ 40.00	\$ 40.00 x
8	1	Front no plate	necessary	\$ 80.00	\$ 80.00 x
9	1set	Front sports bumper parking sensor nnv	malfunction	\$ 1,400.00	\$ 1,400.00 x
10	1	Front right skirting Repair	warped/grazed	\$ 4,500.00	\$ 4,500.00 x
11	1	Front right skirting sealant x {nnv	necessary	\$ 80.00	\$ 80.00 x
12	10	Front right skirting clips x {nnv	necessary	\$ 60.00	\$ 60.00 x
				<u>\$ 12,612.00</u>	<u>\$ 12,192.00</u>
Total parts				\$ 42,953.10	\$ 42,533.10 2420

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount	
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right affected area parts.	\$ 1,400.00	\$ 1,200.00	400
2	To putty and spray painting front right affected portion.	\$ 1,400.00	\$ 1,200.00	600
3	To apply anti rust proofing to front right affected area.	\$ 120.00	\$ 100.00	60
4	To balance front right wheel.	\$ 50.00	\$ 30.00	/
5	To conduct wheel alignment.	\$ 120.00	\$ 100.00	60
6	To remove and install front right undercarriage parts.	\$ 350.00	\$ 300.00	100
7	To remove and install front power steering rack and pinion assy.	\$ 350.00	\$ 300.00	100
8	To erase and reset fault code if necessary.	\$ 150.00	\$ 120.00	X NV
9	Towing service.	\$ 100.00	\$ 80.00	50
Total labour :		\$ 4,040.00	\$ 3,430.00	1400

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 42,953.10	\$ 42,533.10
Total labour :	\$ 4,040.00	\$ 3,430.00
Total repair cost :	\$ 46,993.10	\$ 45,963.10

Adjusted Repair Cost (Lump Sum Repair)

\$ 36,800.00

14773.5
29% = 11800

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 15:26
Date Of Accident	16/02/2019 12:40
Exact Location Of Accident	JOO CHIAT PLACE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SBA113D
Insured/Policyholder	
Name Of Registered Owner	LIM BOON HUAT
NRIC No	S1583287H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98310138
Alternative Phone No	OTHERS-98310138
Vehicle Particulars	
Manufacturer	BMW
Model	X6 M AT ABS D/AB 4WD TC 5DR GAS/D SR HUD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V14087/VPE/R00
Cover Note Number	
Driver	
Name of Driver	LIM BOON HUAT
NRIC No	S1583287H
Date Of Birth	23/10/1963
Occupation	INDOOR
Date Of Driving Pass	04/07/1985
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98310138
Fax Number	
Contact Number	OTHERS-98310138
Email Address	NOEMAIL

Address	31 CHAPEL ROAD
Postcode	429537
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME9645A
Vehicle Make/Model/Colour	BLUECAR BLUECAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH HWEE LIN
NRIC/Passport Number	S7612300D
Contact Number	90492477
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

18 FEB 2013

IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SBA113D

B: SME 9645A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary at Joo Chuan place, in front of
 ferret bean tan mee store, car park lot No. 32.
 Vehicle B was travelling at Joo Chuan place. Suddenly vehicle B
 swung ~~suddenly~~ in and hit my vehicle, and push it moving ~~forward~~ to
 I come out found that vehicle B hit my vehicle from driver side
 and in the result, my vehicle can't move.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

18 FEB 2010

IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4

Reporting Centre Singapore 415933
 Name: Tel: 67416697
 NRIC/FIN No.: Fax: 67492305
 Email: vackb@singnet.com.sg

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0030 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
18th: 58550000 / 627 Reg. No.: M400017795

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MVA 319022449 / VAC - BUKIT Vehicle Registration No: SBA 113D
Name (as shown in NRIC) : Lim Boon Huat NRIC/FIN/Passport No : S1583287H
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 31 Chapel Road (429537) Singapore ()
Contact (Tel) : _____ Mobile No. : 9831038
Email Address : NA
Date of Accident : 16/02/2019 Time of Accident : 12:40
Place of Accident : Joo chiat place
Insurance Company : liberty insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Please amend Accident Time to : 12:40pm

X [Signature]
Policyholder / Driver's Signature
Date: _____

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre Personnel's Signature
Name: _____
Tel: 67416698
Fax: 67492305
NRIC/FIN No: _____
Date: _____
Email: vackb@singnet.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 14:41
Date Of Accident	16/02/2019 13:00
Exact Location Of Accident	72 JOO CHIAT PLACE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME9645A
Insured/Policyholder	
Name Of Registered Owner	BLUECAR EAST ASIA PTE LTD
Co Reg No	201617259H
Email Address	CLAIMS@BLUESG.COM.SG
Mobile Phone No	(LOCAL) +65-97365541
Alternative Phone No	Office-31637900

Vehicle Particulars

Manufacturer	BLUECAR
Model	BLUECAR-(A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCP/18-000001
Cover Note Number	

Driver

Name of Driver	KOH HWEE LIN
NRIC No	S7612300D
Date Of Birth	01/05/1976
Occupation	INDOOR
Date Of Driving Pass	31/03/1998
Driving Experience	20 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90492477

Fax Number	
Contact Number	
EEmail Address	HL_KOH@YAHOO.COM.SG
Address	BLK 166 HOUGANG AVE. 1 #13-1572
Postcode	530166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer circumstance to sketch plan.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBA113D
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

31 Mar 1998

Licence No: 57612306D



Driving License

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Portrait photo of a woman

License Number: **S7612300D**

Name: **KOH HWEE LIN**

Birth Date: **01 May 1976**

Issue Date: **26 Mar 2003**

Barcode: **000329621A**

Identification Card



Identification Card



Accident Photo



Accident Photo





































...CLAIM SUBFOLDER...(Pending for Survey Report)











CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Feb 2019		20 Feb 2019 09:42 Edit Adj Rpt	S\$11,800.00 Edit Estimates	S\$11,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BLUECAR EAST ASIA PTE LTD , Co. Reg. No.: 201617259H								
Main Claimant:	LIM BOON HUAT , ID: S1583287H								
Vehicle Reg. No.:	SBA113D	Date of Loss:	16/02/2019 13:00 - :59 [85 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 585367	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SME9645A	Policy No. (Claimant):							
		Excess:							
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2019]								
Driver/Custodian (Insured):	KOH HWEE LIN (), NRIC: S7612300D, Tel: +6590492477 Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEAR. CONTACT: FABIEN TEO/YI XIN 9839 1666/9839 1555								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (19/06/2019): Report Send Back Alerts - SBA113D (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBA113D (585367)**
[SME9645A]
TP
LIM BOON HUAT
Feb 16 2019 1:00PM
[BLUECAR EAST ASIA PTE LTD]
Xin Yun Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/02/19 13:48	Accident Statement <small>From: SC - Reg. No: SME9645A, Claimant: BLUECAR EAST ASIA PTE LTD</small>	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/02/19 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/02/19 13:48	SBA113D TP E-FILE REPORT	 Load PDF	
2	19/02/19 13:48	EMAIL FROM TP TO ARRANGE SURVEY	 Load PDF	
3	19/02/19 15:54	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
4	30/05/19 15:26	LOD with supporting documents - SBA113D	 Load PDF	
5	30/05/19 15:26	TPD SBA113D - SURVEY REPORT & INVOICE	 Load PDF	
6	30/05/19 15:26	TPD SBA113D - COLOUR PHOTO A	 Load PDF	
7	30/05/19 15:26	TPD SBA113D - COLOUR PHOTO B	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/19 12:28	Colour Photo	 Load PDF	
2	09/07/19 12:28	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003183/GSD3E2-1

Date: 09/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29112616MCY

Claimant Vehicle
No : SBA113D

Insured Vehicle No : SME9645A

Date of Loss: 16/02/2019

Nature of Claim: TP

Claim No: 585367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBA113D

Make & Model: BMW X6, 4.4 (M)

Reg. Date: 23/12/2011 (Man. Year: 2011)

Colour: White

Engine Capacity: 4395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 20150001S63B44A

Chassis No: WBSGZ02040LJ89096

Odometer: 98960 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/25Z R23

Rear Tyre Size: 315/25Z R23

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,953.10	13,373.50	29,579.60	68.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,400.00	2,640.00	65.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,993.10	14,773.50	32,219.60	68.56
Approved Total (Overridden) (S\$)		11,800.00		
Nett Amount (S\$)	46,993.10	11,800.00	35,193.10	74.89

INSPECTION

Date of Assignment: 20/02/2019

Date Inspected: 20/02/2019 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23
PREMIER @KAKI BUKIT
Singapore 415675

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2019)
Parts:	M1-SUV	BMW X6 4.4 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBA113D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SPORTS BUMPER WITH PDC	Grazed / Cut / Warped	4,800.00 FL	*2,400.00 FL
2	1		*FRONT BUMPER RIGHT RETAINER	Not Necessary	241.00 FL	*- FL
3	1		*FRONT BUMPER RIGHT BRACKET	Not Necessary	158.00 FL	*- FL
4	2		*FRONT BUMPER TOW COVER	Not Necessary	132.00 FL	*- FL
5	1		*FRONT BUMPER LOWER COVER	Cracked	1,285.00 FL	*640.00 FL
6	1		*FRONT BUMPER LOWER SIDE INNER GARNISH	N/S Not Necessary /O/S Cracked	287.00 FL	*140.00 FL
7	1		*FRONT BUMPER LOWER SIDE GARNISH	N/S Not Necessary /O/S Cracked	382.00 FL	*190.00 FL
8	2		*FRONT GRILLE ASSY	Not Necessary	856.00 FL	*- FL
9	1		*FRONT RIGHT FENDER	Dented / Warped	2,850.00 FL	*1,400.00 FL
10	1		*FRONT RIGHT FENDER UPPER COWLING	Not Necessary	395.00 FL	*- FL
11	1		*FRONT RIGHT FENDER LOWER COWLING	Not Necessary	395.00 FL	*- FL
12	1		*SET FRONT RIGHT FENDER INNER SHIELD	Cracked	382.00 FL	*190.00 FL
13	1		*FRONT RIGHT ELECTRIC SUSPENSION ASSY	Malfunction	3,660.00 FL	*1,800.00 FL
14	1		*FRONT RIGHT LOWER ARM	Bent	950.00 FL	*480.00 FL
15	1		*FRONT RIGHT BRAKE DISC	Not Necessary	387.00 FL	*- FL
16	1		*FRONT RIGHT BRAKE AIR DUCT	Not Necessary	250.00 FL	*- FL
17	1		*FRONT RIGHT UPPER ARM	Bent	1,050.00 FL	*525.00 FL
18	1		*FRONT RIGHT WHEEL HUB BEARING	Bent	515.00 FL	*250.00 FL
19	1		*FRONT RIGHT CAMBER ARM	Not Necessary	760.00 FL	*- FL
20	1		*FRONT RIGHT TRAILING ARM	Not Necessary	720.00 FL	*- FL
21	1		*FRONT RIGHT TRAILING LINK	Not Necessary	320.00 FL	*- FL
22	1		*FRONT RIGHT STABILIZER LINK	Bent	315.00 FL	*315.00 FL
23	1		*FRONT RIGHT DRIVE SHAFT	Not Necessary	3,813.00 FL	*- FL
24	1		*FRONT POWER STEERING RACK AND PINION ASSY	Malfunction / Broken	6,400.00 FL	*3,200.00 FL
25	1		*FRONT SPORTS BUMPER WIRE MESH	Not Necessary	450.00 FL	*- FL
26	1		*FRONT SPORTS BUMPER CLIPS (16PCS)	Necessary	80.00 FS	*50.00 FS
27	8		*FRONT RIGHT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
28	8		*FRONT RIGHT FENDER UPPER COWLING CLIPS	Necessary	30.00 FS	*20.00 FS
29	8		*FRONT RIGHT FENDER LOWER COWLING CLIPS	Necessary	30.00 FS	*20.00 FS
30	1		*FRONT RIGHT SPORTS RIM	Grazed / Dented / Warped	4,882.00 FS	*1,800.00 FS
31	1		*FRONT RIGHT TYRE	Warped / Cut	1,400.00 FS	*500.00 FS
32	6		*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*FRONT NO PLATE	Not Necessary	80.00 FS	*- FS
34	1		*SET FRONT SPORTS BUMPER PARKING SENSOR	Not Necessary	1,400.00 FS	*- FS
35	1		*FRONT RIGHT SKIRTING	Repair	4,500.00 FS	*- FS
36	1		*FRONT RIGHT SKIRTING SEALANT	Not Necessary	80.00 FS	*- FS
37	10		*FRONT RIGHT SKIRTING CLIPS	Not Necessary	60.00 FS	*- FS
38	1		*FRONT RIGHT BRAKE DISC PLATE	Not Necessary	185.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	44,550.00	13,950.00
- List Item Discount on L Items 5.00/5.00% (\$\$)		1,596.90	576.50

Total Parts (\$\$)	42,953.10	13,373.50
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT AFFECTED AREA PARTS	New	1,400.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AFFECTED PORTION	New	1,400.00	600.00
3	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	120.00	60.00
4	TO BALANCE FRONT RIGHT WHEEL	New	50.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	350.00	100.00
7	TO REMOVE AND INSTALL FRONT POWER STEERING RACK AND PINION ASSY	New	350.00	100.00
8	TO ERASE AND RESET FAULT CODE IF NECESSARY	New	150.00	0.00
9	TOWING SERVICES	New	100.00	50.00
Gross Labour Cost (S\$)			4,040.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >