

ASS. REC. BY:

REF:

C/AIG/190/0876 /kt d3ⁿ²

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Hui Yinn

of

AIG

Date/Time:

19/6/19 @ 9.41am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 4821J

Insured:

SLZ 90674

at Workshop in:

Trust Autoworks

Tel:

9108 2728.

of

Blk 5035 #01-345 AMK Ind. park 2

Policy No:

Claim No:

5996734802591

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

15/06/19

CA / REV / REP. / REV 24 HRS

24/6/19

H.O.D. Endorsement:

Date/Time:

11:20am @ 19/6/19

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time

Action/Instruction

SLR 4821J-X


SLZ 90674-NA/IM1/190/0641/24

D.O.A. 15/6/19

27/6 11pm @ 2200 email to confirm. (red: 3364.40:60%)

ASSIGNMENT

From: Date: 24/6/19
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLR 4821 J
 at Workshop m/s: Trust Autoworks
 of Blk 5035 # 01-345 Amk Ind. park 2
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 04 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS 1up
 Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLR 4821 J Vr Regn: 08 17
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or AI
 Make: Honda Civic C.C. 1498
 Colour: M. Black A/C: Insured / Std / NI / NA
 Sp. Reading: 41140 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: NR1HFC1660HT000285
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/50R17
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: Rear:
 R/Bal: 5 mm R/Bal: 6 mm
 L/Bal: 5 mm L/Bal: 6 mm
 D.O.A. 15/6/19 D.O.I. 24/6/19
 Survey held at:
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
o/s body
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 18 JUL 2019

Date/Time, File Pass k/2 12/7 Typist ☐ : Preli. Report ☒ : Final Report
 Date/Time, File Pass k/2
 Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: ☐ : Site Insp. (\$) ☐ : Interview (\$) ☐ : Tech. Insp. (\$) ☐ : Weekend (\$) ☐ : Other (\$)
 Report Format: TP
 Lump Sum / H.R.G. 2260/-
 Survey Fee: 250
 Transportation: 11
 Photos:
 Notes:
 TOTAL: 261

PRE-REPAIR INSPECTION REQUEST – SLR4821J vs SLZ9067U (OI) on D.O.A.: 15/06/2019

From: Hor, Yinnul
To: 'assignments@kkkauts.com'; Admin A (admin-a@kkkauts.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor
Sent: 6/19/2019 9:41:56 AM
Attachments: 20190618133033724.pdf 20190618133033724.pdf

Hi,

Please refer to the enclosed request from **Chia S Arul LLC**.

Claim no : 5996734802SG003
Case Owner : Chan Kian Meng

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
Claim Adjuster II, Singapore PNOL, Claims Operations – Auto
yinnul.Hor@aig.com | www.aig.ae

From: Kelley Choong [mailto:kelley@chiaarul.com]
Sent: Tuesday, June 18, 2019 8:48 PM
To: Azlan, Syazairdina
Cc: Jerone@chiaarul.com; Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Hor, Yinnul
Subject: [EXTERNAL] Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ9067U AND SLR4821J ON 15/06/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Our client is agreeable to Kenneth Kong of LKK.

Kelley

Sent from my iPhone

On 18 Jun 2019, at 16:22, Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-06-25 03:22 CDT to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply do not

knowed by Proofpoint Encryption, Copyright © 2004-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

From: Syazairdina.Azlan@aig.com
To: jerone@chiaarul.com, kelley@chiaarul.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com, Yinnul.Hor@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLZ9067U AND SLR4821J ON 15/06/2019
Date: Tue, 18 Jun 2019 08:22:10 +0000
Without Prejudice

Your Reference : SLR 4821J (kc/jr)
Our Reference : 5996734802SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syazla Indina Azlan

AIG

Express Claims Adjuster II, Singapore F&O, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

SyazlaIndina.Azlan@aig.com | www.aig.sg

From: AIG SGP, Claims-Survey
Sent: Tuesday, June 18, 2019 4:05 PM
To: Azlan, SyazlaIndina
Subject: FW: [EXTERNAL] PRS Notice for SLR 4821J

From: Jerone [mailto:jerone@chiaarul.com]
Sent: Tuesday, June 18, 2019 4:02 PM
To: AIG SGP, Claims-Survey
Cc: 'Kelley Choong'
Subject: [EXTERNAL] PRS Notice for SLR 4821J

This message is from an external sender; be cautious with links and attachments.

O/Ref: SLR 4821J (kc/jr)
Y/Ref: TBA

Dear All,

We refer to the above.

Kindly find enclosed a copy of the PRS Notice for your attention.

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

Mr. Jerone Lee (Paralegal)
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

Our Ref : SLR 4821J (kc/jr)

Your Ref :

18 June 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.
Singapore

BY EMAIL

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : LIM JUN WEN LEWIS
ACCIDENT INVOLVING SLR 4821J & SLZ 9067U ALONG SERANGOON
GARDEN CARPARK ON 15 JUNE 2019

1. We act for LIM JUN WEN LEWIS, the owner of motor vehicle no. SLR 4821J, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SLZ 9067U for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Trust Autoworks at Blk 5035 #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538 and kindly arrange with Mr Anthony Cheong at T: 9108 2728.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to kelley@chiaarul.com.

Yours faithfully,

MR ARULCHELVAN S

cc: Client (By email)

Enquire Vehicle & Owner Information (Vehicle No. SLZ9067U As At 15 Jun 2019 / 22:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: KC

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S8830146Z

Owner Name: AQILAH BINTE JUMA'IN

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 234

Registered Street Name: ANG MO KIO AVENUE 3

Registered Unit No.: # 10 - 1128

Registered Building Name: -

Registered Postal Code: 560234

Current Vehicle Details

Vehicle No.: SLZ9067U

Make Description/Model: MAZDA / MAZDA3 SEDAN 1.5 AT LED EU6

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for existing and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/06/2019 10:14
 Date Of Accident 15/06/2019 22:00
 Exact Location Of Accident SERANGOON GARDEN CARPARK
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR4821J
 Insured/Policyholder
 Name Of Registered Owner LIM JUN WEN LEWIS
 NRIC No S8939318C
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96176317
 Alternative Phone No OFFICE-96176317

Vehicle Particulars
 Manufacturer HONDA
 Model CIVIC 1.5 TURBO VTiS SR
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company
 Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MU008499
 Cover Note Number

Driver

Name of Driver LIM JUN WEN, LEWIS
 NRIC No S8939318C
 Date Of Birth 01/11/1989
 Occupation INDOOR
 Date Of Driving Pass 05/01/2015
 Driving Experience 4 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96176317
 Fax Number
 Contact Number OFFICE-96176317
 Email Address NOEMAIL

Address BLK 415 YISHUN AVENUE 11
#04-309
Postcode 760415
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILE PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY PARKED ONTO THE CARPARK LOT. WHEN I CAME BACK, RETRIEVE MY VEHICLE AND SAW THE VEHICLE B REVERSED HIS VEHICLE INTO OPPOSITE OF THE CARPARK LOT AND GRAZED ONTO MY VEHICLE RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLZ9057U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
SIAA/PTA No.:

Accident Sketch Plan

SKETCH PLAN

Swanton Garden (not part)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to sketch plan.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Person's Signature
Name:
NIC/TIN No.:

Trust Autoworks

Blk 5035 #01-369 Ang Mo Kio Industrial Pk 2 Singapore 569538
H/p 91082728

Lim Jun Wen Lewis
Blk 415 Yishun Ave 11
#04-309
Singapore 760415

Vehicle No : SLR 4821 J
Make : Honda Civic
Year : 2017

*Not Authored
11 Sep 2006
Repair After Paint
4 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s door assy
1 pc	Front o/s door weatherstrip
1 pc	Front o/s door frame black sticker
1 pc	Front o/s door inner trim board
1 pc	Front o/s door regulator/motor assy
1 pc	Front o/s door inner lock
1 pc	Front o/s door outer lock
1 pc	O/S rocker panel garnish
1 pc	Rear o/s door assy

<i>Billway</i>	\$985.70	✓
<i>in</i>	\$155.30	X
<i>in</i>	\$75.00	—
<i>in</i>	\$580.30	X
<i>nil/in</i>	\$385.70	✓
<i>in</i>	\$172.40	X
<i>in</i>	\$517.80	X
<i>Butterfly</i>	\$553.20	X
<i>in</i>	\$905.10	X
	4330 1/2	
Less 20 %	\$866.10	
	\$3,464.40	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting	\$900.00	<i>4501</i>
To putty & spray paint on accident affected portion.	\$900.00	<i>6001</i>
Check/reconnect wiring.	\$30.00	<i>201</i>
To spray anti rust on accident affected portion.	\$120.00	<i>301</i>
Remove/refit front & rear n/s door glass, mechanism, inner lock, trim board to new door.	\$150.00	<i>601</i>
Total	\$5,564.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19010876/KTD3N2

Date: 22/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No : SLR4821J Insured Vehicle No : SLZ9067U
 Date of Loss: 15/06/2019 Nature of Claim: TP Claim No: 5996734802SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR4821J
 Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A) Engine No: L15B72453830
 Reg. Date: 16/08/2017 (Man. Year: 2017) Chassis No: MRHFC1660HT000285
 Colour: Metallic Black Odometer: 41140 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,464.40	1,599.68	1,864.72	53.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,160.00	940.00	44.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,564.40	2,759.68	2,804.72	50.40
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	5,564.40	2,200.00	3,364.40	60.46

INSPECTION

Date of Assignment: 19/06/2019
 Date Inspected: 24/06/2019 Inspected At: Trust Autoworks (HQ)
 BLK 5038 ANG MO KIO INDUSTRIAL
 PARK 2, #01-405 SINGAPORE 569541
 Singapore 569541

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT O/S DOOR ASSY	Bent / Warped	985.70 FL	*985.70 FL
2	1	*FRONT O/S DOOR WEATHERSTRIP	Serviceable	155.30 FL	*- FL
3	1	*FRONT O/S DOOR FRAME BLACK STICKER	Necessary	75.00 FL	*75.00 FL
4	1	*FRONT O/S DOOR INNER TRIM BOARD	Serviceable	580.30 FL	*- FL
5	1	*FRONT O/S DOOR REGULATOR/MOTOR ASSY	Distorted / Jammed	385.70 FL	*385.70 FL
6	1	*FRONT O/S DOOR INNER LOCK	Repair	172.40 FL	*- FL
7	1	*FRONT O/S DOOR OUTER LOCK	Repair	517.80 FL	*- FL
8	1	*O/S ROCKER PANEL GARNISH	Buckled / Dented	553.20 FL	*553.20 FL
9	1	*REAR O/S DOOR ASSY	Repair	905.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **4,330.50** **1,999.60**
 - List Item Discount on L Items 20.00/20.00% (S\$) 866.10 399.92

Total Parts (S\$) **3,464.40** **1,599.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING.	New	900.00	450.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.	New	900.00	600.00
3	CHECK / RECONNECT WIRING.	New	30.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	New	120.00	30.00
5	REMOVE / REFIT FRONT & REAR N/S DOOR GLASS, MECHANISM, INNER LOCK, TRIM BOARD TO NEW DOOR.	New	150.00	60.00
Gross Labour Cost (S\$)			2,100.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >