

ASS. REC. BY: Pome

REF:

ASM(AXA)

W842/11(P)

0190c

ASSIGNMENT

From:

Date:

25/6/19

Estimated Cost:

Veh No:

SLE 7778A

Yr Regn: 2017 / P63

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLE 7778A

Make:

MORCONE PAVZ ALL 250

C.C.

1991

at Workshop m/s

Cycle & Camcorder

Colour:

Blue

A/C: Insured / Std / NI / NA

of

188 pandan loop

Sp. Reading

36255

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

WDC2533462F178881

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

After loan

Modi: Nil / Rim / STD A/Rim or

(Policy Condition)

Go chee cheng

91817717



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: 255/50R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

175K

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

17/06/19

D.O.I.

25/06/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CYCLE

CA / REV / REP. / 24 HRS

wup

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.E. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)