

ASS. REC. BY:

REF: CS35mu 19010907 / R1cd3

Special Instruction:

Survivor: Rusu**ASSIGNMENT (Office)**From (Person): Gmoh Pau Loong of SmoDate/Time: 20-6-19 11:08a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SN 1850 PInsured: GP 1199Lat Workshop m/s Sheng H Lai

Tel:

of ND 2 Kati Bukit Ave 2 #01-36Policy No: D18MTPCVE004535Claim No: CM7D1902947

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17-6-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20-6-19 11:26a.mPerson Contacted: Mr LowVehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SN 1850 P XGP 1199L - NA / INC 17019780 / 24D.O.A - 17/10/2017Dismantle: 20/6/2019After repair: 27/6/2019

Springer Form

REF:

08289


(OE XPIRY: 2029/FEB)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No. SJN 1850P
 at Workshop m/s SHANH LILA
 of NO. 2 KAKI BUKIT RUK 2 #01-36
 Insured: SMO
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 9 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJN 1850P Yr Regn: 2009 / FEB
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA VIOS 1.4 c.c. 1497
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 165699 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MROS3HY9305100161
 Gen. Cond: Good (Fair) / Poor / Burnt
 Steering: (order) / Jammed / Leaked / Burnt or
 Brake: (order) / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MD / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. <u>17/06/19</u>		D.O.I. <u>20/06/19</u>
Survey held at <u>SHANH LILA</u>		
Des. of Damages: <u>(Frt)</u> / <u>(Rear)</u> / O/S / N/S / U/C / Rooftop or		

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimated repair range \$7,000 - \$8,000

RECEIVED 1 JUL 2019

John
28/6/2019.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

) Photos

) Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jun 2019		20 Jun 2019 11:08 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All
CLAIM SUBFOLDER DETAILS								[Created by insurer]
Insured:		COMMAND-AIR PTE LTD, Co. Reg. No.: 199200538H						
Main Claimant:		LOW PEK TOH, ID: S2590828G						
Vehicle Reg. No.:		SJN1850P		Date of Loss:		17/06/2019 11:00 - :59		
Claim Type:		TP / CMTD1902947		Policy/Cover Note No.:		D18MTPCVE003585 (Comprehensive)		
Vehicle Reg. No. (Insured):		GP1199L		Policy No. (Claimant):				
				Excess:				
Repairer:		Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222						
Handling Insurer:		Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]						
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/07/2019]						
Driver/Custodian (Insured):		THAIYANAYAGAM ARUMUGAM (), NRIC: G8455359Q, Tel: +6586465301 Email:						
Adj Asg. Remarks:		WS: MR LOW 6842 0302						
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail
There are no mail for this case.								
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On Done?
No results.								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2019 16:01
Date Of Accident	17/06/2019 13:00
Exact Location Of Accident	WOODLANDS LOOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN1850P
Insured/Policyholder	
Name Of Registered Owner	LOW PEK TOH
NRIC No	S2590828G
Email Address	JOANNELEEHS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97946568
Alternative Phone No	OFFICE-86938668

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01012533
Cover Note Number	

Driver

Name of Driver	LOW PEK TOH
NRIC No	S2590828G
Date Of Birth	27/10/1956
Occupation	INDOOR
Date Of Driving Pass	27/10/1997
Driving Experience	21 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97946568
Fax Number	
Contact Number	OFFICE-86938668
Email Address	JOANNELEEHS@GMAIL.COM

Address

662 WOODLANDS RING RD #06-212 S730662

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GP1199L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver THAIYANAYAGAM ARUMUGAM
NRIC/Passport Number
Contact Number 8646531
Address NA
NA
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

LOO

Policyholder's Signature
Date & Time:

LOO


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SJN1850 P.

B: GP1199L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was parked outside my office. at about 7.45 am, everything was intact & no damage to my car. At around 1300, someone inform my supervisor that my car was being hit. I immediately came out to check, the driver of vehicle B wait my for me, and he told he reversed & hit onto the rear of my car, the impact push my car forward & hit the railway.

INSURER: Sampo
VEHICLE: SJN1850 P.
DOA: 17/6/19.
CLAIM TYPE: TP.
WORKSHOP: Sany & Son

DECLARATION

I/We declare the foregoing particulars are true in every respect.

LOW

LOW

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048523
Tel: 6461 0555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 193005400E | GST Reg. No.: M200903195

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTPV01012533
Insured : LOW PEK TOH
Motor Car (Registration No.) : SJN1850P
Cover : Comprehensive - ExcelDrive GOLD
Policy Commencement Date : 06 AUGUST 2018 00:00
Policy Expiry Date : 05 AUGUST 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$500 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 11 JULY 2018 11:15

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11M04705 & MWP INSURANCE AGENCY CI Code: 22A FR4D05Z4_ML0BHZA

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0828G
Vehicle Details	
Vehicle No.:	SJN1850P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1NZX864168
Chassis No.:	MR053HY9305100161
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,472.00
Original Registration Date:	06 Feb 2009
First Registration Date:	06 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$13,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$25,727.00
COE Rebate Amount:	\$24,685.00
Total Rebate Amount:	\$24,685.00

The information contained herein is correct as at 01 Jul 2019

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2590828G

Name
LOW PEK TOH




刘碧桃

Race
CHINESE

Date of Birth
27-10-1956

Country of Birth
JONORE

Sex
F



REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Number: S2590828G

LOW PEK TOH

Birth Date: 27 Oct 1956

Issue Date: 27 Oct 2003





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

27 Oct 1997

NP 428A

Licence No: S2590528G

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2019		20 Jun 2019 11:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	COMMAND-AIR PTE LTD, Co. Reg. No.: 199200538H			
Main Claimant:	LOW PEK TOH, ID: S2590828G			
Vehicle Reg. No.:	SJN1850P	Date of Loss:	17/06/2019 11:00 - :59 [124 Months and 11 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1902947	Policy/Cover Note No.:	D18MTPCVE003585 (Comprehensive)	
Vehicle Reg. No. (Insured):	GP1199L	Policy No. (Claimant):		
		Excess:		
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/07/2019]			
Driver/Custodian (Insured):	THAIYANAYAGAM ARUMUGAM (), NRIC: G8455359Q, Tel: +6586465301 Email:			
Adj Asg. Remarks:	WS: MR LOW 6842 0302			

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN1850P (CMTD1902947)**
[GP1199L]
TP
LOW PEK TOH
Jun 17 2019 11:00AM
[COMMAND-AIR PTE LTD]
Sheng Li Lai

Upload Documents Upload Photos Compose New Letter
















































View View in Browser ▼










































Assessment Reports

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	20/06/19 11:08	Accident Statement From: SC - Reg. No: GP1199L, Claimant: COMMAND-AIR PTE LTD		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	01/07/19 08:50	General View		Load JPG	
2	01/07/19 08:50	General View		Load JPG	
3	01/07/19 08:50	General View		Load JPG	
4	01/07/19 08:50	General View		Load JPG	
5	01/07/19 08:50	General View		Load JPG	
6	01/07/19 08:50	General View		Load JPG	
7	01/07/19 08:50	General View		Load JPG	
8	01/07/19 08:50	General View		Load JPG	
9	01/07/19 08:50	General View		Load JPG	
10	01/07/19 08:50	General View		Load JPG	
11	01/07/19 08:50	General View		Load JPG	
12	01/07/19 08:50	General View		Load JPG	
13	01/07/19 08:50	General View		Load JPG	
14	01/07/19 08:50	General View		Load JPG	
15	01/07/19 08:50	General View		Load JPG	
16	01/07/19 08:50	General View		Load JPG	
17	01/07/19 08:50	General View		Load JPG	
18	01/07/19 08:50	General View		Load JPG	
19	01/07/19 08:50	General View		Load JPG	
20	01/07/19 08:50	General View		Load JPG	
21	01/07/19 08:50	General View		Load JPG	
22	01/07/19 08:50	General View		Load JPG	
23	01/07/19 08:50	General View		Load JPG	
24	01/07/19 08:50	General View		Load JPG	
25	01/07/19 08:50	General View		Load JPG	
26	01/07/19 08:50	General View		Load JPG	
27	01/07/19 08:50	General View		Load JPG	
28	01/07/19 08:50	General View		Load JPG	
29	01/07/19 08:50	General View		Load JPG	
30	01/07/19 08:50	General View		Load JPG	
31	01/07/19 08:50	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
44	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
50	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
51	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
52	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
53	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
55	01/07/19 08:50	General View	 Load JPG	<input checked="" type="checkbox"/>
56	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	01/07/19 08:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
80	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	01/07/19 08:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	01/07/19 08:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	20/06/19 10:40	Third Party E-filed GIA report(M-SI)	 Load PDF	
2	20/06/19 11:07	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset Save Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19010907/R1CD3S2
Date: 02/07/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPCVE003585
Claimant Vehicle No : SJN1850P **Insured Vehicle No :** GP1199L
Date of Loss: 17/06/2019 **Nature of Claim:** TP **Claim No:** CMTD1902947

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN1850P** Engine No: 1NZX864168
 Make & Model: TOYOTA VIOS, 1.5 (A) Chassis No: MR053HY9305100161
 Reg. Date: 06/02/2009 (Man. Year: 2009) Odometer: 165699 km
 Colour: Black
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/06/2019
 Date Inspected: 20/06/2019 Inspected At: Sheng Li Lai (KAKI BUKIT)
 Estimated Period of Repair: 9.0 days NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT
 Singapore 417921

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/2/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2019)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1850P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >