

22/03/2002

ASS. REC. BY:

REF:

28/MSG19010912/KY/d302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

20.6.19 16.33 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFU 66 D

Insured:

SGJ 3600M

at Workshop m/s

Seng Kin motor

Tel:

6453638

of

Block 1, Sin Ming Industrial Estate #01-13/

Policy No:

804582748mx

Claim No:

596972

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14.6.19

21.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

20.6.19 4.38 p.m

Person Contacted:

Miss Lee

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

25/6/19@ 2.43pm revised to Katherine Wong via Megan.

18/7 11pm 839001 email & confirm (Red \$ 7540, 39%)

(08/11/13)
ASS. REC. BY:


REF MSIG

ASSIGNMENT

From: _____ Date: 21.6.2019
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SFU 66D
at Workshop m/s Seng Kin Motor
of Block 1, Sin ming Industrial Estate #01-13
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 06 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
11/21
CA / REV / REP. / 24 HRS "up"
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SFU 66D Yr Regn: 81, CP
Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Bmw 525i C.C. 2497
Colour: M. D. Blue A/C: Insured / Std / NI / NA
Sp. Reading: 139099 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBANU 5202008 89662
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Rim or
Tyre Size: F: 245/45R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>14/8/19</u>	D.O.I.	<u>21/8/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 AUG 2019

14/8/2019

Date/Time, File Pass to?

1) 15/8/2019

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : MER-TP

Lump Sum / I.B.F. (\$) 3900)

190
11
161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2019		20 Jun 2019 16:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	NG LEE CHUAH, ID: S1606257Z		[Created by insurer]
Main Claimant:	Tay Lee Lin, ID: S8001319A		
Vehicle Reg. No.:	SFU66D	Date of Loss:	14/06/2019 17:00 - :59 [126 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 596972	Policy/Cover Note No.:	80458874QMX (Comprehensive) Coverage: 13/07/2018 - 12/07/2019
Vehicle Reg. No. (Insured):	SGJ3600M	Policy No. (Claimant):	
		Excess:	
Repairer:	Seng Kin Motor Works (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636, 575636 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/06/2019]		
Adj Asg. Remarks:	on WP. to arrange ASAP. Liab: dispute (OI NR) Tp agree on SJE - assign LKK Auto. Contact: 64536238		

ASSOCIATED MAIL RECEIVED

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No	: SGJ3600M	Accident Date	: 14/06/2019
TP Vehicle No	: SFU66D	Assignment Date	: 20/06/2019
Make	: BMW 525I	Est. Duration of Repair	: 6.00
Date of Inspection	: 21/06/2019		
Inspection At	: SENG KIN MOTOR WORKS (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636 SINGAPORE 575636		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,440.00
Revised Amount	:S\$	4,983.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,983.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1319A

Vehicle Details

Vehicle No.: SFU66D
Vehicle to be Exported: Yes
Intended Deregistration Date: 24 Jun 2019
Vehicle Make: B.M.W.
Vehicle Model: 525i XL
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: 78564370N52B25AF
Chassis No.: WBANU52020CZ89662
Maximum Power Output: 160.0 kW (214 bhp)
Open Market Value: \$51,117.00
Original Registration Date: 28 Nov 2008
First Registration Date: 28 Nov 2008
Transfer Count: 1
Actual ARF Paid: \$51,117.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Nov 2028
COE Category: E - Open Category
COE Period(Years): 10
PQP Paid: \$32,121.00
COE Rebate Amount: \$30,274.00
Total Rebate Amount: \$30,274.00

The information contained herein is correct as at 24 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/06/2019 09:22
Date Of Accident	14/06/2019 17:50
Exact Location Of Accident	PAYA LEBAR ROAD TOWARDS PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU66D
Insured/Policyholder	
Name Of Registered Owner	TAY LEE LIN
NRIC No	S8001319A
Email Address	PEKO08@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92222273
Alternative Phone No	OTHERS-92222273

Vehicle Particulars

Manufacturer	BMW
Model	525i-2.5 XL (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0012178
Cover Note Number	

Driver

Name of Driver	TAY LEE LIN
NRIC No	S8001319A
Date Of Birth	14/01/1980
Occupation	INDOOR
Date Of Driving Pass	13/09/1999
Driving Experience	19 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92222273
Fax Number	
Contact Number	OTHERS-92222273
Email Address	PEKO08@HOTMAIL.COM

Address	7 NEWTON ROAD #18-02
Postcode	307945
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NATHAN BENJAMIN TAN ZE RUI
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ3600M
Vehicle Make/Model/Colour	HYUNDAI ELANTRA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG QI MING
NRIC/Passport Number	S9220057D
Contact Number	97554180
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

15 JUN 2019

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H

Sketch Plan Pg. 2

SKETCH PLAN

Daya Lebar Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

14 June 2019, 5:50pm. on my Lebar Road

I'm ~~there~~ driving straight on my lane towards PIE (Tune) when suddenly there's a bang on the right side of my car. I bring my vehicle to a stop, come out from the vehicle and realized what another car had bang into the right side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 15 JUN 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:

Jenny Lim
S6927273H



Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532961 FAX: 64580453
B. Reg. No. 111182/OOW

TAY LEE LIN
7 NEWTON ROAD #18-02
SINGAPORE 307945

Attention : Motor Claim Department
Contact : 92222273

Handwritten signature and date 25/6/19

Estimate : ES000120

*Not Authorized
11/10/19 83900/
Resurvey After Paint*

Date : 24/06/2019
Vehicle Num. : SFU 66D
Make/Model : BMW 525I
Chassis/Eng# : WBANU52020CZ89662
Accident Date : 14/06/2019
Claim No. :
Reference : TP/SK/MSIG/2019/008
Policy No. : M0012178

6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|--------------------------|--|--|
| 1. | 1 PCE | LIST ITEMS : | | |
| 2. | 1 PCE | FRT. O/S DOOR | | |
| 3. | 1 PCE | FRT. O/S DOOR RUBBER | | |
| 4. | 1 PCE | REAR O/S DOOR | | |
| 5. | 1 PCE | REAR O/S DOOR RUBBER | | |
| 6. | 1 PCE | O/S ROCKER PANEL GARNISH | | |

List Total S\$:

LABOUR :

LABOUR CHARGES TO REMOVE FRT. O/S DOOR GLASS,
DOOR LOCK MECHANISM, TRANSFER PRTS TO NEW DOOR.

LABOUR CHARGES TO REMOVE REAR O/S DOOR GLASS, DOOR
DOOR LOCK MECHANISM, TRANSFER PRTS TO NEW DOOR.

LABOUR CHARGES TO KNOCK & STRAIGHTEN REAR O/S FENDER,
ROCKER PANEL AND DISTORTED PARTS. TO REMOVE BODY
DAMAGED PARTS, REPLACE & REFIX SAME,

TO PUTTY AND SPRAY PAINTING

TO SPRAY UNDERSEAL.

Labour Total S\$:

Handwritten calculations:
\$3270
-10% \$327.00
\$2943.00
B/L Warrant
10/8 SN \$160
1,650.00
160.00
1,620.00
160.00
390.00
3,980.00

80.00 *601*

80.00 *601*

1,000.00 *700*

1,200.00 *1000*

100.00 *601*

2,460.00

E. & O.E.

Total S\$: 6,440.00

Handwritten signature

for Seng Kin Motor Works

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2019		20 Jun 2019 16:33 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG LEE CHUAH , ID: S1606257Z								
Main Claimant:	Tay Lee Lin , ID: S8001319A								
Vehicle Reg. No.:	SFU66D	Date of Loss:	14/06/2019 17:00 - :59 [126 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 596972	Policy/Cover Note No.:	80458874QMX (Comprehensive) Coverage: 13/07/2018 - 12/07/2019						
Vehicle Reg. No. (Insured):	SGJ3600M	Policy No. (Claimant):							
		Excess:							
Repairer:	Seng Kin Motor Works (HQ) BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636, 575636 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/07/2019]								
Adj Asg. Remarks:	on WP. to arrange ASAP. Liab: dispute (OI NR) Tp agree on SJE - assign LKK Auto. Contact: 64536238								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFU66D (596972)
[SGJ3600M]
TP
Tay Lee Lin
Jun 14 2019 5:00PM
[NG LEE CHUAH]
Seng Kin Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	19/07/19 10:18	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: OD - Reg. No: SGJ3600M, Claimant: NG LEE CHUAH</small>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/19 14:43	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	13/08/19 14:33	LKK Auto Consultants Pte Ltd (HQ) General View	Load JPG	<input checked="" type="checkbox"/>
2	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/08/19 14:33	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/08/19 14:33	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
18	13/08/19 14:33	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
19	13/08/19 14:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	13/08/19 14:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	13/08/19 14:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	19/06/19 14:31	MSIG Insurance (Singapore) Pte. Ltd. (HQ) PRI from Seng Kin Motor Works	Load PDF	
2	19/06/19 14:31	SFU66D E-file report	Load PDF	
3	20/06/19 16:09	TP agree on SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010912/KQD3E2

Date: 16/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80458874QMX

Claimant Vehicle No : SFU66D

Insured Vehicle No : SGJ3600M

Date of Loss: 14/06/2019

Nature of Claim: TP

Claim No: 596972

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFU66D

Make & Model: BMW 525I, 2.5 XL (A)

Engine No: 78564370N52B25AF

Reg. Date: 28/11/2008 (Man. Year: 2008)

Chassis No: WBANU52020CZ89662

Colour: Metallic Dark Blue

Odometer: 139099 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17

Rear Tyre Size: 245/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,980.00	3,103.00	877.00	22.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,880.00	580.00	23.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,440.00	4,983.00	1,457.00	22.62
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	6,440.00	3,900.00	2,540.00	39.44

INSPECTION

Date of Assignment: 20/06/2019

Date Inspected: 21/06/2019 Inspected At:

Seng Kin Motor Works (HQ)
BLOCK 1, SIN MING INDUSTRIAL
ESTATE #01-131 SINGAPORE 575636
Singapore 575636

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2019)
Parts: 143	BMW 525i 2.5 XL (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFU66D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT O/S DOOR	Bent	1,650.00 F	*1,650.00 FL
2	1		*REAR O/S DOOR	Bent / Warped	1,620.00 F	*1,620.00 FL
3	1		*O/S ROCKER PANEL GARNISH	Repair	390.00 F	*- FL
4	1		*FRT O/S DOOR RUBBER (50%)	Necessary	160.00 FS	*80.00 FS
5	1		*REAR O/S DOOR RUBBER (50%)	Necessary	160.00 FS	*80.00 FS
					Sub Total (\$\$)	3,980.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	3,980.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE FRT O/S DOOR GLASS, DOOR LOCK MECHANISM, TRANSFER PRTS TO NEW DOOR	New	80.00	60.00
2	LABOUR CHARGES TO REMOVE REAR O/S DOOR GLASS, DOOR LOCK MECHANISM, TRANSFER PRTS TO NEW DOOR	New	80.00	60.00
3	LABOUR CHARGES TO KNOCK & STRAIGHTEN REAR O/S FENDER, ROCKER PANEL AND DISTORTED PARTS. TO REMOVE BODY DAMAGED PARTS, REPLACE & REFIX SAME	New	1,000.00	700.00
4	TO PUTTY AND SPRAY PAINTING	New	1,200.00	1,000.00
5	TO SPRAY UNDERSEAL	New	100.00	60.00
Gross Labour Cost (\$\$)			2,460.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >