

All diagnosis code

TEL:

FAX:

Employee, in charge:

E-mail:

Date and time: 7/1/2019 1:07:42 PM

Vehicle: Forester

VIN: JF1SJ5KC5JG104369

Model: 18MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			03734	228100	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 7/1/2019 1:10:37 PM

Vehicle: Forester

VIN: JF1SJ5KC5JG104369

Model: 18MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			03734	432900	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>