

CC 4, III 190 10953, T1 ga34

Surveyor:

MCH

DOI:

ASSIGNMENT

20/6/19

Date / Time:

20/6/19

Registered in Merimen:

20/6/19

Pre-assign / CCU / FTE

SAB4192y



Insured Vehicle No.:

CTPL

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

15/4/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

PRK 1060m



INSRS: WSP: Tel: Liability: RMKS:

HKL



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time

PRK 1060m - treatment 700-480 of y ; 10/6/19
summary of 15/11/19 19/10/19 y ; 10/15/19

STAGE DATE / PIC

- Non-Reporting ltr (1st):
- Non-Reporting ltr (2nd):
- Non-Reporting ltr (Final):
- Notification ltr (if non-pickup):
- Call OI:
- After call ltr to OI:

3/7/19

Conflicting version *
Red AVF from OI / evidence from TP.
Liability unclear send TP.

3/7/19

Send to all in merimen to req AVF from OI.
Final est 1st in via email.

5/8/19

OI AVF in. seek liability approval.
Rec WOR send TP (pending WOI)

21/8/19

LOD M (HKL pass RT type report).

14/9/19

Pending mandat approval (approved).

16/9

Settle @ \$3520.00 as per TP LOD, DV send (pendep DV in).

DV in (file pass Admin to close).

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Others:	<input checked="" type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 45

\$S 3400.00 (6 days) Reduction: \$3150.00 % 48

Email Call

FINAL SETTLEMENT

Date/Time: 4/9/19/9am

Confirm with James

Email Call

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia:

Repair Cost: \$S 3400.00

OI involved TP lane.

Loss of Rental (LOR): \$S - (1 days)

Loss of Use (LOU): \$S 100.00 (\$20 x 6 days)

Loss of Income (LOI): \$S - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

COPY SENT 18/9/19

GIA/LTA Search \$S -

Medical: \$S -

Disbursement: \$S -

Legal Cost \$S -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$350/-

Total: \$S 3520.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email Call

Payee 1: \$S 3520.00

Name 1: HKL UM Team Motorsport

Payee 2: (Strike if N.A.) \$S -

Name 2:

Payee 3: (Strike if N.A.) \$S -

Name 3:

Tampere

REF: 44

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (IP) WS / TP RES / OD RES / EVA / RV / MV

To inspect Vehicle No: _____

at Workshop no: **TIKL**

Insured: _____

Policy No: _____

Claim No: _____

Name Insured: _____ Excess: _____

(Client's Discard)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Val. of Market Value: **76500**

IDAC Accident Report: _____ Complied? Yes or No

GIA / PR Date: _____ Complied? Yes or No

Est. Repair: **6** days Res: Yes or No

Lump Sum: **20** % 3rd: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: **Al Kees**

Vehicle: IN / OUT



Veh No: **FBK 1060M** V1 Logo: **2015 Merck**

Type: **MC** Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda WW150** S/N: **153**

Color: **Grey** A/C: Insured / Std / Nil / NA

Sp. Boarding: _____ T/Cable: Insured / Std / Nil / NA

Eng No: _____

CIN: **RLHKE1849Fyoolist**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: **IN** Inorder / Jammed / Leaked / Burnt or

Mod: **NI** / SRim / STD / RIm or

Tyre Size: F: **80/90R14**

R: **100/40R14**

BS / SUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Ral 5 mm	R/Ral 5 mm
L/Ral _____ mm	L/Ral _____ mm
D.O.A. _____	D.O.A. 20/2/17

Survey held at: **TIKL Lim**

Des. of Damages: **FR** / Rear **OS** / MS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: **body work**

US \$3400/-

(Red = \$3135 / 48%)

Date/Time, FR/Para 1: Preli. Report

2: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$) Interview (\$) Tech Insp (\$) Weekend (\$)

Survey Fee: _____

Transportation: _____

Other: _____

Other: _____

Report Format: _____

Lump Sum / L.S.U. (\$) _____



HKL LIM TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklmteam.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Website: www.hklmteam.com.sg

FBK1060M

1 lamp stay		? \$120 <i>bt</i>
2 meter assy		<i>nn</i> X \$350
3 front fork assy lh / rh		? \$400 <i>bt</i>
4 front fork under bracket		? \$220 <i>bt</i>
5 steering cone bearing		? \$80 <i>bt</i>
6 body frame alignment <i>(Lob)</i>	<i>21/6/19 factory</i> ✓ <i>plus</i>	200? \$550
7 front fender		<i>cut</i> \$120
8 front wheel rim		<i>nn</i> X \$250
9 front wheel shalf		<i>nn</i> X \$60
10 front wheel bearing 2 pcs		<i>nn</i> X \$40
11 front wheel bearing oil seal		<i>nn</i> X \$20
→ 12 front / rear brake disc		* \$150 <i>bt</i>
13 head cowling center		? \$90 <i>de</i>
14 head cowling		<i>cut</i> \$300
15 iu unit		<i>cut</i> \$170
16 iu unit bracket		<i>bt</i> \$30
17 handle bar		? \$90 <i>bt</i>
18 handle bar grip		<i>cut</i> \$20
19 handle bar balancer		<i>cut</i> \$40
20 front no plate		<i>nn</i> X \$10
21 brake lever lh / rh		<i>cut</i> \$50
22 side mirror lh / rh		<i>cut</i> \$80
23 meter panel		<i>nn</i> X \$80
24 compartment		? \$150 <i>de</i>
25 compartment cover		<i>cut</i> \$120
26 lower cowling lh / rh		<i>cut</i> \$240
27 foot panel lh / rh		<i>cut</i> \$240
28 rear foot rest lh / rh		<i>cut</i> \$160
29 exhaust muffler		<i>Rx</i> \$250
30 exhaust muffler cover		<i>cut</i> \$80
31 tailboard lh / rh		<i>LH / RH</i> \$300 <i>150</i>
32 side stand		<i>bt</i> \$55
33 main stand		<i>bt</i> \$120
34 top box		<i>cut</i> \$180

- 35 top box bracket
- 36 iu cover
- 37 vbelt cover
- 38 headlight
- 39 towing
- 40 labour

TOTAL

Let us know if you have any other queries
 • To resurvey damaged parts during resurvey
 • To resurvey damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary items must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:

Rx \$120
 M ✓ \$20
 OR ✓ \$120
 AM ✓ \$380
 ✓ \$30
 300 \$650

\$6,535

Parts - 4185
 Lolo - 3766.50
 Labour - 530

 4296.50
 1/5 @ 3400, 6 days.

Tanfikh 97495749
 WIP
 20/6/19 @ 330pm
 after
 Resurvey before paint
~~not~~ ~~not~~ ~~not~~ parts
 sur@khearts.com
 6 days

Front panel bracket RM - £90/-
 Rear furt bracket RM - £120/-

Resurvey 01/07/19
 Judd



HKL LIM TEAM MOTORSPORT

Blk 100B #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBK1060M

1 lamp stay	? \$120
2 meter assy	X \$350
3 front fork assy lh / rh	? \$400
4 front fork under bracket	? \$220
5 steering cone bearing	? \$80
6 body frame alignment	plus 200? \$550
7 front fender	was ✓ \$120
8 front wheel rim	X \$250
9 front wheel shalf	X \$60
10 front wheel bearing 2 pcs	X \$40
11 front wheel bearing oil seal	X \$20
12 front / rear brake disc	X \$150
13 head cowling center	? \$90
14 head cowling	was ✓ \$300
15 iu unit	cut ✓ \$170
16 iu unit bracket	bt ✓ \$30
17 handle bar	? \$90
18 handle bar grip	cut ✓ \$20
19 handle bar balancer	cut ✓ \$40
20 front no plate	X \$10
21 brake lever lh / rh	cut ✓ \$50
22 side mirror lh / rh	cut ✓ \$80
23 meter panel	X \$80
24 compartment	? \$150
25 compartment cover	was ✓ \$120
26 lower cowling lh / rh	cut ✓ \$240
27 foot panel lh / rh	cut ✓ \$240
28 rear foot rest lh / rh	cut ✓ \$160
29 exhaust muffler	RV \$250
30 exhaust muffler cover	cut ✓ \$80
31 tailboard lh / rh	LH+RH X \$300
32 side stand	bt ✓ \$55
33 main stand	bt ✓ \$120
34 top box	cut ✓ \$180

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3618J

Vehicle Details

Vehicle No.: FBK1060M

Vehicle to be Exported: No

Intended Deregistration Date: 24 Jun 2019

Vehicle Make: HONDA

Vehicle Model: WW150 (PCX150)

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: KF18E5041148

Chassis No.: RLHKF18A9FY001135

Maximum Power Output: -

Open Market Value: \$2,804.00

Original Registration Date: 23 Mar 2015

First Registration Date: 23 Mar 2015

Transfer Count: 1

Actual ARF Paid: \$421.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2025

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$5,610.00

COE Rebate Amount: \$3,218.00

Total Rebate Amount: \$3,218.00

The information contained herein is correct as at 24 Jun 2019

OK

Dear Sir / Madam

I ABDUL RAHMAN BIN ABDUL MAJID NRIC No: 917236181 Owner of the

motorcycle plate number FBK 1060M, authorized

HKL LIM TEAM MOTORSPORT workshop to repair my motorcycle.

My bike is already repaired by **HKL LIM TEAM MOTORSPORT**.

All payment mode and loss of use should be paid to **HKL LIM TEAM**

MOTORSPORT.

Thank You!



Signature

Name : _____

NRIC: _____

Claim No: _____

HKL LIM TEAM MOTORSPORT (53347346B)
BLK 1008 #01-24 Bukit Merah Lane 3 Singapore 159722
Tel: 6275 6566, 6275 6656 Fax: 6272 9291

I ABDUL RAHMAN BIN ABDUL MAJID NRIC No: S1723618J Am very
satisfied with **HKL LIM TEAM MOTORSPORT** workshop for their
repair and the claiming of insurance that they had done for my
motorcycle FBK 1060M.


Signature

Name : _____

NRIC: _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 20 June 2019 2:08 PM
To: HKL Lim Team Motorsport; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Sherini Pillai
Subject: RE: FBK1060M / SHB4192Y on 15/04/2019 Arrange Surveyor
Attachments: FBK1060M 3.jpg; FBK1060M 2.jpg; FBK1060M 1.jpg; FBK1060M 4.jpg; FBK1060M 5.jpg; FBK1060M 6.jpg; FBK1060M 7.jpg; FBK1060M 10.jpg; FBK1060M 8.jpg; FBK1060M 9.jpg

2.30pm @ 20/6/19
vehicle in
person @ James
JRE @ Turfikh

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBK1060M and let us have your report urgently.

This claim will be handled by Ms. Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: HKL Lim Team Motorsport [mailto:hklteam@gmail.com]
Sent: 20 June, 2019 1:55 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: FBK1060M / SHB4192Y on 15/04/2019 Arrange Surveyor

Hi Gabriel wee,

LKK Auto consultants Pte Ltd

On Thu, Jun 20, 2019 at 1:49 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: HKL Lim Team Motorsport [mailto:hklimteam@gmail.com]

Sent: 20 June, 2019 11:36 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: FBK1060M / SHB4192Y on 15/04/2019 Arrange Surveyor

Hi to whom may concern,


Please arrange surveyor for this claim.

Thank You.

Best Regards

James Lim (Keong)

Tel:+65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722

Tel:+65 6275-6656, 6275-6566 Fax: 6272-9291

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination

of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.


Registration No. 198703792-K

--
Thank You.

Best Regards

James Lim (Keong)

Tel:+65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722

Tel:+65 6275-6656, 6275-6566 Fax: 6272-9291

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***FBK1060M (MCT19040425)**
[SHB4192Y]

TP

ABDUL RAHMAN BIN ABDUL MAJID

Apr 15 2019 11:00AM

[-]

Hkl Lim Team Motorsport

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/08/2019 09:10 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3520.00) - FBK1060M - Claim Handler: Sherini Pillai

Approved:3520.00.

ATTN: Ms Sherini

Our Ref: MCT 1904025

Date: 05/07/2019

Subject: Car Regn No : FBK 1060M
Chassis No :

Model : PCX150A-153CC
Regn Date :

Accident involving FBK 1060M & SHD4192Y
on 15/04/2019

Direct settlement

Dear Sirs

The repairs have been completed for FBK 1060M. We submit the following documents for

LUM SUM = \$3400

LOSS OF USE 6 DAYS x \$20 = \$120

Please pay HKL LIM TEAM MOTORSPORT as soon as possible for SS 3520.00 full and final settlement for this accident repair provided no incidental charges are incurred

Your faithfully,



AUTHORISATION TO ACT

I/We, ABDUL RAHMAN BIN ABDUL MAJID (the third party claimant") of BIK 116 BLDOK NORTH ROAD #02-243 S' (460116) (address), owner of FBK 1060M (vehicle no.) hereby authorize HKL LIM TEAM MOTORSPORT ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. FBK 1060M that was damaged pursuant to the accident which occurred on 15/04/2019 (date) along CTE TOWARDS AYE 15.5KM (LAMP POST 503F) (location) involving vehicle no/s SHD 4192Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 4/7/19 (day) of _____ (month) 20__ (year)



Signed by "the third party claimant"
(with company stamp if applicable)



Signed by "the workshop"
(with company stamp)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

WITHOUT PREJUDICE to:
 (a) Insurers' Subrogated Claim and/or
 (b) Any Personal Injury Claims
 [Note: This Notice supercedes any
 inconsistencies found in this
 Discharge Voucher]

India Ref: MCT15040425
 Claimant Ref: FBK 1060M

We/I HKLIM TEAM MOTORSPORT ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,400.00 (repair cost), S\$ 120.00 (loss of use ~~rental~~), S\$ - (search fee), vehicle no. FBK 1060M that was damaged pursuant to the accident which occurred on 15/04/2019 (date) at CTE (location) involving vehicle no. 5HB 4192Y (insured vehicle). This is pursuant to the inspection conducted on 20/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ABDUL RAHMAN BIN ABDUL MAJID ("the third party claimant") of vehicle no. FBK 1060M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to FBK 1060M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,520.00 to HKLIM TEAM MOTORSPORT

Dated this 04 day of 09 2019

CLAIMANT:

Signature:




Signed by "the workshop" (with chop)

Name:

HKL Lim Team Motorsport

NRIC:

53347346B

Address:

Blk 1008 #01-24
 Bukit Merah Lane 3 S159728

Nationality:

Occupation:

WITNESS:

Signature:




Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK 5(408933)

Nationality:

Occupation:



HKL Lim Team Motorsport (53347346B)

1008 Bukit Merah Lane 3, #01-24, Alexandra Village Industrial Estate 159722 Singapore Singapore

Tel No : 62756566, 62756656 Fax No : 62729291 Email : nklimteam@gmail.com

INVOICE

INVOICE : INV-98067

Date : 05/07/2019 (20:20:00)

Page : 1 of 2

Bill To : INDIA INTERNATIONAL INSURANCE PTE LTD

Address :

Job Sheet No : INV09164

Vehicle No. : FBK1060M

Model :

Mileage : 0

PO No. :

Payment : CHEQUE

Client Code : C3718

Contact No. :

Svs. Advisor :

Mechanic :

Description	Qty	Unit Price SGD	Disc %	Sub Total SGD	Total Amount SGD
Labour					
LAMP STAY					0.00
FRONT FORK ASSY LH/RH					0.00
FRONT FORK UNDER BRACKET					0.00
STEERING CONE BEARING					0.00
BODY FRAME ALIGNMENT					0.00
FRONT FENDER					0.00
FRONT BRAKE DISC					0.00
HEAD COWLING CENTER					0.00
HEAD COWLING					0.00
IU UNIT					0.00
IU BRACKET					0.00
HANDLE BAR					0.00
HANDLE BAR GRIP					0.00
HANDLE BAR BALANCER					0.00
BRAKE LEVER LH/RH					0.00
SIDE MIRROR LH/RH					0.00
COMPARTMENT					0.00
COMPARTMENT COVER					0.00
LOWER COWLING LH/RH					0.00
FOOT PANEL LH/RH					0.00
REAR FOOT REST LH/RH					0.00
EXHAUST MUFFLER COVER					0.00
TAILBOARD LH					0.00
SIDE STAND					0.00
MAIN STAND					0.00
TOP BOX					0.00
IU COVER					0.00
VBELT COVER					0.00
HEADLIGHT					0.00
TOWING					0.00
FOOTPANEL BRACKET RH					0.00
REARFOOT BRACKET RH					0.00
LABOUR					0.00
TOTAL	1.00	3,400.00		3,400.00	3,400.00

Remarks



HKL Lim Team Motorsport (53347346B)

1008 Bukit Merah Lane 3, #01-24, Alexandra Village Industrial Estate 159722 Singapore Singapore

Tel No. : 62756566, 62756656 Fax No. : 62729291 Email : hklteam@gmail.com

INVOICE

INVOICE : INV-98067

Date : 05/07/2019 (20:20:00)
Page : 2 of 2

Bill To : INDIA INTERNATIONAL INSURANCE PTE LTD
Address :

Job Sheet No : INV09164
Vehicle No. : FBK1060M
Model :
Mileage : 0
PO No. :
Payment : CHEQUE
Client Code : C3718

Contact No. :
Svs. Advisor :
Mechanic :

Description	Qty	Unit Price SGD	Disc %	Sub Total SGD	Total Amount SGD
-------------	-----	-------------------	--------	------------------	---------------------

Next Service Due : 5,000 K or 03/10/2019, whichever comes first

Goods sold are neither returnable nor refundable.
Thank you for your patronage and support.
Hope to see you again on next service.

Total Amt Due: 3,400.00 3,400.00

Rounding Adj.: 0.00

Total: 3,400.00



Customer's Signature
Name:

Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019 Edit Reg		20 Jun 2019 00:00 Edit Adj Rpt	S\$3,400.00 Edit Estimates	S\$3,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	ABDUL RAHMAN BIN ABDUL MAJID, ID: S1723618J								
Vehicle Reg. No.:	FBK1060M	Date of Loss:	15/04/2019 11:00 - :59 [48 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19040425	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHB4192Y	Policy No. (Claimant):	5078646335-03						
		Excess:							
Repairer:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/07/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> • III_SG (22/08/2019): Alert - Adj Mandate Approved (S\$3520.00) - FBK1060M - Claim Handler: Sherini Pillai • III_SG (31/07/2019): Alert - Adj Mandate Approved (S\$0.00) - FBK1060M - Claim Handler: Sherini Pillai • III_SG (03/07/2019): Alert - Adj Mandate Maintained - FBK1060M - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
Create New Task	Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK1060M (MCT19040425)
[SHB4192Y]
TP
ABDUL RAHMAN BIN ABDUL MAJID
Apr 15 2019 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hkl Lim Team Motorsport

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print			
1	03/07/19 14:53	Video - OID						Load MP4			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
2	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
3	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
4	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
5	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
6	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
7	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
8	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
9	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
10	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
11	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
12	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
13	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
14	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
15	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
16	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
17	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
18	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
19	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
20	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
21	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
22	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
23	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
24	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
25	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
26	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
27	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
28	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
29	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
30	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
31	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
32	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
33	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
34	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
35	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
36	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
37	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
38	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
39	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			
40	18/09/19 19:26	General View						Load JPG <input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
57	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
58	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
59	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
62	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
64	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
65	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
66	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
67	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
69	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
70	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
71	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
72	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
73	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
74	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
75	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
76	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
77	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
78	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
79	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
80	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
81	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
82	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
83	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
84	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
85	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
86	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
87	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
88	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
89	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
90	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
91	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
92	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
93	18/09/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
94	18/09/19 19:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	18/09/19 19:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
97	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
98	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
99	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
100	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
101	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
102	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
103	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
104	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
105	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
106	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
107	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
108	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
109	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
110	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
111	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
112	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
113	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
114	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
115	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
116	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
117	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
118	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
119	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
120	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
121	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
122	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
123	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
124	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
125	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
126	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
127	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
128	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
129	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
130	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
131	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
132	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
133	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
134	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
135	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
136	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
137	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
138	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
139	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
140	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
141	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
142	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
143	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
144	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
145	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
146	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
147	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
148	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
149	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
150	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
151	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
152	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
153	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
154	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
155	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
156	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
157	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
158	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
159	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
160	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
161	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
162	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
163	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
164	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
165	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
166	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
167	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
168	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
169	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
170	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
171	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
172	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
173	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
174	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
175	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
176	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
177	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
178	18/09/19 19:27	Reinspection Photo		<input checked="" type="checkbox"/>
179	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
180	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
181	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
182	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
183	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
184	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
185	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
186	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
187	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
188	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
189	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
190	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
191	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
192	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
193	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
194	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
195	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
196	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
197	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
198	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
199	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
200	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
201	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
202	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
203	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
204	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
205	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
206	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
207	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
208	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
209	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
210	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
211	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
212	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
213	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
214	18/09/19 19:28	Reinspection Photo		<input checked="" type="checkbox"/>
215	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
216	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
217	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
218	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
219	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
220	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
221	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
222	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
223	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
224	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
225	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
226	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
227	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
228	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
229	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
230	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
231	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>
232	18/09/19 19:28	Dismantled Parts		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/19 08:36	ACKNOWLEDGEMENT EMAIL TO III DD 20.06.2019		<input type="checkbox"/>
2	25/06/19 10:03	TP ESTIMATE - MARKED		<input type="checkbox"/>
3	25/06/19 10:03	TP GIA REPORT		<input type="checkbox"/>
4	21/08/19 16:20	WORKSHOP INVOICE		<input type="checkbox"/>
5	21/08/19 16:20	LOD		<input type="checkbox"/>
6	19/09/19 10:38	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
7	19/09/19 10:38	DISCHARGE VOUCHER		<input type="checkbox"/>

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 08:56	Singapore Accident Statement		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010953/T1GA3Q2
Date: 19/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : FBK1060M	Insured Vehicle No :	SHB4192Y	
Date of Loss: 15/04/2019	Nature of Claim:	TP	Claim No: MCT19040425

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK1060M		
Make & Model:	HONDA WW150, 153cc	Engine No:	KF18E5041148
Reg. Date:	23/03/2015 (Man. Year: 2014)	Chassis No:	RLHKF18A9FY001135
Colour:	Grey	Odometer:	0 km
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 R14	Rear Tyre Size:	100/90 R14
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,515.00	3,766.50	1,748.50	31.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	530.00	700.00	56.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,745.00	4,296.50	2,448.50	36.30
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	6,745.00	3,400.00	3,345.00	49.59
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
	Nett Liability (S\$)	3,520.00		

INSPECTION

Date of Assignment:	20/06/2019	
Date Inspected:	20/06/2019	Inspected At:
		Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Aug 2019)	
Parts:	N/A	HONDA WW150 153cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK1060M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP STAY	Bent	120.00 F	*120.00 FL
2	1		*METER ASSY	Not Necessary	350.00 F	*- FL
3	2		*FRONT FORK ASSY LH/RH	Bent	400.00 F	*400.00 FL
4	1		*FRONT FORK UNDER BRACKET	Bent	220.00 F	*220.00 FL
5	1		*STEERING CONE BEARING	Necessary	80.00 F	*80.00 FL
6	1		*FRONT FENDER	Cracked	120.00 F	*120.00 FL
7	1		*FRONT WHEEL RIM	Not Necessary	250.00 F	*- FL
8	1		*FRONT WHEEL SHALF	Not Necessary	60.00 F	*- FL
9	2		*FRONT WHEEL BEARING	Not Necessary	40.00 F	*- FL
10	1		*FRONT WHEEL BEARING OIL SEAL	Not Necessary	20.00 F	*- FL
11	1		*FRONT BRAKE DISC	Bent	150.00 F	*150.00 FL
12	1		*HEAD COWLING CENTER	Deformed	90.00 F	*90.00 FL
13	1		*HEAD COWLING	Cut	300.00 F	*300.00 FL
14	1		*IU UNIT	Cut	170.00 F	*170.00 FL
15	1		*IU UNIT BRACKET	Bent	30.00 F	*30.00 FL
16	1		*HANDLE BAR	Bent	90.00 F	*90.00 FL
17	1		*HANDLE BAR GRIP	Cut	20.00 F	*20.00 FL
18	1		*HANDLE BAR BALANCER	Cut	40.00 F	*40.00 FL
19	1		*FRONT NO PLATE	Not Necessary	10.00 F	*- FL
20	2		*BRAKE LEVER LH/RH	Cut	50.00 F	*50.00 FL
21	2		*SIDE MIRROR LH/RH	Cut	80.00 F	*80.00 FL
22	1		*METER PANEL	Not Necessary	80.00 F	*- FL
23	1		*COMPARTMENT	Deformed	150.00 F	*150.00 FL
24	1		*COMPARTMENT COVER	Cracked	120.00 F	*120.00 FL
25	2		*LOWER COWLING LH/RH	Cut	240.00 F	*240.00 FL
26	2		*FOOT PANEL LH/RH	Cut	240.00 F	*240.00 FL
27	2		*REAR FOOT REST LH/RH	Cut	160.00 F	*160.00 FL
28	1		*EXHAUST MUFFLER	Repair	250.00 F	*- FL
29	1		*EXHAUST MUFFLER COVER	Cut	80.00 F	*80.00 FL
30	1		*TAILBOARD LH/RH	N/S Cut	300.00 F	*150.00 FL
31	1		*SIDE STAND	Bent	55.00 F	*55.00 FL
32	1		*MAIN STAND	Bent	120.00 F	*120.00 FL
33	1		*TOP BOX	Cut	180.00 F	*180.00 FL
34	1		*TOP BOX BRACKET	Repair	120.00 F	*- FL
35	1		*IU COVER	Torn	20.00 F	*20.00 FL
36	1		*VBELT COVER	Cracked	120.00 F	*120.00 FL
37	1		*HEADLIGHT	Cracked	380.00 F	*380.00 FL
38	1		*FOOT PANEL BRACKET RH	Bent	90.00 F	*90.00 FL
39	1		*REAR FOOT BRACKET RH	Bent	120.00 F	*120.00 FL

F=Franchise part. L=ListitemDisc.

Sub Total (\$\$)	5,515.00	4,185.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	418.50

Total Parts (\$\$)	5,515.00	3,766.50
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY FRAME ALIGNMENT	New	550.00	200.00
2	TOWING	New	30.00	30.00
3	LABOUR	New	650.00	300.00
Gross Labour Cost (S\$)			1,230.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >