

22/03/2002

ASS. REC. BY:

REF: CS3/SMO19010992/Bcd/307

Special Instruction:

Survivor: Lim

**ASSIGNMENT (Office)**

From (Person): Hwang Shiang Yi

of

SMO

Date/Time: 21.6.19 14.37p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJF 3607E

Insured: GBF 5076T

at Workshop m/s Beng Hai

Tel: 96631569

of BIK 3012 Bedok Industrial Park E #01-205B

Policy No: DIGMT PCVE004014

Claim No: CMTD1902988

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.6.19 2.46p.m

Person Contacted: Beng Hai

Vehicle: IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

SJF 3607E - X

GBF 5076T - CS/SMO190033221 Vg. 302 D.O.A. - 20/02/2019

Dismantle = 24/6/2019

SMD

## ASSIGNMENT

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
	Range 6,000/z - 7,000/z
	MV 52,000/z PV 35,041/z NV 16,959/z
	Trim line 26/7/19

TOTAL

100
60
11
171

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019		21 Jun 2019 14:37 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG MEI ENTERPRISES, Co. Reg. No.: 23204600W		
Main Claimant:	SIM EE CHENG, ID: S6912248E		
Vehicle Reg. No.:	SJF3607E	Date of Loss:	20/06/2019 13:00 - :59
Claim Type:	TP / CMTD1902988	Policy/Cover Note No.:	D18MTPCVE004014 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF5076T	Policy No. (Claimant):	
		Excess:	
Repairer:	Beng Hai Motor Service (bedok) (HQ) Blk 3012 Bedok Industrial Park E #01-2058, 489978 Bedok - Tel: 9663 1569		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/07/2019]		
Adj Asg. Remarks:	WS: BENG HAI 4441544 HP 96631569 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	248E
<b>Vehicle Details</b>	
Vehicle No.:	SJF3607E
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SP
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	Z6692794
Chassis No.:	JM6BK106280414071
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,308.00
Original Registration Date:	28 May 2008
First Registration Date:	28 May 2008
Transfer Count:	1
Actual ARF Paid:	\$15,308.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Nov 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$41,994.00
COE Rebate Amount:	\$35,041.00
<b>Total Rebate Amount:</b>	<b>\$35,041.00</b>

The information contained herein is correct as at 26 Jul 2019

OK

Dep 6,500/yr

COE left 8yr Amthw

MV : 52,000/2

PV 35,041/2

NV 16,959/2

Reim Min  
26/7/19

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2019 09:14
Date Of Accident	20/06/2019 13:00
Exact Location Of Accident	ALONG BLK 501 BISHAN STREET 11 SINGAPORE 570501
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF3607E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIM EE CHENG
NRIC No	S6912248E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91144548
Alternative Phone No	OFFICE-91144548

### Vehicle Particulars

Manufacturer	MAZDA
Model	3 SP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088435871-02
Cover Note Number	

### Driver

Name of Driver	SIM EE CHENG
NRIC No	S6912248E
Date Of Birth	13/04/1969
Occupation	OUTDOOR
Date Of Driving Pass	02/09/1996
Driving Experience	22 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91144548
Fax Number	
Contact Number	OFFICE-91144548
EMail Address	NOEMAIL

Address	99 ROSEWOOD DRIVE #01-141 PARC ROSEWOOD
Postcode	737797
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF5076T
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) Involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature

Date & Time: 20 Jan 2019  
2:38 pm

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING TO BISHAN STREET II BLK SOI CARPARK
ON 20TH JUNE 2014 AROUND 1 PM I WAS QUEUING AT
CARPARK ENTRANCE. IN FRONT OF MY CAR, THERE WAS A
PICK UP TRUCK VEH NO <sup>G8F</sup> 5076 T. AS THE PICK UP DRIVER
SUDDENLY REVERSE HIS VEHICLE VERY QUICKLY, I HONK
TO HIM LOUDLY. HE COULDN'T HEAR MY HONKING AND
HIS CAR HIT REAR SIDE OF HIS CAR HIT MY FRONT CAR
MY CAR HAS A HUGE HOLE AND THE FRONT BONNET RAISED
UP.
PICK UP DRIVER ASK ME TO GIVE HIM A DAY FOR HIM
TO DECIDE <del>WITH</del> HOW HE WANTS TO SETTLE THIS MATTER
PICK UP DRIVER NAME IS LIM SEE LEE
NRIC NO S0170 556 C HP NO 98256125
ACCIDENT AREA: BLK SOI BISHAN STREET II
CARPARK LOCATION NO BIBE 21

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 20 June 2014  
7:38 pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2019		21 Jun 2019 14:37 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	HONG MEI ENTERPRISES, Co. Reg. No.: 23204600W			
Main Claimant:	SIM EE CHENG, ID: S6912248E			
Vehicle Reg. No.:	SJF3607E	Date of Loss:	20/06/2019 13:00 - :59 [132 Months and 23 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1902988	Policy/Cover Note No.:	D18MTPCVE004014 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBF5076T	Policy No. (Claimant):		
		Excess:		
Repairer:	Beng Hai Motor Service (bedok) (HQ) Blk 3012 Bedok Industrial Park E #01-2058, 489978 Bedok - Tel: 9663 1569			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 02/07/2019]			
Adj Asg. Remarks:	WS: BENG HAI 4441544 HP 96631569 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT			






































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SJF3607E (CMTD1902988)  
[GBF5076T]  
TP  
SIM EE CHENG  
Jun 20 2019 1:00PM  
[HONG MEI ENTERPRISES]  
Beng Hai Motor Service (bedok)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		▼
Photos/Images								3 per page		▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
2	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
3	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
4	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
5	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
6	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
7	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
8	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
9	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
10	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
11	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
12	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
13	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
14	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
15	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
16	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
17	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
18	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
19	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
20	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
21	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
22	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
23	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
24	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
25	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
26	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
27	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
28	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
29	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
30	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
31	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
32	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
33	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
34	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
35	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
36	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	
37	26/07/19 19:11	General View							Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/07/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 19:11	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 19:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/06/19 14:19	Pre-Repair Survey+GIA	 Load PDF	
2	21/06/19 14:38	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19010992/BCD3E2

Date: 29/07/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE004014
Claimant Vehicle No :	SJF3607E	Insured Vehicle No :	GBF5076T
Date of Loss:	20/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902988

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJF3607E</b>		
Make & Model:	MAZDA 3, SP 1.6 (A)	Engine No:	Z6692794
Reg. Date:	28/05/2008 (Man. Year: 2008)	Chassis No:	JM6BK106280414071
Colour:	Blue	Odometer:	115500 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	21/06/2019	
Date Inspected:	21/06/2019 Inspected At:	Beng Hai Motor Service (bedok) (HQ) Blk 3012 Bedok Industrial Park E #01-2058 Singapore 489978
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

## REPAIR DETAILS

Reference		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
<b>Parts:</b>	144	MAZDA 3 SP 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJF3607E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >