

15/5/2010

INS. CASE OWNER:

CC 3/CTI1901

1008, Edw3

LKK:

IDAC:

Surveyor:

Kenneth.

DOI:

ASSIGNMENT

20/6/10

Date / Time :

20/6/10

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SFV 1689U.

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A :

12/6/10

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHD 5077E



INSRS:

WSP:

Tel :

Liability :

RMKS:

trans
cmb

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SHD 5077E - X SFV 1689U - X	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice	☐
	LTA / GIA :	☐
Medical Bill:	☐	
PIR:	☐	
Mandate/Reject Instruction:	☐	
LOD	☐	
Payment Breakdown Form:	☐	
PRELIMINARY ADVICE Date/Time: Sent By:		Post-Repair Photos: ☐
		Others: ☐
FINALIZATION Date/Time: Confirm with:		Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: Confirm with		Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	(days)	
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	S\$	
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S\$	3) Survey fee:
Total: S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time: Confirm with:		Email ☐ Call ☐
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

ASS. REC. BY:

REF: CT21Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

2 1/2 days

Res.: Yes or No

Lum Sum: _____

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + R.S. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Veh No: S14D 3077EYr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 24Make: Perout Latitude

c.c

1995Colour M. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading 132571

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABCL15AUC 283375Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/6/19D.O.I. 20/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.