

22/03/2011

A.S.S. REC. BY:

Surveyor: RGSU

REF:

es/CTI/19011011/Rlv3eb

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

21/6/19 3.33pm

Estimated Cost:

Bill to:

~~OD/TP/WS/TP~~ RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 5498J

Insured:

YM 9886L

at Workshop m/s

Burneo Motor

Tel:

98476171

of

2 pendan Crescent

Policy No:

Claim No:

SNM19D202881

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/06/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3.53pm 21/6/19

Person Contacted:

Thomas

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

SME 5498J - X

YM 9886L - X

13/8/19

Final fig \$ 3482.79 (Red 1461.05, 30%) Confirmed by email



**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 21 June 2019 3:33 PM  
**To:** Ashlyn Chng  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D202881/CHONGBS - Direct Settlement (TP) - Accident involving SME5498J & YM9886L DOA 18/06/2019

**WITHOUT PREJUDICE**

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Ashlyn Chng [<mailto:Ashlyn.Chng@inchcape.com.sg>]  
**Sent:** Friday, 21 June, 2019 3:00 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D202881/CHONGBS - Direct Settlement (TP) - Accident involving SME5498J & YM9886L DOA 18/06/2019

Dear Boon Sen,

We would like to choose XING QUO QIANG to conduct the assessment.

Please revert with your insured liability.

Thank you.

Regards,  
Ashlyn Chng  
D: 6631 1874 | F: 6872 7260 | E: [Ashlyn.chng@inchcape.com.sg](mailto:Ashlyn.chng@inchcape.com.sg)  
Inchcape Centre

Level 4, Bodycare Centre  
2 Pandan Crescent  
Singapore 128462

[www.borneomotors.com.sg](http://www.borneomotors.com.sg) | [www.lexus.com.sg](http://www.lexus.com.sg) | [www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg) | [www.hino.com.sg](http://www.hino.com.sg) | [www.suzukicar.com.sg](http://www.suzukicar.com.sg)

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Friday, 21 June 2019 10:38 AM

**To:** Ashlyn Chng <[Ashlyn.Chng@inchcape.com.sg](mailto:Ashlyn.Chng@inchcape.com.sg)>

**Subject:** RE: OUR REF: SNM19D202881/CHONGBS - Direct Settlement (TP) - Accident involving SME5498J & YM9886L DOA 18/06/2019

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**  
Claims Executive

For more information please visit <http://www.symanteccloud.com>

---

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

AXA INSURANCE PTE LTD  
8 Shenton Way, #24-01  
AXA Tower, Singapore 068811  
Customer Service Centre #01-21  
Tel: 1800 8804888  
Website: www.axa.com.sg  
GST Registration Number: 199903512M  
customer.care@axa.com.sg



# CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2186831 Account No. : 14885  
Coverage : Comprehensive (SmartDrive Toyota Prestige)  
Sum Insured : Market Value At The Time Of Loss  
Name of Policy Holder : LOH WAI LENG  
Vehicle Registration No. : SME5498J  
Period of Insurance : From 04/10/2018 To 03/10/2020 (Both Dates Inclusive)

## PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

- (a) The Policyholder  
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner  
(b) Any other person who is driving on the Policyholder's order or with his permission  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

## LIMITATIONS AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business  
The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 600.00

An Additional Excess is applicable as follows:

S\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOAGPH on 08/10/2018

## IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/06/2019 08:59
Date Of Accident	18/06/2019 17:50
Exact Location Of Accident	AYE NEAR CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME5498J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOH WAI LENG
NRIC No	S0114861C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97529772
Alternative Phone No	OFFICE-97529772

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS PLUS-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2186831
Cover Note Number	

### Driver

Name of Driver	LIM LUCK SER
NRIC No	S0089417F
Date Of Birth	06/07/1949
Occupation	INDOOR
Date Of Driving Pass	15/09/1971
Driving Experience	47 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97529772
Fax Number	
Contact Number	
Email Address	LIMLS@SINGNET.COM.SG

Address	30 TOH TUCK ROAD
Postcode	596705
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YEO TEOW CHEONG
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9886L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	



## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GX9598Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: 7P

## MOTOR ACCIDENT REPORT

Date Of Report: 19 June 2019 Time: 2.40p Date Of Accident: 18 June 2019 Time: 550pm

Exact Location Of Accident: AYE near Clementi Ave 6

Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SME 5498 J

Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S0114861C

Name Of Registered Owner: LOH WAH LENG

Mobile Number:

Alternative No:

Email Address:

## Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: PriusExact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

## Insurance Company

Name of Insurance Company: AXA Insurance

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒

Policy / Cover Note No: VPA/P2186831

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: LIM LUCK SER

NRIC/ Passport / FIN No: S 0089417 F

Date Of Birth: 6 July 1949

Occupation: Indoor ☒ Outdoor ☐

Date Of Driving Pass: 27 July 2004

Gender: Male ☒ Female ☐

Mobile Number: 9752 9772 Fax No:

Alternative No:

Address: 30 Toh Tuck Road

Postal Code: 596705

Email Address: limls@sigmet.com.sg

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Husband

Vehicle Registration Number of Driver's Own Vehicle (if applicable): —

Insurance Company of Driver's Own Vehicle (if applicable): —

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Chain Collision

Number of Passengers in the above vehicle (Including Driver): 2 / If more than 2 Pax Please fill ANNEX B

## PASSENGER 1

Name: YEOW TEOW CHOW Gender: Male ☒ Female ☐Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:

Number of vehicles involved in the accident: 3

Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name: Contact No.: Email:

Was there any other vehicle or property damaged? No ☐ Yes ☒Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☐ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☐ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: YN 9886 L

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number:

GX 9598 Z

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number:

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number:

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

**DETAILS OF OTHER VEHICLE PROPERTY 5**

Vehicle Registration Number:

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

**DETAILS OF INJURED PERSON 2**

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐**DETAILS OF INJURED PERSON 3**

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐**DETAILS OF INJURED PERSON 4**

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐**DETAILS OF INJURED PERSON 5**

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

SKETCH PLAN

A 4 E

SME 5498J



YM 9886L



GX 9598Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Heavy Traffic along A 4 E.

I was driving slowly on the extreme left lane.

I Stopped because front car stopped

After a while, my car was rear-ended by a lorry YM 9886L.

There was another lorry GX 9598Z who involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Co-Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota M account & more!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer Detail

Account Detail	Account No	
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	0
	Document Date	19/06/2019
	Mdm Loh Wai Leng 30 Toh Tuck Road	
	Singapore 596705	
	Mobile: 97529772	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWXEBW S2	ZVW40R	04/10/2018	SME5498J	0	46123	72/DS/SME5498J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDZS3EU90J033667	2ZROC52952	60	Thomas Pang W	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	---------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: TP VEH: YM9886L DATE OF ACC: 18.06.2019				
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)				180.00
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NETT)				122.40
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)				180.00
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1448.00
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1180.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER)				91.59
8	1	TREVSE-47006 16 BACK SENSOR 070 WHITE PEARL	1.00	101.05		101.05
9	2	T52159-47912 COVER, RR BUMPER	1.00	556.40		556.40
10	3	T52023-12240 REAR BPR REINFORCEMENT	1.00	216.80		216.80
11	4	T76891-47040 SPOILER, RR NO.1	1.00	734.60		734.60
12	5	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	4,943.84
		Labour	1,649.85
		Materials	3,202.40
		Lubrication/Fluid	91.59
		Others	0.00
			0.00
		Amount Due	5,289.91

PLEASE TEAR ALONG PERFORATED LINE

3938535

TO SECURITY GUARD

3938535

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/06/2019  
TIME 16:35

VEHICLE NO

SME5498J

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462

Tel no.: 6631 1188  
Customer Detail

Account Detail	Account No	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No	0
	Document Date	07/08/2019
		Mdm Loh Wai Leng 30 Toh Tuck Road  Singapore 596705 Mobile: 97529772

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWXEBW	S2	ZVW40R	04/10/2018	SME5498J	0	46123 72/DS/SME5498J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDZS3EU90J033667 2ZROC52952 60 Thomas Pang W T 05/08/2019 8.00 07/08/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: YM9886L DATE OF ACC: 18.06.2019 BY:LKK-RASUL @ 05.08.2019 03 WORKING DAYS				50.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (N * ETT)				180.00
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NET * T)				122.40
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)	18			180.00
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS * AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				720.00
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS *				590.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE * PER PANEL APPLICATION (REAR BUMPER) PO:23292	164			91.59
8	1	T52159-47912 COVER, RR BUMPER	1.00	556.40		556.40
9	2	T52023-12240 REINFORCEMENT	1.00	216.80		216.80
10	3	T76891-47040 SPOILER, RR NO.1	1.00	734.60		734.60
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4042847

TO SECURITY GUARD

4042847

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 07/08/2019  
TIME 15:25

VEHICLE NO

SME5498J

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape





Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 120462  
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mdm Loh Wai Leng 30 Toh Tuck Road Singapore 596705 Mobile: 97529772
	Document No 0	
	Document Date 07/08/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWXEBW	S2	04/10/2018	SME5498J	0	46123	72/DS/SME5498J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDZS3EU90J033667	22ROC52952	60	Thomas Pang W T	05/08/2019	8.00	07/08/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	4	S52161-OK040 PIECE, RR BUMPER	10.00	4.10		41.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	3,482.79
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	GST 7.00% Less	243.80 0.00
		0.00 0.00	Amount Due	3,726.59

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO  
SME5498J

CUSTOMER

DATE  
TIME  
07/08/2019  
15:25

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

inchcape

4042848

4042848



**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 13 August 2019 10:19 AM  
**To:** Thomas Pang PTCBC; Rasul (LKKAUTO); SUR; Admin A  
**Subject:** RE: Finalize Report for SME5498j

Dear Thomas,

WITHOUT PREJUDICE

Confirmed \$3482.79 before GST @ 3 working days.

**Kindly send Final invoice and all supporting documents directly to CHINA TAIHING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>  
**Sent:** Wednesday, 7 August 2019 3:40 PM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Finalize Report for SME5498j

Dear Rasul,

Attach finalize report for your perusal. 03 working days.

Thank you

Regards

thomas

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2019 17:03		13 Aug 2019 09:28 <a href="#">Edit Adj Rpt</a>	<b>S\$3,482.79</b> <a href="#">Edit Estimates</a>	<b>S\$3,482.79</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>0</b> , Co. Reg. No.: 0									
Main Claimant: <b>LOH WAI LENG</b> , ID: S0114861C									
Vehicle Reg. No.: <b>SME5498J</b>		Date of Loss: 18/06/2019 17:00 - :59 [8 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>YM9886L</b>		Policy No. (Claimant): <b>VPA/P2186831</b>							
		Excess: <b>S\$0.00</b>							
Repairer: <b>Borneo Motors (S) Pte Ltd (Pandan)</b> 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 22/08/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















## Claim Documents

**\*SME5498J**  
**[YM9886L]**  
**TP**  
**LOH WAI LENG**  
**Jun 18 2019 5:00PM**  
**[0]**  
**Borneo Motors (S) Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a>		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	20/06/19 09:08	<b>Accident Statement</b>		Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	20/06/19 09:05	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/08/19 10:51	<b>General View</b>		Load PDF	
2	13/08/19 10:52	<b>Reinspection Photo</b>		Load PDF	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail	Print
1	20/06/19 09:04	<b>Sketch Plan</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 09:04	<b>Sketch Plan #2</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 09:05	<b>CI</b> [Linked Accident Report Documents]		Load TIF	
4	20/06/19 09:05	<b>Identification Card</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 09:05	<b>Identification Card</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

**View** [View In Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/06/19 09:08	Accident Statement	 Load HTML	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	20/06/19 09:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/06/19 09:04	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 09:04	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 09:05	CI	 Load TIF	<input type="checkbox"/>
4	20/06/19 09:05	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 09:05	Identification Card	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div></div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011011/R1VD3E2

Date: 15/08/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SME5498J

Insured Vehicle No : YM9886L

Date of Loss: 18/06/2019

Nature of Claim: TP Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5498J

Make &amp; Model: TOYOTA PRIUS ALPHA, 1.8 (A)

Engine No: 2ZR0C52952

Reg. Date: 04/10/2018 (Man. Year: 2018)

Chassis No: JTDZS3EU90J033667

Colour: White

Odometer: 10811 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size: 205/60R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,749.85	1,598.80	151.05	8.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,193.99	1,883.99	1,310.00	41.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,943.84</b>	<b>3,482.79</b>	<b>1,461.05</b>	<b>29.55</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>346.07</b>	<b>243.80</b>	<b>102.27</b>	<b>29.55</b>
<b>Nett Amount (S\$)</b>	<b>5,289.91</b>	<b>3,726.59</b>	<b>1,563.32</b>	<b>29.55</b>

### INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 05/08/2019 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2019)
<b>Parts:</b>	M1-MPV	TOYOTA PRIUS ALPHA 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME5498J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BACK SENSOR 070 WHITE PEARL	Not Necessary	101.05 FS	*- FS
2	1		*COVER,RR BUMPER	Cut	556.40 FS	*556.40 FS
3	1		*REAR BPR REINFORCEMENT	Bent	216.80 FS	*216.80 FS
4	1		*SPOILER,RR NO.1	Cut	734.60 FS	*734.60 FS
5	10		*PIECE,RR BUMPER	Necessary	41.00 FS	*41.00 FS
6	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>1,749.85</b>	<b>1,598.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	122.40	122.40
3	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	1,440.00	720.00
5	RESPRAY ACC AFFECTED AREAS	New	1,180.00	590.00
6	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER)	New	91.59	91.59
Gross Labour Cost (\$\$)			<b>3,193.99</b>	<b>1,883.99</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >