

ASS. REC. BY:

REF: CS3/CTI19011015/11cd3er2 Special Instruction:

Surveyor: TEJANIKYASSIGNMENT (Office)From (Person): Chong Boon Sen of CTIDate/Time: 21/6/19 @ 1:03pm

Estimated Cost: _____ Bill to: _____

OD PP WS TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: WQU 5449 Insured: SGZ 6082Dat Workshop m/s ACE Autohub Tel: 68441184of 13 kaki Bukit Road # 03-29Policy No: DMPCSN30672918000 Claim No: SNM190202834002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/6/19
(Client's Record)CA / REV / REP. / REV 24 HRS 14721/6/19
H.O.D. Endorsement: _____Date/Time: 3pm @ 21/6/19 Person Contacted: Ann Vehicle IN OUTDate/Time • Action/Instruction Estimate XWQU 5449 - XSGZ 6082D - X25/6/19 @ 12:25pm Janice said they engaged their own Surveyor.Discontinue: 25/6/2019After repair: 5/7/2019


Surveyor: *Tanpin*

REF: *CTI*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 ODV TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

Veh No: *WQ45449* Yr Regn: *2007 Dec.*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Honda Civic* C.C. *1998*
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *160666* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *PMHF D26307D402559*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: *205/45R17*
 R: *205/45R17*



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Continental*
 Front Rear
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. _____ D.O.I. *24/6/19*
 Survey held at *Ace Autolution 13 #03-29*
 Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>No GIA Range + Days \$7000 - \$8000 10 days</i>
	<i>(Signature)</i>
	<i>2/8/2019</i>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____

Days Of Repair: *10*
 Resurvey No. of Trip: *2*

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<i>190</i>
Transportation:	_____
Photos	_____
Others	_____
TOTAL	<i>190</i>

Report Format : *PRC*
 Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:31 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	tai weng kiat								
Vehicle Reg. No.:	WQU5449	Date of Loss:	17/06/2019 00:00 - :59						
Claim Type:	TP / SNM19D202834C02	Policy/Cover Note No.:	DMPCSN30672918000						
Vehicle Reg. No. (Insured):	SGZ6082D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 21 June 2019 1:03 PM
To: Sim Teo Koon
Cc: 'Ace Autolution'; assignments
Subject: RE: OUR REF: SNM19D202834 / JEQ/190542/0619/ACE(ZL)

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: Thursday, 20 June, 2019 10:33 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Ace Autolution' <admin@aceauto.com.sg>
Subject: FW: OUR REF: SNM19D202834 / JEQ/190542/0619/ACE(ZL)

Dear Sir,

We refer to your email / letter.

We are instructed that our client is not agreeable to the surveyors proposed by you.

Please be informed that our client do not have 10 surveyors, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) SK Auto Consultants,
- 2) PAR Automotive Consultancy,
- 3) LCW APPRAISER PTE LTD
- 4) Sincere Appraisal Services,
- 5) Pal's Appraisal Pte Ltd,
- 6) Mc-Coy Appraiser Pte Ltd,

If the above is not agreeable by you, please be informed that our client 's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4
#03-29, Bartley Biz Centre
Singapore 417807
TEL: 6844 1184

*** Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)
JusEquity Law Corporation.
Tel: 6506 6065, Fax: 6536 9339
E-mail: tk_sim@juseq.com.sg

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Wednesday, 19 June, 2019 3:30 PM
To: zul@juseq.com.sg
Subject: OUR REF: SNM19D202834 / JEQ/190542/0619/ACE(ZL)

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **WQUS449**

No. Siri A **5808924**

11F 8/4
 121 03009
 580302086182
 (MAL)

Nama Pemunya Berdaftar

RAHIMI BINTI ARSHAD

Alamat

NO 7-1-1 APRT KENARI JALAN 2/5 TAMAN MELATI
 53100 SETAPAK U.P. KUALA LUMPUR

MRS M/1

No Enjin	: K20Z21922534	B.D.M/B.G.K	: -
No. Casis	: PMHFD26307D402559	B.T.T.	: -
Buatan	: HONDA	Berat Kerb	: -
Nama Model	: CIVIC 2.0L I-VTEC (A)	B.T.M.	: -
Keupayaan Enjin	: 1998 S.P	B.G.1	: -
Bahan Bakar	: PETROL	B.G.2	: -
Warna	: PERSENDIRIAN-MOTOKAR INDIVIDU	B.G.3	: -
Kelas Kegunaan	: MOTOKAR	B.G.4	: -
Jenis Badan	: 2007	B.G.5	: -
Tahun Dibuat	: 14/12/2007	B.G.6	: -
Tarikh Pendaftaran	: PERSENDIRIAN	B.G.7	: -
Status Pemunya		B.G.8	: -
Muatan Tempot	: 5	B.G.9	: -
Duduk		B.G.10	: -
Kadar Lesen		B.G.11	: -
Kenderaan Motor	: RM187.50	B.G.12	: -
	: 12 bulan		
	: RM379.00		

189832081458

Perakuan Pendaftaran ini dikeluarkan oleh Pengarah JPJ Negeri **JPJ UTILAYAH PERSEKUTUAN 01**

Tandatangan Pemunya Berdaftar

PENGANEKAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

1. HAK MILIK DITUNTUT OLEH: **DIBATALKAN** SURAT : 2351



5. HAK MILIK DITUNTUT OLEH: PUBLIC BANK BERHAD NO SIRI : H05/522706/14

7. HAK MILIK DITUNTUT OLEH: **DIBATALKAN** NO SIRI SURAT : H03/523009/13

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikahendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
- Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaruh lesen 60 hari sebelum tempohnya tamat.
- Anda dikahendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikahendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

8/4

Notis Penting : Kami tidak lagi mencetak butir-butir polisi

Certificate of Insurance/Sijil Insuran

ORIGINAL

ROAD TRANSPORT ACT, 1987 (MALAYSIA) / AKTA PENGALUTAN DARATAN 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1995 (MALAYSIA) / PERATURAN PERUBAHAN KESEKELUARAN BERKAITAN DENGAN RISIKO PIHAK KETIGA (1995) (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) (REPUBLIC OF SINGAPORE) / PERATURAN KESEKELUARAN BERKAITAN DENGAN RISIKO PIHAK KETIGA DAN PEMBIAYAN NO. 1 1990 (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1990 (REPUBLIC OF SINGAPORE) / PERATURAN PERUBAHAN KESEKELUARAN BERKAITAN DENGAN RISIKO PIHAK KETIGA DAN PEMBIAYAN 1990 (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 88) (NEIGARA BRUNEI) DAN PERATURAN PERUBAHAN KESEKELUARAN BERKAITAN DENGAN RISIKO PIHAK KETIGA (NEIGARA BRUNEI) DAN PERATURAN PERUBAHAN KESEKELUARAN BERKAITAN DENGAN RISIKO PIHAK KETIGA (NEIGARA BRUNEI)

CERTIFICATE NO. / NO SIJIL 01011BIH2000705

C.I Code / Kod Sijil Insurans : M.X.1

Agent Code : 30862-01-C

Agent Name : LIM KEE HEOH

1. Registration No. / No. Pendaftaran : WQU5449

Cover Type / Jenis Perlindungan: COMPREHENSIVE

2. Name of Policyholder / Nama Pemegang Polisi : TAI WENG KIAT

3. Excess / Lebihan: RM0.00

Sum Insured / Jumlah Diinsuranskan: RM46,000.00

NCB / DTT: 55.00%

4. Hire Purchase / Sewa Beli :

Wef: 24-08-2018

5. Effective Date and Time of Commencement of Insurance for the purpose of the Ordinance / Tarikh dan Masa Permulaan Insurance bagi tujuan Ordinan : 24-08-2018 01:53pm

6. Date and Time of Expiry of the Insurance / Tarikh dan Masa Tamat Insuran: 23-08-2019 12:00am

7. Person or Classes or Persons entitled to drive / Orang atau Kelas Orang yang Layak memandu

Orang atau Kelas Orang yang Layak memandu

a) The policyholder.

b) Any other person who is driving on the Policyholder's order or with his permission.

a) Pemegang Polisi.

b) Sesiapa yang memandu atas arahan Pemegang Polisi atau dengan kebenarannya.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by a Court of Law or by reason of any enactment or Regulation in behalf from driving the Motor Vehicle. / Dengan syarat orang tersebut dibenarkan memandu menguati undang-undang perlesenan atau undang-undang lain atau peraturan lain atau peraturan untuk memandu Kenderaan Bermotor tersebut atau telah dibenarkan dan tidak disifatkan ketidaklayakannya di atas perintah Mahkamah atau oleh sebarang mana-mana enaiktan atau peraturan daripada memandu Kenderaan Bermotor tersebut

B. Limitation as to use* / Had Penggunaan

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pacemaking, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Digunakan hanya untuk tujuan social, domestic dan persiaran and untuk perniagaan Pemegang Polisi.

Polisi ini tidak melindungi kegunaan untuk sewaan atau ganjaran, perlumbaan, mengkadar kelajuan, ujian kebolehpercayaan, ujian kelajuan, membawa barangan selain daripada sampel yang berkaitan dengan apa-apa pekerjaan atau perniagaan atau digunakan untuk apa-apa tujuan yang berkaitan dengan Perdagangan Motor.

* Limitation rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 180) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading. / * Batasan kegunaan tidak berkuatkuasa oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) atau Seksyen 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 180) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam tidak termasuk di bawah tajuk ini.

I/We hereby certify that the Policy to which the Certificate relates is issued in accordance with the Provisions of Part IV of the Road Transport Act, 1987 (Malaysia), The Motor Vehicles (Third Party Risks and Compensation) Ordinance 1990 (Republic of Singapore) and The Motor Vehicles Insurance (Third Party Risks) Enactment 1990 (State of Brunei). Saya/Kami dengan ini menguati bahawa Polisi yang berhubung dengan Sijil ini adalah di bawah perundangan Bahagian IV perundangan-perundangan Akta Pengangkutan Jalan 1987 (Malaysia), Ordinan kenderaan-kenderaan Berling (Risiko-Risiko Pihak Ketiga dan Pembiayaan) 1990 (Repubik Singapura) dan Insuran Kenderaan Berling (Risiko bagi Pihak Ketiga) Enaiktan 1990 (Negara Brunei Darussalam).

You are required to read the Notice in regard to your Personal Data or Sensitive Personal Data. The notice is in Our Website. Please go to www.pacific-orient.com. Anda diwajibkan untuk membaca Nota berkenaan Data Peribadi atau Data Peribadi Sensitif anda. Nota tersebut boleh di-navigasi di Laman Web kami. Sila lawati www.pacific-orient.com.

THIS IS A COMPUTER GENERATED DOCUMENT AND IT DOES NOT REQUIRE SIGNATURE. THIS DOCUMENT SHALL NOT BE INVALIDATED SOLELY ON THE GROUND THAT IT IS NOT SIGNED. INI ADALAH DOKUMEN YANG DIKELUARKAN OLEH KOMPUTER DAN KEKURANGAN TANDA TANGAN. DOKUMEN INI TIDAK HAPUS DITANDAKAN SEMEDERA MATA ATAS ALASAN IA TIDAK DITANDAKAN.



**SINGAPORE
POLICE FORCE**



T/20190617/2169

2 of 3

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20190617/2169

CONTINUATION OF REPORT

Vehicle Owner			
Name	TAI WENG KIAT	ID No.	G7590094K
Related Vehicle	SGZ6082D (Car)	Contact No.	81385554
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	TAN AH KEK	ID No.	S1843352D
Related Vehicle	WQU5449 (Car)	Contact No.	82281731
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/06/2019 at about 1830hrs, I was driving my white Honda civic, WQU5449 at the first lane along BKE expressway in front of lamp post 1171S17F and my vehicle was stationary due to traffic congestion. Subsequently, I felt an impact from my rear portion and when I turn my head, I realized that a white Toyota, SGZ6082D had collided onto my rear portion. Both the drivers and I then alighted from our vehicle to inspect the damage and as a result of the collision my rear left bumper was crumpled together with a crack rear left tail light. After the accident, I felt sharp pain on my rear body and will be seeking medical treatment once I lodged this traffic report. My vehicle is not install with any in-car camera and so far, I do not have any witness.



**SINGAPORE
POLICE FORCE**



T/20190617/2169

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

3 of 3

Report No. T/20190617/2169 ←

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt HEAP ZHI YONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

17/06/2019 21:22

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No.: 65472076

Classification Of Case:

Authentication Stamp

NP168

→
→

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	tai weng kiat								
Vehicle Reg. No.:	WQU5449	Date of Loss:	17/06/2019 00:00 - :59 [138 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202834C02	Policy/Cover Note No.:	DMPCSN30672918000						
Vehicle Reg. No. (Insured):	SGZ6082D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WQU5449 (SNM19D202834C02)
 [SGZ6082D]
 TP
 tai weng kiat
 Jun 17 2019 12:00AM
 [-]
 Ace Autolution

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
2	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
3	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
4	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
5	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
6	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
7	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
8	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
9	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
10	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
11	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
12	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
13	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
14	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
15	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
16	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
17	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
18	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
19	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
20	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
21	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
22	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
23	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
24	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
25	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
26	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
27	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
28	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
29	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
30	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
31	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
32	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
33	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
34	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
35	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
36	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>
37	02/08/19 10:48	General View		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/08/19 10:48	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	02/08/19 10:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	02/08/19 10:50	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/08/19 18:33	pri contact	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119011015/T1CD3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30672918000	
Claimant Vehicle No: WQU5449	Insured Vehicle No: SGZ6082D	
Date of Loss: 17/06/2019	Nature of Claim: TP	Claim No: SNM19D202834C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WQU5449	Engine No: K20Z21922534
Make & Model: HONDA CIVIC, 2.0 L (A)	Chassis No: PMHFD26307D402559
Reg. Date: 14/12/2007 (Man. Year: 2007)	Odometer: 160666 km
Colour: White	
Engine Capacity: 1998 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/45 R17	Rear Tyre Size: 215/45 R17
Front Left Side: Continental 6 mm	Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm	Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2019		
Date Inspected: 24/06/2019	Inspected At:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair: 10.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts: 143	HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WQU5449)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >