

22/03/2002

ASS. REC. BY:

REF: CS/CT119011019/K9/d3

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Hong

of

CT1

Date/Time: 21.6.19 16.29p.m

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM 9422H

Insured:

SVV 389 U

at Workshop m/s MBM wheel power

Tel:

62628888

of 160 Sin Ming Drive #06-02

Policy No: DMPCSM18316318000

Claim No: SNM 19D20288202

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18.6.2019

(Client's Record)

24.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.6.19 4.43p.m

Person Contacted:

cassandra

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKM 9422H-X
	SVV 389U - CC4 / CT117008549 / T1pb3k2 DOA - 26/04/2017
	1/10 U Lim @ 24,800 Ca from (Red P 14688.10, 37%)

(08/11/13)

REF C71

ASS. REC. BY:

ASSIGNMENT

From:

Date: 24.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 94224

at Workshop m/s MBM Wheel Power
of 160 Sin ming Drive #06-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$76k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKM 94224

Yr Regn:

04, 14

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini One

c.c.

1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

43072

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMWSR 32000T80.5599

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

18/6/19

D.O.I.

24/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S, O/S body & Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

1) 04/10/2019

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

24800

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019		21 Jun 2019 16:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Claimant's Insurer:

Adjuster:

LIM BEE LENG, ID: S6934555G

SKM9422H

TP / SNM19D202882C02

SJV389U

MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/07/2019]

Date of Loss:

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

18/06/2019 19:00 - :59

DMPCSN18316318000

5103091733

S\$1,500.00

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4555G
Vehicle Details	
Vehicle No.:	SKM9422H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	MINI
Vehicle Model:	ONE 1.6 AT 3DR ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	B535J622N16B16A
Chassis No.:	WMW5R32000T805599
Maximum Power Output:	72.0 kW (96 bhp)
Open Market Value:	\$21,139.00
Original Registration Date:	25 Apr 2014
First Registration Date:	25 Apr 2014
Transfer Count:	1
Actual ARF Paid:	\$16,595.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2024
PARF Rebate Amount:	\$11,616.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
C/P Paid:	\$71,335.00
COE Rebate Amount:	\$34,474.00
Total Rebate Amount:	\$46,090.00

The information contained herein is correct as at 25 Jun 2019

OK

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKM9422H
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MINI
Vehicle Model:	ONE 1.6 AT 3DR ABS D/AIRBAG 2WD
Chassis No.:	WMWSR32000T805599
Propellant:	Petrol
Engine No.:	B535J622N16B16A
Engine Capacity:	1598 cc
Maximum Power Output:	72.0 kW (96 bhp)
Maximum Laden Weight:	1550 kg
Unladen Weight:	1100 kg
Year Of Manufacture:	2013
Original Registration Date:	25 Apr 2014
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$71,335.00
COE Expiry Date:	24 Apr 2024
Road Tax Expiry Date:	24 Oct 2019
PARF Eligibility Expiry Date:	24 Apr 2024
Inspection Due Date:	24 Apr 2021
Intended Transfer Date:	19 Jun 2019
CO2 Emission:	156.00 (g/km)
CEV/VES Rebate Utilised	\$5,000.00
Amount:	
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Interest Rate From 3.88%, Monthly At \$577, 1 Owner Car



Interest Rate From
3.88%, Monthly At \$577, 1 Owner
Car, Down \$1000.
Car World Automobile. [Share](#)


[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

1 vehicles

MINI One

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MINI One	Any	Any	2013	Any	Any	Any	Available



MINI One 1.6A

\$68,800

\$16,750 /yr

27-Feb-2013

1,598 cc

78,000 km

Hatchback

Available

High Paper Value & Export Body! Guaranteed Best Conditions Mini One In The Market. 2nd Owner. Genuine Low Mileage Of 78k Km. Fully Maintained By Agent Till Warranty. Just Done Full Servicing. No Repai...

Posted: 20-Jun-2019 Tags: 2013 MINI One, 2013 mini one, MINI One, mini one, MINI, One, one, Used MINI

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used MINI One, MINI One Singapore, used MINI One Singapore, used MINI One, used vehicles Singapore or even buy used MINI One Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes-Benz B-Class B180 Style.



1 Owner And Fully Maintained
By C&C, 75K And 90K Service
Package At C&C Included
Direct Owner Stand

HIN LUNG AUTO
 Ho Bee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

30 years
 of car sale

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

6 vehicles

MINI One

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MINI One	Any	Any	2015	Any	Any	Any	Available
	MINI One 1.2A SDR	\$80,900	\$11,610 /yr	31-Dec-2015	1,198 cc	55,000 km	Hatchback	Available
Lowest Monthly Installment Of \$774, Consignment Car, Pepper White, Start/Stop Button, 6 Speed Automatic Transmission, 6 x Airbags, Full Serviced Record, Extended Warranty Available, Please Call For VL... Eurokars Next Pte Ltd Posted: 15-Jun-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								
	MINI One 1.2A	\$64,800	\$11,050 /yr	30-Jan-2015	1,198 cc	56,000 km	Hatchback	Available
Tip Top Condition Mini ONE, 365 Days Under Shelter, 1 Careful Owner With Very Low Usage At 56000km, Fully Agent Service Since Day 1 Till Now, Well Maintained View To Believe. Posted: 15-Jun-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								
	MINI One 1.2A	\$71,570	\$10,980 /yr	22-Jul-2015	1,198 cc	70,000 km	Hatchback	Available
Start/Stop Button, 6 Speed Automatic. Posted: 15-Jun-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								
	MINI One 1.2A	\$62,800	\$10,760 /yr	08-Jan-2015	1,198 cc	61,000 km	Hatchback	Available
Interest Rate 2.48% Only! Secured And Well Maintained By Fussy Owner. Immaculate Condition Inside And Outside. Certified With Assurance And Quality From STA Evaluation. Give Yourself A Peace Of Mind! ... Car Search Posted: 24-May-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								
<div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> Buy Tyres Online! Latest Special Offers from Tyrepac! </div>								
	MINI One 1.2A SDR	\$75,888	\$12,430 /yr	20-May-2015	1,198 cc	52,000 km	Hatchback	Available
Vehicle Are Sold Through AA Trust Consignment Scheme From Direct Seller To Our Valued Buyer. AA Trust Automotive Posted: 14-May-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								
	MINI One 1.2A	\$68,000	\$11,720 /yr	02-Jan-2015	1,198 cc	50,000 km	Hatchback	Available
Never Fail To Keep You Smiling Each Time You Are About To Step In This Nice Cheerful Sunshine Orange Color Mini One With Unique Checker Leather Upholstery. Zippy And Nippy Towncar With Interchangeable... Posted: 14-May-2019 Tags: 2015 MINI One, 2015 mini one, MINI One, mini one, MINI, One, one, Used MINI								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2019 14:06
Date Of Accident	18/06/2019 19:35
Exact Location Of Accident	ALONG PUNGGOL EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM9422H
Insured/Policyholder	
Name Of Registered Owner	LIM BEE LENG
NRIC No	S6934555G
Email Address	EMILIE5115@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91005115
Alternative Phone No	OFFICE-91005115
Vehicle Particulars	
Manufacturer	MINI
Model	ONE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103091733
Cover Note Number	
Driver	
Name of Driver	LIM BEE LENG
NRIC No	S6934555G
Date Of Birth	03/10/1969
Occupation	OUTDOOR
Date Of Driving Pass	09/09/1997
Driving Experience	21 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91005115
Fax Number	
Contact Number	OFFICE-91005115
Email Address	EMILIE5115@GMAIL.COM

Address	75C LUCKY HEIGHTS
Postcode	467625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN AND POLICE REPORT NO.: T20190619/7001 DRIVER OF SKM9422H WAS CONVEYED TO HOSPITAL AFTER THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV389U
Vehicle Make/Model/Colour	LEXUS / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH BAN YONG (DU WANGYANG)
NRIC/Passport Number	
Contact Number	81289449
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLF2984Z
Vehicle Make/Model/Colour TOYOTA SIENTA / SILVER
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver OMAR KHAN
NRIC/Passport Number S1709113A
Contact Number 96643414
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMH5826E
Vehicle Make/Model/Colour MITSUBISHI
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver MRS LOH
NRIC/Passport Number
Contact Number 96693090
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM BEE LENG
Approximate Age
Injuries Sustain UPPER TORSO
Injured person in which vehicle? SKM9422H
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to police report no.: T/20190619/7001

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190619/7001

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190619/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/06/2019 02:32			Vide Report No.: G/20190618/0186		Station Diary No.:
Informant's Particulars					
Name of Informant: LIM BEE LENG			Address: 75C LUCKY HEIGHTS SINGAPORE 467625		
ID Type / ID No.: NRIC NO / S6934555G			Contact No.: Home/Office:		Mobile: 91005115
Nationality: SINGAPORE CITIZEN			Email: emilie5115@gmail.com		
Sex: Female	Age: 49	Date of Birth: 03/10/1969	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/06/2019 19:35	Type of Location: Straight Road
Location: PUNGGOL EAST				
Weather: Drizzling		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between moving vehicle rear to head				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJV389U	Car	LEXUS	IS250	Black		0
SKM9422H	Car	MINI	ONE 1.6 AT 3DR ABS D/AIRBAG 2WD	Black		0
SLF2984Z	Car	TOYOTA	Sienta	Silver		1
SMH5826E	Car	MITSUBISHI		Silver		0

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190619/7001

2 of 4

Report No. T/20190619/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKM9422H	NTUC Income Insurance Co-Operative Limited	5103091733	15/08/2018	24/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	LIM BEE LENG		ID No.	S6934555G
Related Vehicle	SKM9422H (Car)		Contact No.	91005115
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	18/06/2019		Date Discharge	18/06/2019
No. of Days granted Medical Leave	03		Degree of Injury	Slight
Driver				
Name	OMAR KHAN		ID No.	S1709113A
Related Vehicle	NIL		Contact No.	96643414
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	MRS LOH		ID No.	NIL
Related Vehicle	NIL		Contact No.	96693090
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190619/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20190619/7001

CONTINUATION OF REPORT

Driver			
Name	TOH BAN YONG (DU WANGYANG)		ID No. S802844
Related Vehicle	NIL		Contact No. 81289449
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Three other cars involved are SJV389U, SLF2984Z, SMH5826E.
Accident happened along Punggol East, near the Golf Range.

I was driving at a normal speed along Punggol East towards Punggol Central, out of a sudden felt a huge impact from the rear and felt my car swayed. I was momentary blackout. When I come about, I felt pain on my right upper collar bone, arms and elbow, and my hands and legs were trembling uncontrollably. A guy from SLF2984Z came to my window and ask for my driving license but I didn't have the energy to get it from my wallet. Subsequently another guy from SJV389U ask for my handphone number. I asked him who is the driver that hit my car, he said he was the one and he said he got lost and was checking on his phone GPS for some split seconds and this accident came about. I called 999 reported the accident and my physical & mental condition. I also called my husband to come over to help me. I stayed put in my car until the ambulance medical personnel arrived to help me out and was transported by ambulance to Sengkang General Hospital.

My husband remain on site to assist the police on my behalf. My car's video camera One IRoad 32GB Micro SD was surrendered to the police on site for investigation purpose.

The A&E doctor reviewed and took some X-ray and prescribed to me some medications and also given me 3 days MC for my condition.
I was advised to go home to rest and should any persist pain or discomfort to return to the hospital for another check.

Contacted the IO Mr Fazal after discharge from hospital, and he advised me to go to the nearest police station to make a traffic accident report. I head to Chai Chee Drive Police Station wanted to file the report, but the police lady told me the system is under maintenance till 2am, she said I can lodge the report via singpass online. Hence I am submitting this report online.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190619/7001

4 of 4

Report No. T/20190619/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / TPIB /
NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
19/06/2019 02:32

Classification Of Case:



DESCRIPTION	QTY	Unit Price	List Price
FRONT BUMPER	1	\$	2,318.00
FRONT BUMPER TOW COVER	1	\$	65.00
FRONT BUMPER LOWER TRIM AIR INLET	1	\$	278.00
FRONT BUMPER LOWER CENTER FRAME	1	\$	337.00
FRONT BUMPER RH FOG LAMP COVER	1	\$	79.00
FRONT BUMPER AIR DUCT RH	1	\$	92.00
FRONT BUMPER SPONGE	1	\$	162.00
FRONT REINFORCEMENT	1	\$	690.00
RADIATOR GRILLE TOP MOULDING	1	\$	183.00
RADIATOR CENTER GRILLE	1	\$	332.00
RADIATOR GRILLE FRONT TRIM	1	\$	158.00
RADIATOR GRILLE CENTER BOTTOM	1	\$	244.00
RADIATOR FINISHER ROD	1	\$	209.00
FRONT BUMPER LOWER SPOILER	1	\$	880.00
FRONT DEFLECTOR LIP RH	1	\$	63.00
FRONT RH FENDER	1	\$	866.00
BONNET	1	\$	3,024.00
BONNET FRONT CHROME MOULDING	1	\$	183.00
BONNET FRONT SEAL	1	\$	125.00
BONNET HINGE LH	1	\$	179.00
BONNET HINGE RH	1	\$	179.00
BONNET LOCK	1	\$	151.00
FRONT RH DOOR	1	\$	3,150.00
TAIL GATE	1	\$	3,024.00
TAIL GATE WEATHERSTRIP	1	\$	378.00

TAIL GATE "ONE" EMBLEM	1	\$	<i>M</i>	158.00
TAIL GATE "MINI" LOGO	1	\$	<i>M</i>	176.00
REAR BUMPER	1	\$	<i>R</i>	2,444.00
REAR BUMPER TOW COVER RH	1	\$	<i>nd R</i>	60.00
REAR BUMPER LOWER SPOILER	1	\$	<i>Br 1 Tr</i>	740.00
REAR BUMPER FOG LAMP COVER	1	\$	<i>nd</i>	252.00
REAR BUMPER GUIDE RAIL	1	\$	<i>Sw 7</i>	65.00
REAR BUMPER BRACKET	1	\$	<i>R 7</i>	45.00
REAR BUMPER RH SUPPORT	1	\$	<i>Sw</i>	40.00
REAR REINFORCEMENT	1	\$	<i>R 7</i>	629.00
REAR BUMPER SPONGE	1	\$	<i>CM 7</i>	201.00
REAR END PANEL OUTER	1	\$	<i>R</i>	1,208.00
REAR END PANEL INNER	1	\$	<i>R</i>	1,134.00
REAR RH FENDER WHEEL ARCH MOULDING	1	\$	<i>Bu</i>	277.00
RH HEAD LAMP	1	\$	<i>mg CM</i>	1,032.00
RH HEAD LAMP OUTER TRIM	1	\$	<i>Tr 7</i>	103.00
FRONT RH FOG LAMP ASSY	1	\$	<i>Bu</i>	390.00
PARKING LIGHT	1	\$	<i>Sw</i>	372.00
TAIL LAMP RH	1	\$	<i>Sw</i>	620.00
REAR FOG LIGHT	1	\$	<i>R</i>	252.00
EXHAUST PIPE	1	\$	<i>R 7</i>	1,913.00
EXHAUST RUBBER MOUNTING	2	\$	<i>Tr 7</i>	160.00
EXHAUST PIPE BRACKET LH	1	\$	<i>DIS 7</i>	131.00
EXHAUST PIPE BRACKET RH	1	\$	<i>DIS 7</i>	131.00
BUMPER CLIPS	20	\$	<i>M</i>	120.00
Total: \$				30,002.00
LESS 10% \$				(3,000.20)
Parts Total: \$				27,001.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT	1	\$	80.00
REVERSE SENSOR	1 SET	\$	400.00
WINDSCREEN SEALANT	1	\$	80.00
DOOR TAPE	1	\$	200.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	2,100.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	80.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	200.00
TO REMOVE AND REPLACE REAR WINDSCREEN	\$	150.00
TO DISMANTLE & TRANSFER DOOR / TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE & DOOR / FACILITATE REPAIR	\$	200.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	100.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	150.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	40.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00
TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)	\$	400.00
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	\$	100.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	2,600.00

Total: \$ 33,961.80

7% GST: \$ 2,377.33

Grand Total: \$ 36,339.13

39488.10

MBM WHEELPOWER PTE LTD

Your Ref: SJV389U
Our Ref: SKM9422H



To: CHINA TAIPING

CC

Fax

Date: 23/8/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MINI ONE 1.6 AT
Chassis No.: WMWSR32000T805599
Engine No.: B535J622N16B16A
Year of Make: 2013
Accident Date: 18 June 2019

ESTIMATE FOR VEHICLE NO. : SKM9422H

DESCRIPTION	QTY	List Price
FRONT BUMPER	1	\$ 2,318.00
FRONT BUMPER TOW COVER	1	\$ 65.00
FRONT BUMPER LOWER TRIM AIR INLET	1	\$ 278.00
FRONT BUMPER LOWER CENTER FRAME	1	\$ 337.00
FRONT BUMPER RH FOG LAMP COVER	1	\$ 79.00
FRONT BUMPER SPONGE	1	\$ 162.00
FRONT REINFORCEMENT	1	\$ 690.00
RADIATOR GRILLE TOP MOULDING	1	\$ 183.00
RADIATOR CENTER GRILLE	1	\$ 332.00
RADIATOR GRILLE FRONT TRIM	1	\$ 158.00
RADIATOR GRILLE CENTER BOTTOM	1	\$ 244.00
RADIATOR FINISHER ROD	1	\$ 209.00
FRONT BUMPER LOWER SPOILER	1	\$ 880.00
FRONT DEFLECTOR LIP RH	1	\$ 63.00
FRONT RH FENDER	1	\$ 866.00
BONNET	1	\$ 3,024.00
BONNET FRONT CHROME MOULDING	1	\$ 183.00
BONNET LOCK	1	\$ 151.00
TAIL GATE	1	\$ 3,024.00
TAIL GATE "ONE" EMBLEM	1	\$ 158.00
TAIL GATE "MINI" LOGO	1	\$ 176.00
REAR BUMPER	1	\$ 2,444.00
REAR BUMPER TOW COVER RH	1	\$ 60.00
REAR BUMPER LOWER SPOILER	1	\$ 740.00
REAR BUMPER FOG LAMP COVER	1	\$ 252.00

REAR REINFORCEMENT	1	\$	629.00
REAR BUMPER SPONGE	1	\$	201.00
REAR END PANEL OUTER	1	\$	1,208.00
REAR RH FENDER WHEEL ARCH MOULDING	1	\$	277.00
RH HEAD LAMP	1	\$	1,032.00
RH HEAD LAMP OUTER TRIM	1	\$	103.00
FRONT RH FOG LAMP ASSY	1	\$	390.00
EXHAUST PIPE	1	\$	1,913.00
EXHAUST RUBBER MOUNTING	2	\$	160.00
EXHAUST PIPE BRACKET LH	1	\$	131.00
EXHAUST PIPE BRACKET RH	1	\$	131.00
BUMPER CLIPS	20	\$	120.00
Total:		\$	23,371.00
LESS 10%		\$	(2,337.10)
Parts Total:		\$	21,033.90

SPECIAL NETT

REVERSE SENSOR	1 SET	\$	400.00
WINDSCREEN SEALANT	1	\$	40.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	1,200.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	60.00
TO REMOVE AND REPLACE REAR WINDSCREEN	\$	120.00
TO DISMANTLE & TRANSFER DOOR / TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE & DOOR / FACILITATE REPAIR	\$	60.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	100.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	150.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	40.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	40.00
TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)	\$	400.00
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	\$	60.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1,800.00
Total:	\$	25,503.90
Supp:	\$	5,526.30
Total:	\$	31,030.20
Less 20%	\$	(6,206.04)
Total:	\$	24,824.16

Lump Sum: \$	24,800.00
	14 Days Repair

MBM WHEELPOWER PTE LTD

Your Ref: SJV389U
Our Ref: SKM9422H



To: CHINA TAIPING

CC

Fax

Date: 23/8/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MINI ONE 1.6 AT
Chassis No.: WMWSR32000T805599
Engine No.: B535J622N16B16A
Year of Make: 2013
Accident Date: 18 June 2019

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SKM9422H

DESCRIPTION	Part Number	QTY	List Price	
FRONT RH FENDER INNER SHIELD	51717207578	1	\$ CM 180.00	✓
REAR RH FENDER INNER SHIELD	51717136168	1	\$ CM 180.00	✓
EXPANDING RIVET	7130702966	20	\$ M 180.00	✓
REAR RH EXHAUST HEAT SHIELD	51482757191	1	\$ B 504.00	✓
FRONT RH FOG LAMP HOLDER	51117248797	1	\$ D 68.00	✓
CLIPS	7132757821	10	\$ M 90.00	✓
SPOILER RIVET	51472754477	2	\$ M 10.00	✓
SPOILER CLIP	07130702 966	10	\$ M 90.00	✓
EXPANDING RIVET (D=8MM)	51471911992	4	\$ M 20.00	✓
BONNET CLIPS	51132752145	6	\$ M 30.00	✓
REAR SPOILER RIVET (D=7.5MM)	51481915964	2	\$ M 10.00	✓
REAR BUMPER RIVET	003-90-14345	10	\$ M 90.00	✓
FRONT CENTER PANEL	51647248799	1	\$ B 1,382.00	✓
DISTANCE SENSOR		1	\$ Shar 250.00	✓
DECOUPLING RING		4	\$ CM 60.00	✓
AIR HORN HIGH	61337313624	1	\$ CM 205.00	✓
AIR HORN LOW	61337313625	1	\$ CM 205.00	✓
EXHAUST PIPE CHROME TIP		1	\$ Rd 126.00	✓
LIGHTING WIRING SET		1	\$ T 1,252.00	✓
AIR-CON CONDENSER		1	\$ M 527.00	✓
FRONT RH FENDER WHEEL ARCH MOULDING		1	\$ Rd 198.00	✓
		Total:	\$ 5,657.00	
		LESS 10%	\$ (565.70)	
		Parts Total:	\$ 5,091.30	

SPECIAL NET:

REAR RH TYRE - PIRELLI P1 CINTURATO (195/55R16)	1	\$	CM 295.00	Bobn
TOWING	1	\$	(Bill) 100.00	✓
REAR NUMBER PLATE & HOLDER	1	\$	Rd 40.00	✓
		Total:	\$ 5,526.30	



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1217375

Date: 18/6/19

M/S:

MBM Wheel Dr HD

Vehicle No:

Shirman 224

Model

Cooper

From:

Park A/S Inc

Time Start:

2212

To:

160 Sin Ming

Time End:

1045

Remarks:

☐ Change Tyres / Jump Start

☒ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☐ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 100

GST S\$ 7

TOTAL S\$ 107

bizSAFE₃

Important Note:

Received By

YWM / YM 1928P

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

Adjuster recommendation S\$26,536.00 exceeds max mandate of S\$0.00 given by the insurer for direct offer.
Adjuster must seek a new mandate from insurer.

You cannot authorize this offer because
Adjuster recommendation S\$26,536.00 exceeds max mandate of S\$0.00 given by the insurer for direct offer.
Adjuster must seek a new mandate from insurer.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011019/KQD3
Date: 09/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN18316318000
Claimant Vehicle No: SKM9422H Insured Vehicle No: SJV389U
Date of Loss: 18/06/2019 Nature of Claim: TP Claim No: SNM19D202882C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM9422H
Make & Model: MINI ONE, 1.6 (A) Engine No: B535J622N16B16A
Reg. Date: 25/04/2014 (Man. Year: 2013) Chassis No: WMWSR32000T805599
Colour: Metallic Black Odometer: 43072 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16 Rear Tyre Size: 195/55 R16
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,188.10	26,841.20	6,346.90	19.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	4,130.00	2,170.00	34.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,488.10	30,971.20	8,516.90	21.57
Approved Total (Overridden) (S\$)		24,800.00		
(S\$)	39,488.10	24,800.00	14,688.10	37.20
+ GST 7.00/7.00% (S\$)	2,764.17	1,736.00	1,028.17	37.20
Nett Amount (S\$)	42,252.27	26,536.00	15,716.27	37.20

INSPECTION

Date of Assignment: 21/06/2019
Date Inspected: 24/06/2019 Inspected At: MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability

under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
Parts:	M1-COUPÉ	MINI ONE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM9422H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	2,318.00 FL	*2,318.00 FL
2	1		*FRONT BUMPER TOW COVER	Dented	65.00 FL	*65.00 FL
3	1		*FRONT BUMPER LOWER TRIM AIR INLET	Dented	278.00 FL	*278.00 FL
4	1		*FRONT BUMPER LOWER CENTER FRAME	Cracked	337.00 FL	*337.00 FL
5	1		*FRONT BUMPER RH FOG LAMP COVER	Missing	79.00 FL	*79.00 FL
6	1		*FRONT BUMPER AIR DUCT RH	Serviceable	92.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Cracked	162.00 FL	*162.00 FL
8	1		*FRONT REINFORCEMENT	Bent	690.00 FL	*690.00 FL
9	1		*RADIATOR GRILLE TOP MOULDING	Mtg Cracked	183.00 FL	*183.00 FL
10	1		*RADIATOR CENTRE GRILLE	Scratched	332.00 FL	*332.00 FL
11	1		*RADIATOR GRILLE FRONT TRIM	Cracked	158.00 FL	*158.00 FL
12	1		*RADIATOR GRILLE CENTER BOTTOM	Cracked	244.00 FL	*244.00 FL
13	1		*RADIATOR FINISHER ROD	Dented	209.00 FL	*209.00 FL
14	1		*FRONT BUMPER LOWER SPOILER	Dented / Distorted	880.00 FL	*880.00 FL
15	1		*FRONT DEFLECTOR LIP RH	Dented	63.00 FL	*63.00 FL
16	1		*FRONT RH FENDER	Buckled	866.00 FL	*866.00 FL
17	1		*BONNET	Bent	3,024.00 FL	*3,024.00 FL
18	1		*BONNET FRONT CHROME MOULDING	Mtg Cracked	183.00 FL	*183.00 FL
19	1		*BONNET FRONT SEAL	Serviceable	125.00 FL	*- FL
20	1		*BONNET HINGE LH	Repair	179.00 FL	*- FL
21	1		*BONNET HINGE RH	Repair	179.00 FL	*- FL
22	1		*BONNET LOCK	Distorted	151.00 FL	*151.00 FL
23	1		*FRONT RH DOOR	Repair	3,150.00 FL	*- FL
24	1		*TAIL GATE	Bent	3,024.00 FL	*3,024.00 FL
25	1		*TAIL GATE WEATHERSTRIP	Serviceable	378.00 FL	*- FL
26	1		*TAIL GATE ONE EMBLEM	Necessary	158.00 FL	*158.00 FL
27	1		*TAIL GATE MINI LOGO	Necessary	176.00 FL	*176.00 FL
28	1		*REAR BUMPER	Bent	2,444.00 FL	*2,444.00 FL
29	1		*REAR BUMPER TOW COVER RH	Dented	60.00 FL	*60.00 FL
30	1		*REAR BUMPER LOWER SPOILER	Bent / Torn	740.00 FL	*740.00 FL
31	1		*REAR BUMPER FOG LAMP COVER	Dented	252.00 FL	*252.00 FL
32	1		*REAR BUMPER GUIDE RAIL	Serviceable	65.00 FL	*- FL
33	1		*REAR BUMPER BRACKET	Repair	45.00 FL	*- FL
34	1		*REAR BUMPER RH SUPPORT	Serviceable	40.00 FL	*- FL
35	1		*REAR REINFORCEMENT	Bent	629.00 FL	*629.00 FL
36	1		*REAR BUMPER SPONGE	Cracked	201.00 FL	*201.00 FL
37	1		*REAR END PANEL OUTER	Bent	1,208.00 FL	*1,208.00 FL
38	1		*REAR END PANEL INNER	Repair	1,134.00 FL	*- FL
39	1		*REAR RH FENDER WHEEL ARCH MOULDING	Buckled	277.00 FL	*277.00 FL
40	1		*RH HEAD LAMP	Mtg Cracked	1,032.00 FL	*1,032.00 FL
41	1		*RH HEAD LAMP OUTER TRIM	Missing	103.00 FL	*103.00 FL
42	1		*FRONT RH FOG LAMP ASSY	Broken	390.00 FL	*390.00 FL
43	1		*PARKING LIGHT	Serviceable	372.00 FL	*- FL
44	1		*TAIL LAMP RH	Serviceable	620.00 FL	*- FL
45	1		*REAR FOG LIGHT	Serviceable	252.00 FL	*- FL
46	1		*EXHAUST PIPE	Bent	1,913.00 FL	*1,913.00 FL
47	2		*EXHAUST RUBBER MOUNTING	Torn	160.00 FL	*160.00 FL
48	1		*EXHAUST PIPE BRACKET LH	Distorted	131.00 FL	*131.00 FL
49	1		*EXHAUST PIPE BRACKET RH	Distorted	131.00 FL	*131.00 FL
50	20		*BUMPER CLIPS	Necessary	120.00 FL	*120.00 FL
51	1		*FRONT RH FENDER INNER SHIELD	Cracked	180.00 FL	*180.00 FL
52	1		*REAR RH FENDER INNER SHIELD	Cracked	180.00 FL	*180.00 FL
53	20		*EXPANDING RIVET	Necessary	180.00 FL	*180.00 FL
54	1		*REAR RH EXHAUST HEAT SHIELD	Bent	504.00 FL	*504.00 FL
55	1		*FRONT RH FOG LAMP HOLDER	Distorted	68.00 FL	*68.00 FL
56	10		*CLIPS	Necessary	90.00 FL	*90.00 FL
57	2		*SPOILER RIVET	Necessary	10.00 FL	*10.00 FL
58	10		*SPOILER CLIP	Necessary	90.00 FL	*90.00 FL
59	4		*EXPANDING RIVET (D=8MM)	Necessary	20.00 FL	*20.00 FL
60	6		*BONNET CLIPS	Necessary	30.00 FL	*30.00 FL
61	2		*REAR SPOILER RIVET (D=7, 5MM)	Necessary	10.00 FL	*10.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
62	10		*REAR BUMPER RIVET	Necessary	90.00 FL	*90.00 FL
63	1		*FRONT CENTER PANEL	Bent	1,382.00 FL	*1,382.00 FL
64	1		*DISTANCE SENSOR	Shorted	250.00 FL	*250.00 FL
65	4		*DECOUPLING RING	Cracked	60.00 FL	*60.00 FL
66	1		*AIR HORN HIGH	Cracked	205.00 FL	*205.00 FL
67	1		*AIR HORN LOW	Cracked	205.00 FL	*205.00 FL
68	1		*EXHAUST PIPE CHROME TIP	Dented	126.00 FL	*126.00 FL
69	1		*LIGHTING WIRING SET	Torn	1,252.00 FL	*1,252.00 FL
70	1		*AIR-CON CONDENSER	Bent	527.00 FL	*527.00 FL
71	1		*FRONT RH FENDER WHEEL ARCH MOULDING	Dented	198.00 FL	*198.00 FL
72	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
73	1		*SET REVERSE SENSOR	Shorted	400.00 FS	*400.00 FS
74	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
75	1		*DOOR TAPE	Not Necessary	200.00 FS	*- FS
76	1		*REAR RH TYRE - PIRELLI P1 CINTURATO (195/55 R16)(80%)	Cut	295.00 FS	*236.00 FS
77	1		*REAR NUMBER PLATE & HOLDER	Dented	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$)	36,754.00	29,744.00
- List Item Discount on L Items 10.00/10.00% (\$)	3,565.90	2,902.80
Total Parts (\$)	33,188.10	26,841.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	New	2,100.00	1,200.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT.	New	80.00	60.00
3	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC).	New	200.00	0.00
4	TO REMOVE AND REPLACE REAR WINDSCREEN.	New	150.00	120.00
5	TO DISMANTLE & TRANSFER DOOR / TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE & DOOR / FACILITATE REPAIR.	New	200.00	60.00
6	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR.	New	100.00	100.00
7	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.	New	150.00	150.00
8	TO REMOVE & REPLACE BUMPER SENSORS.	New	40.00	40.00
9	TO CHECK & RECONNECT ALL NECESSARY WIRING.	New	80.00	40.00
10	TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER).	New	400.00	400.00
11	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER.	New	100.00	60.00
12	TO SPRAY PAINT ON THE AFFECTED AREAS.	New	2,600.00	1,800.00
13	TOWING.	New	100.00	100.00
Gross Labour Cost (S\$)			6,300.00	4,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >