

NATIONAL Assessment Centre Services

(wef 1 Jan 05) MNA119081204

Date In: 22/6/19 - 10:21	Job description	Date & Time Completed	Done by
Ref No: NA/MC19011032/24	SAS e-filing		
Veh No: 551938X	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 21/6/19 - 21:20	i-Motor Claim Form	M7/10J086-001	22/6/19 10:29
OD TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (

Tel:

Fax:

TP Particulars:

Veh No: 551938X

INC () / Non-INC ()

Owner / Driver: (

Tel:

Policy No: (

Period: (

Cover Type: (

Confirmed by: (

Date:

Time:

Insured/Driver Liability: () % [Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]

Year of Registration: () Warranty: YES () / NO ()

Excess: (\$) Loading: \$1,000 () / \$2,000 ()

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:-

(INC hotline: 6788 6616)

Date & Time Completed

Done by

1) Apply for Transport Allowance () / Courtesy Car ()

2) QC Check / Post Repair Inspection ()

3) Upload Resurvey Photo [Repair Cost > \$3000] ()

Injury:

Date/Time	Actions

NA1904824	Invoice Preparation Checklist	Amt (\$) Est Bill	Amt (\$) Add Bill
Claimant's Particulars:-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	QD:		
	*N5: Courtesy Car / Tpl Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (N'n INC) against INC \$20		
	9) N12: Idao Mobile 30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

Auditors' Comments:-

Ref 1:

Ref 2/3:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2019 10:21
Date Of Accident	21/06/2019 21:20
Exact Location Of Accident	ECP (CHANGI) BEFORE MARINE VISTA EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1938X
Insured/Policyholder	
Name Of Registered Owner	TAN ZHI YAO JOSHUA
NRIC No	S8838610H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97614861
Alternative Phone No	OFFICE-97614861

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT HYBRID RS 1.2 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103314697
Cover Note Number	

Driver

Name of Driver	TAN ZHI YAO, JOSHUA (CHEN ZHIYAO)
NRIC No	S8838610H
Date Of Birth	07/10/1988
Occupation	INDOOR
Date Of Driving Pass	25/03/2011
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97614861
Fax Number	
Contact Number	OFFICE-97614861
EMail Address	NOEMAIL

Address	BLK 326 UBI AVENUE 1 #06-675
Postcode	400326
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190622/7005.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ7931X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH WEI YANG, KENNETH
NRIC/Passport Number	S9041469J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Handwritten sketch plan on a grid background. The text "ECP (changing)" is written vertically on the left. In the center, there is a small box containing the letters "A" and "B" stacked vertically. To the right, the following text is written:

A: 5LS9138X
B: 5J7431X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 1/20/90622/7205.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190622/7005

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190622/7005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/06/2019 02:21		Vide Report No.: G/20190621/0185		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN ZHI YAO, JOSHUA			Address: APT BLK 326 UBI AVENUE 1 #06-675 SINGAPORE 400326		
ID Type / ID No.: NRIC NO / S8838610H			Contact No.: Home/Office:		Mobile: 97614861
Nationality: SINGAPORE CITIZEN			Email: joshua.zyt@gmail.com		
Sex: Male	Age: 30	Date of Birth: 07/10/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales and marketing manager			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/06/2019 21:20	Type of Location: Straight Road
Location: EAST COAST PARKWAY				
Weather: Clear		Road Surface: Wet		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS1938X	Car	SUZUKI	SWIFT HYBRID RS 1.2 AUTO	White		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS1938X	NTUC Income Insurance Co-Operative Limited	5103314697	13/09/2018	12/09/2019



**SINGAPORE
POLICE FORCE**



T/20190622/7005

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190622/7005

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN ZHI YAO, JOSHUA	ID No.	S8838610H
Related Vehicle	SLS1938X (Car)	Contact No.	97614861
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Video footage from my car camera has been passed via SD card to traffic police on scene.
Accident happened just before Marine Vista exit on ECP towards Changi Airport.

I was driving on lane 1 of the ECP well within the speed limit of 90km/h when i noticed brake lights coming on from the car in-front at a distance, prompting me to start reducing my speed and slowing down.

All of a sudden I noticed the car in-front was starting to jam his brakes abruptly and I followed suit, although I was unable to come to a complete stop and had impact on my front bumper upon the rear bumper of the vehicle (SJJ7931X) in-front of me. This happened around 918pm on 21 Jun 2019.

Me and my passenger were able to get out of the car to observe the collision in front of us and realised that there were 3 other cars who had stopped on the expressway, which explains why the car in-front of my had to also jam his brakes.

I subsequently contacted my insurance provider NTUC who came down to assist, and gave the necessary statements to them and the Traffic Police personnel who later arrived on-scene.



**SINGAPORE
POLICE FORCE**



T/20190622/7005

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190622/7005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
PHUA TIAK YEE
Contact No.: 65472077

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
22/06/2019 02:21

Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8838610H



Name
TAN ZHI YAO, JOSHUA
(CHEN ZHIYAO)
陳智耀

Race
CHINESE

Date of birth
07-10-1988

Sex
M

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8838610H
Name
TAN ZHI YAO, JOSHUA
(CHEN ZHIYAO)

Birth Date: 07 Oct 1988
Issue Date: 17 Jul 2008

001627793C

3415086



NRIC No. S8838610H



Date of issue
17-10-2003

Address
APT BLK 326 UBI AVENUE 1
#06-675
SINGAPORE 400326

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE
17 Jul 2008
25 Mar 2011

Class	Motorcycles	Motor cars
Class 2B	≤ 200 CC	≤ 3000 kg with ≤ 7 passengers, exclusive of the driver, and motor tractors/vehicles ≤ 2500 kg
Class 3		

S8838610H

S / No. 9000140210

Licence No: S8838610H

NP 428A

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	21/06/2019 21:20							
Vehicle No.(For Motor)	SLS1938X	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5103314697		TAN ZHI YAO JOSHUA	S8838610H	GPC	drivo CLASSIC	SLS1938X	SLS1938X	13/09/2018	12/09/2019
Continue										

 Policy Information

Policy No.	5103314697	Policyholder Name	TAN ZHI YAO JOSHUA	Policyholder NRIC	S8838610H
Certificate No.					
Address	BLK 326 #06-675 UBI AVENUE 1 SINGAPORE 400326				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy Issue Date	25/08/2018	Effective Date	13/09/2018 00:00	Expiry Date	12/09/2019 23:59
Excess Type		All Claims Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver Excess	
Agent	B.A.S. INSURANCE AGENCY	Agent Tel.	67492112	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	BLK 326 #06-675	Address 2	UBI AVENUE 1	Address 3	KAMPUNG UBI ESTATE
Address 4	SINGAPORE 400326	Address Type	Singapore address	Post Code	400326
Unit No.	#06-675	Related Policy Number	5103314697		

 Insured Object: SLS1938X

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

• Exit

Accident MT/1050086

Policy No.	S103314697	Vehicle No.	SLS193BX	GST Registration No.	
Certificate No.					
Policyholder Name	TAN ZHI YAO JOSHUA			Policyholder NRIC	S8838610H
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97614861	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

Accident Details

Report Date	22/06/2019 12:27	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	21/06/2019	Time of Accident hh:mm	21:20	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	ECP (CHANGI) BEFORE MARINE VISTA EXIT				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 326 #06-675	Address 2	UBI AVENUE 1	Address 3	KAMPUNG UBI ESTATE
Address 4	SINGAPORE 400326	Address Type	Singapore address	Post Code	400326
Unit No.	#06-675	Related Policy Number	S103314697		

DI Driver Info

Driver Name	TAN ZHI YAO JOSHUA	Driver Type	Named Driver		
Unnamed driver Name		Driver NRIC	S8838610H	Driver DOB	07/10/1988
Register Date of Driver License	25/03/2011	Driver Age	30	Driving Experience	8
Contact No.(Mobile)	97614861	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 326	Address 2	UBI AVENUE 1	Address 3	KAMPUNG UBI ESTATE
Address 4	SINGAPORE 400326	Address Type	Singapore address	Post Code	400326
Unit No.	#06-675				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyzer or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 **New**

Claim Type *	OD-MD	Insured Name	TAN ZHI YAO JOSHUA	Insured NRIC	S8838610H
Contact No.(Mobile)	97614861	Contact No.(Home)	87473370	Contact No.(Office)	
Email Address	JOSHUA_ZYT@GMAIL.COM	DI Vehicle Number	SLS193BX	TP Vehicle Number	S117931X
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	SLS193BX / S117931X ON 21 Jun 2019			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	22/06/2019 12:29	Claim Close Date		Date Received	22/06/2019 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	

☒ Print AK letter

Save Submit

Attachment

Accident No.	MT/1050086	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	22/06/2019 12:30

Path *	Category *	Confidential	Urgency *	Description *

	Browse...	Clear	Please Select	NO	Normal	
	Browse...	Clear	Please Select	NO	Normal	

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CD)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	SAS	Normal	SAS 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:30	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 22 Jun 2019 12:29	Photos	Normal	Photos 2019-6-22		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
		Display in New Window	Scan and uploading	

ASS. REC. BY:

REF:

Assessor:

Mobile: YES / NO

ASSIGNMENT (IDAC)**By CSO- Nature of Accident:**

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn. Property () b) Road Work Object ()
(Eg: signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SLS/938X Yr Regn: 13 Sept 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
/ Truck / Trailer or _____

Make & Model: SUZUKI / SUZUKI Hybrid C.C 1242Colour: white Transmission Type: Auto / ManualEng/No: K12C5158700 Sp. Reading: 25784C/No: 2C53S-104637Gen. Cond: Good / Fair / Poor / Burnt or _____Steering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 185/55 R16R: 185/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mm

Parallel Import: Yes / No?

Towed-In: Yes / No

Repair Type: LS / I.B.I

Towing Required: Yes / NoNo of Repair Days: 7Vehicle in Idac: Yes / NoD.O.I. 24/6/2019Time: 3.00 pm**By Assessor- 2) Comments**

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (Fr)

Aug 2001

Front Portion

2C535

Vehicle No: SLS 1938X

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	MS	✓	
1002	991887	Frt Number Plate Base	RA	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD	✓	
1005	992341	Frt Bumper Clips	NEC	6	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	2	
1008	991433	Frt Bumper Reinforcement	BT	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA	✓	
1011	991427	Frt Bumper <i>Tow Eye Cover</i>	DIS	✓	
1012	991420	Frt Bumper P...			
1013	991363	Frt Bumper Grille	CRA	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	✓	
1022	991328	Frt Grille Emblem	NEC	✓	
1023	991799	Frt Grille Chrome Moulding	CRA	✓	
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	✓	
1026	992025	Frt Support Panel Top Garnish Cover	DIS	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	✓	
1030	991821	Frt RH Headlamp Assy	CRA	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BUC	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT	✓	
1036	990285	Bonnet Insulator	BT	✓	
1037	990273	Bonnet Hinge	BT	✓	
1038	990261	Bonnet Damper	BT	✓	
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT	✓	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	✓	
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	DD	✓	
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe	BT	✓	
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	DD	✓	
1053	992738	Radiator Cowling	CRA	✓	
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top	BT	✓	
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank	DD	✓	
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	DD	✓	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	BUC	✓	
1097	995072	Frt LH Fender Inner Panel	BT	✓	
1098	995147	Frt LH Fender <i>Emblem</i>	NEC	✓	
1099	995148	Frt LH Fender			
1100	991740	Frt LH Fender Inner Shield	CRA	✓	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC	✓	
1106	991739	Frt RH Fender Inner Panel	BT	✓	
1107	991744	Frt RH Fender <i>Emblem</i>	NEC	✓	
1108	991752	Frt RH Fender P...			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy	BR	✓	
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag	BUC	✓	
1128	994485	Steering Wheel Airbag Sensor	NEC	✓	
1129	990749	Dashboard Airbag	BUC	✓	
1130	990750	Dashboard Airbag Sensor	NEC	✓	
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy	JM	✓	
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy	JM	✓	
1136	990247	Sticker			
		<i>Frt LH Door</i>	SRR	✓	
		<i>Frt RH Door</i>	SRR	✓	

No of Items:

Assessor:

Claim Handling

[Task Transfer](#) [Exit](#)

Accident MT/1050086

[LOS](#) [SAL](#) [SUB](#)

Policy No.	S103314697	Vehicle No.	SLS1938X	GST Registration No.	
Certificate No.					
Policyholder Name	TAN ZHI YAO JOSHUA	Cover Type	drive CLASSIC	Policyholder NRIC	S8838610H
Product Code	PRIVATE CAR INSURANCE	Contact No. (Office)	0	Loading	0
Contact No. (Mobile)	97614861	Special Remark		Contact No. (Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KFK	☒ No ☐ Yes	NCD Entitlement(%)	10	#Code Reason	
NCD Protection	No			Private Hire	No

Accident Details

Report Date	22/06/2019 12:27	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	21/06/2019	Time of Accident hh:mm	21:20	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	ECP (CHANGI) BEFORE MARINE VISTA EXIT				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes

Policyholder Mailing Address

Address 1	BLK 326 #06-675	Address 2	UBI AVENUE 1	Address 3	KAMPUNG UBI ESTATE
Address 4	SINGAPORE 400326	Address Type	Singapore address	Post Code	400326
Unit No.	#06-675	Related Policy Number	S103314697		

OT Driver Info

Driver Name	TAN ZHI YAO JOSHUA	Driver Type	Named Driver	Driver DOB	07/10/1988
Unnamed driver Name		Driver NRIC	S8838610H	Driving Experience	8
Register Date of Driver License	25/02/2011	Driver Age	30	Contact No. (Home)	0
Contact No. (Mobile)	97614861	Contact No. (Office)	0	Address 3	KAMPUNG UBI ESTATE
Address 1	BLK 326	Address 2	UBI AVENUE 1	Post Code	400326
Address 4	SINGAPORE 400326	Address Type	Singapore address		
Unit No.	#06-675				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

[LOS](#) [SAL](#) [SUB](#)

Claim Type	OD-MD	Insured Name	TAN ZHI YAO JOSHUA	Insured NRIC	S8838610H
Contact No. (Mobile)	97614861	Contact No. (Home)	67473370	Contact No. (Office)	
Email Address	JOSHUA.ZYT@GMAIL.COM	OT Vehicle Number	SLS1938X	TP Vehicle Number	SJ37931X
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	SLS1938X / SJ37931X ON 21 Jun 2019			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	22/06/2019 12:31	Claim Close Date		Date Received	22/06/2019 00:00
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	SUZUKI	Vehicle Model	SWIFT	Engine Capacity	
Date of Registration	01/01/2017	Chassis No.	ZCS3S104637		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	

IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA
Windscreens Parts & Labour Cost		Total Loss *	☐ Yes ☒ No
Market Value(\$)		Scrap Value(\$)	
		Economical Repair Value(\$)	
Remark	REMARK: NO OF REPAIR DAY: 7 DAYS. 1 X FRT BUMPER TOW EYE COVER - REPLACE. 1 X FRT GRILLE CHROME Moulding - REPLACE. 1 X FRT SUPPORT PANEL TOP GARNISH COVER - REPLACE. 1 X AIR CON SUCTION PIPE (LOW PRESSURE) - REPLACE. 1 X AIR CON SUCTION HOSE - UNCONFIRM. 1 X AIR CON DISCHARGE PIPE (HIGH PRESSURE) - REPLACE. 1 X AIR CON LIQUID PIPE - REPLACE. 1 X AIR DUCT - UNCONFIRM. 1 X AIR CLEANER ASSY - UNCONFIRM. 1 X RELAY BOX - UNCONFIRM. 1 X FRT LH FENDER EMBLEM - REPLACE. 1 X FRT RH FENDER EMBLEM - REPLACE. 1 X STEERING WHEEL AIRBAG - REPLACE. 1 X STEERING WHEEL AIRBAG SENSOR - REPLACE.		

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	26600102	FUSE BOX (CENTRE)	1	Unconfirm	X
ABS	2	454012	WIPER WASHER TANK	1	Replace	X
ACCELERATOR	3	454014	WIPER WASHER TANK MOTOR	1	unconfirm	X
ACTUATOR	4	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ADVERTISMENT STICKER	5	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
AIR BAG	6	16000101	BUMPER (FRONT)	1	Replace	X
AIR BLOWER	7	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
AIR BOX	8	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
AIR CHAMBER BOX	9	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR CLEANER	10	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR COMPRESSOR	11	16005901	BUMPER SPONGE (FRONT)	1	Replace	X
AIR CON	12	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR CON (VAN)	13	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
AIR COOLER	14	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
AIR DISTRIBUTOR	15	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	X
AIR FILTER	16	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm	X
AIR FLOW	17	27100101	GRILLE (FRONT)	1	Replace	X
AIR GRILLE	18	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR HORN	19	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
AIR INTAKE	20	28500101	HORN (LEFT)	1	Unconfirm	X
AIR RESONATOR BOX	21	15600101	BRACE PANEL (FRONT)	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR	22	27700101	HEAD LAMP (LEFT)	1	Replace	X
ALARM	23	27700102	HEAD LAMP (RIGHT)	1	Replace	X
ALTERNATOR	24	149001	BONNET	1	Replace	X
ALUMINIUM PANEL - SIDE	25	14903401	BONNET LOCK (LOWER)	1	Replace	X
AMPLIFIER	26	149029	BONNET INSULATOR	1	Replace	X
ANTENNA	27	14902201	BONNET HINGE (LEFT)	1	Replace	X
ANTI ROLL	28	14902202	BONNET HINGE (RIGHT)	1	Replace	X
APRON	29	112023	AIR CON CONDENSER	1	Replace	X
ARCH	30	112060	AIR CON FAN	1	Unconfirm	X
ARM REST	31	112043	AIR CON DISCHARGE HOSE	1	Unconfirm	X
ASH TRAY	32	344001	RADIATOR	1	Replace	X
AUTO CLUTCH	33	344005	RADIATOR COWLING	1	Replace	X
AUTO COOLER PIPE	34	344006	RADIATOR FAN	1	Unconfirm	X
AUTO CRUISE MOTOR	35	344011	RADIATOR FAN CLUTCH	1	Unconfirm	X
AUTO TRANSMISSION	36	34402802	RADIATOR HOSE (TOP)	1	Replace	X
AXLE	37	34402801	RADIATOR HOSE (BOTTOM)	1	Unconfirm	X
BACK REST (MC)	38	344007	RADIATOR EXPANSION TANK	1	Replace	X
BACK SEAT	39	11001302	AIR CLEANER HOSE (CENTRE)	1	Unconfirm	X
BALANCER	40	141001	BATTERY	1	Unconfirm	X
BATTERY	41	141005	BATTERY COVER	1	Replace	X
BEADING (MC)	42	25400102	FENDER (FRONT LEFT)	1	Replace	X
BELT COVER (MC)	43	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
BELT TENSIONER	44	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair	X
BODY	45	25400103	FENDER (FRONT RIGHT)	1	Replace	X
BODY (MC)	46	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
BOLT CAP (MC)	47	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm	X
BOLT HEAD COVER (MC)	48	454009	WIPER PANEL GARNISH	1	Unconfirm	X
BONNET	49	22600101	DASHBOARD (BOTTOM)	1	Replace	X
BOOT	50	226002	DASHBOARD AIR BAG	1	Replace	X
BOX (MC)	51	226003	DASHBOARD AIR BAG SENSOR	1	Replace	X
BOX BRACKET (MC)	52	106007	AIR BAG CONTROL UNIT	1	Unconfirm	X
BOX CARRIER (MC)	53	36300102	SEAT BELT (FRONT RIGHT)	1	Replace	X
BOX DOOR	54	36300101	SEAT BELT (FRONT LEFT)	1	Replace	X
BOX STICKER (MC)						
BRACE PANEL						
BRAKE						
BRAKE - ABS						
BRAKE (MC)						
BUMPER						
CABIN						
CAMBER						
CAMSHAFT						
CAR AUDIO SYSTEM						
CAR JACK						
CARBURATOR						
CARGO						
CARRIAGE						
CARRIER MOUNTING						
CASTOR						
CATALYTIC CONVERTOR						
CD CHANGER						
CD PLAYER						
CD UNIT (MC)						
CENTRE BOTTOM						
CENTRE BRACKET						
CENTRE CONSOLE						
CENTRE COWLING (MC)						
CENTRE CROSS MEMBER						
CENTRE EXHAUST						

55	23300201	DOOR (FRONT LEFT)	1	Repair	X
56	23300202	DOOR (FRONT RIGHT)	1	Repair	X

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Wednesday, 26 June 2019 5:47 PM
To: NAC ; Hock Wah Motor Pte Ltd
Subject: SLS1938X, OD claim no : MT/1050086

Importance: High

Dear IDAC and Hock Wah,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear Hock Wah,

OD excess of \$600/- is applicable, pls assist to liaise with owner Mr Tan at tel : 97614861.

Survey required and you have to arrange personally at mtsurvey@income.com.sg

FOR PAYMENT: Please forward the Invoice & Discharge Voucher together within 14 days after the repair has been done/ finalized with Surveyor to my email.

Regards.

Tan Siew Choo
Senior Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1050086-001/TSC
26 Jun 2019

HOCK WAH MOTOR WORKSHOP PTE LTD
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1050086-001

REPAIR OF VEHICLE NUMBER: SLS1938X

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 26 Jun 2019

Make: SUZUKI

Model: SWIFT

Estimated Repair Days: 30

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SW5 1938X Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: HOCK WAH MOTOR

Collection Date: 27/06/19 Time: 0910 with Keys: Yes / No

Tow Truck No: YH 1382L Tow Man: ONG ENG BEAT NRIC: S7042447K

Signature: _____

For office use

Attended by: Shan Hui

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____