

22/03/2002

ASS. REC. BY:

REF: CS3 / C1219011047 / G001302

Special Instruction:

Survivor: GR

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of C12 Date/Time: 24.6.19 9.29 a.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 7470R Insured: SGK 5755

at Workshop m/s Teamwork Tel: 6944 2476

of 53 ubi Ave 1 #01-24

Policy No: DMPC 5430431218000 Claim No: SKM 19 1202838002

Sum Insured: Excess:

Make of Veh: D.O.A. 18.6.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24.6.19 10.29 a.m. Person Contacted: Darren Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJW 7470R - NA / INC 19/06/2019
	SGK 5755 - NA / INC 19/06/2019
	Dismantle: 26/6/2019.

ASSIGNMENT

From: Date: 24.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 7470R

at Workshop m/s Teamwork

of 53 ubi Ave 1 #01-24

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$16500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW7470R Yr Regn: 14 Apr 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit colt plus 1.5 c.c. 1499

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 182768 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYLT823W9Z000179

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50 R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 24-06-19

Survey held at W/S 11:30

Des. of Damages: F/R / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair limit \$5000

~~\$7000~~ \$8000 - \$10K.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 10

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Report Format: PRS.

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019		24 Jun 2019 09:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: CHANG PRIVAUTO , Co. Reg. No.: 53366420M									
Vehicle Reg. No.:		SJW7470R	Date of Loss:	18/06/2019 20:00 - :59					
Claim Type:		TP / SNM19D202838C02	Policy/Cover Note No.:	DMPCSN30431218000					
Vehicle Reg. No. (Insured):		SGK575S	Policy No. (Claimant):	5102231153-01					
		Excess:	S\$1,000.00						
Repairer:		Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/07/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail 									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	6420M
Vehicle No.:	SJW7470R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	COLTPLUS 1.5
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	4A910141622
Chassis No.:	JMYLTZ23W9Z000179
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$18,143.00
Original Registration Date:	14 Apr 2010
First Registration Date:	14 Apr 2010
Transfer Count:	2
Actual ARF Paid:	\$18,143.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2020
PARF Rebate Amount:	\$9,071.00
COE Expiry Date:	13 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$28,389.00
COE Rebate Amount:	\$2,285.00
Total Rebate Amount:	\$11,356.00

The information contained herein is correct as at 24 Jun 2019

OK

▶ Mitsubishi Colt Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Mitsubishi Colt Plus 1.5A	\$19,600	\$8,390 /yr	30-Sep-2010	1,499 cc	79,000 km	Choon Bee Motor & Credit	Available

Most Of The Wear And Tear Has Been Done Up. Drive With A Peace Of Mind For The Next 12 Months. Arrange An Appointment With Us To Now. Loan And Insurance Packages.

Office No. - 64474586

Ah Cheng - 97374349 | David C W Gan - 93851233 | Candy - 91064188

Mitsubishi Colt Version-R Turbo	\$32,000	\$14,170 /yr	14-Dec-2010	1,468 cc	87,000 km	Autodinic Car Warranty & Leasing Pte. Ltd	Available
---------------------------------	----------	--------------	-------------	----------	-----------	---	-----------

Trust Exhaust With Cert, Front-Mount Intercooler, Greddy Boost Controller, TEIN Coilover System. No Repairs Needed! Accident-Free With No Repairs Needed! Superbly Well Maintained By Previous Owner. Fu...

Office No. - 66862511

Goh - 93368442

Mitsubishi Colt Version-R Turbo	\$29,800	\$12,500 /yr	14-Dec-2010	1,468 cc	-		Available
---------------------------------	----------	--------------	-------------	----------	---	--	-----------

Well Maintained. Serviced Regularly.

Office No. - -

Slyvester - 86886544

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2019 18:49
Date Of Accident	18/06/2019 20:10
Exact Location Of Accident	SIMS AVE TWDS PAYA LEBAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW7470R
Insured/Policyholder	
Name Of Registered Owner	CHANG PRIVAUTO
Co Reg No	53366420M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97167740
Alternative Phone No	OFFICE-97167740

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	COLTPLUS 1.5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5102231153-01
Cover Note Number	

Driver

Name of Driver	ONG TONG LING @ONG TONG LENG
NRIC No	S1327168B
Date Of Birth	01/08/1958
Occupation	INDOOR
Date Of Driving Pass	04/08/1986
Driving Experience	32 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97167740
Fax Number	
Contact Number	OFFICE-97167740
Email Address	NOEMAIL

Address	BLK 533 PASIR RIS DRIVE 1 #02-254
Postcode	510533
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HUANG YANG SHAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK575S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH TONG HWA
NRIC/Passport Number	S1508603C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJN9855Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver WU XIN
NRIC/Passport Number S2665778D
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG TONG LING @ONG TONG LENG
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SJW7470R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name HUANG YANG SHAN
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SJW7470R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, Agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING STRAIGHT ALONG SIMS AVENUE TOWARDS PAYA LEBAR ROAD. VEHICLE (C) WHO WAS IN FRONT OF ME SLOW DOWN AND STOP. HENCE I FOLLOW SUIT TO SLOW DOWN AND STOP WITHOUT ANY CONTACT. OUT OF SUDDEN, I FELT AN IMPACT FROM MY VEHICLE REAR PORTION. THE IMPACT WAS SO GREAT THAT IT PUSHES ME FORWARD. WHEN I GOT DOWN, I SAW THAT I WAS INVOLVED IN A 3 CAR CHAIN COLLISION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2019		24 Jun 2019 09:29 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	CHANG PRIVAUTO , Co. Reg. No.: 53366420M								
Vehicle Reg. No.:	SGW7470R	Date of Loss:	18/06/2019 20:00 - :59 [110 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202838C02	Policy/Cover Note No.:	DMPCSN30431218000						
Vehicle Reg. No. (Insured):	SGK575S	Policy No. (Claimant):	5102231153-01						
		Excess:	S\$1,000.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents









*SJW7470R (SNM19D202838C02)
[SGK575S]
TP
CHANG PRIVAUTO
Jun 18 2019 8:00PM
[-]
Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
2	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
3	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
4	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
5	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
6	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
7	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
8	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
9	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
10	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
11	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
12	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
13	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
14	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
15	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
16	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
17	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
18	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
19	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
20	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
21	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
22	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
23	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
24	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
25	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
26	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
27	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
28	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
29	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
30	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
31	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
32	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
33	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
34	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
35	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
36	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	
37	27/06/19 10:00	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/06/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/06/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/06/19 10:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
41	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/06/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	27/06/19 10:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

			View	View In Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/06/19 19:00	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
9	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	19/06/19 18:57	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/06/19 18:58	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	19/06/19 18:58	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	19/06/19 18:58	Acra	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19011047/GCD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30431218000

Claimant Vehicle
No : SJW7470RInsured Vehicle
No : SGK575S

Date of Loss: 18/06/2019

Nature of Claim: TP

Claim
No: SNM19D202838C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW7470R**

Make & Model: MITSUBISHI COLT PLUS, 1.5 (A)

Reg. Date: 14/04/2010 (Man. Year: 2009)

Colour: Blue

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 4A910141622

Chassis No: JMYLTZ23W9Z000179

Odometer: 182768 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/06/2019

Date Inspected: 24/06/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$10,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2019)
Parts:	144	MITSUBISHI COLT PLUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW7470R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >