

reference

A.S. REC. BY:

REF: CS/CT19011075/kvd302

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Tankah leong of CTI

Date/Time: 24/6/19 @ 2:10pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SJQ 1459X Insured: SKH 5642S

at Workshop n/a: Chew goon Motor Tel: 6484/626

of Blk 10 Amk Ind. Park 2A Ave 5 # 01-15

Policy No: Claim No: SNMMD202904

Sum Insured: Excess:

Make of Veh: D.O.A. 18/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:10pm @ 24/6/19 Person Contacted: Kelly Vehicle IN/OUT

Date/Time Action/Instruction

SJQ 1459X: /

SKH 5642S: /

27/6 11 Lyr 811, Good email

22/7/19 @ 10:30am LS \$11,600 confirmed with Kelly (Red 6172.65, 3510)

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

825k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

RECEIVED 27 JUL 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 2017 - typist

Report Format:

men men

Lump Sum / I.B.I. (\$) 11,600/-

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RLS \$

: Fines

: Others

TOTAL

210

Veh No:

STA 1459X Yr Regn: 04, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai / Namy c.c 1591

Colour:

M. Gold

A/C: Insured / Std / NI / NA

Sp. Reading

310296

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM14DU41 BR 94750837

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/6/19

D.O.I.

24/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

RM C/S

The UIC / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 24 June 2019 2:10 PM
To: Chew Goon Motor(ad3); assignments@lkkauto.com
Subject: RE: OUR REF: SNM19D202904-TANKL- PRS -SJQ1459X Accident Date: 18.06.2019

WITHOUT PREJUDICE

Dear Kelly,

We refer to your email of 21.06.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Angie Foo
Sent: Monday, 24 June, 2019 10:10 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Cc: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Subject: OUR REF: SNM19D202904-TANKL- PRS -SJQ1459X Accident Date: 18.06.2019

Dear Kah Leong,

Please conduct PRS -SJQ1459X -soonest possible.

File with officer in charge Tan Kah Leong -6389 6193.

Regards

Angie Foo
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896186 - F: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chew Goon Motor(ad3) [<mailto:ad3@chewgoonmotor.com.sg>]

Sent: Friday, 21 June, 2019 4:39 PM

To: Claims Dept of CTI; Angie Foo

Cc: chewgoon@singnet.com.sg; Eric

Subject: SJQ1459X Claiming Against Your Insured SKH5642S Accident Date: 18.06.2019

Dear Sir/Mdm,

Vehicle SJQ1459X is lying at our workshop.

According to your list, we will prefer **LKK Auto Consultants Pte Ltd** to survey the vehicle.

Kindly arrange for survey.

Thanks & Regards,

Kelly

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,

Ave 5 #01-15, 16 & 17,

Ang Mo Kio Autopoint

Singapore 568047

Tel : 6484 1626

Fax : 6484 0465

Sent from [Mail](#) for Windows 10

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1568C

Vehicle Details

Vehicle No.:	SJQ1459X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	G4FC9U647798
Chassis No.:	KMH DU41BR9U750837
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,706.00
Original Registration Date:	27 Apr 2009
First Registration Date:	27 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$11,706.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$12,200.00
Total Rebate Amount:	\$12,200.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2019 10:48
Date Of Accident	18/06/2019 20:00
Exact Location Of Accident	JUNCTION OF ANCHORVALE DR & SENGKANG EAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ1459X
Insured/Policyholder	
Name Of Registered Owner	LIM CHIK SIEN
NRIC No	S7981568C
Email Address	KENZO_JOEY@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91822717
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10147266R00
Cover Note Number	

Driver

Name of Driver	LIM CHIK SIEN
NRIC No	S7981568C
Date Of Birth	22/02/1979
Occupation	INDOOR
Date Of Driving Pass	23/08/2001
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91822717
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	KENZO_JOEY@YAHOO.COM

Address	BLK 469C SENGKANG WEST WAY #26-630
Postcode	793469
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	DRIZZING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH5642S
Vehicle Make/Model/Colour	HONDA CIVIC
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG GUO HAO
NRIC/Passport Number	S8932324Z
Contact Number	9655 5588
Address	BLK 203C COMPASSVALE ROAD #12-25
Postcode	543203
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

DETAILS OF INJURED PERSON 1

Name

LIM CHIK SIEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJQ1459X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: 8JQ 14591X
ACCIDENT DATE: 18/06/2019 09:30:00

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GiA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature

Date & Time:

19/6/19, 10:06am

Driver's Signature

(If driver is not the policyholder)

Date & Time:


CHARN'S CUSTOM CRAFT

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 8pm. 18/6/2019 I was driving at Anchorvale Dr. towards Sengkang Library. While approaching the junction between Anchorvale Drive and Sengkang East Road, vehicle with car plate SK1P5642S suddenly did a u-turn into my car lane (extremely left lane).

As my vehicle was traveling at lane 2 (left lane) and there was green traffic light and the above mentioned vehicle just suddenly perform a u-turn into my lane, as when the SK1P5642S performed u-turn, there's another vehicle in front of it which proposed to turn right at the junction. It blocked my view hence I wasn't able to do emergency brake and had a crash with SK1P5642S.

OWN DAMAGE ☒ 3RD PARTY CLAIM ☐ REPORTING ONLY ☐ OWN WORKSHOP ☐

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 10:06 pm. 19/6/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOM CRAFT
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190620/2048

1 of 4

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No: T/20190620/2048

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2019 12:04		Vide Report No.:		Station Diary No.: 52	
Informant's Particulars					
Name of Informant: LIM CHIK SIEN			Address: APT BLK 489C SENGKANG WEST WAY #26-030 SINGAPORE 793400		
ID Type / ID No.: NRIC NO / S7981568G			Contact No.: Home/Office: Mobile: 91822717		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 22/02/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TECHNICAL CONSULTANT			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/08/2019 08:00	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 ANCHORVALE DRIVE SENGKANG EAST ROAD				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJQ1459X	Car	HYUNDAI	HD AVANTE 1.6 A	Beige	Seriously Damaged	0
SKH5642S	Car	HONDA	CIVIC	White	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SJQ1459X	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED	P10147266R00	27/04/2019	26/04/2020



**SINGAPORE
POLICE FORCE**



T/20190620/2048

2 of 4

Report No. T/20190620/2048

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM CHIK SIEN	ID No.	S7981568C
Related Vehicle	SJQ1459X (Car)	Contact No.	91822717
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	ANG GUO HAO	ID No.	S8932324Z
Related Vehicle	SKH5642S (Car)	Contact No.	96555588
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/06/2019 at about 2000hrs, I was driving along Anchorvale Drive on the extreme left lane, towards Sengkang East Road. As I was approaching the X-junction of Anchorvale Drive and Sengkang East Road, I slowed down a little and noticed that the traffic light was in my favour, as such I proceeded on.

As I was about to go pass the junction, a vehicle, SKH5642S, suddenly did a U-turn and collided into my car on the extreme left lane. There was another vehicle preparing to turn right, in front of that said vehicle that collided with my car, hence it blocked my view of that said vehicle doing the U-turn, thus I was not able to break in time.

I alighted and make a check and my front part of my vehicle was totally damaged. Subsequently paramedics and traffic police came and suffered some abrasion on my left knee area and felt some pain on my chest and neck area

On the same day at about 2150hrs, I went to see a doctor and was given one day MC. However I felt severe pain still the next day and went back to see the doctor on 19/06/19 and was given 2 more days of MC.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999



T/20190620/2048

4 of 4

Report No. T/20190620/2048

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F/

Staff Sgt TAN YIK MONG, RYAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MOHAMED RIZWAN BIN IBRAHIM

Contact No.: 93265045

Signature Of Informant:

Date/Time:

20/06/2019 12:04

Classification Of Case:

Authentication Stamp
NP168



Signature:

Singapore Police Force



**SINGAPORE
POLICE FORCE**



T/20190620/2048

3 of 4

Report No. T/20190620/2048

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10147266R00 (Comprehensive / Named Driver Plan)

- | | | |
|--|---|--------------------|
| 1) Vehicle Registration Number | : | SJQ1459X |
| Chassis Number | : | KMH DU41BR9U750837 |
| 2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act | : | 27/04/2019 (00:00) |
| 3) Date / Time of Expiry of Insurance | : | 26/04/2020 (23:59) |
| 4) Excess (i) Policy | : | S\$ 600.00 |
| (ii) Windscreen | : | S\$ 100.00 |
| 5) Policyholder | : | Lim Chik Sien |

6) Persons or Classes of Persons Entitled to Drive*

Drivers named as a Main / Named Driver in this Certificate of Insurance only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.

Main Driver / Date of Birth : Lim Chik Sien (22/02/1979)

Named Driver(s) / Date of Birth : Lim Su Chin (22/07/1981)

7) Limitation as to use*

Use only for social, domestic and pleasure purposes and for the occasional business purposes of the drivers listed above. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

- | | | |
|--------------------|---|----------------------|
| 8) Finance Company | : | Speed Credit Pte Ltd |
|--------------------|---|----------------------|

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.


Issued in Singapore on
25/03/2019

Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance



Simon Birch

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7981568C



Name
LIM CHIK SIEN
@PHUA SIEN
林 許 先


Race
CHINESE

Date of birth
22-02-1979

Country/Place of birth
MALAYSIA

Sex
M

S7981568C



REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification No. **S7981568C**

Name
LIM CHIK SIEN

Birth Date **22 Feb 1979**

Issue Date **10 Mar 2000**




5449801



NRIC No. **S7981568C**



Date of return
07-04-2018

APT BLK 489C SENGKANG WEST WAY #28-830
SINGAPORE 783488


NRIC No. **S7981568C** | Date **28/09/2018 (R)**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 25 Motorcycles \leq 200 cc	22 Aug 2001
Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver, and other motor vehicles \leq 2500kg	23 Aug 2001

NR 475A

License No. **S7981568C**



趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Notified
11 Days @ ?
Recovery After Painting
8-10 days

To: First Capital Insurance Limited

Policy No: _____ Third Party

Accident Date : 18.06.2019

Date: 22.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S			
1pc	Bonnet		R ₁ 1,792.40
2pcs	Bonnet Hinges	95.00	R ₁ /R ₂ 190.00
1pc	Bonnet Rubber Seal		C _M 16.20
1pc	Bonnet Insulator		C _M 231.00
9pcs	Bonnet Insulator Clips	3.00	R ₂ 27.00
1pc	Bonnet Lock		R ₂ 225.00
1pc	Bonnet Lock Lower Cover		R ₁ 16.00
1pc	Bonnet Lock Cable		C _M 170.00
1pc	Front Wiper Ganish		R ₁ 150.00
2pcs	Front Wiper Ganish End Cover	59.00	R ₁ 118.00
1pc	Wiper Tank		C _M 70.40
1pc	Wiper Tank Motor		C _M 250.00
1pc	Grille		C _M 438.90
2pcs	Headlamps Assy	577.50	R ₁ 1,155.00
1pc	Front Bumper		R ₂ 556.60
10pcs	Front Bumper Clips	3.30	R ₂ 33.00
2pcs	Front Bumper Brackets	35.20	R ₁ 70.40
2pcs	Front Bumper Top Retainers	24.20	R ₁ 48.40
1pc	Front Bumper Reinforcement		R ₂ 306.90
1pc	Front Bumper Sponge		C _M 136.40
2pcs	Front Bumper Corner Retainers	20.00	R ₁ 40.00
1pc	Front Bumper Center Air Grille		C _M 57.20
1pc	Front Bumper Lower Rubber Guard		C _M 48.00
1pc	Front Bumper Lower Splash Shield		C _M 51.70
2pcs	Front Bumper Fog Lamps	150.00	R ₁ 300.00
2pcs	Front Fenders	513.70	R ₁ /R ₂ 1,027.40
2pcs	Front Fenders Badge	22.00	R ₂ 44.00
1pc	Front Fender Signal Lamp RH		C _M 125.00
1pc	Front Fender Splash Shield RH		C _M 48.00
1pc	Front Fender Inner Panel RH		R ₁ /R ₂ 494.00
1pc	Support Panel		R ₁ /C _M 946.00
1pc	Radiator		647.00
1pc	Radiator Top Bracket RH		15.00
1pc	Radiator Fan Assy		624.00
1pc	Radiator Top Hose		R ₂ 42.00
1pc	Radiator Lower Hose		42.00
1pc	Radiator Expansion Tank		C _M 145.20
			10,698.10
			10,698.10

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Accident Date : 18.06.2019

Date: 22.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S			
		B/F	10,698.10
1pc	Air Con Condenser		1,070.00 ?
1pc	Air Con Condenser Side Air Guide		16.00 ?
1pc	Air Con Discharge Hose		192.00 ?
1pc	Air Con Liquid Pipe		643.00 ?
1pc	Alternator		766.00 ?
1pc	Engine Top Ganish Cover		203.00 ?
1pc	Engine Mounting RH		304.00 ✓
1pc	Engine Mounting Front		217.00 ?
1pc	Engine Lower Sub Frame		309.00 ?
4pcs	Engine Lower Sub Frame Mounting	261.00	1,044.00 ?
1pc	Engine Intake Manifold		407.00 ?
1pc	Engine Intake Manifold Gasket		85.00 ?
1pc	Air Cleaner Intake Duct		97.00 ✓
1pc	Front Shock Absorber RH		281.16 X
1pc	Front Knuckle Arm		403.70 X
1pc	Front Knuckle Arm Bearing		124.60 X
1pc	Front Lower Arm		337.70 X
1pc	Front Lower Arm Ball Joint		91.30 X
	Less 20%		17,289.56 3,457.91 13,831.65
	Grille Emblem		80.00 SN ✓
	Front Number Plate		45.00 SN ✓
	To Conduct Front Electrical Check, Focus Headlamp etc		30.00 201
	To Remove / Refit Air Con Condenser & Refill Gas		120.00 1001
	To Remove / Refit. Radiator System, Bleed, Refill Coolant		60.00 501
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 ✓
	To Dismantle / Replace Engine Parts etc		250.00 ?
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		200.00 ?
		C/F	14,716.65

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Date: 22.06.2019

Accident Date : 18.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S		
		B/F	14,716.65
	To Provide Transportation (Towing)		Bill 80.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 601
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, O/S Fender, Whell Housing, Front O/S Door, Windscreen Pillar, cnt, Weld Fender Inner Panel and Parts Replacement		1600 1,300.00
	To Respray Affected Areas		1100 1,200.00
		Total :	<u>17,376.65</u>

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
61 Sm & 11, 600t Max
Permy After Paint

To: First Capital Insurance Limited

- 10 days

Policy No: _____ Third Party

Date: 22.06.2019

Accident Date : 18.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S			
1pc	Bonnet		<i>Rh</i> 1,792.40
2pcs	Bonnet Hinges	95.00	<i>RH/RH</i> 190.00
1pc	Bonnet Rubber Seal		<i>CM</i> 16.20
1pc	Bonnet Insulator		<i>CM</i> 231.00
9pcs	Bonnet Insulator Clips	3.00	<i>CM</i> 27.00
1pc	Bonnet Lock		<i>Rh</i> 225.00
1pc	Bonnet Lock Lower Cover		<i>RH</i> 16.00
1pc	Bonnet Lock Cable		<i>CM</i> 170.00
1pc	Front Wiper Ganish		<i>CM</i> 150.00
2pcs	Front Wiper Ganish End Cover	59.00	<i>RH</i> 118.00
1pc	Wiper Tank		<i>CM</i> 70.40
1pc	Wiper Tank Motor		<i>CM</i> 250.00
1pc	Grille		<i>CM</i> 438.90
2pcs	Headlamps Assy	<i>CLS Bn</i> <i>NLS M3 CM</i> 577.50	<i>CM</i> 1,155.00
1pc	Front Bumper		<i>Rh</i> 556.60
10pcs	Front Bumper Clips	3.30	<i>CM</i> 33.00
2pcs	Front Bumper Brackets	<i>CLS Bn</i> 35.20	<i>RH</i> 70.40
2pcs	Front Bumper Top Retainers	24.20	<i>RH</i> 48.40
1pc	Front Bumper Reinforcement		<i>CM</i> 306.90
1pc	Front Bumper Sponge		<i>CM</i> 136.40
2pcs	Front Bumper Corner Retainers	20.00	<i>RH</i> 40.00
1pc	Front Bumper Center Air Grille		<i>CM</i> 57.20
1pc	Front Bumper Lower Rubber Guard		<i>CM</i> 48.00
1pc	Front Bumper Lower Splash Shield		<i>CM</i> 51.70
2pcs	Front Bumper Fog Lamps	<i>CLS Bn</i> <i>NLS CM</i> 150.00	<i>CM</i> 300.00
2pcs	Front Fenders	513.70	<i>RH/Bn</i> 1,027.40
2pcs	Front Fenders Badge	22.00	<i>CM</i> 44.00
1pc	Front Fender Signal Lamp RH		<i>CM</i> 125.00
1pc	Front Fender Splash Shield RH		<i>CM</i> 48.00
1pc	Front Fender Inner Panel RH		<i>Rh</i> 494.00
1pc	Support Panel		<i>RH/CM</i> 946.00
1pc	Radiator		<i>Rh</i> 647.00
1pc	Radiator Top Bracket RH		<i>RH</i> 15.00
1pc	Radiator Fan Assy		<i>CM</i> 624.00
1pc	Radiator Top Hose		<i>Rh</i> 42.00
1pc	Radiator Lower Hose		<i>Rh</i> 42.00
1pc	Radiator Expansion Tank		<i>CM</i> 145.20
			10,698.10
C/F			10,698.10

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Date: 22.06.2019

Accident Date : 18.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S		
		B/F	10,698.10
1pc	Air Con Condenser		1,070.00
1pc	Air Con Condenser Side Air Guide		16.00
1pc	Air Con Discharge Hose		192.00
1pc	Air Con Liquid Pipe		643.00
1pc	Alternator		766.00
1pc	Engine Top Ganish Cover		203.00
1pc	Engine Mounting RH		304.00
1pc	Engine Mounting Front		217.00
1pc	Engine Lower Sub Frame		309.00
4pcs	Engine Lower Sub Frame Mounting	261.00	1,044.00
1pc	Engine Intake Manifold		407.00
1pc	Engine Intake Manifold Gasket		85.00
1pc	Air Cleaner Intake Duct		97.00
1pc	Front Shock Absorber RH		281.16
1pc	Front Knuckle Arm		403.70
1pc	Front Knuckle Arm Bearing		124.60
1pc	Front Lower Arm		337.70
1pc	Front Lower Arm Ball Joint		91.30
	Less 20%		17,289.66
			3,457.91
			13,831.65
	Grille Emblem		80.00
	Front Number Plate		45.00
	To Conduct Front Electrical Check, Focus Headlamp etc		30.00
	To Remove / Refit Air Con Condenser & Refill Gas		120.00
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00
	To Dismantle / Replace Engine Parts etc		250.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		200.00
		C/F	14,716.65

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Policy No: Third Party

Date: 22.06.2019

Accident Date : 18.06.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Hyundai Avante" Reg. No. SJQ1459X Claiming Against Your Insured Veh. No. SKH5642S		
		B/F	14,716.65
	To Provide Transportation (Towing)		Bill 80.00 5d
	To Conduct Computerize Wheel Alignment Test		80.00 601
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, O/S Fender, Whell Housing, Front O/S Door, Windscreen Pillar, cnt, Weld Fender Inner Panel and Parts Replacement		1600 1,300.00
	To Respray Affected Areas		1100 1,200.00
		Total :	17,376.65
			17,772.65

趙 源 摩 哆 Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)
Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint
Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车 敲焊打吗 咭喷漆等 ▶

NTUC Income Insurance

Accident Date : 18.06.2019

26.06.2019

Estimate Cost Of Repair To "Hyundai Avante" Reg. No. SJQ1459X
Claiming Against Your Insured Reg. No. SKH5642S

Supplementary		
1pc	Air Con Suction Hose	385.00
1pc	Engine Lower Splash Guard	110.00
		495.00
	Less 20%	99.00
Grand Total :		396.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011075/KVD3N2

Date: 25/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30122719011
Claimant Vehicle No :	SJQ1459X	Insured Vehicle No :	SKH5642S
Date of Loss:	18/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D201017C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ1459X	Engine No:	G4FC9U647798
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U750837
Reg. Date:	27/04/2009 (Man. Year: 2009)	Odometer:	310296 km
Colour:	Metallic Gold		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,352.65	13,158.68	1,193.97	8.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,660.00	760.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,772.65	15,818.68	1,953.97	10.99
Approved Total (Overridden) (\$\$)		11,600.00		
(\$\$)	17,772.65	11,600.00	6,172.65	34.73
+ GST 7.00/7.00% (\$\$)	1,244.09	812.00	432.09	34.73
Nett Amount (\$\$)	19,016.74	12,412.00	6,604.74	34.73

INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 24/06/2019 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2019)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ1459X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,792.40 FL	*1,792.40 FL
2	2		*BONNET HINGES	Distorted/Bent	190.00 FL	*190.00 FL
3	1		*BONNET RUBBER SEAL	Cut	16.20 FL	*16.20 FL
4	1		*BONNET INSULATOR	Cracked	231.00 FL	*231.00 FL
5	9		*BONNET INSULATOR CLIPS	Necessary	27.00 FL	*27.00 FL
6	1		*BONNET LOCK	Bent	225.00 FL	*225.00 FL
7	1		*BONNET LOCK LOWER COVER	Missing	16.00 FL	*16.00 FL
8	1		*BONNET LOCK CABLE	Jammed	170.00 FL	*170.00 FL
9	1		*FRONT WIPER GARNISH	Cracked	150.00 FL	*150.00 FL
10	2		*FRONT WIPER GARNISH END COVER	Missing	118.00 FL	*118.00 FL
11	1		*WIPER TANK	Cracked	70.40 FL	*70.40 FL
12	1		*WIPER TANK MOTOR	Cracked	250.00 FL	*250.00 FL
13	1		*GRILLE	Cracked	438.90 FL	*438.90 FL
14	2		*HEADLAMPS ASSY	O/s Broken/N/s Mtg Cracked	1,155.00 FL	*1,155.00 FL
15	1		*FRONT BUMPER	Bent	556.60 FL	*556.60 FL
16	10		*FRONT BUMPER CLIPS	Necessary	33.00 FL	*33.00 FL
17	1		*FRONT BUMPER BRACKETS	O/s Bent	70.40 FL	*35.20 FL
18	2		*FRONT BUMPER TOP RETAINERS	Distorted	48.40 FL	*48.40 FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	306.90 FL	*306.90 FL
20	1		*FRONT BUMPER SPONGE	Cracked	136.40 FL	*136.40 FL
21	2		*FRONT BUMPER CORNER RETAINERS	Distorted	40.00 FL	*40.00 FL
22	1		*FRONT BUMPER CENTRE AIR GRILLE	Cracked	57.20 FL	*57.20 FL
23	1		*FRONT BUMPER LOWER RUBBER GUARD	Cracked	48.00 FL	*48.00 FL
24	1		*FRONT BUMPER LOWER SPLASH SHIELD	Cracked	51.70 FL	*51.70 FL
25	2		*FRONT BUMPER FOG LAMPS	O/s Broken/N/s Cracked	300.00 FL	*300.00 FL
26	2		*FRONT FENDERS	Bent/Buckled	1,027.40 FL	*1,027.40 FL
27	2		*FRONT FENDERS BADGE	Necessary	44.00 FL	*44.00 FL
28	1		*FRONT FENDER SIGNAL LAMP RH	Cracked	125.00 FL	*125.00 FL
29	1		*FRONT FENDER SPLASH SHIELD RH	Cracked	48.00 FL	*48.00 FL
30	1		*FRONT FENDER INNER PANEL RH	Repair	494.00 FL	*- FL
31	1		*SUPPORT PANEL	Bent/Cracked	946.00 FL	*946.00 FL
32	1		*RADIATOR	Bent	647.00 FL	*647.00 FL
33	1		*RADIATOR TOP BRACKET RH	Distorted	15.00 FL	*15.00 FL
34	1		*RADIATOR FAN ASSY	Cracked	624.00 FL	*624.00 FL
35	1		*RADIATOR TOP HOSE	Punctured	42.00 FL	*42.00 FL
36	1		*RADIATOR LOWER HOSE	Punctured	42.00 FL	*42.00 FL
37	1		*RADIATOR EXPANSION TANK	Cracked	145.20 FL	*145.20 FL
38	1		*AIR CON CONDENSER	Bent	1,070.00 FL	*1,070.00 FL
39	1		*AIR CON CONDENSER SIDE AIR GUIDE	Cracked	16.00 FL	*16.00 FL
40	1		*AIR CON DISCHARGE HOSE	Bent	192.00 FL	*192.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*AIR CON LIQUID PIPE	Bent	643.00 FL	*643.00 FL
42	1		*ALTERNATOR	Cracked	766.00 FL	*766.00 FL
43	1		*ENGINE TOP GARNISH COVER	Cracked	203.00 FL	*203.00 FL
44	1		*ENGINE MOUNTING RH	Cracked	304.00 FL	*304.00 FL
45	1		*ENGINE MOUNTING FRONT	Cracked	217.00 FL	*217.00 FL
46	1		*ENGINE LOWER SUB FRAME	Bent	309.00 FL	*309.00 FL
47	4		*ENGINE LOWER SUB FRAME MOUNTING	Necessary	1,044.00 FL	*1,044.00 FL
48	1		*ENGINE INTAKE MANIFOLD	Cracked	407.00 FL	*407.00 FL
49	1		*ENGINE INTAKE MANIFOLD GASKET	Necessary	85.00 FL	*85.00 FL
50	1		*AIR CLEANER INTAKE DUCT	Cracked	97.00 FL	*97.00 FL
51	1		*FRONT SHOCK ABSORBER RH	Serviceable	281.16 FL	*- FL
52	1		*FRONT KNUCKLE ARM	Serviceable	403.70 FL	*- FL
53	1		*FRONT KNUCKLE ARM BEARING	Serviceable	124.60 FL	*- FL
54	1		*FRONT LOWER ARM	Bent	337.70 FL	*337.70 FL
55	1		*FRONT LOWER ARM BALL JOINT	Serviceable	91.30 FL	*- FL
56	1		*AIR CON SUCTION HOSE	Cut	385.00 FL	*385.00 FL
57	1		*ENGINE LOWER SPLASH GUARD	Cracked	110.00 FL	*110.00 FL
58	1		*GRILLE EMBLEM	Necessary	80.00 FS	*30.00 FS
59	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,909.56	16,429.60
- List Item Discount on L Items 20.00/20.00% (S\$)	3,556.91	3,270.92
Total Parts (S\$)	14,352.65	13,158.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT FRONT ELECTRICAL CHECK, FOCUS HEADLAMP ETC	New	30.00	20.00
2	TO REMOVE/REFIT AIR CON CONDENSER & REFILL GAS	New	120.00	100.00
3	TO REMOVE/REFIT, RADIATOR SYSTEM, BLEED, REFILL COOLANT	New	60.00	50.00
4	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	100.00	100.00
5	TO DISMANTLE/REPLACE ENGINE PARTS ETC	New	250.00	0.00
6	TO DISMANTLE/REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	200.00	180.00
7	TO PROVIDE TRANSPORTATION (TOWING)	New	80.00	50.00
8	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
9	LABOUR CHARGE-PANEL BEATING, REPAIRING OF FRONT CHASSIS MEMBER, INNER PANEL, O/S FENDER, WHEEL HOUSING, FRONT O/S DOOR, WINDSCREEN PILLAR, CNT, WELD FENDER INNER PANEL AND PARTS REPLACEMENT	New	1,300.00	1,000.00
10	TO RESPRAY AFFECTED AREAS	New	1,200.00	1,100.00
Gross Labour Cost (\$\$)			3,420.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >