

ASS. REC. BY:

REF: CS3/MSG19011105/JC d302

Special Instruction:

Surveyor: Hwa Jie

ASSIGNMENT (Office)

Verinder

From (Person): Jayn Tay Mei Ling of MSIG Date/Time: 24.6.19 16.40pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGR 1351H Insured: SG 6291G

at Workshop m/s Legacy Technica motorsports Tel: 8858 8851  
of 39 woodlands Close, #01-08 mega

Policy No: 804630400MX Claim No: 597429

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A 18.6.19  
(Client's Record) 22.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 24.6.19 4.47pm Person Contacted: Eric wang Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SGR 1351H: /
	SG 6291G: /

**ASSIGNMENT**

PRS

From: \_\_\_\_\_ Date: 25.6.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGQ 1351H

at Workshop m/s Legacy Technica  
of 39 woodland close, #01-08

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: \$18k

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp<sup>17</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGQ1351H Yr Regn: 5 Jan/2007

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_

Make: Toyota Altis c.c. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS32EC107137839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195/60 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/6/19 D.O.I. 25/6/19

Survey held at Legacy

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: <del>\$4000</del> - \$5000 6 days. <u>mon</u> 25/6/2019

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: PRC

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Days Of Repair: 6

Resurvey No. of Trip: 2

- Add Fee:
- : Site Insp (\$ \_\_\_\_\_ )
  - : Interview (\$ \_\_\_\_\_ )
  - : Tech. Invs (\$ \_\_\_\_\_ )
  - : Weekend (\$ \_\_\_\_\_ )

Survey Fee:	<u>120</u>
Transportation:	
3 + RS, SI	
Photos	
Others	<u>11</u>
TOTAL	<u>131</u>

### ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019		24 Jun 2019 16:40 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

Insured:	<b>CAVIN MAK CHEE WAI</b> , ID: S9137974J		
Main Claimant:	<b>LEOW HIAN CHYE</b> , ID: S7524195Z		
Vehicle Reg. No.:	<b>SGQ1351H</b>	Date of Loss:	18/06/2019 18:00 - :59 [149 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	80463040QMX (Comprehensive) Coverage: 13/10/2018 - 12/10/2019
Vehicle Reg. No. (Insured):	<b>SJG6291G</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Legacy Technica Motorsports (woodlands) (HQ)</b> 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS, 737856 Woodlands - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Imm.Advice due 25/06/2019</b> ]		
Driver/Custodian (Insured):	MAK HOCK LEONG (63 / Male), NRIC: S1166416D Email:		
Adj Asg. Remarks:	on WP. Liab: 100%. TP Lawyer disagree on SJE - assign LKK Auto. Contact: Eric W Ong @ 8858 8851/ 62561519		

**ASSOCIATED MAIL RECEIVED**

View All

Compose Case Mail

There are no mail for this case.


**ALL ASSOCIATED TASKS**

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4195Z
Vehicle Details	
Vehicle No.:	SGQ1351H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4622085
Chassis No.:	MR053ZEC107137859
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	05 Jan 2007
First Registration Date:	05 Jan 2007
Transfer Count:	2
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,323.00
COE Rebate Amount:	\$12,797.00
<b>Total Rebate Amount:</b>	<b>\$12,797.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jun 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	24/06/2019 09:31
Date Of Accident	18/06/2019 18:45
Exact Location Of Accident	OUTSIDE VIVOCITY ALONG TELOK BLANGAH RD LP 36-38
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ1351H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEOW HIAN CHYE
NRIC No	S7524195Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82284808
Alternative Phone No	OFFICE-82284808

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5097808659-01
Cover Note Number	

#### Driver

Name of Driver	LEOW HIAN CHYE
NRIC No	S7524195Z
Date Of Birth	07/08/1975
Occupation	OUTDOOR
Date Of Driving Pass	06/03/1996
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82284808
Fax Number	
Contact Number	OFFICE-82284808
EEmail Address	NOEMAIL

Address	BLK 204 PETIR ROAD #05-623
Postcode	670204
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG6291G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAK HOCK LEONG
NRIC/Passport Number	S1166416D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

\* No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	LEOW HIAN CHYE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SGQ1351H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**DETAILS OF INJURED PERSON 2**

Name	MAK HOCK LEONG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJG6291G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN




Along Telok Blangah Road Towards Pasir Panjang.  
Between lamp pole 36-38


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20190622/7010

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3  
Report No. T/20190622/7010

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEOW HIAN CHYE	ID No.	S7524195Z
Related Vehicle	SGQ1351H (Car)	Contact No.	82284808
Hospital/Clinic	SGH SPECIALIST PRACTICE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	18/06/2019	Date Discharge	21/06/2019
No. of Days granted Medical Leave	32	Degree of Injury	Slight
Driver			
Name	MAK HOCK LEONG	ID No.	S1166416D
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

## Brief Details.

I WAS DRIVING(SGQ1351H) ALONG TELOK BLANGAH ROAD TOWARDS PASIR PANJANG ROAD ON THE 18/JUNE/2019 AROUND 1845HRS. MY CAR WAS STATIONARY AT THE TRAFFIC LIGHT BETWEEN LAMP POLE 36 & 38. AS I WAS WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN, A VEHICLE SJG6291G COLLIDE & BANG ON TO THE REAR OF MY VEHICLE. THE 3RD PARTY DRIVER WAS INJURED, AND I WAS ALSO INJURED. TRAFFIC POLICE AND AMBULANCE WAS PRESENT, AND WE WERE BOTH SENT TO HOSPITAL. I WAS DISCHARGE FROM THE HOSPITAL ON THE 21 JUNE 2019.

Sketch Plan #5



**SINGAPORE  
POLICE FORCE**



T/20190622/7010

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190622/7010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 22/06/2019 11:26
Officer In Charge Of Case: TP / TPHQ / MOHAMED RIZWAN BIN IBRAHIM Contact No.: 93265045	Classification Of Case:

Authentication Stamp

NP168

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019		24 Jun 2019 16:40 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by insurer]</span>									
Insured:	<b>CAVIN MAK CHEE WAI</b> , ID: S9137974J								
Main Claimant:	<b>LEOW HIAN CHYE</b> , ID: S7524195Z								
Vehicle Reg. No.:	<b>SGQ1351H</b>	Date of Loss:	18/06/2019 18:00 - :59 [149 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 597429</b>	Policy/Cover Note No.:	80463040QMX (Comprehensive) Coverage: 13/10/2018 - 12/10/2019						
Vehicle Reg. No. (Insured):	<b>SJG6291G</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Legacy Technica Motorsports (woodlands) (HQ)</b> 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS, 737856 Woodlands - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Imm.Advice due 25/06/2019]								
Driver/Custodian (Insured):	MAK HOCK LEONG (63 / Male) , NRIC: S1166416D Email:								
Adj Asg. Remarks:	on WP. Liab: 100%. TP Lawyer disagree on SJE - assign LKK Auto. Contact: Eric WOnG @ 8858 8851/ 62561519								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SGQ1351H (597429)  
 [SJG6291G]  
 TP  
 LEOW HIAN CHYE  
 Jun 18 2019 6:00PM  
 [CAVIN MAK CHEE WAI]  
 Legacy Technica Motorsports (woodlands)

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
2	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
3	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
4	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
5	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
6	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
7	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
8	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
9	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
10	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
11	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
12	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
13	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
14	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
15	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
16	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
17	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
18	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
19	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
20	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
21	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
22	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
23	25/06/19 17:37	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
24	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
25	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
26	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
27	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
28	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
29	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
30	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
31	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
32	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
33	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
34	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
35	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
36	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
37	06/07/19 17:34	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	06/07/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
<b>Documentation</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/06/19 15:15	<b>PRI</b>	Load PDF	
2	24/06/19 15:15	<b>OI Accident Report</b>	Load PDF	
3	24/06/19 15:15	<b>TP SGQ1351H E-REPORT</b>	Load PDF	
4	24/06/19 15:25	<b>TP disagree on SJE</b>	Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG19011105/JCD3E2

**Date:** 11/07/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80463040QMX
<b>Claimant Vehicle No :</b> SGQ1351H	<b>Insured Vehicle No :</b>	SJG6291G
Date of Loss: 18/06/2019	Nature of Claim:	TP <span style="float: right;">Claim No: 597429</span>

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGQ1351H</b>	
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Engine No: 3ZZ4622085
Reg. Date:	05/01/2007 (Man. Year: 2006)	Chassis No: MR053ZEC107137859
Colour:	Grey	Odometer: 0 km
Engine Capacity:	1598 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	24/06/2019	
Date Inspected:	25/06/2019 Inspected At:	Legacy Technica Motorsports (woodlands) (HQ) 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS Singapore 737856
Estimated Period of Repair:	6.0 days	

**Adjuster:** ONG HWEE JIE

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2019)	
<b>Parts:</b> 143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SGQ1351H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >