

Tang J. Loh

EQ

11116/T11

2017 May

Vehicle No. SEN 7956E

Type Car / Bus / Van / Truck / Trailer or Semi Trailer

Make Toyota Prius

Color Silver

Sp. Reading 120753

License No. JA DRB3F4003558489

Steering Inoperative / Jammed / Leaked / Burnt or

Brake Inoperative / Jammed / Leaked / Burnt or

Mod. Hil / STD / Air Rim or

Tyre Size F 195/65R15

BS / DUN / EXNOVA / GY / FS / LL / A / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Wal 6 mm L/Wal 6 mm

D.O.A. 26/6/19


Survey held at Bonnie Rindan

Loc. of Damages Front / Rear / Q/S / H/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Person Contacted Thomas Francis

Date / Time Action / Instruction



Days Of Repair: 1 2 3 4 5 6 7 8 9 10 11 12

Resurvey No. of Trip: 1 2 3 4 5 6 7 8 9 10

Add Fee: Site Insp. (\$) Interview (\$) Tech. Inv. (\$) Weekend (\$)

Report Format: Long Form Short Form Other

Lump Sum / L.R.E. (\$)

Survey Fee: Transportation Other

Total