EQ 11138 | T1 (P)

Triangle

2019 May.

Date:

Estimated Cost:

Cap: / WS / IF / FS / OH / SH / VA / RV / MS

Inspect Vehicle No:

Appointed Inspector:

at:

Inspected:

Policy No:

Change No:

Sum Insured: Excess:

(Insured's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Scan: Consistent? Yes or No

Est. Repairs: days Rec: Yes or No

Loss Sum: % JV.Al: Yes or No

GA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time	Action / Instruction

Date/Time File Pass In?

Prelt. Report

Final Report

Date/Time File Returned?

Report Format:

Lump Sum / EDI: Y/N

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Late Insp. $

Interview $

Tech. Inv. $

Weekend $

Survey Fee:

Transportation:

Photo:

Other:

Total:

Sub No: SFW11269

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Attrage 1.2 1193

Colour: white

Cap Reading: 2385

Eng No: MM8STA13AKH001846

C/No:

Gen. Cond.: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi.: Nil / S.Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R:

DUN / EXNOVA / GY / FS / LEA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I.	26/6/19 @ 4.15pm	

Survey held at: C&C Panda Garage

Dgs. of Damages: F / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision