

ASS. REC. BY:

REF: CS/MSG/19011136/utd3n2

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Jasmine Lok Khing Kwai of MSIG

Date/Time: 24.6.19 17.13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 907H

Insured: FBF 4540B

at Workshop m/s S M spray painting

Tel: 9822 8246

of 25 Koki Built Road 4 # 08-30

Policy No: ms D1 vms/19-394670

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.6.19 9.06am

Person Contacted: Darren

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBF 4540B: ✓
	SJX 907H: CC6/11129007524/ App3 D.O.A: 25/04/2019
26/6-	Revised via menmen preli advise.

(08/11/13)

ASS. REC. BY:

REF

MSG

ASSIGNMENT

From: Date: 25.6.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. SJK 907H

at Workshop n/s SM Spray Painting

of 25 Kari Bukit Road 4 #08-30

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

50k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my' 47A292W

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJK 907H Yr Regn: 10,08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Volkswagen Golf GTI c.c. 1984

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 147778 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ1KZ8W142330

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 235/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/6/19

D.O.I. 25/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s &

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/8/19 2-10-2019
 confirmed 2/5 & 2350 w.l.c. verify. (Red: 469.60: 66%)

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

1) 8/7 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 23504

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

150

11

161

Signature
 8/7/2019

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 26 Jun 2019

Preliminary Advice

Insured Vehicle No	: FBF4540B	Accident Date	: 21/06/2019
TP Vehicle No	: SJK907H	Assignment Date	: 24/06/2019
Make	: VOLKSWAGEN GOLF GTI	Est. Duration of Repair	: 3.00
Date of Inspection	: 25/06/2019		
Inspection At	: S M SPRAY PAINTING (HQ) 25 KAKI BUKIT ROAD 4 #08-30, SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	0.00
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2019		24 Jun 2019 17:13 Assign				New Assignment Cancel Case

Main
Reference
Claim Details
Documents
Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	IRWAN BIN ABDUL RAHNI , ID: S8511059D		
Main Claimant:	SUTANTO IDRIES , ID: S7517096C		
Vehicle Reg. No.:	SJK907H	Date of Loss:	21/06/2019 14:00 - :59 [128 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMS/19-394670 (TP, Fire & Theft) Coverage: 28/01/2019 - 27/01/2020
Vehicle Reg. No. (Insured):	FBF4540B	Policy No. (Claimant):	
		Excess:	
Repairer:	S M Spray Painting (HQ) 25 Kaki Bukit Road 4 #08-30, Synergy@KB, 417800 Kaki Bukit - Tel: 98228346		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/06/2019]		
Adj Asg. Remarks:	on WP. (manual assigned) Liab: dispute (OI NR) TP lawyer agree on SJE - assign Marcus Chua from LKK Auto Consultants. Contact: Wendy @ 6384 1755 / 1766. Manually assigned to LKK via email on 24/06/2019.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



DW
Daniel Wellington
31 Different Types
to Choose From



Disc **47%** Direct from Japan
SHOP NOW >>

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes-Benz B-Class B180 Style.



1 Owner And Fully Maintained
By C&C, 75K And 90K Service
Package At C&C Included
Direct Owner StarAd

HIN LUNG AUTO
HoBee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sales

Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

Golf GTI

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Golf GTI		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Volkswagen	Golf GTI 5DR (COE till 10/2028)	\$63,800	\$6,850 /yr	15-Oct-2008	1,984 cc	150,000 km	Sports	Available
	The Most Sort After GTI In The Market. The Legendary MK5 GTI. A True Hot Hatch Deserving Of Its Name. Owner Looking To Handover This Beauty. Practical 5 Door Family Hatch. Consignment Unit! Trade In A...								
	Prem Roy Motoring								
	Posted: 24-Jun-2019 Tags: 2008 Volkswagen Golf, 2008 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen	Golf GTI 5DR (COE till 02/2029)	\$58,000	\$5,990 /yr	09-Apr-2009	1,984 cc	-	Sports	Available
	Lowest Price, Lowest Depreciation. 90% Loan Available. Well Maintained GTI With Wear & Tear Parts Replaced Ahead Of Schedule. Groomed Weekly, Zero Issues On The Car. Own A German Hot Hatchback At A Pr...								
	Bavarian Marques Pte Ltd								
	Posted: 20-Jun-2019 Tags: 2009 Volkswagen Golf, 2009 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen	Golf GTI 5DR (COE till 04/2029)	\$68,888	\$6,990 /yr	02-Oct-1999	1,781 cc	145,000 km	Sports	Available
	Rare VW Golf GTI Mk4. One Of The Last Few In SG. Extremely Well Maintained And Serviced. Engine Fully Rebuilt, New Turbos And Upholstery!								
	Posted: 20-Jun-2019 Tags: 1999 Volkswagen Golf, 1999 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								
	Volkswagen	Golf GTI 3DR (COE till 07/2021)	\$55,800	\$26,550 /yr	14-May-1982	1,588 cc	-	Sports	Available
	Favourite Collection Car! Well Maintain By Owner. Consignment Unit. For Viewing Please Make An Appointment With Us. Call Now!								
	Car Search								
	Posted: 02-Jun-2019 Tags: 1982 Volkswagen Golf, 1982 volkswagen golf, Volkswagen Golf, volkswagen golf, Volkswagen, Golf, golf, Used Volkswagen								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Golf GTI, Golf GTI Singapore, used Golf GTI Singapore, used Golf GTI, used vehicles Singapore or even buy used Golf GTI Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7096C

Vehicle Details

Vehicle No.:	SJK907H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF GTI 3DR
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	BWA163877
Chassis No.:	WVWZZZ1KZ8W142330
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$29,769.00
Original Registration Date:	03 Oct 2008
First Registration Date:	03 Oct 2008
Transfer Count:	0
Actual ARF Paid:	\$29,769.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Oct 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$29,920.00
Total Rebate Amount:	\$29,920.00

The information contained herein is correct as at 25 Jun 2019

OK

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4

#01-12/13 Synergy@KB

Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:		Date:	6/24/2019 4:49 PM
Company:		VIN	
License NO:	SJK907H	Technician:	
Odometer:	147777KM	Order NO:	

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, GOLF VI [5K], 09-13, (G03, G08) Sportsline GTi

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	7°10'	8°10'	----
		Right	----	7°10'	8°10'	----
	Camber	Left	-1°00'	-1°14'	-0°14'	-1°00'
		Right	-1°06'	-1°14'	-0°14'	-1°06'
	Toe	Left	-1°00'	0°00'	0°10'	-1°00'
		Right	1°03'	0°00'	0°10'	1°03'
Total		0°03'	0°00'	0°20'	0°03'	
Rear	Camber	Left	-0°48'	-2°15'	-1°15'	-0°54'
		Right	-1°36'	-2°15'	-1°15'	-1°36'
	Toe	Left	2°27'	-0°01'	0°11'	2°27'
		Right	0°06'	-0°01'	0°11'	0°06'
		Total	2°33'	-0°02'	0°22'	2°33'
	Max Thrust Angle		-1°11'	0°10'		-1°11'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	----	----	----
	Right		----	----	----	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	1°02'	1°42'	----
	Right		----	1°02'	1°42'	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		7mm	----	----	7mm
	Rear		12mm	----	----	12mm
Track Width Diff. Wheel Base Diff.			21mm -5mm			21mm -5mm
Front Ride Height	Left		----	350mm	370mm	----
	Right		----	350mm	370mm	----
Rear Ride Height	Left		----	355mm	375mm	----
	Right		----	355mm	375mm	----
Frame Angle						----

www.stamfordtyres.com

not pass

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4

#01-12/13 Synergy@KB

Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:		Date:	6/26/2019 3:31 PM
Company:		VIN	
License NO:	SJK907H	Technician:	
Odometer:	147'780KM	Order NO:	

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, GOLF V [1K], 04-08, (G08) Sportline GTi

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	7°17'	8°17'	----
		Right	----	7°17'	8°17'	----
	Camber	Left	-1°00'	-1°14'	-0°14'	-1°00'
		Right	-1°06'	-1°14'	-0°14'	-1°06'
	Toe	Left	0°54'	0°00'	0°10'	0°06'
		Right	-0°54'	0°00'	0°10'	0°06'
Total		0°00'	0°00'	0°20'	0°12'	
Rear	Camber	Left	-1°24'	-2°15'	-1°15'	-1°30'
		Right	-1°42'	-2°15'	-1°15'	-1°36'
	Toe	Left	-0°24'	-0°01'	0°11'	0°09'
		Right	0°18'	-0°01'	0°11'	0°09'
		Total	-0°06'	-0°02'	0°22'	0°18'
	Max Thrust Angle		0°21'	0°10'		0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	----	----	----
		Right	----	----	----	----
Included Angle		Left	----	----	----	----
		Right	----	----	----	----
Toe Out On Turns		Left	----	1°02'	1°42'	----
		Right	----	1°02'	1°42'	----
Max Turn Inside		Left	----	----	----	----
		Right	----	----	----	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	9mm	----	----	9mm
		Rear	-12mm	----	----	-11mm
Track Width Diff.			25mm			25mm
Wheel Base Diff.			21mm			20mm
Front Ride Height		Left	----	350mm	370mm	----
		Right	----	350mm	370mm	----
Rear Ride Height		Left	----	355mm	375mm	----
		Right	----	355mm	375mm	----
Frame Angle						----

www.stamfordtyres.com

SM SPRAY PAINTING

SM Auto Coat wants hence notify the Repayer of the following:

- To insure by 10 days after spray painting
- To avoid any damaged part(s) during resurvey
- Repair must be subject to confirmation
- Third Party Claims on a "Without Prejudice" basis
- No further adjustments is allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SJK907H	Excess.	NIL
Policy No.	MT/00096515/06	Coverage.	
Claiming Against.	FBF4540B		
Insured Under.	DIRECT ASIA		

Acknowledged by Repayer

Signature:

NIL

Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF
Engine No.	BWA163877
Chassis No.	WVWZZZ1KZ8W142330
Odometer	
Engine CC.	2000
Year Of Reg.	2008
Colour.	RED
Parf/COE Rebate.	\$ 29,929.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

REAR PORTION

General Information

Accident Date. 21/6/2019
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

Handwritten notes:
26/6/19
Not Adh
LH
h/s 2350
3 day
25/6/19
Tech Pte Atty

SM SPRAY PAINTING

Qty.

Description Of Parts

Pricing

1	REAR BUMPER	955.18
1	REAR BUMPER SIDE RETAINER LH	
1	REAR BUMPER BRACKET LH	
1	REAR AXLE BEAM	
1	REAR LOWER ARM LH	
1	REAR SHOCK ABSORBER LH	
1	REAR THRUST ARM LH	315.00

Dis	\$	970.00	✓
11	\$	48.00	X
Bul	\$	55.00	✓
11	\$	1,390.00	X
11	\$	390.00	X
11	\$	285.00	X
Bul	\$	330.00	✓
List items	\$	3,468.00	
Less 5%	\$	173.40	
Sub Total	\$	3,294.60	

1	REAR BUMPER CLIPS	
1	REAR BUMPER LOWER SKIRT	
1	REAR BUMPER SENSORS (1 SET)	
1	REAR WHEEL RIM (SPORTS) LH	

11	\$	45.00	✓
Bul	\$	700.00	✓
11	\$	220.00	X
R	\$	550.00	X
S/N	\$	1,515.00	

1- 1325.18
 52
 1258.92

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panel for rust protection.	11 \$ 50.00 X
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 60.00 20
	To Carry-Out Body Cavity Preservation.	11 \$ 50.00 X
	To remove and refit rear bumper sensors.	\$ 80.00 50
	Computer wheel alignment	\$ 100.00 60
	To dismantle and refit rear undercarriage.	\$ 220.00 120
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,000.00 300
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 600.00 400
	LABOUR	\$ 2,160.00 950
	Sub Total.	\$ 6,969.60
	7% GST	\$ 487.87
	Grand Total	\$ 7,457.47

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

P- 1258.92
 S.N. 745.00
 Labor - 950.00

 2953.92
 2360

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011136/UTD3N2

Date: 10/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-394670
Claimant Vehicle No :	SJK907H	Insured Vehicle No :	FBF4540B
Date of Loss:	21/06/2019	Nature of Claim:	TP
		Claim No:	MSCN/19-000728

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK907H	Engine No:	BWA163877
Make & Model:	VOLKSWAGEN GOLF GTI, 2.0 3DR 5K19V3 (A)	Chassis No:	WVWZZZ1KZ8W142330
Reg. Date:	03/10/2008 (Man. Year: 2007)	Odometer:	147778 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40R18	Rear Tyre Size:	235/40R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,809.60	2,003.92	2,805.68	58.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	950.00	1,210.00	56.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,969.60	2,953.92	4,015.68	57.62
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	6,969.60	2,350.00	4,619.60	66.28
+ GST 7.00/7.00% (S\$)	487.87	164.50	323.37	66.28
Nett Amount (S\$)	7,457.47	2,514.50	4,942.97	66.28

INSPECTION

Date of Assignment:	24/06/2019	
Date Inspected:	25/06/2019 Inspected At:	S M Spray Painting (HQ) 25 Kaki Bukit Road 4 #08-30, Synergy@KB Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	144	VOLKSWAGEN GOLF GTI 2.0 3DR 5K19V3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK907H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	970.00 FL	*955.18 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	48.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LH	Bent	55.00 FL	*55.00 FL
4	1		*REAR AXLE BEAM	No such part	1,390.00 FL	*- FL
5	1		*REAR LOWER ARM LH	Not Necessary	390.00 FL	*- FL
6	1		*REAR SHOCK ABSORBER LH	Not Necessary	285.00 FL	*- FL
7	1		*REAR THRUST ARM LH	Bent	330.00 FL	*315.00 FL
8	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
9	1		*REAR BUMPER LOWER SKIRT	Broken	700.00 FS	*700.00 FS
10	1		*SET REAR BUMPER SENSORS	Not Necessary	220.00 FS	*- FS
11	1		*REAR WHEEL RIM (SPORTS) LH	Repair	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,983.00	2,070.18
- List Item Discount on L Items 5.00/5.00% (\$\$)	173.40	66.26
Total Parts (\$\$)	4,809.60	2,003.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANEL FOR RUST PROTECTION	New	50.00	0.00
2	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	60.00	20.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	50.00	0.00
4	TO REMOVE AND REFIT REAR BUMPER SENSORS	New	80.00	50.00
5	COMPUTER WHEEL ALIGNMENT	New	100.00	60.00
6	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE	New	220.00	120.00
7	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	300.00
8	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS,CLEANING & SANDING OF SURFACES,FINAL POLISING & WAXING ARE ALSO AVAILABLE	New	600.00	400.00
Gross Labour Cost (\$\$)			2,160.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >