

ASS. REC. BY:

REF: (S3/CTI19011167/Acd3SM)

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CTIDate/Time: 15.6.19 9.05 a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 7768BInsured: SW 33534at Workshop m/s ACE AutolubTel: 68441184of 13 Kaki Bukit Road 4 #03-29Policy No: DMPSEN30109619088Claim No: SNM190202873COR

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 19.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

sup

H.O.D. Endorsement: _____

Date/Time: 15.6.19 12.00 p.mPerson Contacted: JennyVehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SW 33534 : /
	SMH 7768B : /
1/7/19	@ 12.47pm Jenny said no est provided
	Dismanle: 28/6/2019
	After repair: 2/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		01 Jul 2019 16:12 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LIM SOON HUAT, ID: S7000688Z		
Vehicle Reg. No.:	SMH7768B	Date of Loss:	19/06/2019 09:00 - :59
Claim Type:	TP / SNM19D202873C02	Policy/Cover Note No.:	DMPCSN30109619088
Vehicle Reg. No. (Insured):	SJW3353Y	Policy No. (Claimant):	SD19V1983/VPC/R00
		Excess:	S\$0.00
Repairer:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 25 June 2019 9:05 AM
To: Sim Teo Koon
Cc: 'Ace Autolution'; assignments
Subject: RE: our ref: snm19d202873 / accident involve smh7768b & sjw3353y on 19.6.19 / YOUR REF: JEQ/190547/0619/ACE(ZL)

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: Monday, 24 June, 2019 10:41 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Ace Autolution' <admin@aceauto.com.sg>
Subject: FW: our ref: snm19d202873 / accident involve smh7768b & sjw3353y on 19.6.19 / YOUR REF: JEQ/190547/0619/ACE(ZL)

Dear Sir,

We refer to your email / letter.

We are instructed that our client is not agreeable to the surveyors proposed by you.

Please be informed that our client do not have 10 surveyors, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1) SK Auto Consultants,

- 2) PAR Automotive Consultancy,
- 3) LCW APPRAISER PTE LTD
- 4) Sincere Appraisal Services,
- 5) Pal's Appraisal Pte Ltd,
- 6) Mc-Coy Appraiser Pte Ltd,

If the above is not agreeable by you, please be informed that our client 's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4
#03-29, Bartley Biz Centre
Singapore 417807
TEL: 6844 1184

*** Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)
JusEquity Law Corporation.
Tel: 6506 6065, Fax: 6536 9339
E-mail: tk_sim@juseq.com.sg

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Friday, 21 June, 2019 10:26 AM

To: zul@juseq.com.sg

Subject: our ref: snm19d202873 / accident involve smh7768b & sjw3353y on 19.6.19 / YOUR REF: JEQ/190547/0619/ACE(ZL)

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI

HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2019 16:41
Date Of Accident	19/06/2019 09:30
Exact Location Of Accident	TUAS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH7768B
Insured/Policyholder	
Name Of Registered Owner	LIM SOON HUAT
NRIC No	S7000688Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97531413
Alternative Phone No	OTHERS-97531413

Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH HYBRID 7-SEATER 1.8X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V1983/VPC/R00
Cover Note Number	

Driver

Name of Driver	LIM SOON HUAT
NRIC No	S7000688Z
Date Of Birth	01/01/1970
Occupation	INDOOR
Date Of Driving Pass	29/09/1989
Driving Experience	29 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97531413
Fax Number	
Contact Number	OTHERS-97531413
Email Address	NOEMAIL

Address	BLK 357 YUNG AN ROAD #12-61
Postcode	610357
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW3353Y
Vehicle Make/Model/Colour	FIAT BRAVO 1.4 M
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability. Facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKTI (VAC)
Reporting Centre
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305
Email: vac@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/6/2019 at 09:30 AM, I was stationary at Tras
Road when _____ Suddenly, vehicle B (SJW 3353 Y) hit
onto my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature
Name: _____ Tel: 67416607
NRIC/FIN No.: _____ Fax: 67492305
Email: vackb@singnet.com.sg

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0688Z
Vehicle Details	
Vehicle No.:	SMH7768B
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 7-SEATER 1.8X CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	2ZR2B14739
Chassis No.:	ZWR800338673
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,395.00
Original Registration Date:	31 Jan 2019
First Registration Date:	31 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$25,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2029
PARF Rebate Amount:	\$19,464.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,689.00
COE Rebate Amount:	\$32,267.00
Total Rebate Amount:	\$51,731.00

The information contained herein is correct as at 01 Jul 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		01 Jul 2019 16:12 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	LIM SOON HUAT , ID: S7000688Z		
Vehicle Reg. No.:	SMH7768B	Date of Loss:	19/06/2019 09:00 - :59 [4 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202873C02	Policy/Cover Note No.:	DMPCSN30109619088
Vehicle Reg. No. (Insured):	SJW3353Y	Policy No. (Claimant):	SD19V1983/VPC/R00
		Excess:	\$0.00
Repairer:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMH7768B (SNM19D202873C02)**
[SJW3353Y]

TP
LIM SOON HUAT
Jun 19 2019 9:00AM
[-]

Ace Autolution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video

No	Finalized On	VAC (Kaki Bukit)	1 per page	Thumbnail	Print
1	19/06/19 16:45	Video - Accident [Linked Accident Report Documents]		Load MP4	































Assessment Reports

No	Finalized On	VAC (Kaki Bukit)	1 per page	Thumbnail	Print
1	19/06/19 16:50	Accident Statement		Load HTM	

Photos/Images

No	Finalized On	VAC (Kaki Bukit)	3 per page	Thumbnail	Print
1	19/06/19 16:48	Driving License [Linked Accident Report Documents]		Load JPG	
2	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	19/06/19 16:48	Accident Photo [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/19 15:40	General View	Load JPG	
2	09/07/19 15:40	General View	Load JPG	
3	09/07/19 15:40	General View	Load JPG	
4	09/07/19 15:40	General View	Load JPG	
5	09/07/19 15:40	General View	Load JPG	
6	09/07/19 15:40	General View	Load JPG	
7	09/07/19 15:40	General View	Load JPG	
8	09/07/19 15:40	General View	Load JPG	
9	09/07/19 15:40	General View	Load JPG	
10	09/07/19 15:40	General View	Load JPG	
11	09/07/19 15:40	General View	Load JPG	
12	09/07/19 15:40	General View	Load JPG	
13	09/07/19 15:40	General View	Load JPG	
14	09/07/19 15:40	General View	Load JPG	
15	09/07/19 15:40	General View	Load JPG	
16	09/07/19 15:40	General View	Load JPG	
17	09/07/19 15:40	General View	Load JPG	
18	09/07/19 15:40	General View	Load JPG	

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
19	09/07/19 15:40	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/07/19 15:40	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/07/19 15:40	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/07/19 15:40	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/07/19 15:40	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/07/19 15:40	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/07/19 15:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/06/19 16:50	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	19/06/19 16:50	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View View In Browser

Video			1 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/06/19 16:45	Video - Accident	Load MP4	

Assessment Reports

			1 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/06/19 16:50	Accident Statement	Load HTM	

Photos/Images

			3 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/06/19 16:48	Driving License	Load JPG	
2	19/06/19 16:48	Accident Photo	Load JPG	
3	19/06/19 16:48	Accident Photo	Load JPG	
4	19/06/19 16:48	Accident Photo	Load JPG	
5	19/06/19 16:48	Accident Photo	Load JPG	
6	19/06/19 16:48	Accident Photo	Load JPG	
7	19/06/19 16:48	Accident Photo	Load JPG	

Documentation

			1 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	19/06/19 16:50	Sketch Plan	Load TIF	
2	19/06/19 16:50	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19011167/ACD3S2

Date: 06/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30109619088		
Claimant Vehicle No :	SMH7768B	Insured Vehicle No :	SJW3353Y		
Date of Loss:	19/06/2019	Nature of Claim:	TP	Claim No:	SNM19D202873C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7768B		Engine No:	2ZR2B14739
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)		Chassis No:	ZWR800338673
Reg. Date:	31/01/2019 (Man. Year: 2018)		Odometer:	10532 km
Colour:	Bronze			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/07/2019	
Date Inspected:	26/06/2019	Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Aug 2019)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH7768B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >