

INS. CASE OWNER:

FA

CC4 / Asm 190

11171

K gaby

LKK:

IDAC

123555

Surveyor:

fsc

DOI:

ASSIGNMENT

28/6/2019

Date / Time:

25/6/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR8666P

Name of Insured:

Ong Thian Lai

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

23/6/2019

Is driver the owner?

(YES)

(NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES/NO)

OI GIA REPORT:

YES

NO

TP GIA REPORT:

YES

NO

Insured Liability:

%

Final ? Yes / No

SLA 1722P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Optima work.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLA 1722P - X	SLR8666P - X	STAGE	DATE / PIC
28/6	BLNK - sent out by letter	Non-Reporting ltr (1st):	
09/07	OI GIA Report in	Non-Reporting ltr (2nd):	
17/9/19	Req. AVP from TP, Req. AVP from OI	Non-Reporting ltr (Final):	
	OI inform to contact his daughter to email AVP. Sent LOI.	Notification ltr (if non-pickup):	
23/9/19	OI AVP in. potential reject TP claim.	Call OI:	7/19
	Seek instruction from AXA on rejection of statutory when collision happen.	After call ltr to OI:	
08/10/19	Rejection email send TP. (TP acknowledge reply in 1).	Documentation Check List:	Handler Typist
17/12/19	File pass me to close.	Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

CELILIA

Y-

2/03/19

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: 01P

SS 950

(2 - days)

Reduction: 824

% 33

Confirm by:

Kenny

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia.:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4251/-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: ADA

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

8500h

(Red = 244 / 33%)

Veh No:

SLA 2722P Yr Regn: 02. 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Siesta cc 1496

Colour:

M. & Pink A/C: Insured / Std / NI / NA

Sp. Reading

45442 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NSP170 7013634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

Hankook 185/60R15

R: Toyo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

7 mm

L/Bal.

6 mm

L/Bal.

7 mm

D.O.A.

23/6/19

D.O.I.

25/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Acc

The U/C / Chassis frame / Body Structure affected due to collision.

GRC

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ = RS. \$

Fuel:

Others:

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 25.06.2019
Vehicle No: SLA2722P
Model: TOYOTA SIENTA 1.5G CVT
Chassis: NSP1707013634 - 2015
Reg.Year: 2016

Third Party Insurer: AXA
Third Party Veh No: SLR8666P
Date of Accident: 23.06.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		REPAIR
2	REAR FENDER RH	1		REPAIR
			SUB TOTAL	\$0.00
			LESS 25%	\$0.00
			PARTS TOTAL	\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	8	\$5.50	~ \$44.00
			S/N TOTAL	\$44.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION
-REAR BUMPER & REAR FENDER RH

\$200.00 100

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION
-REAR BUMPER & REAR FENDER RH

\$500.00 400

LABOUR TOTAL \$700.00

PEI TING TOTAL \$744.00

Not Withheld

2 days

\$500

Let's Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554506
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7304E

Vehicle Details

Vehicle No.: SLA2722P
Vehicle to be Exported: No
Intended Deregistration Date: 16 Mar 2019
Vehicle Make: TOYOTA
Vehicle Model: SIENTA 1.5G CVT
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: 2NR8556594
Chassis No.: NSP1707013634
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$19,882.00
Original Registration Date: 25 Feb 2016
First Registration Date: 25 Feb 2016
Transfer Count: 0
Actual ARF Paid: \$14,882.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Feb 2026
PARF Rebate Amount: \$11,161.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$26,000.00
COE Rebate Amount: \$18,045.00
Total Rebate Amount: \$29,206.00

The information contained herein is correct as at 16 Mar 2019

OK



Service Request Details

Claim

S9M01RQD

Reference

None 

Loss Date

June 23, 2019

Report Date

Jun 25, 2019 9:24:30 AM

Request Date

June 25, 2019

Due Date

July 2, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

PLly
T: 11.340.11
V: 14
E: ✓

Actions

Next Step

Agree to perform service

[Decline Work](#)

[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SLA2722P

REQUEST

UNKNOWN

Service Address

...

Primary Contact/Insured

ONG THIAN LAI

BLK 609 ANG MO KIO AVENUE 4, #06-1163, 560609, Singapore

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: Lily.loi@ow.sg
Sent: Monday, 24 June, 2019 5:12 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Sharon Ten'; angela.tan@ow.sg; hockkong.ong@ow.sg
Subject: PRI - SLA2722P CLAIMING AGAINST SLR8666P DOA 23/06/19 (AXA)

Categories: Santosh

Dear Officer,

Kindly arrange PRI at 9A Serangoon North Ave 5
Thank you

--
Best Regards,

Lily Loi (Ms.)

Senior Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143
Branch: 9A Serangoon North Ave 5 Singapore 554500
Branch: 551 Upp Thomson Road Singapore 574415

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Tel: (+65) 6452 0060 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

25 June, 2019

ONG THIAN LAI
BLK 609 ANG MO KIO AVENUE 4
#06-1163
SINGAPORE 560609

Dear Sir,

OUR REF : S9M01RQD
YOUR REF : SLR 8666P
ACCIDENT INVOLVING SLR 8666P & SLA 2722P ALONG/ AT JALAN LINGKARAN
DALAM ON 23/06/2019

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Singapore Pte Ltd to deal with the third party claim against your motor policy.

We have received a third party claim(s) from **Optima Werkz Pte Ltd** acting on behalf of the owner of **SLA 2722P** against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/motor-claims>

Your full co-operation in the handling of the claim is required and kindly submit the following to <<YOUR EMAIL ADDRESS>> within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 17 July 2019 1:43 PM
To: jassyong3344@hotmail.com
Subject: <STANDARD NOTIFICATION LETTER> OUR REF: CC4/ASM19011171/Kga3 ***
ACCIDENT INVOLVING SLR 8666P & SLA 2722P ON 23/06/2019 ***

17 JULY 2019

ONG THIAN LAI

Dear Sir/ Mdm

OUR REF : CC4/ASM19011171/Kga3

YOUR REF : SLR 8666P

ACCIDENT INVOLVING SLR 8666P AND SLA 2722P ALONG/AT JALAN LINGKARAN DALAM TWDS SINGAPORE ON 23/06/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **OPTIMA WERKZ PTE LTD** acting on behalf of the owner of SLA 2722P against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Re:RE: Re:RE: OI RPTED. Pls check if TP has video footage.

Type

 Question

Message

Hi, pls reject TP's claim, TY

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 13 August 2019 3:10 PM
To: Lily.loi@ow.sg
Cc: 'Sharon Ten'; angela.tan@ow.sg; hockkong.ong@ow.sg
Subject: RE: PRI - SLA2722P CLAIMING AGAINST SLR8666P DOA 23/06/19 (AXA) *** LKK REF: CC4/ASM19011171/ga3
Attachments: OI Video - Accident.MP4

Your Ref: **SLA 2722P** Without Prejudice
Our Ref: CC4/ASM19011171/Kga3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLR 8666P & SLA 2722P ON 23/06/2019

We refer to the above matter.

Attached is a copy of our insured car video footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Your client not only encroached into Our Insured lane and also collided onto Our Insured's stationary vehicle. Our Insured vehicle is not even moving(stationery) when collision happen.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 17 July 2019 11:36 AM
To: 'Lily.loi@ow.sg' <Lily.loi@ow.sg>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19011171/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 20-12-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 8666P	Veh. Inspected	SLA 2722P
Policy No.	VA1/GA480779	Coverage (\$)	0.00
Claim No.	S9M01RQD	Excess (\$)	0.00
Assign From		Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707013634	Colour	METALLIC DARK PINK
Odometer	45442	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	HANKOOK	6 mm
L/H Front Tyre	185/60 R15	HANKOOK	6 mm
R/H Rear Tyre	185/60 R15	TOYO	7 mm
L/H Rear Tyre	185/60 R15	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/06/2019	Inspection Date	25/06/2019
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2722P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-	-
			-	-
SPECIAL NETT ITEMS				
8	REAR BUMPER CLIPS @\$5.50 (SN)(CONSISTENT)	NOT NECESSARY	44.00	-
			44.00	-
LABOUR				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION REAR BUMPER & REAR FENDER RH .INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER RH .		200.00	100.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION REAR BUMPER & REAR FENDER RH .		500.00	400.00
			700.00	500.00
GRAND TOTAL			744.00	500.00
RECOMMENDED COST OF REPAIRS				500.00

Report Ref No. CC4/ASM19011171/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SFM01RQD

Reference

CC4/ASM19011171/Nga2a2

Loss Date

23 June 2019

Report Date

25 Jun 2019 9:24:30 AM

Request Date

25 June 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step: Wait for: Approve Invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SLA27229

Make

TBC

Model

UNKNOWN

Service Address

...

Primary Contact/Insured

ONG THIAN LAI
BLK 609 ANG MO KIO AVENUE 4, #06-1163,
560609, Singapore

Claim Handler

ANG Richard
richard.angbs@axa.com.sg

Additional Instructions

NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR



DATE
UPLOADED

Accident Statement

Reports & Statement

Miscellaneous

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 December 2019
rejection email to tp.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 December 2019
01 Video - Accident.MP4	Evidence	Videos	ANG Richard	21 July 2019
TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
EMAIL FROM WORKSHOP FOR TP REG.mpg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	25 June 2019
LETTER TO INSURED NON REPORTING.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
ACCIDENT SCENE 3.jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
ACCIDENT SCENE 4.jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
ACCIDENT SCENE 1.jpeg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
TP GIA REPORT.PDF	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Google Map.jpg	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TTP)	25 June 2019
 TP ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TTP)	25 June 2019
 ACCIDENT SCENE 2.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TTP)	25 June 2019
 P1992231_RN_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NIKAM Santosh Pandurang	25 June 2019
 P1992231_OI_00002_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NIKAM Santosh Pandurang	25 June 2019