

NATIONAL Assessment Centre Services

[wef 1 Jan 05] MNA119082637

Date In: 25/6/19 - 14:41	Job description	Date & Time Completed	Done by
Ref No: 16/12/19011/25/24	SAS e-filing		
Veh No: SMA 48144	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 25/6/19 - 09:05	i-Motor Claim Form	M/1050485-001	25/6/19 15:25
☒ TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: () Tel: () Fax: ()

TP Particulars:	Veh No: J2221393	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: () %	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

HA150810 Claimant's Particulars:- Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge): Auditors' Comments:- Sat 1: Sat 2/3:	Invoice Preparation Checklist		Amt (\$)	Amt (\$)
	Inc Bill	Add Bill		
	1) AR: Accident Reporting (\$30);			
	2) DA: Damage Assessment (\$100); INC (\$80)			
	3) TF: Towing Fee \$40/\$45			
	4) FT: Follow-Through Survey \$120			
	5) FT: Follow-Through Survey (Resurvey) \$30			
	For claiming against INC Only (wef 10 Jan 2005)			
	6) TR: Re-inspection \$75			
	7) N1: Idac DA + SMRT Survey \$160			
8) NTUC Additional Services:-				
QD*				
*N5: Courtesy Car / Tpl Allowance	\$5			
*N6: Repair Co-ordination	\$10			
*N7: Post Repair Inspection	\$25			
*N8: DV / Collect Excess Coordination	\$5			
TF (N11): TP (N-in INC) against INC	\$20			
9) N12: Idac Mobile	\$0			
Invoice dated	Fee Charged			
Invoice dated	Fee Charged			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2019 14:41
Date Of Accident	25/06/2019 09:05
Exact Location Of Accident	ONE NORTH LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA4814H
Insured/Policyholder	
Name Of Registered Owner	FAST RENTAL CAR PTE LTD
Co Reg No	201617492M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID 1.5 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101258436-01
Cover Note Number	

Driver

Name of Driver	WONG MEI YUEN
NRIC No	S7540681I
Date Of Birth	26/03/1975
Occupation	OUTDOOR
Date Of Driving Pass	16/08/2005
Driving Experience	13 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93882485
Fax Number	
Contact Number	OFFICE-93882485
Email Address	NOEMAIL

Address	BLK 165 GANGSA ROAD #10-74
Postcode	670165
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190625/2051.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ2139S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	WONG MEI YUEN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SMA4814H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DOA: 25/6/14

A: SMA 48/4H

B: SLZ 21395



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Personal Particulars

Date of Accident: 25/6/19 Time of Accident: 9.03 am
Exact Location of Accident: One north link
Owner's Name: Fast Rental Car Pte Ltd NRIC No: _____ HP No: _____
Driver's Name: Heatherjen Wong Mei Yuen NRIC No: 57540681 HP No: 93882485
Date of Birth: 26/3/1975 Driving Licence Passing Date: 16/8/2005 Occupation: Indoor / Outdoor
Address: 165 Gongsa Rd #10-74 (670165)
Relationship of Driver with Insured: Wife Email Address: _____
Vehicle No: SMA 4814H Make & Model: Honda ~~Shuttle~~ Shuttle
Insurance Co: N TUC Coverage: Comprehensive Policy No: _____

*Purpose of Reporting? ☒ Own Damage Claim / 3rd Party Claim / Not Claiming, Just Reporting Only

*Exact Purpose of The Vehicle Was Being Used At Time Of Accident: Private Use / ☒ Work

*Weather Condition ? ☒ Clear / Raining / Others: _____ Wet / ☒ Dry / Others: _____

*Any passenger inside vehicle involved? (Yes / No) If yes, Vehicle No & How many pax:

A: 1 + 1 B: _____ C: _____ D: _____
Woman

*Was Anybody Injured ? (Yes / No) If yes,

Name / NRIC / In Vehicle: Driver only

*Was The Accident Reported To The Police ?

☐ No ☒ Yes, Which Police Station? _____

*Does the Driver Own Any Other Vehicle?

☐ No ☐ Yes, Vehicle Registration No: _____ Insurer: _____

*Was any foreign vehicle involved? (Yes / ☒ No) If yes, Vehicle No & Category: _____

*Was there any video captured by Car Camera? (Yes / ☒ No)

Third Party Driver's Particulars

Vehicle B No: SL2 21398 Make & Model: _____
Driver's Name: _____ NRIC No: _____ HP No: _____
Vehicle C No: _____ Make & Model: _____
Driver's Name: _____ NRIC No: _____ HP No: _____

Witness Particulars

Name: _____ NRIC No: _____ HP No: _____



**SINGAPORE
POLICE FORCE**



T/20190625/2051

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 3

Report No. T/20190625/2051

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/06/2019 13:31	Vide Report No.: D/20190625/0039	Station Diary No.: 78
--	-------------------------------------	--------------------------

Informant's Particulars

Informant's particulars

Name of Informant: HEATHERJEN WONG MEI YUEN			Address: APT BLK 165 GANGSA ROAD #10-74 SINGAPORE 670165	
ID Type / ID No.: NRIC NO / S75406811			Contact No.: Home/Office: Mobile: 93882485	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 44	Date of Birth: 26/03/1975	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: GOJEK DRIVER			Driving Licence Information: Class: 3A	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/06/2019 09:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BIOPOLIS ROAD ONE-NORTH LINK CROSS JUNCTION BETWEEN ONE NORTH LINK AND BIOPOLIS ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLZ2139S	Car	TOYOTA	WISH	Grey	Seriously Damaged	0
SMA4814H	Car	HONDA	SHUTTLE	White	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190625/2051

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

CONTINUATION OF REPORT

Report No. T/20190625/2051

2 of 3

Driver			
Name	HEATHERJEN WONG MEI YUEN	ID No.	S75406811
Related Vehicle	SMA4814H (Car)	Contact No.	93882485
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.


On 25/6/19 at about 0900hrs, I am working as a GOJEK driver driving car (SMA4814H), driving my 1 passenger along Biopolis Road. While driving along that road, I had noticed that the road is a two way lane, and the road of my direction was all parked with big construction lorries. Hence, after ensuring that the traffic was clear, I overtake these lorries and approached the Cross Junction of Biopolis Road and One North Link. However, while I am crossing the junction at a very slow speed after ensuring the traffic was clear, suddenly a car (SLZ2139S) came at a high speed and hit onto the left side of my car.

Traffic police and ambulance attended to this accident vide Dr/20190625/0039. The male driver was subsequently conveyed to the hospital by the ambulance. No government property was damaged. I also noticed at his front portion of his car was badly damaged, with both the front airbag being deployed. I also noticed my left portion of my car was also badly damaged. Both cars were towed away afterwards. My car doesn't have an in car camera. I had also asked my passenger and she informed that she wasn't injured.

I wish to state that my kneecap was suffering pain right now, and I will be seeking medical attention after this report.



**SINGAPORE
POLICE FORCE**



T/20190625/2051

3 of 3

Report No. T/20190625/2051

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

E /

Sgt 2 LIN XUETONG, TOM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

25/06/2019 13:31

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt RAZIZ BIN HARAB


Contact No.: 65476200

Classification Of Case:

SN 168

Authentication Stamp

NP168



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7540681I**
Name: **WONG MEI YUEN**

Birth Date: 26 Mar 1975
Issue Date: 16 Aug 2005

001362367C

For LKK/NAC Use Only

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7540681I**

Name: **HEATHERJEN WONG MEI YUEN**
王美云

Race: **CHINESE**
Date of birth: **26-03-1975** Sex: **F**
Country of birth: **SINGAPORE**

4894394

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3A Motor cars without clutch pedals =< 3000kg with =< 7 passengers, exclusive of the driver, and motor tractors/vehicles without clutch pedals =< 2500 kg

PASS DATE: 16 Aug 2005

NP 428A

Licence No: S7540681I

For LKK/NAC Use Only

4894394

HRIC No: **S7540681I**

Date of issue: 25-09-2012

Address: **APT BLK 165 GANGSA ROAD
#10-74
SINGAPORE 670165**

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.		Date of Accident	25/06/2019 09:05
Vehicle No. (For Motor)	SMA4814H	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5101258436-01		FAST RENTAL CAR PTE LTD	201617492M	GPC	drivo CLASSIC	SMA4814H	SMA4814H	08/06/2019	07/06/2020

 Policy Information

Policy No.	5101258436-01	Policyholder Name	FAST RENTAL CAR PTE LTD	Policyholder NRIC	201617492M
Certificate No.					
Address	BLK 161 #03-148 BISHAN STREET 13 BISHAN CRESTA SINGAPORE 570161				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy Issue Date	21/05/2019	Effective Date	08/06/2019 00:00	Expiry Date	07/06/2020 23:59
Excess Type	Per Accident	All Claims Excess			
Third Party Excess	1500	Own damage Excess	2000	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	2000	Outside Singapore TP Excess	1500	Young/Inexperience Driver Excess	
Agent	SININS AGENCY PTE. LTD.	Agent Tel.	69503050	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	BLK 161 #03-148	Address 2	BISHAN STREET 13	Address 3	BISHAN CRESTA
Address 4	SINGAPORE 570161	Address Type	Singapore address	Post Code	570161
Unit No.	03-148	Related Policy Number	5101111205-01		

 Insured Object: SMA4814H

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
----------	---------------------	------------------	--------------------	---------------------

Continue

Cancel

Claim Handling

Accident MT/1050485

Exit

Policy No.	5101258436-01	Vehicle No.	SMA4814H	GST Registration No.	
Certificate No.					
Policyholder Name	FAST RENTAL CAR PTE LTD	Cover Type	drive CLASSIC	Policyholder NRIC	201617492H
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)	0	Loading	0
Contact No.(Mobile)	0	Special Remark		Contact No.(Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KFK	☒ No ☐ Yes	NCD Entitlement(%)	10	eCode Reason	
NCD Protection	No			Private Hire	Yes
Accident Details					
Report Date	25/06/2019 14:59	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major Minor Road
Date of Accident	25/06/2019	Time of Accident hh:mm	09:05	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	ONE NORTH LINK				
Total Excess Applicable					
Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	2,000.00	TP Standard Excess	1,500.00		
YIED OD Excess	500.00	YIED TP Excess		Driver is Covered?	
Additional Excess	0				
Total OD Excess Applicable	2500.00	Total TP Excess Applicable			

Benefits	
GST Registered Information	
GST Registered	No
GST Registration No.	
Modification History	25/06/2019 15:00:51 System changed GST Status Verified from No to Yes
GST Registration Date	
GST Status Verified	Yes

Policyholder Mailing Address	
Address 1	BLK 161 #03-148
Address 4	SINGAPORE 570161
Unit No.	03-148
Address 2	BISHAN STREET 13
Address Type	Singapore address
Related Policy Number	5101111205-01
Address 3	BISHAN CRESTA
Post Code	570161

OT Driver Info	
Driver Name	Unnamed Driver
Unnamed driver Name	WONG MEI YUEN
Register Date of Driver License	16/08/2005
Contact No.(Mobile)	93882485
Address 1	BLK 165
Address 4	
Unit No.	10-74
Does he own a Singapore Registered car?	☐ Yes ☒ No
Driver Type	Unnamed Driver
Driver NRIC	S75406811
Driver Age	44
Contact No.(Office)	0
Address 2	GANGSA ROAD
Address Type	Singapore address
Driver DOB	26/03/1975
Driving Experience	13
Contact No.(Home)	0
Address 3	SINGAPORE 670165
Post Code	670165
Driver Insurer Company	

Declaration	
Breathalyser or Blood Test Reading?	0 mg
Any injury?	☒ Yes ☐ No

Modification History

Claim 001 New

Claim Type *	OD-MD	Insured Name	FAST RENTAL CAR PTE LTD	Insured NRIC	201617492H
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	NIL
Email Address		OT Vehicle Number	SMA4814H	TP Vehicle Number	SL221395
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRIC *			
Claimant Address					
Claim Description	SMA4814H / SL221395 ON 25 Jun 2019				
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault	Name of Preferred Workshop	
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	25/06/2019 15:05	Claim Close Date		Date Received	25/06/2019 00:00
Report Taken By	Jackson				
☒ Print AK letter				OD Excess Collected by Workshop	

Attachment

Accident No.	MT/1050485	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	25/06/2019 15:06
Path * Browse... Clear Please Select			
Category *	Confidential	Urgency *	Normal
Description *			

	Browse...	Clear	Please Select	NO	Normal	
	Browse...	Clear	Please Select	NO	Normal	
	Browse...	Clear	Please Select	NO	Normal	
	Browse...	Clear	Please Select	NO	Normal	
	Browse...	Clear	Please Select	NO	Normal	

☐ Send Message

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	SAS	Normal	SAS 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:06	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICE) on 25 Jun 2019 15:05	Photos	Normal	Photos 2019-6-25		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
		Display in New Window	Scan and uploading	

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle: () 2) Vehicle hit ?? ()
- a) Motor car () a) Pedestrian ()
- b) Motorcycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn Property () b) Road Work Object ()
(E.g. signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, ()
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
when recovered
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: **SMA 4814 H** Yr Regn: **8 Jun 2018**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Trailer or

Make & Model: **Honda Shuttle Hybrid 15** cc **1496**

Colour: **White** Transmission Type: Auto Manual

Eng/No: Sp. Reading: **71980**

C/No: **GP7 1208626**

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: In order Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **185/60R15**

R: **V**

- **Falken**
- **Yoko**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **As above**

Front

R/Bal. **4** mm

L/Bal. **4** mm

Rear

R/Bal. **6** mm

L/Bal. **6** mm

Parallel Import: Yes / No

Towed-In: Yes / No

Repair Type: LS / LB.I

Towing Required: Yes / No

No. of Repair Days: **7**

Vehicle in Idac: Yes / No

D.O.I. **26/6/2019**

Time: **10.05am**

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (Frt)

ACT0811AC

(1)Replace (✓) (2)Repair (G) (3)Check (7)

(4)For Confirmation (FIC)

1003

1782

Front Portion

Vehicle No:

SMA 48144

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		
1005	992341	Frt Bumper Clips	KEC		6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS		2
1008	991433	Frt Bumper Reinforcement	DD		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	CUT		
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CUT		
1022	991328	Frt Grille Emblem	NEC		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	R	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD	R	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	BT	2	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air-Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	DD	R	
1097	995072	Frt LH Fender Inner Panel	BT	R	
1098	995147	Frt LH Fender Emblem	NEC		
1099	995148	Frt LH Fender Triangle Glass			
1100	991740	Frt LH Fender Inner Shield	CRA		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	DD	R	
1103	994025	Frt LH Rim Cover	CUT		
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	DD	R	
1106	991739	Frt RH Fender Emblem	NEC		
1107	991744	Frt RH Fender			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

Frt LH Door -
LH side skirting.

SCRIP

No of Items:

Accessories:

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (7)
(4) Not Consistent (NC)

Aug 2005

2 of 2

Undercarriage

Vehicle No: **SMA4814H**

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber	BT	✓	
1373	991944	Frt LH Shock Absorber Mounting		✓	
1374	990632	Frt LH Coil Spring		✓	
1375	995198	Frt LH Knuckle Arm	DIS	✓	
1376	995199	Frt LH Knuckle Arm Bearing	NEC	✓	
1377	995178	Frt LH Lower Arm	BT	✓	
1378	995169	Frt LH Upper Arm		✓	
1379	995183	Frt LH Tie Rod		✓	
1380	995143	Frt LH Drive Shaft		✓	
1381	990661	Frt LH Control Arm		✓	
1382	992062	Frt LH Trailing Arm		✓	
1383	991848	Frt LH Leaf Spring		✓	
1384	991293	Frt LH Brake Disc Rotor		✓	
1385	991281	Frt LH Brake Caliper		✓	
1386	991292	Frt LH Brake Pipe		✓	
1387	991287	Frt LH Brake Hose		✓	
1388	991295	Frt LH Brake Sensor Wire		✓	
1389	991989	Frt Stay Bar Bracket		✓	
1390	994455	Steering Rack & Pinion		✓	
1391	994435	Steering Cross Member		✓	
1392	994519	Frt Sub Frame		✓	
1393	992003	Frt Sub Frame Mounting		✓	
1394	991217	Frt Anti Roll Bar		✓	
1395	991219	Frt Anti Roll Bar Linkage LH		✓	
1396	990887	Engine Block		✓	
1397	990890	Engine Block Gasket		✓	
1398	990972	Engine Oil Sump		✓	
1399	990960	Engine Oil		✓	
1400	992224	Gear Box Assy		✓	
1401	992229	Gear Box Gasket		✓	
1402	992241	Gear Box Oil Sump		✓	
1403	992257	Gear Oil		✓	
1210	990534	Centre Exhaust Pipe Assy		✓	
1211	990532	Centre Exhaust Mounting		✓	
1404	991134	Floor Panel		✓	
1405	993719	Rear LH Shock Absorber		✓	
1406	993723	Rear LH Shock Absorber Mounting		✓	
1407	993170	Rear LH Coil Spring		✓	
1408	993550	Rear LH Knuckle Arm		✓	
1409	993551	Rear LH Knuckle Arm Bearing		✓	
1410	993597	Rear LH Lower Arm		✓	
1411	993884	Rear LH Upper Arm		✓	
1412	995161	Rear LH Drive Shaft		✓	
1413	995216	Rear LH Control Arm		✓	
1414	993881	Rear LH Trailing Arm		✓	
1415	993573	Rear LH Leaf Spring		✓	
1416	992941	Rear LH Brake Disc Rotor		✓	
1417	992937	Rear LH Brake Caliper Assy		✓	
1418	990434	Rear LH Brake Pipe		✓	
1419	992946	Rear LH Brake Hose		✓	
1420	993819	Rear Sub Frame		✓	
1421	993820	Rear Sub Frame Mounting		✓	
1422	992813	Rear Anti Roll Bar		✓	
1423	990168	Rear Anti Roll Bar Linkage		✓	
1424	990202	Axle Beam		✓	
1425	990170	Rear Axle Panhard Rod		✓	
1426	990810	Differential Assy		✓	
1427	992706	Propeller Shaft		✓	

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber		✓	
1429	991944	Frt RH Shock Absorber Mounting		✓	
1430	990632	Frt RH Coil Spring		✓	
1431	991844	Frt RH Knuckle Arm		✓	
1432	991845	Frt RH Knuckle Arm Bearing		✓	
1433	991851	Frt RH Lower Arm		✓	
1434	992064	Frt RH Upper Arm		✓	
1435	992040	Frt RH Tie Rod		✓	
1436	991692	Frt RH Drive Shaft		✓	
1437	990661	Frt RH Control Arm		✓	
1438	992062	Frt RH Trailing Arm		✓	
1439	991848	Frt RH Leaf Spring		✓	
1440	991293	Frt RH Brake Disc Rotor		✓	
1441	991281	Frt RH Brake Caliper		✓	
1442	991292	Frt RH Brake Pipe		✓	
1443	991287	Frt RH Brake Hose		✓	
1444	991295	Frt RH Brake Sensor Wire		✓	
1445	993720	Rear RH Shock Absorber		✓	
1446	993723	Rear RH Shock Absorber Mounting		✓	
1447	993173	Rear RH Coil Spring		✓	
1448	993550	Rear RH Knuckle Arm		✓	
1449	993551	Rear RH Knuckle Arm Bearing		✓	
1450	993601	Rear RH Lower Arm		✓	
1451	993885	Rear RH Upper Arm		✓	
1452	993322	Rear RH Drive Shaft		✓	
1453	993178	Rear RH Control Arm		✓	
1454	995117	Rear RH Trailing Arm		✓	
1455	995110	Rear RH Leaf Spring		✓	
1456	992942	Rear RH Brake Disc Rotor		✓	
1457	992938	Rear RH Brake Caliper Assy		✓	
1458	990434	Rear RH Brake Pipe		✓	
1459	992947	Rear RH Brake Hose		✓	

No of Items: _____ Assessor: _____

Original copy

Claim Handling

Task Transfer Exit

LOG SAVE SUB

Accident MT/1050485

Policy No.	5101258436-01	Vehicle No.	SMA4814H	GST Registration No.	
Certificate No.					
Policyholder Name	FAST RENTAL CAR PTE LTD	Cover Type	drive CLASSIC	Policyholder NRIC	201617492M
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)	0	Loading	0
Contact No.(Mobile)	0	Special Remark		Contact No.(Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KFK	☒ No ☐ Yes	NCD Entitlement(%)	10	eCode Reason	
NCD Protection	No			Private Hire	Yes

Accident Details

Report Date	25/06/2019 14:59	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major Minor Road
Date of Accident	25/06/2019	Time of Accident hh:mm	09:05	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	SCM No.	
Accident Location	ONE NORTH LINK				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess		TP Standard Excess	1,300.00		
YIED OD Excess		YIED TP Excess		Driver is Covered?	
Additional Excess					
Total OD Excess Applicable		Total TP Excess Applicable			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	25/06/2019 15:00:\$1 System changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	BLK 161 #03-148	Address 2	BISHAN STREET 13	Address 3	BISHAN CRESTA
Address 4	SINGAPORE 570161	Address Type	Singapore address	Post Code	570161
Unit No.	03-148	Related Policy Number	510111205-01		

OT Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	WONG MEI YUEN	Driver NRIC	S75406811	Driver DOB	26/03/1975
Register Date of Driver License	16/08/2005	Driver Age	44	Driving Experience	13
Contact No.(Mobile)	93682485	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 165	Address 2	GANGSA ROAD	Address 3	SINGAPORE 670165
Address 4		Address Type	Singapore address	Post Code	670165
Unit No.	10-74				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Zaramee Bin Mantau

LOG SAVE SUB

Claim Type	OD-MD	Insured Name	FAST RENTAL CAR PTE LTD	Insured NRIC	201617492M
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	NIL
Email Address		OT Vehicle Number	SMA4814H	TP Vehicle Number	5L221395
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	SMA4814H / 5L221395 ON 25 Jun 2019				Name of Preferred Workshop
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	25/06/2019 15:07	Claim Close Date		Date Received	25/06/2019 00:00
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make:	HONDA	Vehicle Model:	SHUTTLE	Engine Capacity:	
Date of Registration:	06/06/2018	Class No.:	GP71208626	Parallel Import:	☒ Yes ☐ No
Towing Required:	☒ Yes ☐ No	Vehicle in IDAC:	☒ Yes ☐ No	Survey Current Status:	
Type of Tender:	Own Damage	Assessor Name:	SIMON		
IDAC/Workshop Name:	NATIONAL ASSESSMENT CENTRE	IDAC/Workshop Location:	31 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost:		Total Loss:	☐ Yes ☒ No		
Market Value(\$):		Scrap Value(\$):		Economical Repair Value(\$):	

REMARK: NO OF REPAIR DAY: 7 DAYS. 1 X FRT GRILLE CHROME MOULDING - UNCONFIRM. 1 X FRT SUPPORT PANEL TOP GARNISH COVER - UNCONFIRM. 1 X FRT LH FENDER EMBLEM - REPLACE. 1 X FRT LH FENDER TRIANGLE GLASS - UNCONFIRM. 1 X FRT LH RIM COVER - REPLACE. 1 X FRT RH FENDER EMBLEM - REPLACE. 1 X LH SIDE SKIRTING - UNCONFIRM. 1 X FRT LH TIE ROD - UNCONFIRM. 1 X FRT LH ANTI ROLL BAR LINKAGE - UNCONFIRM.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	16000101	BUMPER (FRONT)	1	Replace	X
ABS	2	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ABSORBER	3	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
ACCELERATOR	4	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
ACTUATOR	5	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
ADVERTISEMENT STICKER	6	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm	X
AIR BAG	7	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR BLOWER	8	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace	X
AIR BOX	9	27100101	GRILLE (FRONT)	1	Replace	X
AIR CHAMBER BOX	10	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR CLEANER	11	41300101	SUPPORT PANEL (FRONT)	1	Repair	X
AIR COMPRESSOR	12	27700101	HEAD LAMP (LEFT)	1	Replace	X
AIR CON	13	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	X
AIR CON (VAN)	14	149001	BONNET	1	Repair	X
AIR COOLER	15	14902201	BONNET HINGE (LEFT)	1	Replace	X
AIR DISTRIBUTOR	16	14902202	BONNET HINGE (RIGHT)	1	Replace	X
AIR FILTER	17	112023	AIR CON CONDENSER	1	Unconfirm	X
AIR FLOW	18	344001	RADIATOR	1	Unconfirm	X
AIR GRILLE	19	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Replace	X
AIR HORN	20	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	X
AIR INTAKE	21	30000101	KNUCKLE ARM (FRONT LEFT)	1	Replace	X
AIR RESONATOR BOX	22	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Replace	X
AIR THROTTLE BODY AND SENSOR	23	30500101	LOWER ARM (FRONT LEFT)	1	Replace	X
ALARM	24	23600101	DRIVE SHAFT (FRONT LEFT)	1	Unconfirm	X
ALTERNATOR	25	401028	STEERING RACK & PINION	1	Unconfirm	X
ALUMINIUM PANEL - SIDE	26	401021	STEERING CROSS MEMBER	1	Unconfirm	X
AMPLIFIER	27	12800101	ANTI ROLL BAR (FRONT)	1	Unconfirm	X
ANTENNA	28	25400102	FENDER (FRONT LEFT)	1	Replace	X
ANTI ROLL	29	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair	X
APRON	30	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
ARCH	31	446014	WHEEL RIM	1	Replace	X
ARM REST	32	43600101	TYRE (FRONT LEFT)	1	Unconfirm	X
ASH TRAY	33	25400103	FENDER (FRONT RIGHT)	1	Repair	X
AUTO CLUTCH	34	454009	WIPER PANEL GARNISH	1	Unconfirm	X
AUTO COOLER PIPE	35	23300201	DOOR (FRONT LEFT)	1	Repair	X
AUTO CRUISE MOTOR						
AUTO TRANSMISSION						
AXLE						
BACK REST (MC)						
BACK SEAT						
BALANCER						
BATTERY						
BEADING (MC)						
BELT COVER (MC)						
BELT TENSIONER						
BODY						
BODY (MC)						
BOLT CAP (MC)						
BOLT HEAD COVER (MC)						
BONNET						
BOOT						
BOX (MC)						

Save Submit

LKK Paya Ubi

From: Zuraimee Bin Mantau <zuraimee.mantau@income.com.sg>
Sent: Friday, 28 June 2019 9:38 AM
To: Hock Wah
Cc: LKK Paya Ubi
Subject: Vehicle SMA4814H, OD Claim No: MT/1050485-001, DOA: 25/06/2019

Dear Hock Wah Motor

OD Excess \$2000/- applies.

Vehicle is currently at NAC Paya Ubi.

Please arrange to tow away and update vehicle's rep, Mr Ken at 81230603 on the repair status.

Strictly no further supplementary is allowed. **Survey before repair** required.

Please forward the invoice and DV within 7 working days to us once repairs has been done and survey conducted. Update the 'Repair Status' when repairs are done.

XX

Our Ref: MT/CA/OD/051/1050485-001/ZBM

28 Jun 2019

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12

BEDOK INDUSTRIAL PARK E

SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1050485-001

REPAIR OF VEHICLE NUMBER: SMA4814H

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 28 Jun 2019

Make: HONDA

Model: SHUTTLE

Estimated Repair Days: 6

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 2000.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimee Bin Mantau at 64307891 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank you

Zuraimee Bin Mantau
Senior Executive
Motor Insurance
T +65 6430 7891
www.income.com.sg

 **income**
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: 5MA4814H Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Hock Wah

Collection Date: 28/06/19 Time: 1230 with Keys: Yes / No

Tow Truck No: YP7951D Tow Man: Faher NRIC: S810C925/2

Signature: _____

For office use

Attended by: ROSLINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____