

ASS. REC. BY:

REF: CS/MSG19011177/K19d3n2 Special Instruction:

Singer: Kalvin

## ASSIGNMENT (Office)

From (Person):

Crystal Lee

of

MSIADate/Time: 25/6/19 @ 9:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 8056B

Insured:

YN 403IP

at Workshop in/s

Comfort Delgro

Tel:

of

59 Layney Drive

Policy No:

MSD/VCC/19-100310-00

Claim No:

MSC/V/19-000714

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:41am @ 25/6/19

Person Contacted:

JimmyVehicle IN/OUT

Date/Time

Action/Instruction

VoluntaryYN 403IP: CS/SMO17017125/Krbn2 D.O.A: 27/08/2017SHC8056B: CS/INC09020711/Kn D.O.A: 09/09/200926/6/19 @10:34am revised to Crystal Lee via Weimann.

108/11/13

Surveyor: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 805 6B Yr Regn: 28 May 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/C / Prime Mover /

Truck / Trailer or

Make: Maruti Suzuki C.C. 2143Colour: White A/C: Insured / Std / NI / NASp. Reading: 58061x T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: LDJ21200128/69977Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Not Jammed / Leaked / Burnt orBrake: Inorder / Not Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD Wheel orTyre Size: F: 225/55 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wetake

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 2/6/19 D.O.I. 25/6/19Survey held at CPGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S wing mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/6/19 Insured 45 \$ 900 / 1 Pk. (Red & 444.64, 33.6) MSZ

RECEIVED 04 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report1) 04/7 2019 ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 1Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : \_\_\_\_\_

Photos

\_\_\_\_\_

150

11

161

Report Format:

mer-p900

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 26 Jun 2019

**Preliminary Advice**

Insured Vehicle No	: YN4031P	Accident Date	: 21/06/2019
TP Vehicle No	: SHC8056B	Assignment Date	: 25/06/2019
Make	: MERCEDES-BENZ E220 BLUETEC	Est. Duration of Repair	: 1.00
Date of Inspection	: 25/06/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s wing mirror and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,344.64
Revised Amount	:S\$	1,154.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,154.64

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Tuesday, 25 June 2019 9:10 AM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 25062019090619.pdf

### Pre Repair Survey for SHC8056B (Your Ref: YN4031P)

#### Manual Assigned

Dear LKK,

Refer to the attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

**Crystal Lee**

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

RE: Accident involving SHC8056B and your insured YN4031P (MSIG)  
dated 21.06.19 / \*\*\*\*Pending for surveyor\*\*\*\*

Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>

Tue 25/6/2019 9:58 AM

To Lim Tien Siong <limts@cdge.com.sg>;

Cc Jowyn Tay <jowyn\_tay@sg.msig-asia.com>; Roger How Keen Meng <rogerhow@cdge.com.sg>;

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

Hi Tien Song,

We have outsource the case to LKK Auto Consultants to attend to the survey.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Lim Tien Siong [mailto:limts@cdge.com.sg]

**Sent:** Tuesday, 25 June, 2019 9:27 AM

**To:** Nabilah Rasol <nabilah\_rasol@sg.msig-asia.com>

**Cc:** Jowyn Tay <jowyn\_tay@sg.msig-asia.com>; Roger How Keen Meng <rogerhow@cdge.com.sg>

**Subject:** Re: Accident involving SHC8056B and your insured YN4031P (MSIG) dated 21.06.19 / \*\*\*\*Pending for surveyor\*\*\*\*

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Hi Nabilah,

Fyi - 48 hrs approaching soon today at 12:41 hrs (based on my first below email requests dd 21/6)

I continue to wait for your in-house surveyor ?

Please advise.

Best Regards,

Lim Tien Siong

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156

---

**From:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Sent:** Tuesday, 25 June 2019 8:44 AM

**To:** Lim Tien Siong

**Cc:** Jowyn Tay

**Subject:** RE: Accident involving SHC8056B and your insured YN4031P (MSIG) dated 21.06.19

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

---

Hi Tien Siong,

We refer to your email dated 24/06/2019.

We will proceed to assign MSIG In-house surveyor via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Lim Tien Siong [<mailto:limts@cdge.com.sg>]

**Sent:** Monday, 24 June, 2019 3:37 PM

**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>

**Subject:** Fw: Accident involving SHC8056B and your insured YN4031P dated 21.06.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Officer in charge,

A gentle reminder.

Thanks.

Best Regards,  
Lim Tien Siong  
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd  
Off:62148398 / Fax:65468156

---

**From:** Lim Tien Siong  
**Sent:** Friday, 21 June 2019 12:41 PM  
**To:** [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)  
**Subject:** Accident involving SHC8056B and your insured YN4031P dated 21.06.19

Officer in charge,

Best Regards,  
Lim Tien Siong  
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd  
Off:62148398 / Fax:65468156

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/06/2019 11:40
Date Of Accident	21/06/2019 09:30
Exact Location Of Accident	383 SIN MING DR ( CDGE SIN MING WORKSHOP )
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8056B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	190303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TENG KOK YUEN
NRIC No	S1264850B
Date Of Birth	20/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	11/06/1979
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87234525
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	BLK 388 YISHUN RING ROAD #04-1671
Postcode	760388
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4031P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LIN YUANFEI
NRIC/Passport Number	G7758066U
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	LEFT REAR
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name: **Loke Wei Yieng**  
NRIC/FIN No.:

## SKETCH PLAN

CDGE Sin Ming  
Workshop

A: SHC 8056 B

B: YN 4031P



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/6/19 at about 09:30 hrs, my taxi

veh A was parked at above said location.

Shortly veh B it left rear portion hit onto

the right wing mirror of my taxi.

No person in my taxi. No injury reported in this

accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821RPolicyholder's Signature  
Date & Time:Driver's Signature  
(If driver is not the policyholder)  
Date & Time:Reporting Centre Personnel's Signature  
Name: **Loke Wei Yieng**  
NRIC/FIN No.:

COMFORTDELGRO  
ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

211 Serangoon Road, Singapore 550211  
Mainline + 65 6342 0322 Faxline + 65 6342 9718  
Workshops:  
23 Loyang Drive, Singapore 505069 24 Serangoon Road, Singapore 554138  
383 Sin Ming Drive, Singapore 575717 7 Gulubeh Road, Singapore 738751  
45 Pandan Road, Singapore 609236 901 Yishun Industrial Park A, Singapore 768732  
220 Ubi Road 2, Singapore 408602


Date/Time: 21.06.2019 12:22 Page : 1

Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO: 305305330
CUSTOMER	COMFORT TRANSPORTATION PTE LTD		REGN NO:	SHC8056B
CUSTOMER NO:	7010045		MAKE :	MERCEDES BENZ
ADDRESS	383 SIN MING DRIVE		MODEL	E220CDI (E6)
	Singapore SINGAPORE 575717		DATE/TIME IN	21.06.2019 10:45
L (R)	65508755	(C)	YR OF MANU.	28.05.2015
(P)			TARGET DATE	
COUNT CARD NO:			CHASSIS CODE	WDD2120012B169977
			COMPLETION DATE/TIME	

JOB DESCRIPTION

Accident Date: 21.06.2019  
NATURE: 3P 21.06.19

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED-OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC8056B                      LIMITS

Vehicle No.: SHC8056B

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

COMFORTDELGRO ENGINEERING PTE LTD

Date: 21.06.2019

Time: 12:36:57

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305305330  
 REGN NO : SHC8056B  
 MILEAGE : 0000000000  
 MAKE : MERCEDES BENZ  
 MODEL : E220CDI(E6)  
 DATE OF REGN : 28.05.2015  
 DATE/TIME IN : 21.06.2019 10:45  
 ACCIDENT DATE : 21.06.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0202-2058-G	W/MIRROR COVER RH	1	69.50 20.00 55.60
0002	04-01-0202-2100-G	W/MIRROR GLASS RH	1	239.90 20.00 191.92
0003	04-01-0202-0898-G	W/MIRROR HOUSING RH	1	385.90 20.00 308.72
0004	04-01-0202-2099-G	W/MIRROR MOTOR RH	1	560.50 20.00 448.40

SUB-TOTAL : 1,004.64

## JOB NATURE

0000 PB	PANEL BEATING	150.00
0001 SP	SPRAYPAINT CHARGE	150.00
0002 17-01	WIRING CHECK	40.00

SUB-TOTAL : 340.00

MVA NAME & SIGNATURE  
 DATE :

SURVEYOR NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO

TOTAL : 1,344.64

For claimants hence notify  
 the following:  
 • To a party during resurvey  
 • No illegal modification  
 • Supplementary items  
 subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date:

16/6/19  
 25/6/19  
 1050h  
 1 Py  
 L/S  
 Ask Rep photo

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305305330  
Date : 26/06/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax :  
Attn : KALVIN ANG  
Vehicle Reg No. : SHC8056B Date of Accident : 21-Jun-19


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- The repair job shall bill to: MSIG --- YN4031P
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges

**Total for Part-By-Part Repair Cost**

  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$900.00  
**Final Lumpsum Repair cost \$900.00**
- Estimated normal period for repairs: 1 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 27/6/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011177/K1QD3N2

Date: 10/07/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/19-000310-00
Claimant Vehicle No :	SHC8056B	Insured Vehicle No :	YN4031P
Date of Loss:	21/06/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000714

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC8056B	Engine No:	65192432750478
Make & Model:	MERCEDES-BENZ E220 BLUETEC, 2.1 D (A)	Chassis No:	WDD2120012B169977
Reg. Date:	28/05/2015 (Man. Year: 2015)	Odometer:	580614 km
Colour:	White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,004.64	1,004.64	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	340.00	150.00	190.00	55.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,344.64</b>	<b>1,154.64</b>	<b>190.00</b>	<b>14.13</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>900.00</b>		
<b>(\$\$)</b>	1,344.64	900.00	444.64	33.07
<b>+ GST 7.00/7.00% (\$\$)</b>	94.12	63.00	31.12	33.06
<b>Nett Amount (\$\$)</b>	<b>1,438.76</b>	<b>963.00</b>	<b>475.76</b>	<b>33.07</b>

## INSPECTION

Date of Assignment:	25/06/2019	
Date Inspected:	25/06/2019	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 1.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
<b>Parts:</b>	143	MERCEDES-BENZ E220 BLUETEC 2.1 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC8056B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*W/MIRROR COVER RH	Missing	69.50 FL	*69.50 FL
2	1		*W/MIRROR GLASS RH	Cracked	239.90 FL	*239.90 FL
3	1		*W/MIRROR HOUSING RH	Cracked	385.90 FL	*385.90 FL
4	1		*W/MIRROR MOTOR RH	Cracked	560.50 FL	*560.50 FL
					<b>Sub Total (\$\$)</b>	<b>1,255.80</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>251.16</b>
					<b>Total Parts (\$\$)</b>	<b>1,004.64</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	150.00	100.00
2	SPRAYPAINT CHARGE	New	150.00	50.00
3	WIRING CHECK	New	40.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>340.00</b>	<b>150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >