

INS. CASE OWNER

CC 4, MG 190 11194, K/da3%

LKK:  
IDAC:

Surveyor:

AME RAM

DOI:

ASSIGNMENT

26/6/2019

Date / Time:

26/6/19

Registered in Merimen:

28/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMH 9259R

Claim No.:

Name of Insured:

Mansoor S/O Tayabulhai Gandhi

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II:SS

D.O.A.:

25/6/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHA 28082



INSRS:

WSP:

Tel:

Liability:

RMKS:

Mansoor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

19/12/19 - FILE PAS TO LHM TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (w/411)

S\$ 1926.00

Loss of Rental (LOR):

S\$ 332.01

(

3 days) x \$110.67

Loss of Use (LOU):

S\$

-

(\$

x 3 days)

Loss of Income (LOI):

S\$ 150.00

(\$

50

x 3 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

Total: S\$ 2415.50 Global Sum S\$: 2400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 2400.00

Name 1:

Comfort Delgro Engineering Pte Ltd

Payee 2 (Strike if N.A.):

S\$

Name 2:

Payee 3 (Strike if N.A.):

S\$

Name 3:

Kahn

AB

AG

# ASSIGNMENT

From

Date

26/6/19

Veh No

SHA28082

Reg

21 Mar 2019

Estimated Cost

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To inspect Vehicle No

SHA 28082

Make:

Hyundai 210

C.C

1685

at Workshop n/s

Comfort Delgro

Colour:

Blue

A/C:

Insured

Std / Nil / NA

of

59 Loyang Drive

Sp. Reading

127086

T/Radio:

Insured

Std / Nil / NA

Insured

Eng No

Policy No

C/No

Km HLBX1UM F405286

Claims No

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Sum Insured

Excess

Steering: Inoper / ☒ Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inoper / ☒ Jammed / Leaked / Burnt or

Make of Veh

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

205/60R16

R:

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HaKa

Est. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? - Yes or No

R/Bal

7

mm

R/Bal

7

mm

GIA / PR Seen:

Consistent? - Yes or No

L/Bal

7

mm

L/Bal

7

mm

Est. Repairs:

2

days

Res:

Yes or No

D.O.A

25/6/19

D.O.I

26/6/19

Lum Sum:

20

%

3 Val:

Yes or No

Survey held at

CPHE (Loyang)

CA / REV / REP. / 24 HRS

1up

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

a/b Fnt.

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4.

L/S - \$1800 (Red \$3592.24/67.1)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

Y

☐

Final Report

Resturvey No. of Trip:

Date/Time, File Return to?

Y

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Workshop (\$

Survey Fee:

Transportation:

3 x \$5.00

Tools:

Other:

TOTAL

Report Format:

Emp. Sign / Date:

REPAIR ESTIMATE\*

VEHICLE NO : SHA 2808Z

DATE : 25.06.2019

MAKE :

MODEL : HYUNDAI i40

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>cm</i>			\$ 544.50
	Front Bumper Sponge <i>x su</i>			\$ 99.20
	Front Bumper Reinforcement <i>x su</i>			\$ 402.10
	Front Bumper Grille (LH) <i>x su</i>			\$ 41.60
	Front Bumper Bracket Top (LH) <i>x su</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>x su</i>			\$ 24.60
	Headlamp Support Top Cover <i>x su</i>			\$ 222.60
	Headlamp Support Panel Assy <i>x su</i>			\$ 907.40
	Headlamp (LH) <i>— hazard</i>			\$ 1,388.00
	Front Fender (LH) <i>x rep</i>			\$ 663.00
	Front Fender Shield (LH) <i>x su</i>			\$ 174.90

COMFORT DELGRO

Date/Time: 25.06.2019 15:09

Page : 1

Team: ARC Repair TP(CLSO)1

## JOB CARD

Sales Order:

JO NO: 305306310

COMFORT TRANSPORTATION PTE LTD  
7010045  
383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

REGD NO:	SHA2808Z	MILEAGE
MAKE:	HYUNDAI	FUEL
MODEL:	I-40	DATE/TIME IN
YR OF MANU:	21.03.2014	TARGET DATE
CHASSIS CODE:	KMHLB41UMEU052861	COMPLETION DATE/TIME


AIG

JUNT CARD NO:

## JOB DESCRIPTION

Accident Date: 25.06.2019  
NATURE: 3P 25.06.2019

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No: SHA2808Z LKE

Vehicle No: SHA2808Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE\*

VEHICLE NO : SHA 2808Z

DATE : 25.06.2019

MAKE :

MODEL : HYUNDAI i40

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Front Bumper Sponge ✕			\$ 99.20
	Front Bumper Reinforcement ✕			\$ 402.10
	Front Bumper Grille (LH) ?			\$ 41.60
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp Support Top Cover ✕			\$ 222.60
	Headlamp Support Panel Assy ✕			\$ 907.40
	Headlamp (LH) —			\$ 1,388.00
	Front Fender (LH) ✕ reg			\$ 663.00
	Front Fender Shield (LH) ✕			\$ 174.90
	<b>SUB TOTAL</b>			<b>\$ 4,490.30</b>
	<b>LESS 20%</b>			<b>\$ 898.06</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,592.24</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>1,000.00</del> 300
	Spray Painting Charge			\$ <del>500.00</del> 400
	Wiring Charge			\$ <del>50.00</del> 20
	Tuff Kote			\$ <del>50.00</del> ✕
	Towing Charge			\$ <del>50.00</del> ✕
	Remove/Refix Aircon & Refill Gas			\$ <del>150.00</del> ✕
	<b>TOTAL LABOUR</b>			<b>\$ 1,800.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,392.24</b>
<p>Kahr (16/16)</p> <p>M 26/6/19 1040L</p> <p>26/6/19</p> <p>4/5</p> <p>Atta Rqr pld</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO  
ENGINEERING

Our Job Ref No 305306310

Date : 27.06.19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive, Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHA2808Z CTPL

25.06.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **AIG** --- **SMH9259R**
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)
  - Total for Lumpsum repair cost after Less: 20% **\$1,800.00**
  - Final Lumpsum Repair cost** **\$1,800.00**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Kaha

Date : 28/6/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Reply | ▾ Delete Junk | ▾ ...

## RE: SHA2808Z with your insured SMH9259R

AC

AIG SGP, Claims-Survey &lt;AIGSGP\_ClaimsSurvey@aig.com&gt;

📎 📧 ➡ Reply | ▾

Tue 25/6/2019 3:44 PM

To: ✓ Lim Kwok Eng

Cc: Ng Nyuk Phin; ✓ Roger How Keen Meng

Inbox

### WITHOUT PREJUDICE

Hi Sir,

● We'll appoint LKK to survey.

Thanks.

AIG Claims Survey

---

**From:** Lim Kwok Eng [mailto:limke@cdge.com.sg]**Sent:** Tuesday, June 25, 2019 3:39 PM**To:** AIG SGP, Claims-Survey**Cc:** Ng Nyuk Phin; Roger How Keen Meng**Subject:** [EXTERNAL] SHA2808Z with your insured SMH9259R

● This message is from an external sender; be cautious with links and attachments.

To Officer In Charge

Pls arrange surveyor, refer attachment

Best Regards


Lim Kwok Eng

Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8355 / 6214-8156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately. Any further or onward use, copy, copy/paste, print, distribution or disclosure of any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelgro.

**SHA2808Z with your insured SMH9259R**

From: Chin, Lee-Ying  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY  
Sent: 6/25/2019 3:42:56 PM  
Attachments:  [img-625152846-0001.pdf](#)

---

Hi LKK,

Kindly assist to survey.

4.17pm 28/6/19  
vehicle in  
agreed by on 26/6

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Lim Kwok Eng [mailto:[limke@cdge.com.sg](mailto:limke@cdge.com.sg)]  
**Sent:** Tuesday, June 25, 2019 3:39 PM  
**To:** AIG SGP, Claims-Survey  
**Cc:** Ng Nyuk Phin; Roger How Keen Meng  
**Subject:** [EXTERNAL] SHA2808Z with your insured SMH9259R

This message is from an external sender; be cautious with links and attachments.

To Officer In Charge

Pls arrange surveyor, refer attachment

Best Regards  
Lim Kwok Eng  
Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd  
Tel. 6214-8355 / 6214-8156

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to



print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref: 305306310

Date: 25/6/19

Time of Fax: \_\_\_\_\_

Via Fax: Email

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.odge.com.sg

Company Registration No: 190506048W

Workshop

Loyang  
59 Loyang Drive  
Singapore 508969

→ AIG

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHA2808Z

Your Insured: SMH9259R

Date of Acc: 25/6/19

\* 7 pages

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

3 Enclosed, please find :

- I) Our initial estimate of repairs of the damaged vehicle.
- II) Accident report made by our client.

4 I would appreciate it if you could call us to arrange for the survey of the vehicle


→ Lim Kwok Eng. Tel no. 62148355 or Hp no. 98240811  
Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305  
Lim Tien Siong Tel no. 62148398 or Hp no. 96358546  
Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006  
Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176  
Larry Ng Tel: 6214 8316

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully



for Vice President

Crash Repairs & Claims Recovery

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2019 <a href="#">Edit Reg</a>		25 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	MANSOOR S/O TAYABBHAI GANDHI, ID: S7533881C		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA2808Z	Date of Loss:	25/06/2019 10:00 - :59 [63 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0527128917SG	Policy/Cover Note No.:	1900014433 (Comprehensive)
Vehicle Reg. No. (Insured):	SMH9259R	Policy No. (Claimant):	D-18088936MFSH
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 04/07/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (03/07/2019): Re: No OI GIA Report
- AIG\_SG (26/06/2019): No OI GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHA2808Z (0527128917SG)  
[SMH9259R]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Jun 25 2019 10:15AM  
[MANSOOR S/O TAYABBHAI GANDHI]  
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser</span>	
<b>Video</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	26/07/19 15:37	Video - Accident							Load MP4		
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	03/07/19 15:52	Accident Statement <small>From: SC - Reg. No: SMH9259R, Claimant: MANSOOR S/O TAYABBHAI GANDHI</small>							Load HTM		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/06/19 08:46	General View							Load JPG		
2	27/06/19 08:46	General View							Load JPG		
3	27/06/19 08:46	General View							Load JPG		
4	27/06/19 08:46	General View							Load JPG		
5	27/06/19 08:46	General View							Load JPG		
6	27/06/19 08:46	General View							Load JPG		
7	27/06/19 08:46	General View							Load JPG		
8	27/06/19 08:46	General View							Load JPG		
9	27/06/19 08:46	General View							Load JPG		
10	27/06/19 08:46	General View							Load JPG		
11	27/06/19 08:46	General View							Load JPG		
12	27/06/19 08:46	General View							Load JPG		
13	27/06/19 08:46	General View							Load JPG		
14	27/06/19 08:46	General View							Load JPG		
15	27/06/19 08:46	General View							Load JPG		
16	27/06/19 08:46	General View							Load JPG		
17	27/06/19 08:46	General View							Load JPG		
18	27/06/19 08:46	General View							Load JPG		
19	27/06/19 08:46	General View							Load JPG		
20	27/06/19 08:46	General View							Load JPG		
21	27/06/19 08:46	General View							Load JPG		
22	27/06/19 08:46	General View							Load JPG		
23	27/06/19 08:46	General View							Load JPG		
24	27/06/19 08:46	General View							Load JPG		
25	27/06/19 08:46	General View							Load JPG		
26	01/07/19 08:54	Reinspection Photo							Load JPG		
27	01/07/19 08:54	Reinspection Photo							Load JPG		
28	01/07/19 08:54	Reinspection Photo							Load JPG		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/06/19 16:18	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT							Load PDF		
2	25/06/19 16:18	EMAIL FROM AIG DD 25.06.2019							Load PDF		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	25/06/19 17:50	ACKNOWLEDGEMENT EMAIL TO AIG DD 25.06.2019		Load PDF
4	02/07/19 09:28	TP ESTIMATE		Load PDF
5	02/01/20 11:00	WORKSHOP INVOICE		Load PDF
6	02/01/20 11:00	AUTHORISATION TO ACT FORM		Load PDF
7	02/01/20 11:00	Release Voucher		Load PDF
8	02/01/20 11:00	RENTAL RECEIPT		Load PDF
9	02/01/20 11:00	RENTAL MILEAGE		Load PDF
10	02/01/20 11:00	LTA SEARCH		Load PDF
11	02/01/20 11:00	LOD		Load PDF
12	02/01/20 11:00	LETTER TO OI		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div></div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMH9259R (Insd veh)	Model:	HYUNDAI i40 1.7 L CRDI AT
	SHA2808Z (TP veh)		ABS AIRBAG 4DR (A)
Date of Accident:	25/06/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	5,769.70
Final Repair Cost	:	\$	2,400.00
Loss of Use	:	\$	3.00 days at \$50.00 per day
Rental (if any)	:	\$	3 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,400.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability \_\_\_\_\_ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 2,400.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

02 Jan  
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011194/FDA3Q2

Date: 02/01/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900014433  
 Claimant: SHA2808Z Insured Vehicle No: SMH9259R  
 Vehicle No: Date of Loss: 25/06/2019 Nature of Claim: TP Claim No: 0527128917SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHA2808Z  
 Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDGU625910  
 Reg. Date: 21/03/2014 (Man. Year: 2014) Chassis No: KMHLB41UMEU052861  
 Colour: Blue Odometer: 927086 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm  
 Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,592.24	1,546.00	2,046.24	56.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	720.00	1,080.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,392.24</b>	<b>2,266.00</b>	<b>3,126.24</b>	<b>57.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	5,392.24	1,800.00	3,592.24	66.62
<b>+ GST 7.00/7.00% (S\$)</b>	<b>377.46</b>	<b>126.00</b>	<b>251.46</b>	<b>66.62</b>
<b>Nett Amount (S\$)</b>	<b>5,769.70</b>	<b>1,926.00</b>	<b>3,843.70</b>	<b>66.62</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$110.67/day) (S\$)</b>		332.01		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,415.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,400.00</b>		

## INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 26/06/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	544.50 FL	*544.50 FL
2	1		*FRONT BUMPER SPONGE	Serviceable	99.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Serviceable	402.10 FL	*- FL
4	1		*FRONT BUMPER GRILLE (LH)	Serviceable	41.60 FL	*- FL
5	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	22.40 FL	*- FL
6	1		*FRONT BUMPER BRACKET (LH)	Serviceable	24.60 FL	*- FL
7	1		*HEADLAMP SUPPORT TOP COVER	Serviceable	222.60 FL	*- FL
8	1		*HEADLAMP SUPPORT PANEL ASSY	Serviceable	907.40 FL	*- FL
9	1		*HEADLAMP (LH)	Grazed	1,388.00 FL	*1,388.00 FL
10	1		*FRONT FENDER (LH)	Repair	663.00 FL	*- FL
11	1		*FRONT FENDER SHIELD (LH)	Serviceable	174.90 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,490.30</b>	<b>1,932.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>898.06</b>	<b>386.50</b>
<b>Total Parts (S\$)</b>	<b>3,592.24</b>	<b>1,546.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	300.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	0.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
Gross Labour Cost (S\$)			1,800.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >