



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19011217/Bba3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 21-04-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 4247U	Veh. Inspected	SLR 423B
Policy No.	GA416061/1	Coverage (\$)	0.00
Claim No.	S9M01RLS	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31253551	Colour	WHITE
Odometer	046155	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DANAGES SEE DETAILS.
--

5. General Information

Accident Date	22/06/2019	Inspection Date	28/06/2019
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------