

(08/11/13)

ASS. REC. BY: Wise Jle

REF

MSIG CC3/MSG 19011224 J90307

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 80766069Claims No. 5977463

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: ✓ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SG5786X Yr Regn: 19 Aug 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Man A95 c.c. 10518Colour: Green A/C: Insured / Std / NI / NASp. Reading: 241803 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA95ZZ967003279Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/70 R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 21/6/19 D.O.I. 24/6/19Survey held at SumitDes. of Damages: Front Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SG5786X - CC4/ASM 18015360 / nhg 292 DOA - 22/03/2018
	SKA 160K - X
26/6/19 @ 10.18am	Email GIA report & estimate and revised to MSIG.
05/07/19 @ 2.07pm	confirmed with Catherine final fig \$1058, 2 days. by email.
	Cred \$1767.70, 62%)
	RECEIVED 10 JUL 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 10/7 Wise Jle☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: MSIG-TPLump Sum / I.B.I: (\$ 1058)

150
11
161

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 9 July 2019 2:07 PM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses); SUR
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); AutoSvs-ARC (Bus)
Subject: RE: Finalisation - SG5786X (BUS/06/19/1063 - MSIG)

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$1,058.00 before GST and 2 repair days.

Kindly send the relevant documents to MSIG Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/AR & SC/Buses) <catherineleesc@smrt.com.sg>
Sent: Friday, 5 July 2019 2:26 PM
To: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-ARCBus@smrt.com.sg>
Subject: Finalisation - SG5786X (BUS/06/19/1063 - MSIG)

Hi Hwee Jie,

Attached herewith our copy of the bus repair estimate for the case.
Our finalised amount is \$1,058.00 @ 2 working days under part by part repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 26 June 2019 10:18 AM
To: Motor Survey
Cc: KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SG 5786X, INSURED VEHICLE: SKA 160K, DOA: 21-06-2019)
Attachments: SG5786 EST.pdf; SG5786 GIA.pdf; CC3MSG19011222Jqd3.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle **SG 5786X** at M/s: **SMRT AUTOMOTIVE SERVICES PTE LTD**, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: Please advise

Date: 26th June 2019

Our Ref: CC3/MSG19011222/Jqd3

The Motor Claims Department
MSIG Insurance Singapore Pte Ltd

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SG 5786X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/06/2019 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,820.70</u>
Revised Estimate Amount	: S\$ <u>1,058.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Hwee Jie
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SG5786X
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	MAN
Vehicle Model:	A95
Primary Colour:	Multi-Colour
Manufacturing Year:	2016
Engine No.:	50343741104378
Chassis No.:	WMAA95ZZ9G7003279
Maximum Power Output:	-
Open Market Value:	\$438,406.00
Original Registration Date:	19 Aug 2016
First Registration Date:	19 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 26 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/06/2019 13:07
Date Of Accident	21/06/2019 12:40
Exact Location Of Accident	BENCOOLEN STREET
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SG5786X
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MAN
Model	MAN A95
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	
Driver	
Name of Driver	SOONG CHEONG LOON
NRIC No	S1404368C
Date Of Birth	01/11/1960
Occupation	OUTDOOR
Date Of Driving Pass	01/03/1984
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 15

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20190621/2114 ON 21/06/2019 AT ABOUT 1240HRS, I WAS FILTERING THE SMRT BUS FROM THE BUS LANE TO THE 3RD LANE. AT THE SAME TIME, THERE WAS ANOTHER CAR FILTERING FROM THE 2ND LANE TO THE 3RD LANE. AS BOTH VEHICLES WERE FILTERING INTO THE SAME LANE AT THE SAME TIME, IT WAS TOO LATE UPON SEEING IT. I APPLIED E-BRAKE BUT WAS STILL UNABLE TO AVOID THE COLLISION IN TIME. DURING TO THE BRAKING, ONE OF THE PASSENGER (MDM YEOW YING LIH HP:98457861) WAS PUSHED TOWARD AND HER HEAD HIT THE FRONT SEAT, CAUSING SOME ABRASION AND HEADACHE. AMBULANCE WAS SUMMONED AND THE SAID PASSENGER WAS CONVEYED TO RAFFLES HOSPITAL. DAMAGES OF THE BUS WAS DENT/SCRATCHES AT THE FRONT RIGHT CORNER. DAMAGES OF THE CAR WAS AT THE LEFT SIDE CAR DOORS. TP ATTENDED TO THE ACCIDENT AND THE INCIDENT NUMBER WAS A/20190621/0061.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKA160K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1	
Name	MDM YEOW YING LIH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SG5786X
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

<p>Policyholder's Signature</p> <p>Date & Time:</p>	<p>Driver's Signature</p> <p>(If driver is not the policyholder)</p> <p>Date & Time:</p>	<p>Reporting Centre</p> <p>Name:</p> <p>NRIC/FIN No.:</p>
---	--	---

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



DECLARATION I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
Title/JIN No.:






SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/06/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SG5786X
Case Reference Number	BUS/06/19/1063
Registration Date	19/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Soong Cheong Loon
Type of Accident	Side Swipe
Accident Date and Time	21/6/2019 12:40 PM
Accident Reported Date and Time	21/6/2019 2:44 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5786X-RIGHT FRONT PORTION SKA160K (TP) INSURED WITH MSIG
Prepared Date and Time	24/6/2019 1:32 PM
Chassis Number	WMAA95ZZ9G7003279
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,846.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	24/06/2019 2:46 PM	
Signature		X
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/06/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00 <i>530</i>	
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00 <i>528</i>	
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
8010152	Body	F01001-CW266	COVER, HEADLAMP: FRT. RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	<i>X</i>
Total					\$974.70		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Have die-LKK
24/6/19
P/P 2days.
gls





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/07/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5786X
Case Reference Number	BUS/06/19/1063
Registration Date	19/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Soong Cheong Loon
Type of Accident	Side Swipe
Accident Date and Time	21/6/2019 12:40 PM
Accident Reported Date and Time	21/6/2019 2:44 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24102123
Special Instruction to ARC, if any	SG5786X-RIGHT FRONT PORTION SKA160K (TP) INSURED WITH MSIG
Prepared Date and Time	24/6/2019 1:32 PM
Chassis Number	WMAA95ZZ9G7003279
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$786.00	\$528.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,846.00	\$1,058.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Hwee Jie
ARC / Surveyor Sign Off Date	24/06/2019 2:46 PM	24/06/2019 3:33 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/07/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	\$530.00
Total Labour	\$1,060.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$528.00
Total Spray Painting & Panel Beating	\$786.00	\$528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
Total					\$974.70		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2019		26 Jun 2019 14:28 Edit Adj Rpt	S\$1,058.00 Edit Estimates	S\$1,058.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIM AI LIAN , ID: S1373937D, Tel: +6596302601, Email: LIM_ALIAN@YAHOO.COM.SG									
Main Claimant: SMRT BUSES LTD , Co. Reg. No.: 198202292D									
Vehicle Reg. No.:	SG5786X	Date of Loss:	21/06/2019 12:00 - :59 [34 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 597463	Policy/Cover Note No.:	80266069 (Comprehensive) Coverage: 08/11/2018 - 07/11/2019						
Vehicle Reg. No. (Insured):	SKA160K	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 27/06/2019]								
Driver/Custodian (Insured):	LIM AI LIAN (59 / Female), NRIC: S1373937D, Tel: +6596302601 Email: LIM_ALIAN@YAHOO.COM.SG								
Adj Asg. Remarks:	Direct Survey done								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SG5786X (597463)**
[SKA160K]
TP
SMRT BUSES LTD
Jun 21 2019 12:00PM
[LIM AI LIAN]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/07/19 14:04	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/07/19 14:04	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
9	09/07/19 14:04	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
10	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
11	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
12	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
13	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	09/07/19 14:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/06/19 14:29	Direct survey email frm LKK	Load PDF	
2	26/06/19 14:30	LKK Preliminary Advice	Load PDF	
3	26/06/19 14:30	TP Estimate	Load PDF	
4	26/06/19 14:30	TP GIA Rpt	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19011222/JQD3E2

Date: 12/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80266069

Claimant Vehicle No : SG5786X

Insured Vehicle No : SKA160K

Date of Loss: 21/06/2019

Nature of Claim: TP Claim No: 597463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG5786X

Make & Model: MAN A95, 10.5 D (A)

Engine No: 50343741104378

Reg. Date: 19/08/2016 (Man. Year: 2016)

Chassis No: WMAA95ZZ9G7003279

Colour: Green

Odometer: 241803 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7/7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	974.70	0.00	974.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,846.00	1,058.00	788.00	42.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,820.70	1,058.00	1,762.70	62.49

INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 24/06/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference		
Part Source:	(Last Synchronised: 12 Jul 2019)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5786X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,HEADLAMP:FRT,RH,FOR MAN A22 BUS	Not Necessary	974.70 F	*- F
F=Franchise part.						
				Total Parts (S\$)	974.70	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	786.00	528.00
Gross Labour Cost (S\$)			1,846.00	1,058.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >