



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18017729/R1vd3n2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 05-09-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 2439S	Veh. Inspected	SDT 8209K
Policy No.	Z18VP05017506	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020953	Excess (\$)	0.00
Assign From	GERALD	Assign Date	24/06/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ 200E A	c.c	1996
Engine No.	HIDDEN	Year of Reg.	1990
Chassis No.	WDB1240212B214985	Colour	BLACK
Odometer	720641	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/09/2018	Inspection Date	02/10/2018
Survey held at	TMF AUTOMOTIVE PTE LTD 7 SOON LEE STREET #01-34 ISPACE SINGAPORE 627608		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------