

ASS. REC. BY: Surveyor REF: CS3/LPC18017729/R1v13-1 ⁿ² 24.6.2019
 Surveyor: Reisel ASSIGNMENT (Office)
 From (Person): Gerald poh of LPC Date/Time: 24.6.2019
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SDT 8209K Insured: SJR 2439S
 at Workshop m/s: TME AUTOMOTIVE Tel: 6898 1533
 of: 7 Soon Lee St # 01-34
 Policy No: _____ Claim No: 18/18/18/VPOS/020953
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 27.9.2016
 (Client's Record) 02/10/18 2 Moring
 CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____
 Date/Time: 2:43pm 11/10/18 Person Contacted: Ah Kaw Vehicle: IN OUT

Date/Time	Action/Instruction (x) Estimate	(call with hbr going)
	SDT 8209K - NA/INC11011561/jl	DOA: 15/6/2011
	SJR 2439S - X	
	Repairer agreed survey on 2/10/18	
	Taukikh - 4/10/18, 8/10/18	

10/10/18 Submit PRS report
 2/1/19 Submit LS \$ 750 (Red 5400, 4370),
 10 days


 1/7/2019

RECEIVED 02 JUL 2019

NAME: Prime REF: LPC 12224 COE XPRY: 2025/SEP PIS call Repeater before going 02/10/18 ASSIGNMENT SDT 8209K 1990 APR Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover Truck / Trailer or Make: MERCEDES Benz 200E A 1996 Colour: Black A/C Insured / Std / Nil / NA Sp Reading: 720641 T/E: Insured / Std / Nil / NA Engine: C/N: WDB1240 212 P 214 985 Gen. Cond: Good / ☒ Poor / Burnt Steering: ☒ Jammed / Leaked / Burnt or Brake: ☒ Jammed / Leaked / Burnt or Mod: Nil / ☒ STD A/Rim or Tyre Size: F 195/65R15 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FRANK Front: 6 mm Rear: 6 mm R.Bal: 6 mm L.Bal: 6 mm D.O.A: 27/09/18 D.O.I: 02/10/18 12.11 pm Survey held at: TMF Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S The U/C / Chassis frame / Body Structure affected due to collision	SDT 8209K 1990 APR Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover Truck / Trailer or Make: MERCEDES Benz 200E A 1996 Colour: Black A/C Insured / Std / Nil / NA Sp Reading: 720641 T/E: Insured / Std / Nil / NA Engine: C/N: WDB1240 212 P 214 985 Gen. Cond: Good / ☒ Poor / Burnt Steering: ☒ Jammed / Leaked / Burnt or Brake: ☒ Jammed / Leaked / Burnt or Mod: Nil / ☒ STD A/Rim or Tyre Size: F 195/65R15 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FRANK Front: 6 mm Rear: 6 mm R.Bal: 6 mm L.Bal: 6 mm D.O.A: 27/09/18 D.O.I: 02/10/18 12.11 pm Survey held at: TMF Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S The U/C / Chassis frame / Body Structure affected due to collision
--	--

RECEIVED 2018

Days Of Repair Resurvey No. of Trip: Survey Fee Transcript 10/10- typist Report Format Lump Sum / L.B. 1000	☐ : Proli. Report ☐ : Final Report Add Fee: ☐ Site Insp 15 ☐ Interview 15 ☐ Test 15 ☐ Voucher 15	450
--	---	------------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1222H

Vehicle Details

Vehicle No.: SDT8209K
Vehicle to be Exported: No
Intended Deregistration Date: 04 Oct 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: 200E AUTO
Primary Colour: Blue
Manufacturing Year: 1990
Engine No.: 10296322016866
Chassis No.: WDB1240212B214985
Maximum Power Output: -
Open Market Value: \$42,753.00
Original Registration Date: 28 Apr 1990
First Registration Date: 28 Apr 1990
Transfer Count: 4
Actual ARF Paid: \$74,618.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2028
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$33,377.00
COE Rebate Amount: \$33,339.00
Total Rebate Amount: \$33,339.00

The information contained herein is correct as at 04 Oct 2018

OK

42K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/09/2018 16:49
Date Of Accident	27/09/2018 14:55
Exact Location Of Accident	SLE TOWARDS CTE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJR2439S
Insured/Policyholder	
Name Of Registered Owner	RAMACHANDRAN MURUGESAN
NRIC No	S7864461C
Email Address	MURU132@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93374002
Alternative Phone No	OTHERS-93374002
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017506
Cover Note Number	13/2/18-12/2/19
Driver	
Name of Driver	RAMACHANDRAN MURUGESAN
NRIC No	S7864461C
Date Of Birth	21/07/1978
Occupation	INDOOR
Date Of Driving Pass	24/01/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93374002
Fax Number	
Contact Number	OTHERS-93374002
Email Address	MURU132@GMAIL.COM

Address	9 WOODLANDS DR 72 #07-17
Postcode	738093
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV8930S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HWEE LING
NRIC/Passport Number	S8015705C
Contact Number	81282925
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SDT8209K
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	DAVID LIM
NRIC/Passport Number	S0168657G
Contact Number	97551998
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SJR 2424 S
INSURER : LONRIC
DATE & TIME: 27/4/18 2.55 PM

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 27 Sep 18
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

 27/9/18
Reporting Centre Personnel's Signature
Name: Wendy
NRIC/FIN No: W

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I drive my car SJR 24395 to meet my customer in changing near to the Lentor exit I reduce my car speed due to my front car (SFR 8209K) reducing their speed. At the same time my car was knocked by behind car (SKV 89305) and my car hit my front car.

We then stop our cars and take the incident photo, 1 photo and share our phone numbers.

The time around 3:00pm 27 Sept 18.

There was no visual injury to anyone.

Repair by my own workshop

Dmotorworks pte ltd

28 Woodlands Ind park ES

01-03 5-757322

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

<i>[Signature]</i> 27 Sept 18 Policyholder's Signature Date & Time:	<i>[Signature]</i> Driver's Signature (If driver is not the policyholder) Date & Time:	<i>[Signature]</i> 27/9/18 Reporting Centre Personnel's Signature Name: <i>[Signature]</i> SPIC/IN No: <i>WL</i>
☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only ☒ Claim OD/TP at other workshop ()		

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE



SCENE



SCENE



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2018 13:54
Date Of Accident	27/09/2018 15:00
Exact Location Of Accident	ALONG SLE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT8209K
Insured/Policyholder	
Name Of Registered Owner	PAUL KENNY LIM KOON YEW
NRIC No	S8121222H
Email Address	WCP.ENGINEERING@ICCP-MGPS.COM.SG
Mobile Phone No	(LOCAL) +65-97551998
Alternative Phone No	OFFICE-68977577

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5051969106-06
Cover Note Number	

Driver

Name of Driver	DAVID LIM YONG KEONG
NRIC No	S0168657G
Date Of Birth	06/06/1951
Occupation	INDOOR
Date Of Driving Pass	25/06/1973
Driving Experience	45 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97551998
Fax Number	
Contact Number	OFFICE-97551998
Email Address	WCP.ENGINEERING@ICCP-MGPS.COM.SG

Address	BLK 248 COMPASSVALE ROAD #08-618
Postcode	540248
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAUL KENNY LIM KOON NYEW
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR2439S
Vehicle Make/Model/Colour	NA
Details Of Properties	FRONT AND REAR PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	93374002
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKV8930S
Vehicle Make/Model/Colour	NA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am the Driver and driving at the first lane suddenly I felt a big bang on my vehicle. I stop and came out and saw two vehicles behind me. Total 3 vehicles were involved and damaged to 3 vehicles

DECLARATION

We declare the foregoing particulars are true in every respect

No. of vehicles involved

No. of vehicles involved

No. of vehicles involved

28/9/2018

Sketch Plan #2

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or accessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same, as well as in the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service provider(s) or agents/including their lawyers/law firms), which may be acted outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for compliance with requirements under any regulations, laws or court orders.

Policyholder's Signature
(in A-Type)

Driver's Signature
If the driver is not the Policyholder:
Name & Name

28/9/2018

Reporting Centre Person's Signature
(Date)
GIA's Stamp

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/18/18/VP05/020953

Your Ref : CS3/LPC18077729/R1vd3n2

24 June 2019

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SDT8209K

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SDT8209K
- b) GIA report SDT8209K
- c) GIA report and photos of SJR2439S

Kindly study the documents and let us have your report by 9 July 2019.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

天
馬
福



TMF AUTOMOTIVE PTE LTD

7 Soon Lee Street, #01-34 I-space Building, Singapore 627608.

Tel : 6898 1533 Fax : 6268 1988

GST Reg. No. : 201619883C

30 May 2019

PAUL KENNY LIM KOON YEW
C/O 7 Soon Lee Street #01-34
I-Space Building Singapore 627608

REPAIR BILL FOR VEHICLE NO. SDT 8209 K

Total Repair Cost	\$12,650.00
Add 7% GST	\$ 885.50
Total:	<u>\$13,535.50</u>

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers
17 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

PAUL KENNY LIM KOON YEW
C/O 7 Soon Lee Street #01-34 I-space
Building Singapore 627608

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 27 September 2018
Assignment Date : 28 September 2018
Inspection Date : 28 September 2018
Our Reference No. : PAS/TMF/190511/TP

Inspection Report Date : 30 May 2019

Workshop Name :

TMF AUTOMOTIVE PTE LTD

Inspection Address :

7 Soon Lee Street #01-34 I-space Building
Singapore 627608

PARTICULARS OF VEHICLE

Registration No. : SDT 8209 K
Make/Model : MERCEDES BENZ 200E AUTO
Yr of Manuf/Regn : 1990
Carrying Capacity : 4 Seater
Chassis No. : WDB1240212B214985
Engine No. : 10296322016866
Colour : Metallic Black
Class : Passenger (Private)

Mileage : 720641 Km/h
Radio/Casette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror Other : Fitted
Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Parf) : -

TYRE SIZE & CONDITION

Front N/s Size : 195/65R15 80 %
Make : FALKEN
Rear N/s size : 195/65R15 80 %
Make : FALKEN
Spare Size : 195/65R15 80 %
Make : FALKEN

Front O/s Size : 195/65R15 80 %
Make : FALKEN
Rear O/s Size : 195/65R15 80 %
Make : FALKEN
Spare Size :
Make :
Jack & Tools : Intact/Missing

Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

SDT 8209 K

PAS/TMF/190511/TP

10-Jun-19

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO :

1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
				\$ cts	\$ cts
		PARTS SUPPLY - NETT ITEMS			
1	1pc	Bootlid	Badly Dented	1261.00	1261.00
2	1pc	Bootlid centre logo	Necessary	56.00	56.00
3	1pc	Bootlid 'E200' emblem	Necessary	68.00	68.00
4	1pc	Bootlid 'Masterpiece' emblem	Necessary	78.00	78.00
5	1pc	Bootlid upper lock	Bent	185.00	185.00
6	1pc	Bootlid key lock	Dented	225.00	225.00
7	1pc	Bootlid central lock	Dented	488.00	488.00
8	1pc	Bootlid lower lock	Bent	455.00	455.00
9	2pcs	Bootlid hinges @\$145	Bent	290.00	290.00
10	1pc	Boot rubber	Torn	188.00	188.00
11	1pc	Taillamp assy @\$502	Cracked LH, RH - NN	1004.00	1004.00
12	1pc	Rear bumper	Badly Dented	1148.00	1148.00
13	1pc	Rear bumper centre mldg	Necessary DIS	189.00	189.00
14	1pc	Rear bumper corner mldg @\$163	Necessary LH-DIS, RH-NN	326.00	326.00
15	1pc	Rear bumper centre garnish	Badly Dented	398.00	398.00
16	1pc	Rear N/s Fender	Badly Dented	1195.43	1195.43
17	1pc	Rear bumper sponge	Serviceable	171.00	-
18	1set	Rear windscreen mldg	Necessary	241.00	241.00
19	1pc	Rear panel	Badly Dented	578.00	578.00
20	1pc	Rear panel top garnish	Warped	95.00	95.00
21	2pcs	Rear bumper bracket @\$44	N/s Cracked	88.00	44.00
22	1pc	Rear N/s Shock absorber	Bent	176.90	176.90
23	1pc	Rear N/s Control Arm	Bent	130.41	130.41
24	1pc	Rear N/s torque arm	Bent	144.20	144.20
25	1pc	Rear N/s lateral arm	Bent	138.90	138.90
26	1pc	Rear N/s thrust arm	Bent	55.95	55.95
27	1pc	Rear N/s knuckle arm	Bent	244.82	244.82
28	1pc	Rear N/s torsion bar	Bent	237.54	237.54
29	1pc	Rear N/s stabilizer link	Bent	88.00	88.00
30	1pc	Spare tyre well	Badly Dented	2080.35	2080.35
		Spare tyre well cover	Cracked	180.09	180.09
		Less: 10% discount		12204.59	11989.59
					1198.96
				12204.59	10790.63
		SPECIAL NETT ITEMS			
1	1set	Rear windscreen sealant	Necessary	50.00	50.00
2	1set	Rear bumper sensor	Dented	350.00	250.00
3	1set	Rear panel sealant	Necessary	50.00	50.00
4	1set	Bootfloor sealant	Necessary	50.00	50.00
				12604.59	11090.63
		LABOUR & MISC. CHARGES			
1		Towing - 2Trips		400.00	250.00
2		Remove the necessary affected parts, cut/weld rear panel, spare tyre well, rear n/s fender, straighten both rear chassis rear o/s fender, rear n/s door and replace parts			
3		Putty and spraypaint on all affected parts		2000.00	1600.00
4		Check electrical		2000.00	1600.00
5		Tuff Kote		100.00	80.00
6		Remove and refit rear windscreen		100.00	60.00
7		Remove and refit rear bumper sensors		150.00	120.00
8		Remove and refit rear n/s suspension		100.00	60.00
9		Rewire rear portion		400.00	300.00
10		Reset Wheel Alignment - Before Repaired		50.00	30.00
11		Reset Wheel Alignment - After Repaired		100.00	80.00
12		Remove and refit fuel tank		100.00	80.00
13		Remove and repair rear suspension crossmember & rear axle components		100.00	80.00
14		Remove and refit bootlid components		400.00	300.00
		Note: Recommended lump sum repair at \$12,650.00nett.		100.00	80.00
			xxx	18704.59	15810.63
			SUB / GRAND TOTAL		

PRECISION APPRAISAL SERVICES



PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers




VEHICLE REGISTRATION NO. : SGH 9687 J

APPENDIX A

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its Rear Portion. (see Diagram D)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The bootlid, rear bumper and panel, both rear chassis and fenders, spare tyre well, rear n/s door were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 28/09/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s TMF AUTOMOTIVE PTE LTD as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 12,650.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Repares Parts	12604	59	11090	63
Towing Charges	400	00	250	00
LAB Labour Charges	2000	00	1600	00
Others Misc Charges	1700	00	1270	00
Paintwork	2000	00	1600	00
Total	\$ 18704	59	\$ 15810	63

Under normal circumstances, the duration of repairs should not exceed Sixteen (16) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame.

Attached photographs taken during inspection One Hundred & Seventy - Five (175) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 03/10/2018, we examined the extent of damages
3. On 12/11/2018, we examined the repaired vehicle.

Yours Faithfully,



TFNG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 30 May 2019

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18017729/R1vd3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 03-07-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 2439S	Veh. Inspected	SDT 8209K	
Policy No.	Z18VP05017506	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020953	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	24/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ 200E A	c.c	1996	
Engine No.	HIDDEN	Year of Reg.	1990	
Chassis No.	WDB1240212B214985	Colour	BLACK	
Odometer	720641	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2018	Inspection Date	02/10/2018	
Survey held at	TMF AUTOMOTIVE PTE LTD 7 SOON LEE STREET #01-34 ISPACE SINGAPORE 627608			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 8209K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID (N)	BADLY DENTED	1,261.00	1,261.00
1	BOOTLID CENTRE LOGO (N)	NECESSARY	56.00	56.00
1	BOOTLID "E200" EMBLEM (N)	NECESSARY	68.00	68.00
1	BOOTLID "MASTERPIECE" EMBLEM (N)	NOT FITTED	78.00	-
1	BOOTLID UPPER LOCK (N)	BENT	185.00	185.00
1	BOOTLID KEY LOCK (N)	DENTED	225.00	225.00
1	BOOTLID CENTRAL LOCK (N)	SERVICEABLE	488.00	-
1	BOOTLID LOWER LOCK (N)	SERVICEABLE	455.00	-
2	BOOTLID HINGES @\$145.00 (N)	SERVICEABLE	290.00	-
1	BOOT RUBBER (N)	TORN	188.00	188.00
2	TAILLAMP ASSY @\$502.00 (N)	N/S SCRATCHED / O/S NOT NECESSARY	1,004.00	502.00
1	REAR BUMPER (N)	BADLY DENTED	1,148.00	1,148.00
1	REAR BUMPER CENTRE MLDG (N)	DISTORTED	189.00	189.00
2	REAR BUMPER CORNER MLDG @\$163.00 (N)	N/S DISTORTED / O/S NOT NECESSARY	326.00	163.00
1	REAR BUMPER CENTRE GARNISH (N)	BADLY DENTED	398.00	398.00
1	REAR N/S FENDER (N)	BADLY DENTED	1,195.43	1,195.43
1	REAR BUMPER SPONGE (N)	SERVICEABLE	171.00	-
1	SET REAR WINDSCREEN MLDG (N)	NECESSARY	241.00	241.00
1	REAR PANEL (N)	BADLY DENTED	578.00	578.00
1	REAR PANEL TOP GARNISH (N)	WARPED	95.00	95.00
2	REAR BUMPER BRACKET @\$44.00 (N)	N/S CRACKED	88.00	44.00
1	REAR N/S SHOCK ABSORBER (N)	NOT NECESSARY	176.90	-
1	REAR N/S CONTROL ARM (N)	NOT NECESSARY	130.41	-
1	REAR N/S TORQUE ARM (N)	NOT NECESSARY	144.20	-
1	REAR N/S LATERAL ARM (N)	NOT NECESSARY	138.90	-
1	REAR N/S THRUST ARM (N)	NOT NECESSARY	55.95	-
1	REAR N/S KNUCKLE ARM (N)	NOT NECESSARY	244.82	-
1	REAR N/S TORSION BAR (N)	NOT NECESSARY	237.54	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR N/S STABILIZER LINK (N)	NOT NECESSARY	88.00	-
1	SPARE TYRE WELL (N)	TO REPAIR SEE LABOUR	2,080.35	-
1	SPARE TYRE WELL COVER (N)	CRACKED	180.09	180.09
	LESS 10% DISCOUNT		-	-671.65
			12,204.59	6,044.87
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER SENSOR (SN)	DENTED	350.00	200.00
1	SET REAR PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET BOOTFLOOR SEALANT (SN)	NOT NECESSARY	50.00	-
			500.00	300.00
	<u>LABOUR</u>			
	TOWING-2 TRIPS.		400.00	90.00
	REMOVE THE NECESSARY AFFECTED PARTS,CUT/WELD REAR PANEL,SPARE TYRE WELL,REAR N/S FENDER,STRAIGHTEN BOTH REAR CHASSIS,REAR O/S FENDER,REAR N/S DOOR AND REPLACE PARTS.		2,000.00	1,200.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		2,000.00	1,200.00
	CHECK ELECTRICAL.		100.00	30.00
	TUFF KOTE.		100.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	60.00
	REMOVE AND REFIT REAR N/S SUSPENSION.	NOT NECESSARY	400.00	-
	REWIRE REAR PORTION.	NOT NECESSARY	50.00	-
	RESET WHEEL ALIGNMENT-BEFORE REPAIRED.	NOT NECESSARY	100.00	-
	RESET WHEEL ALIGNMENT-AFTER REPAIRED.	NOT NECESSARY	100.00	-
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	100.00	-
	REMOVE AND REPAIR REAR SUSPENSION CROSSMEMBER & REAR AXLE COMPONENTS.	NOT NECESSARY	400.00	-
	REMOVE AND REFIT BOOTLID COMPONENTS.	NOT NECESSARY	100.00	-
			6,100.00	2,760.00
	GRAND TOTAL		18,804.59	9,104.87



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,250.00
---	--	--	----------

Report Ref No. CS3/LPC18017729/R1vd3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.