

1/18/2019

ASS. REC. BY:

REF: C/TPD19011066/P2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kamaliah Kamic

of

SPF

Date/Time: 20/6/2019

Estimated Cost:

Bill to:

OD TP WS+TP RES / OD RES / EVA / INV / MV / CS

To suspect Vehicle No: SKE 2457X

Insured:

At Workshop m/s

Tel:

of

Policy No: MHASPF06000020127

Claim No: TP/1P/25861/2019

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A. 19/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time Action/Instruction () Estimate

SKE 2457X - X

E B

NO-K

Can do

these

form

(Total loss)

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Thursday, 20 June, 2019 6:00 PM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Muhammad Afiq RAHMAT (SPF); Yus Mastari I KHAZALI (SPF); Nor Hidayu ABDUL SAMAD (SPF); Junxiang MA (SPF); Norashikin DAUD (SPF)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **30 vehicles** below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

- a) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBK6016J (TP/IP/25861/2019)
b) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SKE2457X (TP/IP/25861/2019) - (FAIT)

On 19 April 2019 at about 11.45 pm, the deceased was riding motorcycle FBK 6016 J on lane 1 of 6 lanes along CTE towards City when car driver of motor car SKE 2457 X lost control of her vehicle collided onto 3 other vehicle before encroaching onto the path of the deceased resulting in the deceased motorcycle to collide onto the motor car. The deceased was pronounced dead at the scene.

Vehicles to be inspected: FBK6016J - Rider (Deceased)
SKE2457X - Defendant

IO In-Charge: SIO Mohd Yazid

- c) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Bus, CB6563G (TP/IP/31357/2019)

On 15 May 2019 at about 6.07 pm, the driver of motor bus CB 6563 G was travelling along Tuas Road towards Tuas Basin on lane 2 of 3 lanes when the driver collided onto a pedestrian (Deceased) who was running from the driver's left to right. The deceased succumbed to his injuries on the same day in hospital.

Vehicle to be inspected: CB6563G - Defendant

IO In-Charge: SIO Mohd Yazid

- d) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle VCN9549 (TP/IP/32821/2019)

On 24/05/2019 at about 3.36 am, the Deceased was riding motor cycle VCN9549 along PIE (AP) when he lost control and collided onto the centre divider railing. The Deceased sustained fatal injuries and passed away at the accident scene.

Vehicles to be inspected: VCN9549 - Rider (Deceased)

IO In-Charge: SIO Farhan

- e) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Lorry, GBB5739K (TP/IP/33089/2019)