

DATE

ASS. REC. BY:

REF: CHPDI9011211/E

Special Instruction:

SURVYOR:

ASSIGNMENT (Office)

From (Person): Kamaliah Kaula of SPP

Date/Time: 30/6/2019

Estimated Cost: _____ Bill to: _____

OD+TP+WS+TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: GBE 4790B

Insured: _____

at Workshop m/s _____

Tel: _____

of _____

Policy No: MHASPF06000020127

Claim No: TP/IP/24959/2019

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. 11/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time _____

Person Contacted: _____

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>GBE 4790B-X</u>
	<u>500/</u>
	<u>488/</u>

E61

IO In-Charge: IO Dylan Ma

x) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SJD3446M (TP/IP/25257/2019)

On 15 April 2019 at about 6.08pm, the driver was driving his motor car on the right lane of 5 lanes, along Central Boulevard towards Cross Street when the driver lost control of his vehicle and skidded towards the right before the car plunges into a group of pedestrians standing along the pavement. As a result of the accident, multiple victims were conveyed with slight to serious injuries.

Vehicles to be inspected: SJD3446M - Defendant

IO In-Charge: IO Dylan Ma

y) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SGK6971S (TP/IP/35671/2019)

On 04 June 2019 at about 6.57pm, the driver was driving his motor car along car park service road of Blk 809 Hougang Central. Whilst approaching the exit car park gantry, driver claimed he was stepping on his brake. However, his vehicle suddenly surged forward before bashing through the gantry and collided onto another motor car and a pedestrian. As a result of the accident, the pedestrian sustained fracture and was conveyed to Sengkang Hospital.

Vehicles to be inspected: SGK6971S - Defendant

IO In-Charge: IO Dylan Ma

z) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SMES202X (TP/IP/17453/2019)
aa) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SME5695G (TP/IP/17453/2019)

On 20 March 2019 at about 2.40 am. The Deceased was riding his motorcycle along Tampines South Flyover lost control of his motorcycle veered to the left hit onto the left guard railing and fell off from the guard railing and landed onto the centre of 3-lanes along PIE towards ECP. Thereafter, the deceased was ran over by two motor cars, SMES202X and SME5695G. Both vehicles were inspected by Mr Lim Chwee Hai. However, DPP Deborah Lee directed to send both motor cars for full mechanical inspection by LKK Consultant.

Vehicles to be inspected: SMES202X - Involved Party
SME5695G - Involved Party

IO In-Charge: SIO Dzul Hairie

(GI)

Urgent
↑

bb) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Van, GBE4790B (TP/IP/24959/2019)

On 14 April 2019 at about 9.29 pm., the said motor car was involved in an accident along Woodlands Ave 1. The said driver claimed that he lost control because the tyre punctured and he collided onto the victim's front right portion of vehicle. A mechanical inspection is required for motor van, GBE4790B to check whether the front left tyre puncture prior to the accident or after the impact of the collision.

Vehicles to be inspected: GBE4790B - Defendant

IO In-Charge: SIO Norashikin