

ASS. REC. BY:

REF: CS3/III/19011303/TICd3⁵²

Special Instructions:

Surveyor: Taufik

ASSIGNMENT (Office)

merimen

From (Person):

Gabriel Wee

of

III

Date/Time:

26/6/19 @ 1:43pm

Estimated Cost:

Bill to:

OD ☒ FWS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 1584G

Insured:

SHD3143K

at Workshop m/s

Wai Leong Motor

Tel:

9788 2224

of

Blk 1001 Bukit Merah Lane 3 # 01-61

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/06/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

3pm @ 26/6/19

Person Contacted:

Sharon

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(X)
	SJS 1584G : NBA/INC19011254/Y D.O.A: 21/06/2019
	SHD3143K : NBA/INC19011254/Y D.O.A: 21/06/2019
	Disassemble: 27/6/2019 4:55pm

Tanfield

REF

III

ASSIGNMENT

W.E. 229.54y
2009-74y

From _____ Date _____
Estimated Cost _____
OD / TP / WS / TP / RES / OD / RES / EVA / RV / MV
To inspect Vehicle No. _____
at Work Shop No. _____
of _____
Insured _____
Policy No. _____
Claim No. _____
Sum Insured _____ Excess _____
(Client's Record)
Make of Veh. _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Est. or Market Value _____
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Score _____ Consistent? : Yes or No
Est. Repairs _____ days Res. : Yes or No
Lump Sum _____ % 3 Val : Yes or No
CA / REV / REP. / 24 HRS
Date _____ Person Contacted _____
Vehicle: IN / OUT



Veh No. S 5815846 or Regn 2009-74y
Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or _____
Make Toyota Vios E A CC 1497
Colour white APC Insured / Std / RT / NA
Cap Branding 181841 Insured / Std / RT / NA
Emp No _____
C/Nr M2053109305122159
Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ Bunk
Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Modi: ☒ Nil / ☐ STD A/Rim or 185/6.15
Tyre Size F: _____ R: _____
BS / DUN / EXH / VA / GY / ES / LZA / MIC / OITSU / PIR / SUMI /
TOYO / YOKO or TOYO
Front _____ Rear _____
R/Ral 6 mm D/Ral 6 mm
L/Ral 6 mm L/Ral 6 mm
D.O.A. _____ D.O.I. 22/6/13 pm
Survey held at Wai Leng
Des. of Damages: ☒ Frl / ☐ Rear / ☐ OS / ☐ HS / ☐ UR / ☐ Rooftop or
The UR / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to: ☐ : Prelim. Report
1) ☐ : Final Report
Date/Time, File Return to: _____

Days Of Repair: _____
Resurvey No. of Trip: 1

Report Format: PRE
Lump Sum / L.B.L: (\$)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inv. (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation: _____
50 RS. 24
Photos: _____
Others: _____
Total: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	(Not Notified) Edit Reg		26 Jun 2019 00:00 Edit Adj Rpt			
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[\[Created by adjuster\]](#)

CLAIM SUBFOLDER DETAILS

Insured:				
Main Claimant:	Q LEASING, Co. Reg. No.: 53384683L			
Vehicle Reg. No.:	SJS1584G	Date of Loss:	21/06/2019 00:00 - :59	
Claim Type:	TP	Policy/Cover Note No.:	(Comprehensive)	
Vehicle Reg. No. (Insured):	SHD3143K	Policy No. (Claimant):		
		Excess:		
Repairer:	Wai Leong Carcare Centre (HQ) BLK 1001 BUKIT MERAH LANE 3, #01-61, 159718 Bukit Merah - Tel:			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2019]			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 26 June 2019 1:43 PM
To: Yvonne; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Sundari Nagarajan - III
Subject: RE: India Insured SHD3143K [EAL.2019.6376.MK.ya - SJS1584G]
Attachments: 190626-GIA report of SJS1584G(new).pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJS1584G
III INSURED VEHICLE NO. : SHD3143K
DATE OF LOSS : 21.06.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: 26 June, 2019 11:14 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: India Insured SHD3143K [EAL.2019.6376.MK.ya - SJS1584G]

Our ref : 2019.6376.MK.ya - **SJS1584G**
Your ref : **SHD3143K**

India International Insurance Pte Ltd
64 Cecil Street,
#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **SHD3143K**
Comfort Transportation Pte Ltd
383 Sin Ming Drive
GAS Building
Singapore 575717

Dear Sir/Madam,

CLAIMANT: Q LEASING

ACCIDENT INVOLVING SJS1584G & SHD3143K ON 21 JUNE 2019 ALONG EAST COAST PARKWAY NEAR MARINE VISTA EXIT AT ABOUT 0930 HOURS

We are instructed by **Q LEASING** to notify you (the insurer of **SHD3143K**) of a road traffic accident on **21 JUNE 2019 ALONG EAST COAST PARKWAY NEAR MARINE VISTA EXIT AT ABOUT 0930 HOURS** involving our client's vehicle registration number **SJS1584G** and vehicle registration number **SHD3143K** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **SJS1584G** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Dennis Yap Teck Wee - Pal's Appraiser Pte Ltd

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Nivitha (LKK Auto)

From: Yvonne <yvonne@ealc.com.sg>
Sent: Wednesday, 26 June 2019 1:48 PM
To: Motor Claim - III; 'sur@lkkauto.com'; admin-d@lkkauto.com; assignments
Cc: Sundari Nagarajan - III
Subject: PRI: India Insured SHD3143K [EAL.2019.6376.EA.MK.ya - SJS1584G]

Our ref : 2019.6376.EA.MK.ya - **SJS1584G**
Your ref : **SHD3143K**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

India International Insurance Pte Ltd
64 Cecil Street,
#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s India International Insurance Pte Ltd
Vehicle **SJS1584G** inspected as follows by Name:

Before repair	Parts removed	After repair
_____ Signature Date/ Time:	_____ Signature Date/ Time:	_____ Signature Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: Q LEASING

ACCIDENT INVOLVING SJS1584G & SHD3143K ON 21 JUNE 2019 ALONG EAST COAST PARKWAY NEAR MARINE VISTA EXIT AT ABOUT 0930 HOURS

We refer to the above matter wherein we are instructed to act for **Q LEASING**, the owner of vehicle no. **SJS1584G**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SJS1584G** is available as follows, **please call prior appointment** for the pre-repair inspection:

M/s Wai Leong Carcare Centre
Block 1001 Bukit Merah Lane 3
#01-61
Singapore 159718
Tel: 97882224 (Sharon)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2019 09:48
Date Of Accident	21/06/2019 09:30
Exact Location Of Accident	ALONG EAST COAST PARKWAY NEAR MARINE VISTA EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS1584G
Insured/Policyholder	
Name Of Registered Owner	Q LEASING
Co Reg No	53384683L
Email Address	GRACEYSH93@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96989428
Alternative Phone No	OFFICE-96989428

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	DRIVING GRAB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5103987921
Cover Note Number	

Driver

Name of Driver	GRACE YEO SHU HUI
NRIC No	S9305847Z
Date Of Birth	16/02/1993
Occupation	OUTDOOR
Date Of Driving Pass	20/02/2014
Driving Experience	5 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96989428
Fax Number	
Contact Number	OTHERS-96989428
EMail Address	GRACEYSH93@GMAIL.COM

Address BLK 442 JURONG WEST AVENUE 1
#03-752

Postcode 640442

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : PASSENGER
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20190625/2097

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO LARGE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3143K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver TAN CHOO TAN

NRIC/Passport Number S0207232G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GRACE YEO SHU HUI

Approximate Age

Injuries Sustain SERIOUS INJURY

Injured person in which vehicle? SJS1584G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE




1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No. 

Accident Sketch Plan

SKETCH PLAN

ALONG EAST COAST PARKWAY NEAR MARINE
VISTA EX17

B) 835 15846

B) 9HD 3143K

A
A
B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

NO REFERENCE TO POLICE REPORT
7/10/2017

DECLARATION

(We declare the foregoing particulars are true in every respect)

Signature
Date & Time:



Signature
(If driver is not the policyholder)
Date & Time:

26/6/2017
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190625/2097

Police Station Of Origin
Jurong West N P C
700 Corporation Road SINGAPORE 649618
Tel No. 1800-2689999

1 of 3

Report No. T/20190625/2097

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 25/06/2019 15:54	Vide Report No.	Station Diary No 123
---	-----------------	-------------------------

Informant's Particulars

Name of Informant GRACE YEO SHU HUI			Address APT BLK 442 JURONG WEST AVENUE 1 #03-752 SINGAPORE 640442		
ID Type / ID No NRIC NO / S9305847Z			Contact No.: Home/Office: Mobile 96989428		
Nationality SINGAPORE CITIZEN			Email		
Sex Female	Age 26	Date of Birth 16/02/1993	Type of Informant Driver		
Race Chinese			Language		Institution / School Name
Occupation GRAB DRIVER			Driving Licence Information Class 3A Date of Expiry		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/06/2019 09:30	Type of Location: Straight Road
Location: Along Road 1 EAST COAST PARKWAY				
Along East Coast Parkway, near Marine Vista Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD3143K	Car				No Damage	3
SJS1584G	Car				Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190625/2097

Police Station Of Origin
Jurong West N P C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No: T/20190625/2097

CONTINUATION OF REPORT

Driver			
Name	TAN CHOO TAN		ID No. S0207232G
Related Vehicle	SHD3143K (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	GRACE YEO SHU HUI		ID No. S9305847Z
Related Vehicle	SJS1584G (Car)		Contact No. 96989428
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	22/06/2019	Date Discharge	25/06/2019
No. of Days granted Medical Leave	15	Degree of Injury	Serious

Brief Details.

On 21.06.2019, at about 2130hrs, I was driving along East Coast Parkway on the first lane in my vehicle SJS1584G, subsequently, the car in front of me suddenly braked, causing me to effect e-brake, and my car came to a stop. At this point, the vehicle bearing license plate SHD3143K collided with the back of my car and my car jitted forward from the impact. I then alighted my vehicle, and we exchanged particulars with the driver who is Tan Choo Tan. Someone from behind then called the police and police came to attend (ref: G/20190621/0185), however Tan Choo Tan left before the police or the ambulance arrived.

Subsequently when the ambulance arrived, I was not conveyed as I was in a state of shock, and there was not any physical injuries visible at that point in time. It was only when I went home and reached home at about 2310hrs that I realized that I was feeling unwell, and lost a sense of feeling in my left arm. Subsequently, I went to the A&E in NTFGH and was treated there. I was diagnosed with a sensory loss in the left side of my upper body and was given 15 days of MC. I was hospitalized from the 22.06.2019 to 25.06.2019. Hence, I came to make a traffic report.

The back of my car was seriously damaged, with the bumper detached, and a huge dent at the car boot and bumper area. My rear lights were also damaged and broken.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190625/2097

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3
Report No: T/20190625/2097

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

SC2 TAY HUANG DA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NOR HIDAYU BINTE ABDUL

SAMAD

Contact No: 65476423

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

25/06/2019 15:54

Classification Of Case:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 4683L

Vehicle Details

Vehicle No.: SJS1584G
Vehicle to be Exported: No
Intended Deregistration Date: 26 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: VIOS E AUTO
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 1NZX937919
Chassis No.: MR053HY9305122159
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,468.00
Original Registration Date: 30 Jul 2009
First Registration Date: 30 Jul 2009
Transfer Count: 4
Actual ARF Paid: \$11,738.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Jul 2019
PARF Rebate Amount: \$5,869.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$8,754.00
COE Rebate Amount: \$139.00
Total Rebate Amount: \$6,008.00

The information contained herein is correct as at 26 Jun 2019

OK

Learn to trade, practice for free
with \$100,000 of virtual money

OANDA
Click here to register

Toyota Vios

Price Range

Depreciation

2009

Vehicle Type

 Search

Home » Used Cars » Positive Auto » Toyota Vios 1.5A E (New 5-yr COE)

Toyota Vios 1.5A E (New 5-yr COE)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$30,500		
Depreciation	\$6,090 /yr	Reg Date	26-Aug-2009 (5yrs COE left)
Mileage	141,383 km (14.4k /yr)	Manufactured	2009
Road Tax	\$684 /yr	Transmission	Auto
Dereg Value	N.A.	OMV	\$12,717
COE	N.A.	ARF	\$12,717
Engine Cap	1,497 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,095 kg	No. of Owners	3
Type of Vehicle	Mid-Sized Sedan		

Features

Reliable 1.5L VVT-I 4 Cylinders Inline DOHC 16 Valves Engine, 4 Speed Auto Transmission, Dual SRS Airbags, Retractable Side Mirrors With Indicators. View specs of the Toyota Vios (2007-2013)

Accessories

Black Leather Seats, 15" Yokohama BluEarth Tyres With Sports Rims, Toyota CD/AUX/MP3 Player, Reverse Sensor, Door Visor, Solar Film.

Description

New Arrival! Toyota Vios E With Low Mileage Of 14,400km Clocked Per Year! Most Economical & Powerful Vehicle Among Its Class! Famous For It's Low Fuel Consumption & Easily Available Cheap Spare Parts! High Trade-In Value & Flexible Low Interest Financing Package Available To Cater All Your Financial Needs! Pick Your Favourite Number & Contact Our Friendly Sales Consultant For Advice Now! Hurry Up!

Category

COE Car, Premium Ad Car

Status

[Compare](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2019 15:00 Edit Reg		26 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	Q LEASING, Co. Reg. No.: 53384683L		
Vehicle Reg. No.:	SJS1584G	Date of Loss:	21/06/2019 00:00 - :59 [118 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SHD3143K	Policy No. (Claimant):	
		Excess:	
Repairer:	Wai Leong Carcare Centre (HQ) BLK 1001 BUKIT MERAH LANE 3, #01-61, 159718 Bukit Merah - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.




































ALL ASSOCIATED TASKS























[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS1584G
[SHD3143K]
TP
Q LEASING
Jun 21 2019 12:00AM
[-]
Wai Leong Carcare Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
7	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/07/19 11:55	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	27/06/19 09:16	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19011303/T1CD3S2
Date: 17/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJS1584G

Insured Vehicle No : SHD3143K

Date of Loss: 21/06/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS1584G

Make & Model: TOYOTA VIOS, 1.5 (A)

Reg. Date: 30/07/2009 (Man. Year: 2009)

Colour: White

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZX937919

Chassis No: MR053HY9305122159

Odometer: 181841 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Front Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Tyre Size: 185/60R15

Rear Left Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 26/06/2019 Inspected At:

Wai Leong Carcare Centre (HQ)
BLK 1001 BUKIT MERAH LANE 3, #01-61
Singapore 159718

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/17/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2019)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS1584G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >