

*Survey & repair
8.7 @ loan*

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

25 JUN 2019

E S T I M A T E

Estimate No. : b1 51680	Page No. : 1 of 5
Date Estimated : 25/06/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Gerald Faust Kim Seng Road #22-03 Singapore 239432	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL691L	F095724	08/03/2012	335i/4 (A)	0

DESCRIPTION	VALUE
To replace front bumper, attachments and headlamp washer jet.	850 1,275.00
Painting front bumper.	934 1,275.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To replace right headlight.	408 481.00
Sundries.	80.00
Total Labour 1:	3,465.00

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER PANEL TRIM (LINES SRA) <i>repair</i>	1	1,027.25	1,027.25
RH COVER SPRAY NOZZLE PRIMED <i>SEA</i>	1	43.25	43.25
PLAQUE 82MM <i>SEA</i>	1	71.25	71.25
RH TELESCOPING NOZZLE <i>?</i>	1	159.85	159.85
HEADLIGHT RH (XENON/ADAPTIVE) <i>SEA</i>	1	2,501.25	2,501.25
Total Parts :			3,802.85

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51680

Page No. : 2 of 5

Date Estimated : 25/06/2019

Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL691L	F095724	08/03/2012	335i/4 (A)	0

Claims OD / <u>3rd Party</u> Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>08/07/19 @ 15:15</u>	Excess S\$ _____
Surveyor's Name <u>Rahul</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
REPAIR PARTS PHOTO BY SURVEYOR Yes / No _____	PML Yes / No _____
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	3,465.00
Parts	:	3,802.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	508.75
Grand Total	:	7,776.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **